

**HP9000 SERIES 300/400**

***SOFTWARE STATUS BULLETIN***  
**(SSB)**



Information is current as of 11/21/90

Part No. 5960-0682

1190

**HP Computer Museum**  
**[www.hpmuseum.net](http://www.hpmuseum.net)**

**For research and education purposes only.**

## PREFACE

The **SSB\*** lists all known problems in the software product line designated on the cover page. These problems are derived from service requests (SRs) submitted by user's of these products.

There are four separate **SSB** reports contained in this edition. They are separated by a color divider page. Included are:

Section 1 – General S300/and S400 operating system, Databases, Networking and Languages

Section 2 – AdvMail & OpenMail

Section 3 – X10 and X11 products

Section 4 – S300 SRM and related products

All reports have the same organization and consist of five parts as listed below. Each report provides four different methods whereby the known problems can be indexed. The detailed SR reports are listed in part 5. The detailed SR report page numbers are located in the upper right hand corner of each column (printed two per page).

### **1 Software Release Contents (pg 11-12)**

This section *lists the product names, numbers and update/fix levels for all the products* contained in this release. Products that have changed, or are new, are denoted with an asterisk preceding the product name.

### **2 Product Index (pg 13)**

The product index provides the page number on which *detailed SR reports related to a specific product* can be found.

### **3 KPR Number Index (pg 14-18)**

This index is a *sequential list of individual SR numbers* and the page on which they are found.


### **4 Product-Keyword (pg 19-128)**

This index is a *Product-Keyword* sort of SRs. Each entry has a *one line description* of the SR and gives the page on which it is found. Keywords are optional.

### **5 Detailed SR Reports (pg 1-363)**

Each report contains *all available information* relevant to the problem.

**\* The SSB is provided as a benefit of Hewlett-Packard's Account Management, Response Center, and Software Materials support subscriptions.**



Product name	Product number	uu.ff	prev
3179G DISP. STATION	B1001A	07.00	00.00
3778 GATEWAY	98858A	03.00	00.00
3778 GATEWAY UPGRADE	98859A	03.00	00.00
5080 - USER UPGRADE	98856A	03.00	00.00
5080 EMULATOR	98855A	03.00	00.00
5080 GATEWAY UPGRADE	98857A	03.00	00.00
ADA BINDINGS COMMON	ADA-BINDA	00.00	00.00
ADA DS. - 9000/300	98860	04.35	03.25
ADA DS. - COMMON	ADA-DSA	04.35	03.25
ADA SOFTBENCH COMMON	ADA-SBA	00.00	00.00
ADA/300 BINDINGS	98889A	00.00	00.00
ADA/SOFTBENCH 300	92669A	00.00	00.00
AGP/DGL - MU	98600B	07.00	00.00
AXE 16 USER	98595B	07.03	00.00
AXE 16 USER	98595C	07.03	00.00
AXE 2 USER	98515B	07.03	00.00
COBOL/HP-UX S300	35322B	02.00	01.05
COMMON LISP DEVELMNT	HP98678A	02.10	00.00
COMMON LISP EXCUTION	HP98679A	02.10	00.00
COMMON LISP II DE	98688	02.10	00.00
DESIG. JAPANESE FONT	98864A	02.00	00.00
DGL SKELETON	98683X	07.00	00.00
DISPLAY LIST	98674B	07.03	00.00
DISPLAY LIST	98674C	07.03	07.00
DOS COPROCESSOR SFTW	98531A	02.10	00.00
HP PROLOG 1.0	79232U	01.01	00.00
HP SQL/300	79725A	70.00	02.00
HPC++ COMMON	HPCPLUSPLUSA	02.00	00.00
HPC++ S300	B1691A	02.00	00.00
HPUX 6.2 SW BUNDLE	98594A	07.03	00.00
HPUX 7.03 S/W BUNDLE	98594B	07.03	00.00
JAPANESE NL I/O	98861A	07.00	06.10
KOREAN NL I/O	98609A	07.00	06.10
LAN LINK 9000/300	98171A	00.00	00.00
OV NM SERVER 300 DEV	36985A	01.00	00.00
OV NM SERVER 300 RUN	36990A	01.00	00.00
PERSONAL VISUALIZER	B1760A	07.00	00.00
PERSONAL VISUALIZER	B1760B	07.03	00.00
PHIGS DEV. ENVIRON.	B1759A	02.00	00.00
PHIGS RUN TIME ENV.	B1685A	02.00	00.00
PROG. ENVIRON. - MU	98597C	06.50	00.00
RJE/300	31447A	06.00	05.03
RJE/300	50967A	01.00	00.00
S300 GENERAL HPUX	98680B	06.05	00.00
SERIES 300 GKS	98672B	07.03	00.00
SERIES 300 GKS	98672C	07.03	00.00
SIMP-CHINESE NL I/O	98851A	07.00	06.10
SIMPLEX KOREAN FONT	98610A	02.00	00.00
SIMPLEX T-CHINESE	98854A	02.00	00.00
SIMPLX JAPANESE FONT	98591A	02.00	00.00
SNA LU 6.2 300	98162A	00.00	00.00
SNA3270 300	36590A	03.20	00.00
SNA3270 300	36591A	03.20	00.00
SNA3270 300	36978A	00.00	00.00
SNA3270 300	36979A	00.00	00.00

## Software release contents

PAGE I 2

Product name	Product number	uu.ff	prev
SNA3770 300	36976A	07.01	00.00
SNA3770 300	98184A	01.10	00.00
SNA3770 300	98188A	01.10	00.00
SNALINK 300	36592A	03.21	03.20
SNALINK 300/GW	36593A	03.21	03.20
SOFT PC FOR 9000/300	98870A	01.30	00.00
SOFT PC FOR 9000/300	98870B	02.01	00.00
SOFT PC FOR 9000/300	98870C	02.03	02.01
STARBASE RAD & RAY	98885A	01.01	00.00
STARBASE RAD & RAY	98885B	02.00	01.00
TRAD-CHINESE NL I/O	98853A	07.00	06.10
VERSATEC	98053A	05.20	00.00
VISUAL EDITOR	B1500A	01.00	00.00
X.25/300 LINK	36941A	07.00	02.00
X.400 SERV SOFTWARE	32058A	00.00	00.00

Product name	Product number	SSB ISSUE DATE	Page
300/800 COMMON	97089-XXXXX	11/21/90	1
3179G DISP. STATION	B1001A	11/21/90	4
ADA DS. - 9000/300	98860	11/21/90	5
ADA DS. - COMMON	ADA-DSA	11/21/90	21
ADA SOFTBENCH COMMON	ADA-SBA	11/21/90	74
AGP/DGL - MU	98600B	11/21/90	77
COBOL/HP-UX S300	35322B	11/21/90	78
COMMON LISP DEVELMNT	HP98678A	11/21/90	80
COMMON LISP EXECUTION	HP98679A	11/21/90	122
DOS COPROCESSOR SFTW	98531A	11/21/90	123
HP PROLOG 1.0	79232U	11/21/90	127
HP SQL/300	79725A	11/21/90	128
HP SQL/300 C APG	79725-90014	11/21/90	182
HPC++ COMMON	HPCPLUSPLUSA	11/21/90	183
HPC++ S300	B1691A	11/21/90	215
OV NM SERVER 300 DEV	36985A	11/21/90	216
PHIGS DEV. ENVIRON.	B1759A	11/21/90	219
PHIGS FORTRAN MNL.	B1759-90001	11/21/90	222
PROGRAMMERS DOC SET	98794A	11/21/90	223
RJE/300	31447A	11/21/90	232
RJE/300	50967A	11/21/90	235
S300 GENERAL HPUX	98680B	11/21/90	237
SERIES 300 GKS	98672B	11/21/90	304
SNA3270 300	36590A	11/21/90	305
SNA3270 300	36591A	11/21/90	307
SNA3770 300	98184A	11/21/90	309
SNA3770 300	98188A	11/21/90	310
SNALINK 300	36592A	11/21/90	311
SNALINK 300/GW	36593A	11/21/90	314
SOFT PC FOR 9000/300	98870A	11/21/90	318
SOFT PC FOR 9000/300	98870B	11/21/90	340
SOFT PC FOR 9000/300	98870C	11/21/90	357
STARBASE RAD & RAY	98885A	11/21/90	358
X.400 SERV SOFTWARE	32058A	11/21/90	362

KPR number	page	KPR number	page	KPR number	page	KPR number	page
1650040139	237	4000033464	83	4000034116	102	4000055467	22
1650040147	238	4000033472	84	4000034124	103	4000055475	22
1650041160	238	4000033480	84	4000034132	103	4000056341	23
1650041749	122	4000033498	85	4000034140	103	4000056465	23
1650042044	127	4000033506	85	4000034157	104	4000056556	6
1650043760	307	4000033514	85	4000034165	104	4000057836	6
1650050294	239	4000033522	86	4000034173	104	4000057919	23
1650057828	239	4000033530	86	4000034181	105	4000058446	123
1650059014	128	4000033548	87	4000034199	105	4000070896	23
1650063933	304	4000033555	87	4000034207	106	4000070938	7
1650070474	240	4000033563	88	4000034215	106	4000071258	24
1650074385	240	4000033571	88	4000034223	106	4000071357	24
1650076091	240	4000033589	89	4000034231	107	4000071423	25
1650076422	241	4000033597	89	4000034249	107	4000071431	25
1650082529	241	4000033605	89	4000034256	107	4000072603	25
1650085514	242	4000033613	90	4000034264	108	4000078683	124
1650086041	304	4000033621	90	4000034272	108	4000082677	25
1650088997	242	4000033639	90	4000034280	109	4000082727	26
1650090753	243	4000033647	91	4000034298	109	4000082792	26
1650091587	309	4000033654	91	4000034306	109	4000082909	27
1650093328	243	4000033662	92	4000034314	110	4000082925	8
1650093351	243	4000033670	92	4000034322	110	4000084970	235
1650100172	244	4000033688	92	4000034330	110	4000089011	28
1650100230	244	4000033696	93	4000034348	110	4000089037	28
1650101147	245	4000033704	93	4000034355	111	4000089151	28
1650101246	246	4000033712	93	4000034363	111	4000089268	28
1650102194	246	4000033720	94	4000034371	112	4000089466	29
1650107045	310	4000033902	94	4000034389	112	4000089789	29
1650119883	123	4000033910	94	4000034397	112	4000089797	29
1650130989	246	4000033928	95	4000034405	113	4000089870	29
1650134353	247	4000033936	95	4000034413	113	4000089953	30
1650139675	21	4000033944	95	4000034421	114	4000089979	30
4000003756	247	4000033951	96	4000034439	114	4000090860	223
4000003830	248	4000033969	96	4000034447	114	4000091660	318
4000017020	249	4000033977	96	4000034454	114	4000091678	318
4000019570	249	4000033985	97	4000034462	115	4000091702	223
4000023648	1	4000033993	97	4000034462	115	4000091728	318
4000027565	235	4000034009	97	4000034471	116	4000091736	319
4000033357	80	4000034017	98	4000034744	116	4000091926	319
4000033373	80	4000034025	99	4000035634	21	4000091934	320
4000033381	80	4000034033	99	4000036616	117	4000091983	320
4000033399	81	4000034041	100	4000040410	5	4000091991	320
4000033407	81	4000034058	100	4000046110	118	4000092015	321
4000033415	82	4000034066	100	4000046128	118	4000092023	321
4000033423	82	4000034074	101	4000046433	118	4000092049	322
4000033431	82	4000034082	101	4000046441	119	4000092056	322
4000033449	83	4000034090	101	4000046771	119	4000092072	323
4000033456	83	4000034108	102	4000047415	5	4000092098	323



KPR number	page	KPR number	page	KPR number	page	KPR number	page
4000092106	324	4000095455	334	4700594309	132	4700822148	38
4000092130	325	4000095463	334	4700664219	132	4700822155	39
4000092148	325	4000095505	334	4700667519	314	4700822163	39
4000092205	326	4000095588	335	4700667568	311	4700822171	39
4000092437	249	4000095695	335	4700667576	315	4700822189	39
4000093005	30	4000095810	335	4700667584	316	4700822197	40
4000093039	235	4000096115	226	4700667600	307	4700822205	40
4000093161	31	4000096149	34	4700667618	316	4700822213	41
4000093203	31	4000096164	34	4700667626	305	4700822247	41
4000093310	31	4000096172	34	4700667634	305	4700822254	41
4000093328	32	4000096206	336	4700674499	316	4700822270	41
4000093401	124	4000096230	35	4700685560	182	4700822288	42
4000093419	32	4000096321	36	4700687905	132	4700822304	42
4000093435	32	4000096339	36	4700688226	133	4700822312	42
4000093468	32	4000096347	37	4700712463	133	4700822320	43
4000093492	236	4000096396	358	4700713743	134	4700822346	43
4000093567	124	4000096412	358	4700714352	134	4700822353	44
4000093666	327	4000096438	358	4700714915	309	4700822379	44
4000093674	327	4000096446	359	4700720177	134	4700822387	44
4000093690	327	4000096461	359	4700733758	317	4700822395	44
4000093708	328	4000096479	359	4700734566	312	4700822403	45
4000093757	328	4000096487	250	4700740589	135	4700822494	45
4000093765	328	4000097113	360	4700743401	135	4700822510	45
4000093781	329	4000097121	360	4700747246	136	4700822528	46
4000094060	250	4000097139	360	4700748368	136	4700822866	46
4000094243	33	4000097147	361	4700753293	137	4700822874	46
4000094342	223	4000097154	361	4700768077	137	4700822882	47
4000094615	224	4000097428	258	4700768416	138	4700822957	47
4000094623	224	4000097451	259	4700774497	260	4700826735	78
4000094631	224	4000097865	259	4700776633	138	4700827220	9
4000094656	225	4000098293	226	4700776641	138	4700829655	142
4000094664	225	4000098301	226	4700777813	139	4700829911	47
4000094904	329	4000098327	227	4700778951	140	4700829952	143
4000094912	329	4000098343	227	4700793570	140	4700831057	48
4000094920	330	4000098533	361	4700794388	140	4700831065	49
4000094938	225	4000098558	2	4700795872	141	4700831073	50
4000095026	330	4700419606	314	4700795898	141	4700831826	51
4000095034	331	4700420307	311	4700795914	141	4700831875	52
4000095042	331	4700441717	128	4700801597	260	4700831891	53
4000095059	331	4700451161	128	4700803395	141	4700835306	53
4000095067	331	4700455444	129	4700820555	37	4700835397	54
4000095075	332	4700474577	311	4700820704	142	4700835561	144
4000095083	332	4700481937	129	4700822031	8	4700837666	144
4000095091	332	4700539148	130	4700822056	37	4700837781	55
4000095109	333	4700552232	130	4700822106	37	4700839605	55
4000095117	333	4700579508	131	4700822114	38	4700839696	56
4000095190	225	4700590638	131	4700822122	38	4700839746	10
4000095448	333	4700594275	131	4700822130	38	4700839753	57

KPR number	page	KPR number	page	KPR number	page	KPR number	page
4700839761	57	4700882134	64	4700891911	191	4700900720	68
4700839928	145	4700882142	65	4700891945	191	4700901041	261
4700840561	58	4700882399	16	4700891952	192	4700901470	161
4700842864	11	4700882936	153	4700891978	192	4700902122	162
4700842872	58	4700882951	153	4700892448	160	4700902734	215
4700842989	145	4700882985	154	4700892612	160	4700903591	69
4700843672	59	4700883009	155	4700892992	192	4700904516	70
4700843680	12	4700883033	156	4700893008	192	4700905174	70
4700849927	146	4700883066	184	4700893016	193	4700905182	70
4700852525	362	4700883074	18	4700893057	193	4700905216	216
4700852574	146	4700883124	362	4700893065	193	4700905877	162
4700852830	13	4700883280	156	4700893073	194	4700906263	162
4700855932	146	4700883306	157	4700893081	194	4700906339	204
4700857698	60	4700883322	157	4700893099	194	4700906347	204
4700857714	61	4700883330	157	4700893107	194	4700907592	216
4700857938	147	4700883413	158	4700893206	195	4700907600	216
4700858837	147	4700883488	65	4700893487	195	4700907618	216
4700859488	148	4700883959	158	4700893503	195	4700907915	216
4700859660	148	4700883975	158	4700893511	196	4700908079	216
4700861740	61	4700884270	184	4700893529	196	4700908137	163
4700862961	14	4700884635	78	4700893537	196	4700908251	163
4700863472	148	4700885632	362	4700893545	196	4700908285	164
4700863688	15	4700885749	185	4700893552	197	4700908319	164
4700863746	15	4700886150	19	4700893578	197	4700908491	205
4700866459	62	4700886598	185	4700893586	197	4700908509	205
4700866475	62	4700886796	159	4700893610	198	4700908517	205
4700868216	2	4700887711	67	4700893628	198	4700908525	206
4700868893	15	4700887851	340	4700893651	198	4700908533	206
4700869537	149	4700887976	185	4700894113	199	4700908541	206
4700875286	63	4700888925	186	4700894121	199	4700908558	206
4700875468	149	4700889394	186	4700894139	199	4700908566	207
4700876060	151	4700890228	159	4700894147	200	4700908574	207
4700876128	151	4700890368	186	4700894154	200	4700908582	207
4700876516	151	4700890392	186	4700894162	200	4700908921	217
4700876714	362	4700890830	187	4700894188	201	4700909168	165
4700877282	152	4700890848	187	4700894204	201	4700910489	71
4700877944	16	4700890939	74	4700894535	201	4700911537	165
4700878447	152	4700890947	74	4700896944	161	4700911818	340
4700879395	78	4700890962	75	4700897009	202	4700912998	165
4700879403	183	4700890970	75	4700897017	202	4700913459	217
4700879411	183	4700891754	188	4700898460	202	4700913467	217
4700879924	261	4700891762	188	4700898478	202	4700915462	166
4700880062	78	4700891796	189	4700898734	203	4700916627	207
4700880245	64	4700891804	189	4700899278	68	4700916833	4
4700880393	183	4700891846	190	4700899401	203	4700916841	4
4700880401	183	4700891853	190	4700899815	161	4700917161	208
4700880419	184	4700891879	190	4700900100	203	4700917179	218
4700880427	184	4700891887	190	4700900118	204	4700917476	218

KPR number	page	KPR number	page	KPR number	page	KPR number	page
4700917500	218	4700922245	349	4700923300	167	5000170167	120
4700919837	208	4700922252	350	4700923318	168	5000170340	262
4700921429	166	4700922260	350	4700923326	169	5000178038	263
4700921700	340	4700922278	350	4700923334	169	5000184275	263
4700921718	341	4700922286	350	4700923342	170	5000192682	263
4700921726	341	4700922294	351	4700923367	170	5000193656	120
4700921734	341	4700922310	351	4700926865	171	5000195735	77
4700921742	341	4700922328	351	4700927459	209	5000198770	264
4700921759	208	4700922336	351	4700927467	209	5000216697	264
4700921767	208	4700922344	351	4700928325	209	5000219485	265
4700921775	342	4700922351	351	4700929372	362	5000220160	265
4700921783	342	4700922369	351	4700929570	71	5000221259	266
4700921791	337	4700922377	352	4700929679	171	5000224683	266
4700921809	343	4700922385	352	4700929687	172	5000225904	267
4700921825	343	4700922393	352	4700931188	210	5000228635	267
4700921833	343	4700922401	352	4700931626	210	5000232702	268
4700921858	343	4700922419	352	4700931634	211	5000233601	268
4700921866	343	4700922427	352	4700931642	211	5000236984	269
4700921874	344	4700922435	352	4700931667	211	5000244236	269
4700921882	337	4700922443	353	4700931675	212	5000260547	179
4700921890	344	4700922450	353	4700933028	172	5000271213	269
4700921908	344	4700922468	353	4700933580	219	5000272898	121
4700921916	344	4700922476	353	4700933598	219	5000280461	270
4700921965	345	4700922484	353	4700933606	222	5000286476	270
4700921973	345	4700922492	353	4700933788	172	5000290544	271
4700921981	345	4700922500	354	4700934240	212	5000296855	3
4700921999	345	4700922518	354	4700936260	212	5000298687	271
4700922005	345	4700922526	354	4700937037	173	5000299735	272
4700922013	345	4700922534	354	4700938225	173	5000396648	272
4700922021	346	4700922583	354	4700939512	175	5000397711	272
4700922039	346	4700922591	354	4700941633	175	5000397737	274
4700922054	346	4700922757	354	4700941799	176	5000400846	274
4700922070	346	4700922765	354	4700941898	362	5000404012	276
4700922088	346	4700922773	355	4700942342	176	5000410191	276
4700922096	346	4700922781	355	4700942466	212	5000417394	277
4700922104	346	4700922799	355	4700942490	220	5000419028	277
4700922112	347	4700922807	355	4700945311	213	5000419770	277
4700922120	347	4700922815	355	4700945386	213	5000420117	278
4700922138	347	4700922823	355	4700945683	177	5000420307	227
4700922146	347	4700922831	355	4700946400	177	5000429019	125
4700922153	347	4700922849	355	4700946715	177	5000430165	228
4700922161	348	4700922856	356	4700946814	177	5000436899	278
4700922179	348	4700922864	356	4700947523	19	5000437129	279
4700922187	348	4700922880	356	4700948133	178	5000440180	279
4700922203	348	4700922914	357	4700949016	178	5000443366	305
4700922211	349	4700923094	356	4700949685	179	5000445296	280
4700922229	349	4700923268	166	4700949701	179	5000448654	281
4700922237	349	4700923284	167	5000121756	262	5000456640	125

KPR number	page	KPR number	page	KPR number	page	KPR number	page
5000458059	281	5000482943	286	5000510636	296	5000558130	73
5000458380	282	5000484337	287	5000511394	297	5000558338	362
5000461467	228	5000484352	180	5000517565	297	5000566836	180
5000461822	229	5000484360	231	5000519504	297	5000566851	180
5000462242	229	5000484378	287	5000520528	312	5000568196	180
5000463372	337	5000487363	287	5000522854	78	5000579755	302
5000464107	338	5000489187	231	5000522896	298	5000581595	303
5000465161	282	5000493288	287	5000523977	298	5000595447	213
5000467480	230	5000493478	288	5000527143	339	9999004824	232
5000468884	283	5000493999	288	5000527226	298	9999004825	232
5000470922	283	5000495978	289	5000527929	298	9999004826	232
5000471979	283	5000496729	289	5000529883	299	9999004848	232
5000474726	338	5000496885	290	5000535146	72	9999004961	233
5000475186	230	5000499038	291	5000537837	300	9999004997	233
5000475848	284	5000500520	291	5000538983	300	9999005048	233
5000476200	284	5000501296	292	5000538991	300	9999005097	234
5000477828	284	5000502997	293	5000539379	300	9999005225	234
5000478107	285	5000503367	295	5000542357	301	9999005230	234
5000479725	126	5000505990	295	5000542688	313	9999005359	234
5000481465	285	5000508044	295	5000547547	302	9999005459	234
5000482844	286	5000508911	296				

CUMULATIVE KEYWORD INDEX

- 300/800 COMMON - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu	ff	Description	KPR number	page
*****none*****	97089-XXXXX	00	00	Subject: bug in wc documentation	4000098558	2
AWK	97089-XXXXX	00	00	How to configure the 2nd serial I/O port for the 808/815 isn't documented	4700868216	1
DOCUMENTATION	97089-XXXXX	00	00	Errors in awk documentation	4000023648	1
	97089-XXXXX	00	00	Periph Inst Gde, give switch setting for 98550A when 98556A is added.	5000296855	3

- 3179G DISP. STATION - SSB ISSUE DATE: 11/21/90

*****none*****	B1001A	07	00	Programmed Symbols and Image Symbols display wrong on HP700/X terminal.	4700916841	4
	B1001A	01	01	Sense code 08710000 and a negative response are returned at logon time.	4700916833	4

- ADA DS. - 9000/300 - SSB ISSUE DATE: 11/21/90

*****none*****	98860	04	35	Object value corrupted by assignment of array with certain lower bound	4700822031	8
	98860	04	35	Abort never occurs without task reaching sync. point	4700827220	9
	98860	04	35	PROGRAM_ERROR may occur when lib pkg has record w/ dyn array components	4700839746	10
	98860	04	35	Unhandled exception in main subprogram incorrectly kills library tasks	4700842864	11
	98860	04	35	Incorrect aggregate for packed array of a subtype of Boolean	4700843680	12
	98860	04	35	The result of fixed point division is rounded down.	4700852830	13
	98860	04	35	UNIX_ENV not in predefined library as documented.	4700863688	15
	98860	04	35	File name expansion works incorrectly if working directory is /	4700868893	15
	98860	04	35	Incorrect slice assignment when target & source are ref. by same pointer	4700882399	16
	98860	04	35	FLU tools misbehave when arguments are 81 characters or longer.	4700883074	18
	98860	04	34	Ada.Make utility does not work on Ada/300 release 4.35	4700862961	14
	98860	03	00	Constant folding should raise NUMERIC_ERROR but raises CONSTRAINT_ERROR	4000040410	5
	98860	03	00	Unhandled exceptions in a task may fail to produce a traceback.	4000047415	5
	98860	03	00	Poor error message when a subprogram does not conform with its spec	4000070938	7
ADA	98860	03	00	The MACHINE_ROUNDS attribute is wrong for fixed point types	4000082925	8
	98860	03	00	ADDRESS returns bad value if applied to program unit not yet elaborated	4000056556	6
RUNTIME	98860	03	00	No STORAGE_ERROR (or user logged-off) for task stack limit exceeded	4000057836	6
	98860	04	35	Heap memory lost on close of file	4700947523	19
TOOLS	98860	03	25	Shared memory utility "shmat" interferes with Ada heap	4700863746	15
	98860	04	35	Suppressing uncalled subprograms incorrectly turns on binder listing	4700877944	16
	98860	04	35	Binder aborts when considering too many unused subprograms for deletion	4700886150	19

- ADA DS. - COMMON - SSB ISSUE DATE: 11/21/90

*****none*****	ADA-DSA	04	35	AdaProbe's STEP fails on exceptions raised via SIGILL, SIGSEGV or SIGFPE	4000071258	24
	ADA-DSA	04	35	Certain AdaProbe commands following an XTRA.INVOKE are not executed	4000093419	32
	ADA-DSA	04	35	AdaProbe XTRA.EDIT.FIND cmd has non-UNIX concept for regular expressions	4000093435	32
	ADA-DSA	04	35	DISPLAY option of the AdaProbe XTRA.LEARN.EXECUTE cmd works improperly	4000093468	32
	ADA-DSA	04	35	FIX'BASE has incorrect values for attributes 'FIRST and 'LAST	4000094243	33
	ADA-DSA	04	35	AdaProbe decodes the PARAMETER string of EXEC.RESTART inconsistently	4700820555	37
	ADA-DSA	04	35	Assembly output shows misleading record alignment values	4700822056	37
	ADA-DSA	04	35	AdaProbe's XTRA.LEARN.TEACH uses undocumented cursor movement commands	4700822171	39
	ADA-DSA	04	35	AdaProbe does't detect if the program has been removed from the library	4700822189	39
	ADA-DSA	04	35	XTRA.INVOKE within .ada.proberc results in deadlock or INTERNAL_ERROR	4700822197	40

Keyword	Product number	uu.ff	Description	KPR number	page
*****none*****	ADA-DSA	04.35	AdaProbe's online help should contain the same info as the manual.	4700822205	40
	ADA-DSA	04.35	AdaProbe's EXEC STEP from a RETURN may jump to another RETURN point.	4700822247	41
	ADA-DSA	04.35	AdaProbe INTERNAL ERROR when INVOKE file command's strin parm > 85 chars	4700822254	41
	ADA-DSA	04.35	AdaProbe cannot OBJECT_EXAMINE/ASSTGN a separate package body object.	4700822270	41
	ADA-DSA	04.35	AdaProbe detects "Exec Error" at START RESET.1 on EXEC.RESTART.	4700822288	42
	ADA-DSA	04.35	CANCEL of online HELP is inconsistent with the other AdaProbe commands	4700822304	42
	ADA-DSA	04.35	ADACOMP generates incorrect AdaProbe line codes for IF-ELSIF statements.	4700822312	42
	ADA-DSA	04.35	BREAK_RAISE (CURRENT) reacts differently after used with (INTERACTIVE)	4700822320	43
	ADA-DSA	04.35	AdaProbe's XTRA.WINDOWS.WRITE incorrectly deletes blank source lines	4700822346	43
	ADA-DSA	04.35	Several AdaProbe commands overwrite existing files without warning	4700822353	44
	ADA-DSA	04.35	AdaProbe's XTRA.LEARN.TEACH doesn't record mouse input	4700822379	44
	ADA-DSA	04.35	AdaProbe's EXEC.RESTART with incomplete parameters causes INTERNAL ERROR	4700822387	44
	ADA-DSA	04.35	AdaProbe unable to restart after error termination in user program	4700822395	44
	ADA-DSA	04.35	AdaProbe may display an extra box mark when the screen is resized in X11	4700822403	45
	ADA-DSA	04.35	AdaProbe fails to open an X window, it doesn't cleanup after itself.	4700822494	45
	ADA-DSA	04.35	If pseudo token EOFMARK in error message could be better	4700822510	45
	ADA-DSA	04.35	"Too many indicators" message may be unclear and can be truncated	4700822528	46
	ADA-DSA	04.35	Inconsistent AdaProbe handling of quoted strings w/in INVOKE file	4700822882	47
	ADA-DSA	04.35	AdaProbe's OBJECT_EXAMINE gives wrong value for some record components	4700822957	47
	ADA-DSA	04.35	Creation of direct access file that exists doesn't delete old file	4700831826	51
	ADA-DSA	04.35	FLOAT_IO.GET on STRINGS does not raise DATA_ERROR on INTEGER literal	4700831875	52
	ADA-DSA	04.35	Non-blocking open for a terminal can block	4700831891	53
	ADA-DSA	04.35	Bad error message for conversion of string catenation.	4700835306	53
	ADA-DSA	04.35	Subunit incorrectly hides renaming declaration of derived function.	4700835397	54
	ADA-DSA	04.35	Library cannot be deleted with ada.rmlib when created previously	4700837781	55
	ADA-DSA	04.35	Instantiation of generic in package spec raises PROGRAM_ERROR	4700839605	55
	ADA-DSA	04.35	Ada tasks that call interface code may behave incorrectly	4700840561	58
	ADA-DSA	04.35	If two people try "ada.mklib" at same time, one may not finish	4700842872	58
	ADA-DSA	04.35	Compiler aborts on invalid comparison involving renamed "="	4700843672	59
	ADA-DSA	04.35	Listing process does not check for I/O errors, allows SIGPIPE to occur	4700857698	60
	ADA-DSA	04.35	The Unit Manager does not list desired units when library is large.	4700857714	61
	ADA-DSA	04.35	Paths that end with + or .. may be reported by the NAME function	4700866459	62
	ADA-DSA	04.35	Working directory not restored after error when it could be	4700866475	62
	ADA-DSA	04.35	Improve Appendix F so that it describes how to use RECORD_SIZE FORM parm	4700880245	64
	ADA-DSA	04.35	Ada compiler gives meaningless diagnostic and aborts.	4700882134	64
	ADA-DSA	04.35	If the environment variable ENV is set some ada.xxx commands may fail	4700882142	65
	ADA-DSA	04.35	Compiler gives variety of incorrect errors on too many units in library	4700883488	65
	ADA-DSA	04.35	Change default task stack size to 32K.	4700905174	70
	ADA-DSA	04.35	AdaProbe can't display FOR variables	4700905182	70
	ADA-DSA	04.34	Dynamic in-out slice of bit packed boolean array uses wrong elements	4000096230	35
	ADA-DSA	04.34	Front end incorrectly folds constant mod expression	4000096321	36
	ADA-DSA	04.34	HLOPT incorrectly removes good code after FIXED_LARGE attribute.	4700831057	48
	ADA-DSA	04.34	HLOPT incorrectly removes checks, causing bad results	4700831065	49
	ADA-DSA	04.34	HLOPT incorrectly thinks conversion will raise error	4700831073	50
	ADA-DSA	04.31	Setting TASK_STORAGE_SIZE too small not detected	4000096339	36
	ADA-DSA	04.31	Floating point I/O with illegal number causes program to hang	4700829911	47
	ADA-DSA	04.30	Time slicing seems to be ineffective in heavy I/O situations	4700861740	61
	ADA-DSA	04.30	Two ada.mklibs of the same library at the same time can both fail	4000096347	37
	ADA-DSA	04.30	Library manager family information can be "out of date"	4700839753	57

Keyword	Product number	uu.ff	Description	KPR number	page
*****non*****	ADA-DSA	04.30	Mend and Rename allowed with libraries locked, locks may be lost	4700839761	57
	ADA-DSA	04.10	Nested generic instantiation causes compiler to abort	4000093005	30
	ADA-DSA	04.10	Wrong expression eval order when assigning overlapping array slices	4000093203	31
	ADA-DSA	04.10	Wrong HLO effect for variable tested after LOOP which may alter variable	4000093310	31
	ADA-DSA	04.10	Wrong HLO effect when S'LAST is compared to 0, where S is a STRING param	4000093328	32
	ADA-DSA	04.10	Redefined operator may incorrectly not be hidden by a later homograph	4700839696	56
	ADA-DSA	03.25	RENAMING of a component of a transient record causes compiler abort	4000070896	23
	ADA-DSA	03.25	AdaProbe VIEW_NEW incorrectly omits construction statements (eg exceptions)	4000071357	24
	ADA-DSA	03.25	AdaProbe does not detect abnormal termination in interfaced code.	4000071423	25
	ADA-DSA	03.25	System can lock-up when keys are pressed too rapidly in AdaProbe (X11).	4000071431	25
	ADA-DSA	03.25	AdaProbe INTERNAL_ERROR on OBJECT command of generic spec/body object	4000072603	25
	ADA-DSA	03.25	Incorrect error indicator position for infix or inlined function calls	4000082792	26
	ADA-DSA	03.25	AdaProbe's EXEC.RESTART command should signal when loading is complete	4000089011	28
	ADA-DSA	03.25	AdaProbe reverse video disappears when breakpoint set on current line	4000089151	28
	ADA-DSA	03.25	Inlining side-effect functions may affect normal program execution	4000089268	28
	ADA-DSA	03.25	No ambiguity detected in some cases involving overloaded operators	4000089466	29
	ADA-DSA	03.25	Suggestion: AdaProbe EXEC.WHERE cmd should display library unit name	4000089789	29
	ADA-DSA	03.25	AdaXref crashes when library mode file omits "use <library>" as 1st line	4000089797	29
	ADA-DSA	03.25	CALENDAR functions TIME_OF and SPLIT return wrong results for leap year	4000089870	29
	ADA-DSA	03.25	Wrong generic subprogram parameter association for "=" and "/="	4000089953	30
	ADA-DSA	03.25	"-C" compiler option shouldn't affect code of all generic instantiations	4000089979	30
	ADA-DSA	03.25	Unchecked conversion as a function result cannot always be returned	4000096149	34
	ADA-DSA	03.25	Changing terminal characteristics using termio() with tasking fails	4000096172	34
	ADA-DSA	03.25	Using the ESC key in AdaProbe key binding causes an INTERNAL_ERROR	4700822106	37
	ADA-DSA	03.25	Software line control chars used in AdaProbe key bindings cause problems	4700822114	38
	ADA-DSA	03.25	Linked units removed or in locked libraries confuse AdaProbe	4700822122	38
	ADA-DSA	03.25	The menu cursor does not trace AdaProbe's Up_Key in dumb terminal mode	4700822130	38
	ADA-DSA	03.25	AdaProbe's OBJECT.EXAMINE.QUALIFICATION does not detect invalid input	4700822148	38
	ADA-DSA	03.25	AdaProbe's XTRA.VIEW.LIST incorrectly displays all possible line types	4700822155	39
	ADA-DSA	03.25	AdaProbe Windows incorrectly repositioned when main X window is resized	4700822163	39
	ADA-DSA	03.25	AdaProbe PROGRESS may move the cursor to a non-visible source area	4700822213	41
	ADA-DSA	03.25	Menu selected HELP from within an AdaProbe submenu is out of context	4700822866	46
	ADA-DSA	03.20	Abnormal HLO effect for comparison of fixed types in an IF statement	4700822874	46
	ADA-DSA	03.00	Compiler rejects RENAMED entities in separate clauses.	4000093161	31
	ADA-DSA	03.00	DEFAULT command does not attempt to clarify ambiguous abbreviations	4000035634	21
	ADA-DSA	03.00	Compiler goes into an infinite loop on ambiguous overloading	4000082677	25
	ADA-DSA	03.00	Compiler gets INTERNAL_ERROR on fixed point with negative delta	4000082727	26
	ADA-DSA	03.25	AdaXref does not create "introduced" procedure in generic instantiation	4000055467	22
	ADA-DSA	03.25	AdaXref creates irrelevant "renaming procedure" in generic instantiation	4000055475	22
	ADA-DSA	03.25	AdaFormat abnormal early line folding in col 60 of proc body w/no parms	4000056341	23
	ADA-DSA	03.25	AdaFormat produces ugly list of identifiers in multiple declaration	4000056341	23
	ADA-DSA	03.00	Compiler crash when large unit w/generics compiled with "-k" option	4000057919	23
	ADA-DSA	04.35	Compiler gives incorrect error on 'SIZE clause for a private type	4700875286	63
	ADA-DSA	04.35	Size of record component that is mutant record cannot exceed 8192 bytes	4700887711	67
	ADA-DSA	04.35	Compiler needs "-u" to avoid infinite loop on too many generic instances	4700904516	70
	ADA-DSA	04.35	Bad error message on library exceeding max size of 33,553,408 bytes	4700910489	71

ADA

COMPILER



- ADA DS. - COMMON - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
COMPILER RUNTIME	ADA-DSA	04.35 Error not detected when subunit matches wrong overloaded subprogram	4700929570	71
	ADA-DSA	04.35 SEQUENTIAL_IO_END_OF_FILE fails if BUFFER_SIZE FORM parameter used	1650139675	21
	ADA-DSA	04.35 TEXT_IO.SET_INPUT_on_closed file can cause STATUS_ERROR on re-OPEN	4700900720	68
	ADA-DSA	04.35 Input from FIFO pipes incorrectly reads to far ahead, causing blocking	4700903591	69
	ADA-DSA	04.35 FLOAT_IO.PUT incorrectly raises LAYOUT_ERROR on large negative number.	5000558130	73
TOOLS	ADA-DSA	04.35 ada.make incorrectly does not compile units dependent on invalid link	4700899278	68
	ADA-DSA	04.35 ada.mklib needs read&search perms on all dirs in paths of libs in family	5000535146	72

- ADA SOFTBENCH COMMON - SSB ISSUE DATE: 11/21/90

*****none*****	ADA-SBA	00.00 Resizing of FLU Managers may corrupt window layout	4700890939	74
	ADA-SBA	00.00 FLU encapsulations may not run on remote data	4700890947	74
	ADA-SBA	00.00 Dev. Mgr. incorrectly identifies Ada Static Analysis files as executable	4700890962	75
	ADA-SBA	00.00 Program Builder may not recognize references to Ada Ref. Manual	4700890970	75

- AGP/DGL - MU - SSB ISSUE DATE: 11/21/90

*****none*****	98600B	06.50 ZIDRW incorrectly interprets current window coordinates	5000195735	77
----------------	--------	---	------------	----

- COBOL/HP-UX S300 - SSB ISSUE DATE: 11/21/90

*****none*****	35322B	01.50 bcheck does not work with lowercase names	4700879395	78
	35322B	01.08 Numeric move does not move correct value	4700880062	78
	35322B	01.08 Signed numeric decimal move does not move the correct value	4700884635	78
	35322B	01.06 repeated calls to X"82" consume memory	4700826735	78
	35322B	01.06 Compiler option ODOSLIDE causes native code program to abort	5000522854	78

- COMMON LISP DEVELOPMENT - SSB ISSUE DATE: 11/21/90

*****none*****	HP98678A	01.01 Lisp should load required modules automatically.	4000036616	117
	HP98678A	01.01 Setq & self combination results in system termination.	5000170167	120
	HP98678A	01.00 With term0 window, shift left/right arrow key's not decoded	4000033423	82
	HP98678A	01.00 Editing switches to PLS mode not LISP mode.	4000034538	115
	HP98678A	01.00 If a Q-Prolog is loaded, output can go to the wrong window	4000046110	118
	HP98678A	01.00 Current language can get out of sync with mode of buffer	4000046128	118
	HP98678A	01.00 Emacs menu "MODES" not complete.	4000046433	118
	HP98678A	01.00 When loading files, cannot determine use of old or new entry points	4000046441	119
	HP98678A	01.00 inquire hit function not included in HPUX.3g package for LISP	5000193656	120
	HP98678A	00.00 lisp sometimes hangs, this is aggravated by prolog	4000046771	119
	HP98678A	01.01 Error in lisp application note example.	5000272898	121
	HP98678A	01.01 Error in lisp application note example.	5000272898	121
	HP98678A	01.00 C-M-Return doesn't work in the middle of a shell-buffer.	4000033522	86
	HP98678A	01.00 Package objects are accessible as normal vectors or arrays.	4000033902	94
	HP98678A	01.00 Lamdas whose compiled code exceeds 32K bytes will not work.	4000033910	94
	HP98678A	01.00 READ-CHAR-NO-HANG does not work with device files.	4000033928	95

DOCUMENTATION  
LISP



Keyword	Product number	uu:ff	Description	KPR number	page
LISP	HP98678A	01.00	Bare CL always prints system prompt even when user code doing READ.	4000033936	95
	HP98678A	01.00	System not observing restriction of call-arguments-limit (p108 CLtL)	4000033951	96
	HP98678A	01.00	Disassemble output is not compatible with either LAP or UNIX assembler.	4000033977	96
	HP98678A	01.00	pp-expand does not preserve SPECIAL declarations in locally (and let).	4000033985	97
	HP98678A	01.00	Bothtime functions (e.g. proclaim, in package) take only constant args.	4000033993	97
	HP98678A	01.00	(defun nil {} nil) works interpretively, not compiled.	4000034017	98
	HP98678A	01.00	Preprocessor does not handle &key and &rest in the wrong order	4000034025	99
	HP98678A	01.00	Preprocessor error from an eval shows as eval on stack; not the pp fn!	4000034041	100
	HP98678A	01.00	(... &key) causes spurious compiler warning.	4000034066	100
	HP98678A	01.00	Outer eval-when specs don't control inner ones.	4000034074	101
	HP98678A	01.00	PP does not check declare name for symbolp; causes error in printing.	4000034157	104
	HP98678A	01.00	Execution Monitor regs symbol to have function definition to set brkpt.	4000034223	106
	HP98678A	01.00	Fletting a constant folded function gives wrong results.	4000034249	107
	HP98678A	01.00	XM pauses at evaluation of closed var in function call.	4000034264	108
	HP98678A	01.00	Execution Monitor limits maximum indentation to 50.	4000034298	108
	HP98678A	01.00	Can't redefine interpreted fn just before call in XM.	4000034355	109
	HP98678A	01.00	Codegen gives "wrong number of arguments" error.	4000034363	111
	HP98678A	01.00	Optimization bug with (equal 3.0.0).	4000034371	111
	HP98678A	01.00	Defmacro destructuring does not always initialize correctly.	4000034371	112
	HP98678A	01.00	Printing of floats inaccurate if number has large or small abs. value	4000034389	112
	HP98678A	01.00	Subtypep does not work on types created by defstruct.	4000034397	112
	HP98678A	01.00	User initiated read of #, syntax evaluates at read-time.	4000034405	113
	HP98678A	01.00	PPRINT does not work on circular structures.	4000034413	113
	HP98678A	01.00	Double-float-epsilon needs to be different on 881.	4000034421	114
	HP98678A	01.00	Special-form-p of multiple-value-call returns nil.	4000034439	114
	HP98678A	01.00	Read suppress not working with escaped symbols.	4000034447	114
	HP98678A	01.00	pprint seems to print certain forms incorrectly.	4000034454	114
	HP98678A	01.00	Format bug: ~@* directive fails inside ~{...}.	4000034710	116
	HP98678A	01.00	GENSYM message refers to extraneous init forms	4000034744	116
NMODE	HP98678A	01.00	File search indexes allow dup. names and leading/embedded spaces.	4000033357	80
	HP98678A	01.00	Find file on read protected file creates an empty buf & new file msg.	4000033373	80
	HP98678A	01.00	Left locator button clicks above browser items beep; clicks below don't.	4000033381	80
	HP98678A	01.00	Command line of editing buffer sometimes erroneously shows C-M-L.	4000033399	81
	HP98678A	01.00	It's not possible to customize (bind keys to commands) all keyboard keys	4000033407	81
	HP98678A	01.00	Buffers can be accidentally killed if they have long filenames.	4000033415	82
	HP98678A	01.00	Undocumented behavior with cmd-argument to C-X O.	4000033431	82
	HP98678A	01.00	Command functions do not follow M-X conventions.	4000033449	82
	HP98678A	01.00	LISP specific commands do not completely parse all CL systaxes.	4000033456	83
	HP98678A	01.00	M-) command isn't consistent with indentation done by other commands.	4000033464	83
	HP98678A	01.00	White space at the end of a sentence is treated as another sentence.	4000033472	84
	HP98678A	01.00	In auto fill, + text modes Nmode doesn't keep left margin in view.	4000033480	84
	HP98678A	01.00	Receiving input from more than 27 file descriptors causes error.	4000033498	85
	HP98678A	01.00	Hitting [Break] while creating nmode shells causes loss of shell access.	4000033506	85
	HP98678A	01.00	HP-UX command softkey is confusing and may cause garbage.	4000033514	85
	HP98678A	01.00	Shell buffers are not correctly named according to options.	4000033530	86
	HP98678A	01.00	Keyboard and locator inputs not always processed in order entered.	4000033548	87
	HP98678A	01.00	Locator buttons may be missed during switching of windows.	4000033555	87
	HP98678A	01.00	Mouse clicks can cause keystrokes to be ignored.	4000033563	88
	HP98678A	01.00	Changing C block begin/end chars in C Edit Options breaks C-M-F/B.	4000033571	88

CUMULATIVE KEYWORD INDEX

- COMMON LISP DEVELMNT - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff	Description	KPR number	page
NMODE	HP98678A	01.00	Template placeholders can be lost during template edit when CR inserted.	4000033589	89
	HP98678A	01.00	BREAK key typed during load of tutor disables Load command for tutorial.	4000033597	89
	HP98678A	01.00	The Restore key in the NMODE tutorial does not restore all situations.	4000033605	89
	HP98678A	01.00	Where-Am-I for Directories specifies "directories" instead of files.	4000033613	90
	HP98678A	01.00	Help Where-I-Am lists a non-existent function.	4000033621	90
	HP98678A	01.00	Tutorial keys are changed if a breakpoint entered while in the tutorial.	4000033639	90
	HP98678A	01.00	Evaluating a form in customize tutorial will overwrite the instructions.	4000033647	91
	HP98678A	01.00	Online help for C-J-L does not describe fully what the command does.	4000033654	91
	HP98678A	01.00	Documentation of Defuns in any of the online-help info needs further desc	4000033662	92
	HP98678A	01.00	Help frame on Upcase-digit needs description of effective range.	4000033670	92
	HP98678A	01.00	Softkeys can not be used with prefixed commands.	4000033688	92
	HP98678A	01.00	Nmode -t Create window softkey exists even if window support does not.	4000033696	93
	HP98678A	01.00	Softkeys for original window are reset.	4000033704	93
	HP98678A	01.00	Windows in input mode cannot be killed with popup menu.	4000033712	93
	HP98678A	01.00	Lisp L gets errors when run from background.	4000033720	94
	HP98678A	01.00	Load of binary file with other than .b suffix gives unintelligible error	4000033944	95
	HP98678A	01.00	Save-world doesn't unwind bindings, save break state, update open files.	4000033969	96
	HP98678A	01.00	File names containing '\$' are not handled correctly.	4000034009	97
	HP98678A	01.00	Sys: %break-level-limit* & Sys: %break-limit-exceed-limit can work incorr.	4000034033	99
	HP98678A	01.00	Attempt to trace method on undefined type gives meaningless warnings.	4000034058	100
	HP98678A	01.00	DIRECTORY pathname can't read LAN root directory.	4000034082	101
	HP98678A	01.00	Documentation discrepancy on listener-abort/quit/-continue.	4000034090	101
	HP98678A	01.00	After lstep, XM starts a refresh on each new form, losing history.	4000034108	102
	HP98678A	01.00	Misleading error message in step when aborting the computation.	4000034116	102
	HP98678A	01.00	Exec Monitor mismatches the i and v keys.	4000034124	103
	HP98678A	01.00	When ExMON is active, Lisp-a from 2nd window pops up ExMon in 2nd window	4000034132	103
	HP98678A	01.00	Stack overflow makes nmode window the bottom window.	4000034140	103
	HP98678A	01.00	Exec. Monitor does not allow changing the number of function return val.	4000034165	104
	HP98678A	01.00	Error in on-line help text for Exec. Mon.	4000034173	104
	HP98678A	01.00	Meaningless warning msg from Execution Monitor.	4000034181	105
	HP98678A	01.00	Additional facilities prints incorrect message when loading xs browser.	4000034199	105
	HP98678A	01.00	Execution Monitor signals error that a form is not an identifier.	4000034207	106
	HP98678A	01.00	Restoring default Breakpoints in XM options browser bad warn message.	4000034215	107
	HP98678A	01.00	When XM not loaded, (step <form>) EVALs <form>, then says step undefined	4000034231	107
	HP98678A	01.00	Function reported in "Condition signalled in ..." msg not consistent.	4000034256	107
	HP98678A	01.00	In xm, quit acts like an inefficient run (changes modes, run does not).	4000034280	109
	HP98678A	01.00	Stepper resets debug: %step-size* when deferred value is set.	4000034306	109
	HP98678A	01.00	Stepper does not gracefully accept bad input when in input mode.	4000034314	110
	HP98678A	01.00	XM signals non-continuable error if call an undefined function.	4000034322	110
	HP98678A	01.00	V(value) cmd on env item in stack br signals error--should ignore instead	4000034330	110
	HP98678A	01.00	Compile-file creates .b with wrong permissions (should use umask).	4000034348	110
	HP98678A	01.00	y-or-n-p and yes-or-no-p should prompt.	4000034462	115

- COMMON LISP EXECUTION - SSB ISSUE DATE: 11/21/90

\*\*\*\*\*none\*\*\*\*\* HP98679A 01.00 Order of FORTRAN function parameters effects calc when called from LISP. 1650041749 122

- DOS COPROCESSOR SFTW - SSB ISSUE DATE: 11/21/90

\*\*\*\*\*none\*\*\*\*\* 98531A 02.00 If dosconfig used to disconnect & reconnect LPT1->spooler, fails errno32 4000093401 124

- DOS COPROCESSOR SFTW - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	98531A	02.00 README.DOC doesn't mention REDIR when showing how to update AUTOEXEC	4000093567	124
*****none*****	98531A	01.20 dos subsystem ties up system when pressing extend/reset for long time	50000429019	125
*****none*****	98531A	01.06 Shell escape from DOS and try to start DOS again. Font's get trashed.	4000078683	124
*****none*****	98531A	01.05 CTTY does not work with VIAC00PD loaded	40000558446	123
*****none*****	98531A	02.00 format not correctly documented	50000456640	125
*****none*****	98531A	02.00 DOS Co-processor does not work correctly with 98549A	1650119883	123
*****none*****	98531A	01.20 pop up menu under dos.x hangs the dos window	50000479725	126

DOCUMENTATION  
DOS CO-PROCESSOR

- HP PROLOG 1.0 - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
PROLOG	79232U	01.00 PROLOG goes into infinite loop on certain predicates.	1650042044	127

- HP SQL/300 - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	79725A	70.00 Backend process core dump due to unable to allocate free page buffer.	4700839928	145
*****none*****	79725A	70.00 Integer Overflow on Operation Convert when inserting min integer value.	4700857938	147
*****none*****	79725A	70.00 HP SQL internal error (MPE-XL Error 16) occurred: nested query testing	4700877282	152
*****none*****	79725A	70.00 Error 139 may be returned with Read Uncommitted during a timing window.	4700878447	152
*****none*****	79725A	70.00 Query returns DBERR 4053	4700886944	161
*****none*****	79725A	70.00 Start db newlog accepts 'logx and logy' without using Dual log command.	4700905263	162
*****none*****	79725A	70.00 Nested query resulted in TRAP 13	4700915462	166
*****none*****	79725A	70.00 PSQCOB does not allow assigning integer values > 2,147,483,647	4700921429	166
*****none*****	79725A	70.00 Over/underflow may result due to incorrect cost computation in optimizer	4700929687	172
*****none*****	79725A	70.00 NEW and DISPOSE called a lot while executing an SQL program.	4700933788	172
*****none*****	79725A	70.00 A potential undetected deadlock with RU application in a loaded system.	4700939512	175
*****none*****	79725A	70.00 Migrating a DBE with DDL disabled caused DBCore error 134 in CREATE FILE	4700941633	177
*****none*****	79725A	70.00 Slow performance on join of tables	4700945683	177
*****none*****	79725A	70.00 CURRENT DATETIME function is not accurate as its format requires.	4700949016	178
*****none*****	79725A	70.00 incorrect result from retrieving a default value from varbinary column	4700949685	179
*****none*****	79725A	70.00 Incorrect char string is displayed when it's a default val to varbin col	4700949701	179
*****none*****	79725A	20.33 Optimizer may choose sort merge join when nested loop join is faster	4700955877	162
*****none*****	79725A	20.29 BULK FETCHES with KEEP CURSOR WITH NOLOCKS cause DBCORE Internal err 184	4700933028	172
*****none*****	79725A	08.56 Incorrect error message (DBERR 2910) when OPEN CURSOR is used.	4700946715	177
*****none*****	79725A	08.55 FORTRAN preprocessor generates syntax error for valid compiler options.	4700937037	173
*****none*****	79725A	08.03 "DBCon File invalid-DBERR 3066" expected but DBERR 3078 reported on 300.	4700863472	148
*****none*****	79725A	07.26 Declare Cursor with 'LIKE' returns DBERR 4051 from JGEFMT{1}	4700923268	166
*****none*****	79725A	07.26 Complex query with OR predicate runs out of memory and returns TRAP 68	4700923284	167
*****none*****	79725A	07.18 Changing the select list on a 5 table join query returns fewer rows.	4700855932	146
*****none*****	79725A	07.16 Pascal runtime error returned in a 2.0-migrated 7.0 database fails for FLOATs.	4700842989	145
*****none*****	79725A	07.00 An ALTER TABLE section in a 2.0-migrated 7.0 database fails for FLOATs.	4700829952	143
*****none*****	79725A	07.00 Incorrect query results for OR predicate with null indicator set.	4700835561	144
*****none*****	79725A	07.00 While testing FIPS, a particular query hangs.	4700837666	144
*****none*****	79725A	07.00 Internal error on join query including OR and ORDER BY, GROUP BY, DISTINCT	4700852574	146
*****none*****	79725A	07.00 Sort is returning bad data on select on >16 col table with index.	4700858837	147
*****none*****	79725A	07.00 INSERT of REAL number outside of legal negative range is not trapped.	4700859488	148
*****none*****	79725A	07.00 Arithmetic computation results in an integer underflow condition.	4700859660	148
*****none*****	79725A	07.00 Error 1058 result on update after no more tuples code is returned.	4700882951	153

Keyword	Product number	uu.ff	Description	KPR number	page
*****none*****	79725A	07.00	KEEP CURSOR scans can proceed with no system relations locks	4700882985	154
	79725A	07.00	PASCAL preprocessor fails to preprocess SELECT COUNT(*) FROM T1 command	4700883330	157
	79725A	07.00	Internal error 52 occurs in a joined nested query	4700883959	158
	79725A	07.00	Subquery with EXISTS hangs	4700883975	158
	79725A	07.00	Doubly defined error for SQLCODE at compile time - ANSI conform. issue.	4700890228	159
	79725A	07.00	User session waiting for a page can not be aborted due to a hang.	4700892448	160
	79725A	07.00	Null indicator set to 4 on select of dec(4,0) into S9(4) COMP-3 field.	4700923300	167
	79725A	07.00	Packed decimal overflow on operation CONVERT. (DBERR 2605)	4700923318	168
	79725A	07.00	Random DBERR 2605 errors with UNION commands	4700923326	169
	79725A	07.00	DBERR 2413 returned with large number of OR INDEX predicates.	4700923334	169
	79725A	07.00	"Invalid decimal precision error" on UNION command with decimal data.	4700923342	170
	79725A	07.00	Two COMMIT WORK with DDL disabled and KEEP CURSOR in effect causes hang.	4700923367	170
	79725A	07.00	DBERR 4053 may be returned when optimizer not detecting over/underflow	4700929679	171
	79725A	07.00	DBCORE abort (internal error 3822) in a KEEP CURSOR application.	4700938225	173
	79725A	07.00	DBCORE error 181 is returned on fetch from a keep cursor	4700942342	176
	79725A	07.00	DBERR 4000 with five LIKE predicates separated by logical OR.	4700946814	177
	79725A	03.00	START DBE NEW should clean up ALL files in case of failure.	5000566836	180
	79725A	02.00	HP SQL is utilizing a large amount of swap space.	4700899815	161
	79725A	02.00	DBCORE reports "out of disc space" even though entire file is avible.	4700794388	140
	79725A	02.00	2060 2068 during load select - following large delete	4700795872	141
	79725A	02.00	DBERR 4008 on query with BEGIN WORK RC or CS and involving sort.	4700795898	141
	79725A	02.00	SQL may choose force index plan when standard plan is better.	4700876128	151
	79725A	02.00	COBOL PP inserts 1-byte filler for variables outside DECLARE SECTION.	4700941799	176
	79725A	01.10	Data or Index space exhausted in DBFILE0 (DBERR 2502).	5000484352	180
	79725A	01.05	Computing COUNT over an empty set returns no row instead of zero	1650059014	128
	79725A	01.01	FORTTRAN preprocessor doesn't allow underscores in variable names	4700712453	133
	79725A	01.01	incorrect and nonexistent error msg (DBERR 3045) output	4700713743	134
	79725A	01.01	select while in unwritable directory causes abort from isql	4700714352	134
	79725A	01.01	ER to keep daemon from outputting errors to /dev/console	4700720177	134
	79725A	01.01	Internal error occurs in a query with 2 aggregates in an expression.	4700740589	135
	79725A	01.01	For certain decimal type fields, negative numbers are stored as positive	4700743401	135
	79725A	01.01	4053 on an update of a table with multiple indexes	4700747246	136
	79725A	01.01	DBCORE 285 caused by application with CS (or RC) and ORDER BY clause.	4700748368	136
	79725A	01.01	With NEQ operator, tuples w/ unknown search condition value are returned	4700753293	137
	79725A	01.01	Query with 13 between clauses fails with DBCore Internal Error 216.	4700768077	137
	79725A	01.01	ISQL help text examples should display the semicolon at end of command.	4700776633	138
	79725A	01.01	Incorrect error msg from ISQL when ran out of disk space for tmp file.	4700776641	138
	79725A	01.01	Problem with using ISQL on 700/43 terminals	4700777813	139
	79725A	01.01	hpbdaemon dies on CONNECT (error 1067) on S300 w/ floating pt accel.	4700778951	140
	79725A	01.01	After update or delete, opened cursor reads old data within transaction.	4700793350	140
	79725A	01.01	Data corrupted on 2048 byte when entering char string > 2048 bytes	4700803395	141
	79725A	01.01	Query result was sorted in ASC order although DESC was specified.	4700820704	142
	79725A	01.01	The bugcatcher on the 300 aborts with segmentation violation	4700829655	142
	79725A	01.01	ISQL is not checking for overflow on a 4 byte FLOAT.	4700849927	146
	79725A	01.01	DBERR 13262 and RC 196 on SELECT w/ IN predicate during regression test	4700876060	151
	79725A	01.01	"HPSQL not running" appears twice for commands after TERMINATE USER	4700883280	156
	79725A	01.01	ISQL: Entering 'non-existent' command gives DBERR 2102	4700883322	157
	79725A	01.01	C preprocessor appears to cause byte alignment problems with application	4700901470	161

- HP SQL/300 - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff	Description	KPR number	page
*****none*****	79725A	01.01	ALLBASE is not catching the error when Long Field output device too long	4700902122	162
*****none*****	79725A	01.00	Must enter EXIT a few times to exit ISQL when user #2 does a STOP DBE	4700883306	157
*****none*****	79725A	01.00	Preprocessing "C" application with LANG=korean gives DBERRS 10908/11014.	4700892612	160
*****none*****	79725A	01.00	wrong user used by sql for authorization after an su was done	5000260547	179
*****none*****	79725A	00.00	we need to raise the minimum number of log pages allowed	4700441717	128
*****none*****	79725A	00.00	'unload to external..' from cmd file requires all params on one line	4700451161	128
*****none*****	79725A	00.00	illegal syntax error generated due to bigfile processing	4700455444	129
*****none*****	79725A	00.00	installation module size not compatible with that of hp sql/800	4700481937	129
*****none*****	79725A	00.00	BULK FETCH bug. Can only retrieve a certain number of rows.	4700539148	130
*****none*****	79725A	00.00	LOAD command failing when pattern matching specified	4700552232	130
*****none*****	79725A	00.00	negative numbers improperly sorted by ORDER BY	4700579508	131
*****none*****	79725A	00.00	multi-table joins may cause memory allocation failures	4700590638	131
*****none*****	79725A	00.00	incorrect error msg when using isql from directory w/bad permissions	4700594275	131
*****none*****	79725A	00.00	unload command with embedded select stmt causes syntax error	4700594309	132
*****none*****	79725A	00.00	internal error msg returned for < minimum log pages on start db	4700664219	132
*****none*****	79725A	00.00	C compiler cannot resolve symbols when linking more than 1 object file.	4700687905	132
*****none*****	79725A	00.00	DBERR 8207 returned by SHOWDBE command in SQLUTIL.	4700869537	149
*****none*****	79725A	00.00	Missing tuple in a multi-user KC test	4700875468	149
*****none*****	79725A	00.00	DBCORE error 2060 from aci fetchc (reproducible through Info Access)	4700876516	151
*****none*****	79725A	00.00	Large variable index keys do not work correctly.	4700882936	153
*****none*****	79725A	00.00	DBFile existence not being verified in rollover recovery	4700883009	155
*****none*****	79725A	00.00	DBCORE Internal Error 1057 returned when log full during SORT.	4700883033	156
*****none*****	79725A	00.00	ISQL does not allow > 255 when SELECT includes joined tables	4700883413	158
*****none*****	79725A	00.00	HPDBAEMON needs to be more robust in its error handling	4700886796	159
*****none*****	79725A	00.00	ISQL sometimes returns DBERR 49 when not recognizing in START file	4700908137	163
*****none*****	79725A	00.00	Problems: Literals with '--' and parameter prompt in ISQL is	4700908251	163
*****none*****	79725A	00.00	HPSQL Alignment error(DBERR 4200) when using column of type DATETIME.	4700908285	164
*****none*****	79725A	00.00	C Preprocessor truncates .c filenames when using -i option.	4700908319	164
*****none*****	79725A	00.00	DBCORE gets a file open error when the number of files open exceeds limit	4700909168	165
*****none*****	79725A	00.00	ISQL doesn't prompt correctly when user enters ; for command file parm	4700911537	165
*****none*****	79725A	00.00	Corner case found with PAGE ALLOCATION log recs where rolloff may fail.	4700912998	165
*****none*****	79725A	00.00	DBERR 4050 internal error in JBIREF(1) when selecting from a view.	4700926865	171
*****none*****	79725A	00.00	Need to increase the SQLUTIL max runtime control blocks constant.	4700946400	177
*****none*****	79725A	00.00	HPIMAGE/DBCORE pass 34 page corruption bug during B-tree migration	4700948133	178
*****none*****	79725A	00.00	SQLUTIL STORE command truncates storefile names longer than 44 chars.	5000566851	180
*****none*****	79725A	00.00	SQLUTIL STORE gives confusing message with write-protected directory.	5000568196	180
*****none*****	79725A	02.00	UNLOAD EXTERNAL using SELECT on a Japanese database aborts ISQL with (0)	4700768416	138
*****none*****	79725A	00.00	ISQL exhibits transaction errors when loading large table from external.	4700688226	133
*****none*****	79725A	02.00	UNLOAD EXTERNAL using SELECT on a Japanese database aborts ISQL with (0)	4700768416	138

- HP SQL/300 C APG - SSB ISSUE DATE: 11/21/90

*****none*****	79725-90014	88.02	Compilation statement specifies libraries in incorrect order.	4700685560	182
----------------	-------------	-------	---	------------	-----

- HPC++ COMMON - SSB ISSUE DATE: 11/21/90

*****none*****	HPCPLUSPLUSA	02.00	unnamed bit fields are initialized, even in ANSI mode (+a1).	4700880393	183
----------------	--------------	-------	--	------------	-----

Keyword	Product number	uuff	Description	KPR number	page
*****none*****	HPCPLUSPLUSA	02.00	passing a float const arg with a cast to inline func is botched.	4700890392	186
	HPCPLUSPLUSA	02.00	Pointers to members cannot always be assigned the constant zero.	4700890830	187
	HPCPLUSPLUSA	02.00	Cfront allows a const object to not be passed to non const member func.	4700890848	187
	HPCPLUSPLUSA	02.00	Bad debug info if only the enum tag from a class is referenced	4700891754	188
	HPCPLUSPLUSA	02.00	Forward struct references in inner scopes cause problems	4700891762	188
	HPCPLUSPLUSA	02.00	warning, not error, given for item declared as both signed and unsigned	4700891804	189
	HPCPLUSPLUSA	02.00	demangler does not handle leading correctly on s300s	4700891887	190
	HPCPLUSPLUSA	02.00	incorrect debug info emitted for local static cfront temps	4700891911	191
	HPCPLUSPLUSA	02.00	member function call returns wrong value if access declaration used.	4700892992	192
	HPCPLUSPLUSA	02.00	pointer to the virtual table is being copied when it should not be	4700893016	193
	HPCPLUSPLUSA	02.00	cfront crashes when calling static function inherited from virtual base	4700893073	194
	HPCPLUSPLUSA	02.00	cfront puts out incorrect warnings about integral type compatibility.	4700893099	194
	HPCPLUSPLUSA	02.00	The debugger does not understand the void data type	4700893107	194
	HPCPLUSPLUSA	02.00	bogus error message for implicit conversion to int for unary op.	4700893206	195
	HPCPLUSPLUSA	02.00	Wide string literals are unimplemented	4700893503	195
	HPCPLUSPLUSA	02.00	Enum's aren't scoped properly	4700893511	196
	HPCPLUSPLUSA	02.00	Cfront allows duplicate declarations of enum's	4700893529	196
	HPCPLUSPLUSA	02.00	Incorrect handling of redefinition of classes in blocks	4700893537	196
	HPCPLUSPLUSA	02.00	Cfront does not catch calls to main, violation of sec. 3.4 in ref manual	4700893545	196
	HPCPLUSPLUSA	02.00	Cfront does not correctly mangle member funcs. for tagless classes	4700893552	197
	HPCPLUSPLUSA	02.00	reference to type void should get error	4700893578	197
	HPCPLUSPLUSA	02.00	redefinition of enum tag name in inner scope not allowed	4700893586	197
	HPCPLUSPLUSA	02.00	cfront using +d option works incorrectly.	4700893628	198
	HPCPLUSPLUSA	02.00	cfront does not complain about anon member and local var with same name	4700894113	199
	HPCPLUSPLUSA	02.00	cfront does not handle static anonymous unions properly	4700894121	199
	HPCPLUSPLUSA	02.00	Variable with the same name as a label is not emitted.	4700894139	199
	HPCPLUSPLUSA	02.00	Invalid code generation for pointers to static members.	4700894154	200
	HPCPLUSPLUSA	02.00	link-time unsat for derived class ptbl when using +e0/tel facility	4700894162	200
	HPCPLUSPLUSA	02.00	xdb may print the incorrect value for members of a virtual base class	4700894535	201
	HPCPLUSPLUSA	02.00	allows declaration of uninitialized const structs, classes, & unions	4700897009	202
	HPCPLUSPLUSA	02.00	member function declared volatile treated same as const	4700897017	202
	HPCPLUSPLUSA	02.00	initialization of union unimplemented	4700898460	202
	HPCPLUSPLUSA	02.00	line numbers not monotonic for inlined constructor	4700898478	202
	HPCPLUSPLUSA	02.00	typedef altered by cfront that invalidates future declarations	4700898734	203
	HPCPLUSPLUSA	02.00	initialization of AUTO struct (using +al) gets bus error.	4700899401	203
	HPCPLUSPLUSA	02.00	Stream operator<< occasionally appends garbage to output string.	4700900100	203
	HPCPLUSPLUSA	02.00	cfront does not catch access violation when accessed mem is overloaded.	4700900118	204
	HPCPLUSPLUSA	02.00	Misleading message when a break occurs within {} in a switch statement.	4700906339	204
	HPCPLUSPLUSA	02.00	Generated code jumps to address 0 instead of to virtual function.	4700906347	204
	HPCPLUSPLUSA	02.00	not implemented 2012: general initializer in initializer list	4700908491	205
	HPCPLUSPLUSA	02.00	Bad C code generated with +d for class declared within a class	4700908509	205
	HPCPLUSPLUSA	02.00	garbled error message 1227 and internal error 3058 and bus error	4700908517	205
	HPCPLUSPLUSA	02.00	Internal error 3058: bus error for simple syntax error	4700908525	206
	HPCPLUSPLUSA	02.00	not implemented 2020: cannot expand inline function with static var	4700908533	206
	HPCPLUSPLUSA	02.00	no "arg not used" warning for array args	4700908541	206
	HPCPLUSPLUSA	02.00	internal error 3111: can't find vptr for some nested class definition	4700908558	206
	HPCPLUSPLUSA	02.00	unclear constructor-argument error messages for normal errors	4700908566	207
	HPCPLUSPLUSA	02.00	phrase "struct A" can't be used in a type cast in struct A definition	4700908574	207
	HPCPLUSPLUSA	02.00	xdb++ -- empty classes show a member "w1"	4700908582	207



Keyword	Product number	uu. ff Description	KPR number	page
*****none*****	HPCPLUSPLUSA	02.00 Bad function prototype for stats: 2nd param should be struct stats *	4700916627	207
	HPCPLUSPLUSA	02.00 CC +p -g: c++merge terminated with signal 11	4700919837	208
	HPCPLUSPLUSA	02.00 debugger prints name of local class member function incorrectly	4700921759	208
	HPCPLUSPLUSA	02.00 Several func. prototypes missing from <X11/XHplib.h>	4700927459	209
	HPCPLUSPLUSA	02.00 <CC/dir.h> header has indented #defines which affects /lib/cpp.	4700927467	209
	HPCPLUSPLUSA	02.00 compiler puts out bad debug info for members of type static anon. union	4700931188	210
	HPCPLUSPLUSA	02.00 xdb++ -- "l" gets confused with breakpoint (using +d): bad debug info.	4700931626	210
	HPCPLUSPLUSA	02.00 CC gens questionable C code: cc warning "Redeclaration of identifier"	4700931634	211
	HPCPLUSPLUSA	02.00 Int. error on array initializers for classes with user-def. constructors	4700931642	211
	HPCPLUSPLUSA	02.00 HPC++ error messages should be in 'standard' (/bin/cc) format	4700931667	211
	HPCPLUSPLUSA	02.00 c++merge does not detect /bin/cc 'static' information	4700931675	212
	HPCPLUSPLUSA	02.00 'sizeof variable name', as dimension in array decl. gets spurious errors.	4700934240	212
	HPCPLUSPLUSA	02.00 xdb fails to indicate that a member function has been declared "const"	4700936260	212
	HPCPLUSPLUSA	02.00 Cfront crashes when a non-member function is declared as const.	4700942466	212
	HPCPLUSPLUSA	02.00 cfront doesn't always detect creating an instance of an abstract class	4700945311	213
	HPCPLUSPLUSA	02.00 Duplicate enumerators not caught in presence of a label	4700945386	213
	HPCPLUSPLUSA	02.00 Yacc stack overflow	5000595447	213
	HPCPLUSPLUSA	00.06 assignment to data member overwrites virtual base class pointer	4700891945	191
	HPCPLUSPLUSA	00.04 DNTT_LABEL's address field not set correctly	4700880401	183
	HPCPLUSPLUSA	00.04 passing function pointer as parameter causes internal error	4700880419	184
	HPCPLUSPLUSA	00.04 cfront creates this pointer for static member function	4700883066	184
	HPCPLUSPLUSA	00.04 Conditional operator takes wrong path.	4700921767	208
	HPCPLUSPLUSA	00.03 Compile time for HPC++ is 2-3 times slower than bare cfront	4700885749	185
	HPCPLUSPLUSA	00.03 CC +al generates bad C code -- cc fails	4700887976	185
	HPCPLUSPLUSA	00.03 CC doesn't cast 0 to an array type	4700888925	186
	HPCPLUSPLUSA	00.03 Struct member w/in struct not declared in generated C code.	4700889394	186
	HPCPLUSPLUSA	00.03 Should be error to init const pointer to non-const data with const data	4700891879	190
	HPCPLUSPLUSA	00.03 Compiling with +d and -g is ~60% slower than just -g	4700891952	192
	HPCPLUSPLUSA	00.03 CC +w: cc warning for virtual function call	4700891978	192
	HPCPLUSPLUSA	00.03 typedef of unsigned long within func does not work.	4700893057	193
	HPCPLUSPLUSA	00.03 Destructor cannot delete pointer to class returned by inline func.	4700893065	193
	HPCPLUSPLUSA	00.03 Math.h lacks decls for abs(int) and abs(double), incompatible with ATT	4700894204	201
	HPCPLUSPLUSA	00.03 union initialization in +a0: -- bad C code is generated. cc fails	4700917161	208
	HPCPLUSPLUSA	00.02 names are given to nameless classes in debug information	4700928325	209
	HPCPLUSPLUSA	00.02 array of class objects containing const enum causes bus error	4700891853	190
	HPCPLUSPLUSA	00.02 incorrect warning given for overloading based on enum vs. int.	4700893081	194
	HPCPLUSPLUSA	00.02 redefinition of default argument not caught as error by cfront	4700893651	198
	HPCPLUSPLUSA	00.02 like-named classes in two different functions disallow ptr to member	4700894147	200
	HPCPLUSPLUSA	00.01 Can't compile with <starbase.c.h>. Undefined c_draw2d(), c_move2d().	4700894188	201
	HPCPLUSPLUSA	00.01 cannot find function symbols for nameless class	4700879403	183
	HPCPLUSPLUSA	00.01 initialization not required for const non-external struct	4700891846	190
	HPCPLUSPLUSA	00.01 cfront allows user to define body for pure virtual function!	4700893008	192
	HPCPLUSPLUSA	00.01 CC gets internal error on abstract virtual operator declaration.	4700893487	195
	HPCPLUSPLUSA	00.00 sys/ns ipc.h file not converted for HP C++	4700893610	198
	HPCPLUSPLUSA	00.00 no include file for net_aton or net_ntoa(3N)	4700879411	183
	HPCPLUSPLUSA	00.00 merger is zapping out SRCFILE entries that should not be zapped	4700880427	184
	HPCPLUSPLUSA	00.00 Need to build libC.ansi.a and add this file to the file set	4700884270	184
	HPCPLUSPLUSA	00.00 Cfront core dumps in making a long signature name	4700886598	185
	HPCPLUSPLUSA		4700890368	186

CUMULATIVE KEYWORD INDEX

- HPC++ COMMON - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	HPCPLUSPLUSA	00.00 scope of names redeclared in inner scope sometimes leads to surprise	4700891796	189

- HPC++ S300 - SSB ISSUE DATE: 11/21/90

*****none*****	B1691A	02.00 <stdarg> macros don't work on the 300 if the last parm is a reference.	4700902734	215
----------------	--------	--	------------	-----

- OV NM SERVER 300 DEV - SSB ISSUE DATE: 11/21/90

*****none*****	36985A	01.00 sieve manager is not deleting obsolete sieves	4700905216	216
*****none*****	36985A	01.00 Unable to compile a managed object class with filter syntax attribute	4700907592	216
*****none*****	36985A	01.00 Misspelling of domainName field for CmoSystemID in the database.	4700907600	216
*****none*****	36985A	01.00 A sequence or set syntax can only have 1 field with an identified value.	4700907618	216
*****none*****	36985A	01.00 Failure occurs on version access of instance with many attributes.	4700907915	216
*****none*****	36985A	01.00 Getting scoped versioned data fails if parent instance does not exist	4700908079	216
*****none*****	36985A	01.00 OVeCnvAddr () always return -63001 even if input address is valid	4700908921	217
*****none*****	36985A	01.00 op blocks not cleared when association is aborted	4700913459	217
*****none*****	36985A	01.00 On rose, rosy fatal errors, the association is not aborted or cleared.	4700913467	217
*****none*****	36985A	01.00 wrong type of results accepted (delete result is accepted for an event)	4700917179	218
*****none*****	36985A	01.00 request id's are non-negative, man pages say they are positive	4700917476	218
*****none*****	36985A	01.00 if dopSdata decodes an invoke w/o args, data struct is never freed	4700917500	218

- PHIGS DEV. ENVIRON. - SSB ISSUE DATE: 11/21/90

*****none*****	B1759A	02.00 Cursor in wrong position when doing picking in Genesis window.	4700933580	219
*****none*****	B1759A	02.00 Events are not flushed from queue when a workstation is closed.	4700933598	219
*****none*****	B1759A	02.00 PSCMR handles the definition of zero pseudo colours incorrectly [4,3,-1]	4700942490	220

- PHIGS FORTRAN MNL. - SSB ISSUE DATE: 11/21/90

*****none*****	B1759-90001	00.00 Cannot access reset_rawdev man page on-line	4700933606	222
----------------	-------------	---	------------	-----

- PROGRAMMERS DOC SET - SSB ISSUE DATE: 11/21/90

*****none*****	98794A	06.50 man pages on AXE are missing, and don't work anyway	4000095190	225
*****none*****	98794A	06.06 Missing asterisks in sigsetops(3C) manual entry in SYNOPSIS	4000094631	224
*****none*****	98794A	06.05 Missing acLenrystart(3C) link to strtoc(3C) manual entry (oops)	4000094342	223
*****none*****	98794A	06.05 truncate(2) still contains an invalid BUGS section;	4000094615	224
*****none*****	98794A	06.05 open(2), close(2) (and others?) don't mention behavior w.r.t. sockets	4000094623	224
*****none*****	98794A	06.05 typo, affect should be effect	4000094656	225
*****none*****	98794A	06.05 Man page: "b" command shows wrong syntax for [count] (should be [\count])	4000094664	225
*****none*****	98794A	06.05 iomap man page example contains /n instead of \n	4000094938	225
*****none*****	98794A	06.05 mount(1M) manpage example options not in same order as SYNOPSIS	4000096115	226
*****none*****	98794A	06.05 group(4) should be linked to loggingroup(4)	4000098293	226
*****none*****	98794A	06.05 setsigmask(2) Manual entry refers to signal(5) Does not exist!	4000098301	226



- PROGRAMMERS DOC SET - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	98794A	06.05 Doesn't document "-a" option	4000098343	227
CHECKLIST	98794A	06.02 Sys Admin Manual says do get tools with floppy 8, should be floppy 3	4000090860	223
CU	98794A	00.00 Documenting "lpadmin-g" as setting print job priority.	4000098327	227
DOCUMENTATION	98794A	06.05 Sys Admin Manual contains incorrect example of editing checklist file.	5000484360	231
	98794A	06.05 the suspend feature of cu is not completely documented	5000489187	231
	98794A	06.05 Incorrect command for copying from one root disk to another.	5000462242	229
	98794A	06.02 system admin manual misname device bit	4000091702	223
	98794A	06.02 Explain the difference between symbolic links and hard links.	5000461467	228
	98794A	06.02 Peripheral guide recommends wrong cable for use with built-in RS232	5000467480	230
	98794A	06.00 System admin. manual documents checklist wrong.	5000461822	229
FIND	98794A	03.01 Change man page entry and HP-UX Reference Vol2 Sec5 from /usr/lib/term	5000475186	230
STARBASE	98794A	06.02 The find(1) manual entry does not warn about Context-Dependent Files.	5000420307	227
	98794A	06.02 the README FIRST for 6.02 incorrectly documents Pdriver	5000430165	228

- RJE/300 - SSB ISSUE DATE: 11/21/90

*****none*****	50967A	01.00 If the background process cannot access rje_joblog, user waits 90 sec.	4000027565	235
COMM	50967A	01.00 RJE/300 does not work with long file names	4000084970	235
COMMANDS	50967A	01.00 Binary files of certain lengths sent incorrectly using ~ control lines	4000093039	235
OS	31447A	01.00 rje_bg or rje_router can hang writing job notification to PTY terminal	4000093492	236
RJE300	31447A	05.03 Crash when receive null block from IBM	9999005459	234
SF18	31447A	05.02 System crash while doing a send message	9999005359	234
	31447A	05.02 RJE USING "commandfile" does not work.	9999005225	234
	31447A	04.01 Problem W/RJE -Configured for 2780 emulation s/be no space compression.	9999004824	232
	31447A	05.02 Command file from workstation causes crash after SIGNON.	9999005048	233
	31447A	04.01 First 15 bytes of message not transmitted.	9999004825	232
	31447A	04.01 Unreasonable errors occur with Edit Commands softkey.	9999004826	232
	31447A	04.01 Executive command receive error.	9999004848	232
	31447A	04.01 The S in SELECT SOFTKEY truncated from message window.	9999004961	233
	31447A	04.01 Error 'Automatic Receive, on Receive file invalid'.	9999004997	233
	31447A	04.01 Crash during file transfer from 250 to 300.	9999005097	234
	31447A	05.02 RJE Using "commandfile" causes crash.	9999005230	234

- S300 GENERAL HPUX - SSB ISSUE DATE: 11/21/90

*****none*****	98680B	06.05 Invalid form in recognize array: During reg alloc because of common sub.	4000094060	250
	98680B	06.05 cc -O chokes on the appended code	4000096487	250
	98680B	06.05 C1 internal error in "function": illegal leaf node 49	4000097451	259
	98680B	06.05 no table entry for op REG (unoptimized)	4700879924	261
	98680B	06.05 'diff-e' ... ed -- results in 2-byte file ("?\n") -- unusual case	4700901041	261
	98680B	06.05 C1 internal error in "xxx": unknown optype passed to find().	5000538983	300
	98680B	06.05 C compiler error: register allocation error	5000538991	300
	98680B	06.05 Using pg "\n" preceded by "\0" doesn't produce new line.	5000539379	300
	98680B	06.05 different results with -O	5000542357	301
	98680B	06.01 a sparse file causes kernel panic	5000299735	271
	98680B	06.00 "/seek" does not work on CTD character special file	5000290544	272
	98680B	05.21 NR0FF STORAGE CAPACITY IS TOO SMALL.	5000417394	277

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	98680B	05.15 jobs disappear from lp queue, but not printed	5000178038	263
	98680B	05.15 line printer spooler can lose data if printer is off line	5000184275	263
	98680B	05.02 PAM does not work properly with 98700 stations.	5000244236	269
	98680B	03.01 Special handling needed for SR #1650102194. See labtext.	1650102194	246
	98680B	03.01 tset does not use is[123] to initialize (see terminfo(4))	4700774497	260
	98680B	03.01 SAM doesn't appear to be able to add fiber link disks.	4700801597	260
	98680B	03.01 swapon -a doesn't work	5000458380	282
	98680B	03.01 SAM incorrectly translates mux0 driver LU in special file minor number	5000482943	286
	98680B	03.01 /bin/rsh does not allow users to specify paths starting with /	5000484337	287
	98680B	03.00 Using cu over 37212B at 2400 baud results in loss of banner if CCITT.	1650076422	241
	98680B	03.00 "type clash" error points to wrong production	4000097865	259
	98680B	03.00 In SAM, need an optional field for passwd while setting up UUCP	5000419028	277
	98680B	03.00 Lint gives erroneous messages	5000458059	281
	98680B	03.00 diskug and acctdug give different results	5000482844	286
	98680B	02.01 lint false errors on missing library entries mkdir(2) and rename(2)	1650074385	240
	98680B	02.01 acctcom(1) doesn't properly report command exit status codes -- ATT	5000440180	279
	98680B	02.00 Kermit do not handle long filenames correctly.	5000298687	271
	98680B	02.00 Enhancement request to increase the number of files sort can handle	5000397711	272
	98680B	06.05 acctcom(1M) shows time one hour earlier than -e or -s option specified	1650101246	246
	98680B	06.05 HOG factor returns wrong value when CPU-MIN and REAL-MIN are zero	5000499038	291
	98680B	06.02 garbage is printing after login names of 8 char long in accounting	5000508044	295
	98680B	05.11 accounting does not properly report users' connect time.	5000219485	264
	98680B	06.05 ar(1) does not accept long filenames	5000476200	284
	98680B	06.05 AXE lp scheduler tries to use mail(1) but mail is not in AXE	5000523977	298
	98680B	06.00 axe system doesn't have tty command used by lp spooler scripts	5000400846	274
	98680B	06.05 ar(1) does not accept long filenames	5000476200	284
	98680B	03.11 Special handling required for SR #5000121756. See labtext.	5000121756	262
	98680B	06.02 value of boolean expression goes on stack correctly but does not return	1650090753	243
	98680B	05.20 Math routine, pow, does not handle overflow correctly.	4000092437	249
	98680B	01.00 ANSI C: integral constant expression expected on enum range.	5000581595	303
	98680B	00.00 When files are compiled with -g, there is a HUGE expansion in size.	5000579755	302
	98680B	06.02 /usr/lib/mkwhat is script sometimes produces memory fault errors.	1650085514	242
	98680B	05.21 Running catman(1) at high priority (with "nice") causes system errors.	5000236984	269
	98680B	06.05 cdb(1) only reports first value of local variable on stack	1650101147	245
	98680B	06.05 CDB COMES UP IN LINE MODE IF WRONG TERM TYPE SET	5000475848	284
	98680B	06.05 tbl nroff   col gives box with staggered line on Laserjet	1650100230	244
	98680B	05.15 (un)compress may not retain modification time.	5000216697	264
	98680B	06.05 cpio(1) reads table of contents on only one side of optical media	5000527226	298
	98680B	06.05 need to change the effective use of \ in crontab	5000470922	283
	98680B	05.20 Csh(1) documentation in error about some features.	1650040139	237
	98680B	06.05 there is no environment passed when using ~! and cu	1650100172	244
	98680B	05.05 cull) doesn't transmit cursor movement escape codes correctly in vi	5000505990	295
	98680B	06.05 bus error in program on 300 using curses and shared memory allocation	5000495978	289
	98680B	05.05 CONFLICT BETWEEN CURSES, SIGVECTOR AND SETTIMER	5000280461	270
	98680B	06.05 dd(1) will not read from a 9.145 cartridge tape, but tar and tcio will	5000510636	296
	98680B	00.00 Problem with dd with seek and mag tape	4000019570	249
	98680B	05.03 Delta(1) hangs when reading files with very long lines	5000228635	267
	98680B	06.05 du -s on NFS-mounted directory on SUN disk reports in 256-byte blocks	5000496729	289
	98680B	06.05 configuration ref. manual is not current nor complete	5000511394	297

ACCOUNTING

AR

AXE

BACKUP

BOOTSYS

C

CATMAN

CDB

COL

COMPRESS

CPIO

CRON

CSH

CU

CURSES

DD

DELTA

DISC

DOCUMENTATION

Keyword	Product number	uu. ff Description	KPR number	page
DOCUMENTATION	98680B	00.00 Problem with dd with seek and mag tape	4000019570	249
ED	98680B	06.02 ed(1) does not work on files larger than 128k	5000519504	297
EX	98680B	06.05 CTAGS not processing if s properly	5000502997	293
FDB	98680B	06.02 fdb has problems with formal arguments to CHARACTER*(*) subroutines	1650076091	240
FILE	98680B	06.05 ar(1) does not accept long filenames	1650088997	242
FIND	98680B	06.05 "find" command fails to check context dependent files	5000476200	284
FTIO	98680B	06.05 ftio does not work with 7979 tape drive	5000500520	291
FUSER	98680B	06.05 chgrp(1) and newgrp(1) don't handle \ in /etc/groups correctly	5000522896	298
KERMIT	98680B	06.05 Kermit's automatic naming only works once, then overwrites file	5000478107	285
KERNEL	98680B	06.05 kernel should always check either euid or ruid - be consistent	1650134353	247
	98680B	06.05 kernel parameter shmbk should not affect size of kernel data structures	5000445296	280
	98680B	06.00 HPIB printer driver does not handle graphics properly	5000496885	290
	98680B	06.00 defect in terminal driver following multiple fopens and fclose of a file	1650070474	240
KSH	98680B	06.05 problem with timeouts in the Korn shell when in the vi editor	5000271213	269
	98680B	06.05 ksh(1) when trap on exit from a child in vi(1), terminal locks up	5000481465	285
	98680B	06.00 .sh history does not come up as default	5000493288	287
	98680B	05.20 Math routine, pow does not handle overflow correctly.	5000397737	274
LIBM	98680B	05.03 Lifcp with BDAI files not properly documented.	4000092437	249
LIFCP	98680B	05.02 lifcp from a floppy begins with a wrong header and cannot be read	5000220160	265
LINT	98680B	06.02 lint gives unexpected error messages	1650130989	246
LOGIN	98680B	02.00 People may appear logged in when they are not.	1650082529	241
LP	98680B	06.05 Very long fields in /etc/passwd mess up login.	4000003830	248
	98680B	06.05 "lost connection" with remote spooling makes file lpd.log fill up disk	4000097428	258
	98680B	06.05 lp to a 2563 printer inserts extra form feeds	5000501296	292
	98680B	06.05 Permissions on lp(1) are incorrect.	5000547547	302
	98680B	06.02 Cannot do raw output to serial device using the hp2686a model script	5000448654	281
	98680B	06.00 lpstat generates bad output when IO is redirected	5000465161	282
	98680B	06.00 line printer hangs	5000396648	272
	98680B	06.00 LP -W SOMETIMES FAILS TO SENDS MAIL TO PROPER USER	5000410191	276
	98680B	06.00 Lpr script doesn't correctly handle the -R option	5000420117	278
MAIL	98680B	05.05 Slp(1) doesn't allow "-a" and "-d" options together.	5000233360	268
MAN	98680B	06.05 AXE lp scheduler tries to use mail(1) but mail is not in AXE	5000523977	298
MKDIR	98680B	05.50 "man -t" gives core dump.	1650040147	238
MKMF	98680B	06.05 mmdir has undocumented limit of 1000 sub directories	5000471979	283
MKRS	98680B	06.05 MKMF SHOULD UNDERSTAND SCCS FILES	5000477828	284
MM	98680B	06.05 modify mkrs to work with the optical disc	5000529883	299
MOUNT	98680B	05.03 MM ignores Bolding.	5000224683	266
MROFF	98680B	06.05 mount(1), df(1) say device mounted if its minor number same as root disk	5000493478	288
	98680B	05.21 Rev 5.2 mount(1) doesn't work with floppy discs.	5000225904	267
	98680B	06.00 nroff hangs on specific input file	5000404012	276
	98680B	05.14 problems using table for matting and interactive text together	5000192682	263
PASCAL	98680B	04.00 NROFF does not support any printers except the obsolete 2631B.	4000017020	249
PASSWD	98680B	03.11 Special handling required for SR #5000121756. See labtext.	5000121756	262
PWD	98680B	02.00 Very long fields in /etc/passwd mess up login.	4000003830	248
RMNL	98680B	06.05 "pwd" command reports wrong path for symbolic link over "netuname" command	5000527929	298
SCCS	98680B	06.02 return code from "rmnl" is incorrect.	5000437129	279
SH	98680B	05.01 Problems with sccs and files larger than 3.35 megabytes.	5000170340	262
	98680B	06.05 sh(1) loses positional parameters when executing ". script params"	5000508911	296

CUMULATIVE KEYWORD INDEX

- S300 GENERAL HPUX - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
SH	98680B	06.00 Report of shell script that results in unexpected logout when run	1650050294	239
	98680B	06.00 problem with setting term variable	5000286476	270
SHUTDOWN	98680B	05.20 cannot boot from 5.21 recovery system	5000221259	266
STARBASE	98680B	06.05 "init s" or "shutdown 0" causes error message "HOME variable not set"	5000493999	288
	98680B	05.20 "gclose" of "hpgl" driver fails with error about semaphore	5000517565	297
	98680B	03.10 sleep(2) followed by gopen(3) generates core dump	5000503367	295
TAR	98680B	03.00 gopen with RESET DEVICE does not behave properly when using A1047A board	5000468884	283
TBL	98680B	06.05 tar(1) creates files with // in front of file name	5000484378	287
TERMINFO	98680B	06.00 "tbl" doesn't produce proper looking boxes on laser jet printer	1650057828	239
TSORT	98680B	06.05 terminfo, vt100 and xterm do not work together	5000487363	287
UMOUNT	98680B	05.03 Tsort(1) generates spurious output line when processing long file names	5000419770	268
UPDATE	98680B	06.02 AMOUNT DOES NOT REMOVE TMP FILES	5000419770	277
UUCP	98680B	/ETC/MAGIC ALWAYS GETS OVERWRITTEN DURING AN UPDATE	1650093351	243
VI	98680B	06.02 the -j and -o options to uustat return an illegal option message	5000436899	278
	98680B	06.05 vi(1) does not display correct format for information when using telnet	5000537837	300
	98680B	05.15 problem with terminfo and vi using 2392Sa	5000198770	264
	98680B	05.02 PROBLEM WITH UNDO FOR GLOBAL CHANGES IN MACROS IN VI	1650099328	243
XARGS	98680B	05.21 Xargs(1) of more(1) doesn't work as documented	1650041160	238
XDB	98680B	06.02 fdb has problems with formal arguments to CHARACTER*(*) subroutines	1650076091	240

- SERIES 300 GKS - SSB ISSUE DATE: 11/21/90

*****non*****	98672B	06.50 GSPKID returns wrong value	1650063933	304
GKS	98672B	06.50 gsfais() & gfa() don't draw right and bottom edges on xll	1650086041	304
STARBASE	98672B	06.50 gsfais() & gfa() don't draw right and bottom edges on xll	1650086041	304

- SNA3270 300 - SSB ISSUE DATE: 11/21/90

*****non*****	36590A	03.10 SA msg queues should be created with permissions 660, not 666	47006667626	305
	36590A	03.10 sa sna3270 spins if given a remotesplit hostname (hpindlb:ibm)	47006667634	305
	36590A	02.10 SNA3270 causes the 800 to lock up and hang	5000443366	305
	36591A	03.11 SNA3270 uses some help messages reserved for the Nuc.	47006667600	307
	36591A	03.10 Power off LU, send LUSTAT. Power on lu, send Notify ON. This is wrong.	16500443760	307

- SNA3770 300 - SSB ISSUE DATE: 11/21/90

*****non*****	98184A	01.01 AS SOON AS MON3770 SEES TRN IN A PUNCH FILE, IT STOPS INTERPRETING DATA	1650091587	309
	98184A	01.00 JES3 receives Invalid FM header from host with recommended logmode	4700714915	309
	98188A	01.01 Enhancement: Enabling padding with trailing blanks, as real device does.	1650107045	310

- SNALINK 300 - SSB ISSUE DATE: 11/21/90

*****non*****	36592A	03.21 system panic when SNALink is installed and PSIDAD is run	5000520528	312
	36592A	03.21 Snanuc fails when the host sends ua an second snrm.	5000542688	313
	36592A	03.20 if LU name is 8 chars, field formatting messed up in snarpt	4700734566	312

CUMULATIVE KEYWORD INDEX

- SNALINK 300 - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	36592A	03.10 if SA nucleus is dead; error messages aren't very friendly	4700667568	311
	36592A	00.00 When only l lu is defined in the config file, X-f occurs when a key hit	4700420307	311
	36592A	00.00 Session, file transfer, and character drop problems with SNALINK.	4700474577	311

- SNALINK 300/GW - SSB ISSUE DATE: 11/21/90

*****none*****	36593A	03.20 SNALink install script fails on AXE systems which lack /usr/bin/id	4700733758	317
	36593A	03.10 ALPHA-SITE: Mod-2 BIND image rejected by SNALink/SNA3179G.	4700667519	314
	36593A	03.10 Incorrect processing of COMM504 when in an SCP-LU session.	4700667576	315
	36593A	03.10 Incorrect generation display codes when COMM 504 occurs in LU-LU session	4700667584	316
	36593A	03.10 Incorrect msg "sna3270 for LU X is being ordered to terminate."	4700667618	316
	36593A	03.10 snalink has snamchk226: :mch end: code:901 file:././queue/dqemgr.c	4700674499	316
	36593A	00.00 Request to allow more valid PSERVICE parameters in logemode table.	4700419606	314

- SOFT PC FOR 9000/300 - SSB ISSUE DATE: 11/21/90

*****none*****	98870A	01.03 Turbo Prolog under CGA emulation broken.	4000094904	329
	98870A	01.03 ExecutiveMemomaker won't work. Too many file handles. config.sys OK.	4000094912	329
	98870A	01.03 Drawing Gallery drops character when entering a text string.	4000094920	330
	98870A	01.03 Cannot install Lotus 123 using SlavePC, SCR100	4000095026	330
	98870A	01.03 Mouse user interface is unfriendly, can be hard to use, SCR163	4000095034	331
	98870A	01.03 Escape character does not exit demo mode properly MS Flight Sim, SCR161	4000095042	331
	98870A	01.03 Sailing game will not run, encounters illegal instruction, SCR168	4000095059	331
	98870A	01.03 Advance Link won't install from floppy drive A:, SCR170	4000095067	331
	98870A	01.03 The SoftPC cursor was the wrong color with some applications, SCR42	4000095075	332
	98870A	01.03 Graphics problems with text in pc mode 40, with Willy game, SCR102	4000095083	332
	98870A	01.03 Problems updating complete screens of video memory, SCR167	4000095091	332
	98870A	01.03 Round42 game has slow and bad graphics, SCR169	4000095109	333
	98870A	01.03 PrintMaster program will not run from the FSA drive, E:, SCR172	4000095117	333
	98870A	01.03 Mouse attached to Smalltalk V Application is inoperative	4000095448	333
	98870A	01.03 Crosstalk XVI doesn't work with PC bulletin board yellow pages, SCR#162	4000095455	334
	98870A	01.03 Graphics problem with Typ-Set, bad characters and backgrounds, SCR#86	4000095463	334
	98870A	01.03 The scenery flashes when using MS Flight Simulator, SCR205	4000095505	334
	98870A	01.03 MS Windows does not list files selectively with WIN DRAW command, SCR202	4000095588	335
	98870A	01.03 The right hand alt key doesn't work, SCR232	4000095695	335
	98870A	01.03 Crosstalk XVI has timing problems, SCR162	4000095810	335
	98870A	01.03 executing cat890511.exe from hpccf gets "CRC Error" (works on XT)	4000096206	336
	98870A	01.03 Falcon game will not run in Hercules graphics mode	4700921791	337
	98870A	01.03 Test Drive will not run in HGA mode	4700921882	337
	98870B	02.00 Mouse driver: current version is old/doesn't work properly w/new apps.	4700887851	340
	98870B	02.00 Running WordPerfect slows down SoftPC by 4 times	4700911818	340
	98870B	02.00 drive B doesn't work unless on at DOS boot time	4700921700	340
	98870B	02.00 MKS "ls" command makes drive E unusable	4700921718	341
	98870B	02.00 Cursor sometimes vanishes forever	4700921726	341
	98870B	02.00 all files created on drive E have execute permission	4700921734	341
	98870B	02.00 SoftPC terminal version numeric keypad mapping gets confused	4700921809	343
	98870B	02.00 key repeat delay too long	4700921825	343



Keyword	Product number	uu.ff	Description	KPR number	page
*****none*****	98870B	02.00	spc term link should use basename	4700921833	343
	98870B	02.00	EGA area fill test hangs	4700921858	343
	98870B	02.00	Character Attributes do not function properly	4700921874	344
	98870B	02.00	3 5-inch floppy read errors	4700921890	344
	98870B	02.00	FSA, malfunctions with similarly named files, can lose data	4700921908	344
	98870B	02.00	no screen refresh during media init	4700921916	344
	98870B	02.00	Some of the text on the menus is cut off by the borders.	4700921965	345
	98870B	02.00	Codepage Switching command "chcp" sometimes performs incorrectly	4700921973	345
	98870B	02.00	MicroSoft Excel locks up SoftPC if invoked twice in a row	4700921981	345
	98870B	02.00	Word Perfect learn program behaves incorrectly	4700921999	345
	98870B	02.00	Second or Third invocation of SoftPC may fail with internal error	4700922005	345
	98870B	02.00	BIOS Data Wrong coming from Debug program	4700922013	345
	98870B	02.00	Multiple file compare fails with DOS comp command	4700922021	346
	98870B	02.00	Zoom using Mouse	4700922039	346
	98870B	02.00	MS windows logo should not always come up	4700922054	346
	98870B	02.00	Cursor appears in wrong place in Chartmaster	4700922070	346
	98870B	02.00	Caps lock not disabled	4700922088	346
	98870B	02.00	Pointer Stuck on MS Windows	4700922096	346
	98870B	02.00	Data Error using DOS restore	4700922104	346
	98870B	02.00	RMVC causing minor error	4700922112	347
	98870B	02.00	Fastopen works, and probably shouldn't	4700922120	347
	98870B	02.00	Two scrolling Screens have problems with EGA Demo	4700922138	347
	98870B	02.00	Detect Caps and Numlock	4700922179	348
	98870B	02.00	Improper Display with NYET	4700922187	348
	98870B	02.00	Display problems with NYET	4700922229	349
	98870B	02.00	File access error with PFS First Choice	4700922237	349
	98870B	02.00	SKPlus HFX hard disk full	4700922252	350
	98870B	02.00	Error with Framework II reading disk	4700922260	350
	98870B	02.00	MicroSoft RBase volume label bad	4700922278	350
	98870B	02.00	The Antix game hangs when you start it up	4700922294	351
	98870B	02.00	The BIOS test BL-13-3 hangs SoftPC	4700922310	351
	98870B	02.00	Printing a file does not work properly sometimes with a parallel printer	4700922328	351
	98870B	02.00	No error message if spc term run on terminal assigned as com port output	4700922336	351
	98870B	02.00	DOS Graph: Garbage on screen	4700922344	351
	98870B	02.00	Using QI windows small blobs on screen, bad display	4700922351	351
	98870B	02.00	The boot message for SoftPC doesn't include the year 1989	4700922369	351
	98870B	02.00	The SoftPC Mouse may be attached in two SoftPC windows at once	4700922377	352
	98870B	02.00	" " key works intermittently on 2392, 2393, 70094 terminals	4700922385	352
	98870B	02.00	The SoftPC menu editing does not always provide autorepeat	4700922393	352
	98870B	02.00	The SoftPC SlavePC runs very slowly	4700922401	352
	98870B	02.00	PC Tools Deluxe does not display all files properly in a listing	4700922419	352
	98870B	02.00	Cannot play NiteOrc game	4700922427	352
	98870B	02.00	Mouse doesn't work properly with Ventura publishing	4700922435	353
	98870B	02.00	File retrieval with Turbo Prolog may have problems	4700922443	353
	98870B	02.00	The CTL-Break key is not detected properly with test	4700922450	353
	98870B	02.00	SoftPC Filename mapping shouldn't use shell wildcard characters	4700922468	353
	98870B	02.00	The printing key does not function on the 700/44	4700922476	353
	98870B	02.00	Switching graphics modes from EGA to Hercules and back may confuse SPC	4700922492	353

CUMULATIVE KEYWORD INDEX

- SOFT PC FOR 9000/300 - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu. ff Description	KPR number	page
*****none*****	98870B	02.00 Starflight game will not run in EGA mode	4700922500	354
	98870B	02.00 cannot use MODE to set 19.2K baud rate	4700922518	354
	98870B	02.00 SoftPC behaves incorrectly with explicit KB focus policy	4700922526	354
	98870B	02.00 should not permit "block" device files for floppy	4700922534	354
	98870B	02.00 AdvanceLink: Ctrl-F6 doesn't work	4700922583	354
	98870B	02.00 AdvanceLink hangs after Alt-H	4700922591	354
	98870B	02.00 X11 keyboard: Numeric keypad "/" key does not work	4700922757	354
	98870B	02.00 X11 keyboard: ScrLckBreak key does not register on Diagnostic Programs	4700922765	354
	98870B	02.00 Codepage language support: German, "7"key, "\" dead key broken	4700922773	355
	98870B	02.00 70044 terminal: Asterisk key not working on numeric keypad	4700922781	355
	98870B	02.00 FSA, filenames with certain extensions not accessible from SoftPC	4700922799	355
	98870B	02.00 Reverse video does not work on the 2392 2394 and 7009x terminals	4700922807	355
	98870B	02.00 DOS Xcopy command doesn't work properly with FSA directories	4700922815	355
	98870B	02.00 Concurrent PC-DOS won't install on SoftPC	4700922823	355
	98870B	02.00 Displayswrite4 screen not refreshed completely	4700922831	355
	98870B	02.00 Problems resetting LIM (memory) to zero	4700922849	355
	98870B	02.00 Learn program from Microsoft Works locks entire SoftPC window	4700922856	356
	98870B	02.00 Microsoft Works 2.0: using same arrow key causes unwanted repeating	4700922864	356
	98870B	02.00 Trying to start Quattro Pro fails and occasionally locks all windows	4700922880	356
	98870B	02.00 does not handle input before boot message is up	4700923094	356
	98870B	01.30 autofreeze behaves incorrectly with explicit keyboard focus	4700921775	342
	98870B	01.30 Errors when editing or creating drawings with Autocad	4700922146	347
	98870B	01.30 LIM user interface is hard to use	4700922153	347
	98870B	01.30 Tests operate incorrectly with PC Labs	4700922161	348
	98870B	01.30 File error with Multimate advantage	4700922203	348
	98870B	01.30 Executing VGA tests fails with internal error using PCLabs test	4700922211	349
	98870B	01.30 All keys in MS Word autorepeat	4700922245	349
	98870B	01.30 RMVC.SYS formatting /dev/tty to COM1 causes SoftPC to hang	4700922286	350
	98870B	01.20 assigning /dev/tty to COM1 causes SoftPC to hang	4700921783	342
	98870B	01.02 MS Windows 2.03 crashes	4700921866	343
	98870B	01.02 can't use DOS coprocessor hard disk	4700921742	341
	98870C	02.00 spc hangs when HP BASIC-UX is active	4700922914	357
	98870A	01.03 using softpc p 3-4 implies all home directories in /users.	4000093757	328
	98870A	01.03 using slave pc section p.4-21 configuration info inadequate.	4000093765	328
	98870A	01.03 Typing very fast may cause characters to be lost or garble command line	4000091660	318
	98870A	01.03 function keys do not work with evelys word program	4000091678	318
	98870A	01.03 cannot connect an HP-IB plotter to a com port	4000091728	318
	98870A	01.03 "MS Learning DOS" hangs softpc just after start up.SCR160	4000091736	319
	98870A	01.03 caps lock key must be pushed twice to change state.	4000091926	319
	98870A	01.03 sidekick does not work in CGA mode	4000091934	320
	98870A	01.03 SoftPC Comm ports do not have eight bit parity capabilities	4000091983	320
	98870A	01.03 soft PC does not assign colors correctly.SCR254	4000091991	321
	98870A	01.03 copying from com1 to a file doesn't work correctly.SCR246	4000092015	321
	98870A	01.03 word perfect graphics conversion locks up softpc, graphcnv.exe.SCR251	4000092023	322
	98870A	01.03 setup panel highlights random characters.SCR214	4000092056	322
	98870A	01.03 full ibm charact set is not correctly implemented	4000092072	323
	98870A	01.03 all legal termcap ID's for the 2393 terminal are not recognized by Softp	4000092098	323
	98870A	01.03 garbage appears on screen when using model 700/44 terminal.SCR222	4000092106	324
	98870A	01.03 cursor doesn't track properly when running "Word Perfect",SCR250	4000092130	325

DOCUMENTATION

SOFT PC



CUMULATIVE KEYWORD INDEX

- SOFT PC FOR 9000/300 - SSB ISSUE DATE: 11/21/90

Keyword	Product number	uu.ff Description	KPR number	page
SOFT PC	98870A	01.03 line drawing characters aren't mapped correctly	4000092148	325
	98870A	01.03 Cannot connect HPiB printer to comm port properly, SCR220	4000092205	326
	98870A	01.03 softpc kills the bell and autorepear in x11	4000093666	327
	98870A	01.03 softpc will not work properly with some types of reparenting windowmgr	4000093674	327
	98870A	01.03 reassigning devices will lock up soft pc	4000093690	327
	98870A	01.03 /usr/bin/dosls incorrectly specifies volume labels as filenames	4000093708	328
	98870A	01.03 pages A-Z and A-4 "using soft pc: should not refer to the DOS coprocessor	4000093781	329
	98870A	01.03 Soft PC does not understand local:0 DISPLAY variable	5000463372	337
	98870A	01.03 Request: reposition window used to create new devices to avoid overlap	5000464107	338
	98870A	01.03 can't enter text into menu box when adding a new hard drive using menu	5000474726	339
	98870A	01.03 Lotus, Work Perfect will not work with drive e on SPC 1.3	5000527143	339
	98870A	00.00 Color Graphics refresh is slow on Falcon game, SCR143	4000092049	322

- STARBASE RAD & RAY - SSB ISSUE DATE: 11/21/90

*****none*****	98885A	01.00 render scene gives incorrect error message for unclosed trim curves	4000096396	358
	98885A	01.00 Objects disappear when they are place exactly on the hither plane.	4000096412	358
	98885A	01.00 Radiosity shadows not computed for extremely small environments.	4000096438	358
	98885A	01.00 False shadows are produced at some polygon vertices	4000096446	359
	98885A	01.00 Complex polygons may get holes punched in them.	4000096461	359
	98885A	01.00 "Invalid global environment id" should read "Invalid scene id"	4000096479	359
	98885A	01.00 Facets disappear in some ray traced spline surfaces.	4000097113	360
	98885A	01.00 Facets have "acne" in ray trace of certain spline surfaces	4000097121	360
	98885A	01.00 Gamma correction causes a crash for backgrounds and flat shade items.	4000097139	360
	98885A	01.00 Facets get shadowed when radiosity done on specific spline surface	4000097147	361
	98885A	01.00 When a trimming curve is applied to certain spline surfaces edges drop	4000097154	361
	98885A	01.00 Intensities per/vertex not blended correctly on meshed polygons.	4000098533	361

- X.400 SERV SOFTWARE - SSB ISSUE DATE: 11/21/90

*****none*****	32058A	00.00 Some x400 utils, when run as root, leave behind *.conf belonging to root	4700852525	362
	32058A	00.00 MR version contains several man pages from FT	4700876714	362
	32058A	00.00 Queview only works when the full pathname is specified	4700883124	362
	32058A	00.00 x4perm has a problem changing premissions for x4dump, x4mailer, etc	4700885632	362
	32058A	00.00 Zero length subject causes encoder to go down(error 5029 or event 505)	4700929372	362
	32058A	00.00 x4xfer fails if MPE nodename extension is > 16 characters	4700941898	362
	32058A	00.00 x4admin core dumps when hit <field help> on local x.25 nsap field.	5000558338	362



KPR #: 4000023648 Product: 300/800 COMMON 97089-XXXXX 00.00

Keywords: AWK

One-line description:  
Errors in awk documentation.

Problem:  
Errors in awk documentation:  
\* Concepts and Tutorials

On page 11 it shows the string function split but does not show the usage which is  
n=split(.....)

\* Ref. Guide  
Page 2 of awk(1), lines 10 and 11 should be ~(for contains) and !~(for does not contain). The '~' does \*not\* appear.

-----  
This defect entry references errors in three manuals:

Text Processing C&T, awk:  
There is no example of any usage for split (p.16).  
n=split(.....) is one use.

HP-UX Reference, awk(1):  
As of, at least as early as, Release 6.5/3.1 the Ref. Guide did show the tildes. They may have been missing from earlier editions.

Text Formatters C&T, nroff:  
There is no suggestion about using col before sending nroff output to the printer or CRT.

Cause:  
The IBL examples work correctly with troff, but sometimes do not work with nroff. Nroff output should be run through col as explained on col(1) manual page in HP-UX reference.

Temporary solution:  
Need to add note to tutorial explaining the necessity of using col(1) after nroff before sending output to printer or CRT.

-----  
for nroff outputs to CRT or printer, consider, as it appears in HPUX Reference, col(1):  
tbl <filename> | nroff -man | col | more -s  
for awk(1) in the HPUX Reference, use ~ (tilde) as a matching-operator meaning "contains", and use !~ (exclamation-point tilde) as matching-operator meaning "does not contain" in: expression matching-operator regular-expression  
for using split in awk, one use is to determine the number of fields(n) a string is split into:  
n=split(<string>,<array-name>,<separator>)

Fix information:  
Will be fixed in future release

-----  
The HPUX Reference entry for awk(1) is updated to reflect the tilde omission for, at least as early as, Release 6.5/3.1  
The awk C&T\* entry is enhanced to show an example for

Known Problem Reports as of 11/21/90

KPR #: 4000023648 \*\*CONTINUED\*\*

split for Release 8.0  
The nroff C&T\* entry is enhanced to show using col for nroff CRT and printer output for Release 8.0

---  
\* As of Release 8.0, C&T's are restructured and renamed. The new collection is User's Guides, rather than C&T's. awk is a Part of the Text Processing User's Guide; nroff is a Part of the Text Formatting User's Guide. Page numbering may have changed.

KPR #: 4000098558 Product: 300/800 COMMON 97089-XXXXX 00.00

One-line description:  
Subject: bug in wc documentation

Problem:  
Subject: bug in wc documentation

The manual page says that wc prints the file name if multiple files are specified on the command line. Wc prints the file name even if only one file name is specified on the command line.

Temporary solution:  
None needed.

Fix information:  
Fixed several releases ago.

Signed off 07/16/90 in release X05.30

KPR #: 4700868216 Product: 300/800 COMMON 97089-XXXXX 00.00

One-line description:

How to configure the 2nd serial I/O port for the 808/815 isn't documented

Problem:

The HP 9000 Series 800 System Administrator's Manual does not describe how to use the built-in RS232 Port B.

Temporary solution:

The HP9000 Series 800 Installing the HP 815S Integrated System manual, Edition 1, August 1989 (HP Part Number A1071-90000), discusses the use of Port B, but the discussion is not correct.

The sentence on page 5-2 that reads,

Port A is identified to the system as: scc1 lu (logical unit) 0  
address 1. Port B is identified to the system as: scc1 lu 1 address 1.

Should be replaced by the following:

Ports A and B are connected to scc1 interface card, which uses the scc1 driver. This card is identified in the S800 file by the entry,

Known Problem Reports as of 11/21/90

Page: 3

KPR #: 4700868216 \*\*CONTINUED\*\*

scc1 lu 0 address 1.

Port A uses device file "/dev/ttya", and Port B uses device file "/dev/ttyb". The entry, for example, for a terminal using Port B in the /etc/inittab file might be:

ca:2:respawn:/etc/getty ttyb H

Fix information:

As of the next release of HP-UX Series 800 computers, the system will automatically configure the driver for the scc1 interface card. The system will also install the device files, /dev/ttya for Port A and /dev/ttyb for Port B.

The SAM utility will also support the scc1 driver, allowing addition of devices to both Ports A and B.

KPR #: 500296855 Product: 300/800 COMMON 97089-XXXX 00.00

Keywords: DOCUMENTATION

One-line description:

Periph Inst Gde, give switch setting for 98550A when 98556A is added.

Problem:

Switch settings for the 98550A Color Video Board are not given when a 98556A 2D Graphics Accelerator is installed. The display will not work properly without changing these switch settings.

Fix information:

May be fixed in a future release.

Known Problem Reports as of 11/21/90

Page: 4

KPR #: 4700916833 Product: 3179G DISP. STATION B1001A

One-line description:

Sense code 08710000 and a negative response are returned at logon time.

Signed off 07/06/90 in release A01.03

KPR #: 4700916841 Product: 3179G DISP. STATION B1001A 07.00

One-line description:

Programmed Symbols and Image Symbols display wrong on HP700/X terminal.

Signed off 07/06/90 in release A01.03

KPR #: 4000040410 Product: ADA DS. - 9000/300 98860

03.00

One-line description:  
Constant folding should raise NUMERIC\_ERROR but raises CONSTRAINT\_ERROR

Problem:  
Constant folding which results in a value outside of the base type range incorrectly raises a CONSTRAINT\_ERROR rather than a NUMERIC\_ERROR during execution. As in:

```
-----
with text_io;
procedure HP404100M is
  S: short_short_integer;
  negone: integer := -1;
begin
  -- The following incorrectly raises constraint error.
  S := short_short_integer(-128) / short_short_integer(-1);
exception
  when CONSTRAINT_ERROR =>
    TEXT_IO.PUT_LINE("CONSTRAINT_ERROR raised incorrectly");
  when NUMERIC_ERROR =>
    TEXT_IO.PUT_LINE("NUMERIC_ERROR raised correctly");
end;
-----
```

```
begin
  -- The following correctly raises numeric error.
  S := short_short_integer(-128) / short_short_integer(negone);
exception
  when CONSTRAINT_ERROR =>
    TEXT_IO.PUT_LINE("CONSTRAINT_ERROR raised incorrectly");
  when NUMERIC_ERROR =>
    TEXT_IO.PUT_LINE("NUMERIC_ERROR raised correctly");
end;
end HP404100M;
```

Fix information:  
May be corrected in a future release.

KPR #: 4000047415 Product: ADA DS. - 9000/300 98860

03.00

One-line description:  
Unhandled exceptions in a task may fail to produce a traceback.

Problem:  
Unhandled exceptions in tasks should produce a traceback as in the environment task. There is no particular reason the environment task should be singled out for this treatment.

```
-----
with text_io; use text_io;
procedure HA474150M is
  task crash;
```

```
-----
task body crash is
  count : integer := 10;
  frac : float;
```

- ADA DS. - 9000/300 -

KPR #: 4000047415 \*\*CONTINUED\*\*

```
begin
  loop
    -- unhandled exception when count = 0
    frac := float(1/count);
    count := count - 1;
  end loop;
end crash;
```

```
begin
  put_line("Tasks created with unhandled exception.");
  put_line("HA474150M FAILED if no traceback for " &
    "unhandled exception in task");
end HA474150M;
-----
Tasks created with an unhandled exception.
HA474150M FAILED if no traceback for unhandled exception in task.
-----
<No traceback... FAILED>
```

Fix information:  
May be corrected in a future release.

KPR #: 4000056556 Product: ADA DS. - 9000/300 98860

03.00

Keywords: ADA

One-line description:  
'ADDRESS returns bad value if applied to program unit not yet elaborated

Problem:  
Wrong value is returned by the attribute ADDRESS when applied to a program subunit which is not yet elaborated.

```
As in:
with SYSTEM; use SYSTEM;
package PACK is
  procedure P;
  X : ADDRESS := P'ADDRESS; -- P has not been elaborated
end PACK;
```

Temporary solution:  
Insure the elaboration of the program subunit. In the given example, initialize X to P'ADDRESS within the body of PACK (which contains the body of P). Or declare P in another library package; and use pragma ELABORATE of that library package before initializing X to P'ADDRESS within the specification of PACK.

Fix information:  
May be corrected in a future release.

KPR #: 4000057836 Product: ADA DS. - 9000/300 98860

03.00

Keywords: ADA

One-line description:  
No STORAGE\_ERROR (or user logged-off) for task stack limit exceeded

- ADA DS. - 9000/300 -

KPR #: 4000057836 \*\*CONTINUED\*\*

Problem:  
Objects declared within tasks are allocated in the task's stack. If the object is larger than the available task stack limit, then STORAGE\_ERROR (or TASKING\_ERROR depending on where in the task the problem occurred) should be raised, but instead, results in a "Memory fault" with a core dump. Additionally, if the main program happens to be performing IO, the user may get logged-off.

```
Example (no IO in main program):
program MAIN is
  task type T;
  type TA is access T;
  X : TA;
  task body TA is
    O : array (INTEGER range 1..10000) of INTEGER;
  begin
    null;
  end;
begin -- MAIN
  -- The following statement should cause STORAGE_ERROR, but instead
  -- it results in a "Memory fault" with a core dump.
  X := new TA;
end MAIN;
```

Temporary solution:  
By default, task stack limit of a task (not the main program) is 8\*1024 bytes. With the "-w b,-t,<n>" option, this limit can be increased to avoid this problem. Additionally, the user can change the program to declare smaller items or use the heap (rather than the stack).

Fix information:  
May be corrected in a future release.

KPR #: 4000070938 Product: ADA DS. - 9000/300 98860 03.00

One-line description:  
Poor error message when a subprogram does not conform with its spec

Problem:  
When the body proposed for a subprogram P does not conform (profile) with its spec, a short message says "the body of P is missing"; whereas signaling the presence of potentially matching specifications would be more user-friendly.

Fix information:  
May be corrected in a future release.

Signed off 03/27/90 in release A04.35

KPR #: 4000082925 Product: ADA DS. - 9000/300 98860 03.00

One-line description:  
The MACHINE\_ROUNDS attribute is wrong for fixed point types

Problem:  
The following program shows a bug in the 'MACHINE\_ROUNDS' attribute for fixed point types. The program does a division of a fixed point value by an integer. This operation truncates, and does not round. Because of this, fix'MACHINE\_ROUNDS should be FALSE rather than TRUE.

```
with TEXT_IO;
procedure FIXROUNDS is
  type fix is delta 1.0 range -10.0 .. 10.0;
  F: fix;
begin
  F := 3.0;
  F := F / 4;
  -- will either truncate to 0.0 or round to 1.0.
  -- Either are OK according to RM 4.5.7, since the
  -- required bounds on the result is the model
  -- interval 0.0 .. 1.0. However, since division is
  -- a predefined arithmetic operation, if truncation
  -- occurs, fix'MACHINE_ROUNDS should be FALSE, RM
  -- 13.7.3.
  if (F = 0.0) then
    if (fix'MACHINE_ROUNDS) then
      -- This is the message printed!!!!!!!!!!!!!!
      TEXT_IO.PUT_LINE (
        "FAILED, did truncation and MACHINE_ROUNDS was true")
    else
      TEXT_IO.PUT_LINE (
        "PASSED, did truncation and MACHINE_ROUNDS was false");
    end if;
  elsif (F = 1.0) then
    if (fix'MACHINE_ROUNDS) then
      TEXT_IO.PUT_LINE (
        "PASSED, did rounding and MACHINE_ROUNDS was true");
    else
      TEXT_IO.PUT_LINE (
        "PASSED, did rounding and MACHINE_ROUNDS was false");
    end if;
  else
    TEXT_IO.PUT_LINE ("FAILED: F is neither 0.0 or 1.0");
  end if;
end FIXROUNDS;
```

Fix information:  
May be fixed in a future release.

KPR #: 4700822031 Product: ADA DS. - 9000/300 98860 04.35

One-line description:  
Object value corrupted by assignment of array with certain lower bound

Problem:  
If an object is allocated after a variable declaration of an

KPR #: 4700822031 \*\*CONTINUED\*\*

array type having as lower bound T'PRED(X) with X less than T'FIRST, the object value is corrupted after the assignment of that array variable.

Test program follows:

```
with TEXT_IO;
procedure sa3092 is
  type T is range 0 .. 25;
  X : T := 0;
  A : array (T'pred (X) .. 10) of INTEGER;
  Y : INTEGER := 0;
begin
  A := (OTHERS => 1);
  TEXT_IO.PUT (INTEGER'IMAGE(Y));
  if Y = 0 then TEXT_IO.PUT_LINE(" PASSED");
  else TEXT_IO.PUT_LINE(" FAILED");
  end if;
end;
```

KPR #: 4700827220 Product: ADA DS. - 9000/300 98860 04.35

One-line description:  
Abort never occurs without task reaching sync. point

Problem:

The runtime system checks for abnormality before and after it performs operations, e.g., making an entry call, aborting a task, etc. However, it doesn't check if a task becomes abnormal at the end of each time slice. Therefore, if a task only loops around users' code and is aborted, it will never terminate. The following example illustrates:

-- This program never terminates. According to the LRM, it doesn't -- need to, but it would be better if the task were checked for -- abnormality after each time slice. With that, this would terminate.

```
with TEXT_IO;
procedure TA is
  pragma PRIORITY (1);
  MINE: exception;
  task T is
    pragma PRIORITY (1);
  end T;
  task body T is
  begin
    loop
      null;
    end loop;
  end T;
begin
  delay 0.1;
```

- ADA DS. - 9000/300 -

Known Problem Reports as of 11/21/90

KPR #: 4700827220 \*\*CONTINUED\*\*

```
TEXT_IO.PUT_LINE ("About to abort");
abort T;
TEXT_IO.PUT ("Aborted");
end TA;
```

Temporary solution:

We can let the runtime check for abnormality by making an entry call or executing a delay statement in the task being aborted. This forces the aborted task to be swapped out and checked for abnormality. Therefore, task body T in the example above can be modified as :

```
task body T is
begin
  loop
    delay 0.1;
  end loop;
end T;
```

Fix information:

The bug is fixed in 5.32 compiler which has a new tasking model. The abort statement has an immediate effect except for tasks engaged in a rendezvous as callers.

KPR #: 4700839746 Product: ADA DS. - 9000/300 98860 04.35

One-line description:

PROGRAM\_ERROR may occur when lib pkg has record w/ dyn array components

Problem:

PROGRAM\_ERROR raised at execution time when a library package contains an object of a record type having dynamic array components which may raise CONSTRAINT\_ERROR. Test program follows:

```
package SA is
  I : integer := 0;
  type REC2 (size : positive := 1) is
    record
      S : string (1 .. size);
      C1, C2 : integer range 1 .. positive (I);
    end record;
  VAR2 : REC2;
end SA;
with SA;
procedure SA3763 is
begin
  null;
end SA3763;
```

- ADA DS. - 9000/300 -

KPR #: 4700842864 Product: ADA DS. - 9000/300 98860

04.35

One-line description:  
Unhandled exception in main subprogram incorrectly kills library tasks

## Problem:

-- This program shows a bug in Ada/300 only.  
-- It does not appear in Ada/800.

-- We have a library package with a task, and two main subprograms.  
-- If I bind with MAIN\_NORMAL, the main completes normally, and then  
-- waits for the library task to complete. If I bind with MAIN\_EXCEPT,  
-- the main completes by raising an exception. In this case, the  
-- exception manager aborts the program, killing the library  
-- task. This is not correct, it should wait for library tasks.

```

package HAS_TASK is
  task LIB_TASK is
    entry POKE (ARG: in STRING);
  end LIB_TASK;
end HAS_TASK;

with TEXT_IO;
package body HAS_TASK is
  task body LIB_TASK is
  begin
    for I in 1..100 loop
      select
        accept POKE (ARG: in STRING) do
          TEXT_IO.PUT_LINE (ARG);
        end POKE;
      or
        delay 0.5;
      TEXT_IO.PUT_LINE ("In task");
    end select;
  end loop;
end LIB_TASK;

with HAS_TASK;
procedure MAIN_NORMAL is
begin
  for I in 1..5 loop
    delay 2.0;
    HAS_TASK.LIB_TASK.POKE ("In main");
  end loop;
  HAS_TASK.LIB_TASK.POKE ("MAIN DONE!!!");
end MAIN_NORMAL;

with HAS_TASK;
procedure MAIN_EXCEPT is
begin
  for I in 1..5 loop
    delay 2.0;
    HAS_TASK.LIB_TASK.POKE ("In main");
  end loop;
  HAS_TASK.LIB_TASK.POKE ("MAIN RAISING!!!");

```

- ADA DS. - 9000/300 -

KPR #: 4700842864 \*\*CONTINUED\*\*

```

  raise NUMERIC_ERROR;
end MAIN_EXCEPT;

```

## Temporary solution:

Put an exception handler at the end of your main subprogram, as follows:

```

exception
  when others =>
    TEXT_IO.PUT_LINE ("MAIN terminated with exception");
end;

```

This will cause the main to print a message and complete normally, avoiding the bug.

KPR #: 4700843680 Product: ADA DS. - 9000/300 98860 04.35

One-line description:  
Incorrect aggregate for packed array of a subtype of Boolean

## Problem:

The following test case demonstrates a problem with the 68k code generator. When generating code for the (others => TRUE) Statement, the 68k code generator gets the BFEATS instruction wrong.

The problem occurs when a subtype of STANDARD.BOOLEAN is used in a length clause and assigned a size of 1 bit in a size specification. The compiler generates an incorrect MC68020 instruction: BFEATS, when code is emitted for the (others => TRUE) aggregate.

If the code is optimized with HLOPT the problem disappears.

```

with TEXT_IO;
procedure BUG is
  use TEXT_IO;

```

```
begin
```

```

  declare
    type BIT is new BOOLEAN;
    for BIT'SIZE use 1;

    type BITARR is array(0..2) of BIT;
    for BITARR'SIZE use 3;

```

```

  A1 : BITARR := (others => TRUE);
  A2 : BITARR := (0 => TRUE, 1 => TRUE, 2 => TRUE);

```

```
begin
```

```

  PUT_LINE("Case #1:");
  if A1 /= A2 then
    PUT_LINE(" Bad representation for aggregate: " &

```

- ADA DS. - 9000/300 -

KPR #: 4700843680 \*\*CONTINUED\*\*

```

" '(others => TRUE)'. ";
end if;
end;

```

----- CASE #2 -----

```

declare
subtype BIT is BOOLEAN; -- Type BIT renames STANDARD.BOOLEAN

```

```

type BITARR is array(0..2) of BIT;
pragma PACK(BITARR);

```

```

A1 : BITARR := (others => TRUE);
A2 : BITARR := (0 => TRUE, 1 => TRUE, 2 => TRUE);

```

```

begin
PUT_LINE("Case #2:");
-- ERROR CASE
if A1 /= A2 then
PUT_LINE(" Bad representation for aggregate: " &
" '(others => TRUE)'.");
end if;
end;
end BUG;

```

Temporary solution:  
The user can either use STANDARD.BOOLEAN directly or use his own Boolean type which can be declared:

```

type BIT is (FALSE, TRUE); for BIT'SIZE use 1;

```

Also:

There is a patch available, to replace the faulty version of the ada compiler with a working version. The patch is too big to put on the Fort Collins SE machine (hpfscse). If you want a copy call the HP Response Center (the standard HP support channel). (Response Center engineers can call STD Languages Support for details).

Fix information:  
This defect may be repaired in a new release.

KPR #: 4700852830 Product: ADA DS. - 9000/300 98860 04.35

One-line description:

The result of fixed point division is rounded down.

Problem:

The compiler incorrectly truncates (rounds down) the result of a fixed point division. This is incorrect because the Fixed Point attribute F'MACHINE\_ROUNDS returns TRUE.

Temporary solution:  
There is no workaround at this time.

KPR #: 4700852830 \*\*CONTINUED\*\*

Fix information:  
May be fixed in a future release

KPR #: 4700862961 Product: ADA DS. - 9000/300 98860 04.34

One-line description:  
Ada.Make utility does not work on Ada/300 release 4.35

Problem:  
The version of ada.make shipped with HP-UX 7.0 (Ada version 4.35) does not work at all. This is due to a product release problem. Unfortunately, the wrong file got released to manufacturing. Ada.make is the only product component affected by the problem.

Ada.make will issue error messages like the following:

```

*** Error: That's an unknown qualifier DEBUG.

```

```

Make: Error:
| Incorrect parameters, make aborts.
|
ada.make: Errors detected.

```

Ada.make aborts right away, and does not produce any results.

The revision strings of the bad version are as follows (to find these, type: "cd \$ADA\_PATH; what ada.make\*");

```

ada.make: HP98860 A.04.35 89/09/30
ada.make.bin:
HP98860 A.04.35 Ada/300 DS AdaMake 89/09/29

```

Temporary solution:

There is a patch available, to replace the faulty version of the ada.make tool with a working version. The patch is on the Fort Collins SE machine (hpfscse) in directory ~/ftp/unsupp-patches/300-7.0/Ada. The file README in that directory explains the patch. For a copy, call the HP Response Center (the standard HP support channel).

The adamake patch has been incorporated into released product and shipped through manufacturing. This version of the product was shipped on tape with part number 98860-10036.

Fix information:

Fixed in version 4.35 of the product. Fixed is on tape with part number 98860-10036. Customers on update services should have already received the new tape.

Signed off 03/27/90 in release A04.35

KPR #: 4700863688 Product: ADA DS. - 9000/300 98860

04.35

One-line description:  
UNIX\_ENV not in predefined library as documented.

Problem:  
The User's Guide indicates that UNIX\_ENV will be supported in the 4.35 release. However, this package has in fact been eliminated. Some customers who have used previous versions of the HP Ada Development System may have code which makes use of this package.

Temporary solution:  
The UNIX\_ENV package has been replaced by the SYSTEM\_ENVIRONMENT package, which supplies the same functionality. The workaround is use this package instead.

Fix information:  
Mention of the UNIX\_ENV package has been removed from the HP documentation as of revision A.05.35.

KPR #: 4700863746 Product: ADA DS. - 9000/300 98860

03.25

Keywords: RUNTIME

One-line description:  
Shared memory utility "shmat" interferes with Ada heap

Problem:  
A program calls the HP-UX shared memory utility "shmat" to get a shared memory segment. After this, the Ada heap has been reduced to less than 64K bytes of available memory. Seems to be some interaction between "shmat" and the heap. This eventually causes STORAGE\_ERROR.

Temporary solution:  
There is a workaround available. For details, call the HP Response Center (the standard HP support channel). (Response Center engineers can call STD Languages Support for details).

KPR #: 4700868893 Product: ADA DS. - 9000/300 98860

04.35

One-line description:  
File name expansion works incorrectly if working directory is /

Problem:  
Any time an Ada DS component is invoked when the current working directory is the root directory /, some path names displayed by the Ada DS component will start with two slashes // instead of one slash /. This is most noticeable with ada.lslib, but it can occur with any component.

The problem is essentially cosmetic as it will not cause failure of any of the ADS components (HP-UX will ignore the redundant leading / when access is attempted).

KPR #: 4700868893 \*\*CONTINUED\*\*

Temporary solution:  
There is no workaround at this time other than not performing Ada DS operations while the current directory is /. There is no harm in performing Ada DS operations while in /, the product will operate correctly in other respects, displayed file paths simply "look strange" with the leading double /.

Fix information:  
This defect has been corrected for Ada/800 revision 4.35, it will be corrected for Ada/300 at some revision after revision 4.35.

This defect has been corrected for both Ada/300 and Ada/800 at revision 5.3.

KPR #: 4700877944 Product: ADA DS. - 9000/300 98860

04.35

Keywords: TOOLLS

One-line description:  
Suppressing uncalled subprograms incorrectly turns on binder listing

Problem:  
When the removal of uncalled subprograms is suppressed, with the "-w b -k" binder option, it does so, but it also incorrectly turns on the binder map (the "-w b,-l" option). This produces many pages of output. The executable produced is correct, but the extra output is a nuisance.

Temporary solution:  
There is a patch available, to replace the faulty version of the Ada compiler driver with a working version. The patch is on the Ft Collins SE machine (hpfscse) in directory ftp/unsupp-patches/300-7.0/Ada. The file README in that directory explains the patch. If you want a copy, call the HP Response Center (the standard HP support channel).

Fix information:  
The mother program has been fixed.

KPR #: 4700882399 Product: ADA DS. - 9000/300 98860

04.35

One-line description:  
Incorrect slice assignment when target & source are ref. by same pointer

Problem:  
Here is the test program I wrote to demonstrate the reported problem:  
-- This test procedure illustrates the following error produced by the --  
-- ADA compiler: --  
-- --  
-- When the value of a slice is assigned to another slice within the --  
-- same record and the slices are referenced by the same access --  
-- element, the assignment is done incorrectly. --



KPR #: 4700882399 \*\*CONTINUED\*\*

```

--
WITH text_io;
PROCEDURE A IS
  USE text_io;
  PACKAGE int_io IS NEW integer_io (integer);
  USE int_io;
  type array_range is (x, y);
  type array_type is array (array_range) of integer;
  type record_type;
  type record_pointer_type is access record_type;
  type record_type is record
    savepos, pos : array_type := (0, 0);
  end record;
  this_record_pointer : record_pointer_type;
BEGIN
  this_record_pointer := new record_type;
  this_record_pointer.pos := (20, 30);
  -- The following line of code produces incorrect (unexpected) result:
  -- The final value of the second element of savepos is 20, not 30!
  this_record_pointer.savepos := this_record_pointer.pos;
  put ( " pos : " );
  put ( this_record_pointer.pos (x), 0 );
  put ( " " );
  put ( this_record_pointer.pos (y), 0 );
  new_line;
  put ( " savepos : " );
  put ( this_record_pointer.savepos (x), 0 );
  put ( " " );
  put ( this_record_pointer.savepos (y), 0 );
  new_line;
  this_record_pointer.pos := (20, 30);
  -- The following line of code produces correct result.
  this_record_pointer.savepos (x..y) := this_record_pointer.pos (x..y);
  put ( " pos : " );
  put ( this_record_pointer.pos (x), 0 );
  put ( " " );
  put ( this_record_pointer.pos (y), 0 );
  new_line;
  put ( " savepos : " );
  put ( this_record_pointer.savepos (x), 0 );

```

- ADA DS. - 9000/300 -

KPR #: 4700882399 \*\*CONTINUED\*\*

```

put ( " " );
put ( this_record_pointer.savepos (y), 0 );
new_line;
END A;

```

Temporary solution:

Do the assignment into a temporary variable, and then back into the appropriate record.

KPR #: 4700883074 Product: ADA DS. - 9000/300 98860 04.35

One-line description:  
 FLU tools misbehave when arguments are 81 characters or longer.

Problem:

The ada.fmgr, ada.lmgr, and ada.umgr tools misbehave when they are presented with arguments that are 81 characters or longer. In particular, this problem has been noticed in the unit manager and the library manager. Consider the following sample sessions.

```

ada.umgr testlib
Unit_Manager.1 <81char name>

```

```

-- Program terminated by an exception propagated to a non Ada scope.
-- Exception raised: PROGRAM_ERROR
-- Erroneous instruction (address error) at PC: 0x370C6.

```

```

----- Stack trace of the propagation in the main stack -----

```

Compilation unit name	Scope name	Scope kind	Line number
PARSER_LEXICAL	GET_EXTENDED_SYMBOL	SUBPROGRAM	412

```

-- End of propagation: Program aborted.

```

The unit manager sometimes goes into an infinite loop. Sometimes you get the message (unable to reproduce this) error : Command not completed -- unexpected exception.

```

-- UNIX signal #7 raised outside Ada code at PC: 0x8DF60.
-- Program aborted.
sh: 19134 EMT trap - core dumped

```

Temporary solution:  
 Use shorter names in commands.

- ADA DS. - 9000/300 -

KPR #: 4700886150 Product: ADA DS. - 9000/300 98860

04.35

Keywords: TOOLS

One-line description:  
Binder aborts when considering too many unused subprograms for deletion

Problem:  
When binding large programs, the binder aborts with internal error. If we suppress the removal of uncalled subprograms (with the "-w b,-k" option), the binder works fine.  
The error message is:  
Ada Binder: Internal Error: Internal data is inconsistent. Either one of your libraries may have been corrupted, or erroneous code has been generated for one of the units.  
\*\*\* Please contact your HP representative \*\*\*  
Bind of MAIN failed, 1 error.  
No valid object file generated.  
ada: Errors detected.

Temporary solution:

There is a patch available, to replace the faulty version of the binder with a working version. The patch is on the Fort Collins SE machine (hpicse) in directory "ftp/unsupp-patches/300-7.0/Ada. The file README in that directory explains the patch. If you want a copy, call the HP Response Center (the standard HP support channel).

KPR #: 4700947523 Product: ADA DS. - 9000/300 98860

04.35

Keywords: RUNTIME

One-line description:  
Heap memory lost on close of file

Problem:  
There is a memory leak in file I/O. The following program uses up memory and eventually runs out.

```
with TEXT_IO;
procedure F00 is
F: TEXT_IO.FILE_TYPE;
begin
loop
TEXT_IO.OPEN (FILE => F, NAME => "/dev/null",
MODE => TEXT_IO.IN_FILE);
TEXT_IO.CLOSE (FILE => F);
end loop;
end F00;
```

Temporary solution:  
If you can just call RESET on the file, rather than CLOSE followed by OPEN, there is no memory loss.

Fix information:  
The Ada I/O system has been restructured at revision A.05.35 to properly deallocate all heap objects created when files are opened, when files

KPR #: 4700947523 \*\*CONTINUED\*\*

are closed. When compiled/bound with Ada revision A.05.35, the test program supplied with this defect report shows stable memory use (i.e. no increase in actual memory used) no matter how long the program is allowed to run.

KPR #: 1650139675 Product: ADA DS. - COMMON ADA-DSA

04.35

Keywords: RUNTIME

One-line description:  
SEQUENTIAL\_IO.END\_OF\_FILE fails if BUFFER\_SIZE FORM parameter used

Problem:  
The problem is that the function END\_OF\_FILE does not work when the BUFFER\_SIZE FORM parameter has been used.

Temporary solution:  
The workaround is not to use END\_OF\_FILE, but to instead let READ detect the error and raise END\_ERROR. Then, handle the exception and go on from there.

Fix information:  
The I/O buffering mechanism was modified for revision A.05.35 such that END\_OF\_FILE reports the correct result when the BUFFER\_SIZE FORM parameter has been used to change the buffer size to other than the default value.

KPR #: 4000035634 Product: ADA DS. - COMMON ADA-DSA 03.00

One-line description:  
Compiler rejects RENAMED entities in separate clauses.

Problem:  
The following programs illustrate a problem with RENAMES that should work according to the semantics of rename RM 8.5 (3) but does not compile. The problem is that the context manager (CTX) rejects the use of renaming entities in separate clauses.

```
package A is
  package B renames A;
  procedure HP356340M;
end A;
---
package body A is
  procedure HP356340M is separate;
end A;
---
separate (B)
procedure HP356340M is
```

1: \*\*\*CTX F001 The unit to compile is not known in the ADA library.

```
begin
  null;
end HP356340M;
```

```
package A is
  procedure B;
  procedure C renames B;
end A;
```

- ADA DS. - COMMON -

KPR #: 4000035634 \*\*CONTINUED\*\*

```
---
package body A is
  procedure B is separate;
end A;
---
separate (A)
procedure B is
  procedure HP356420M is separate;
begin
  null;
end B;
---
separate (A.C)
procedure HP356420M is
```

1: \*\*\*CTX F001 The unit to compile is not known in the ADA library.

```
begin
  null;
end HP356420M;
```

Fix information:  
May be corrected in a future release.

KPR #: 4000055467 Product: ADA DS. - COMMON ADA-DSA 03.25

Keywords: ADA

One-line description:

AdaXref does not create "introduced" procedure in generic instantiation

Problem:  
-----  
When a procedure is introduced via a generic package instantiation, and referenced in the same unit, the cross referencer tool XREF does not create an "introduced" occurrence in the corresponding entry.

KPR #: 4000055475 Product: ADA DS. - COMMON ADA-DSA 03.25

Keywords: ADA

One-line description:

AdaXref creates irrelevant "renaming procedure" in generic instantiation

Problem:  
-----  
When the defaults are used in a generic instantiation with defaulted formal subprograms, cross referencer tool XREF creates an irrelevant "renaming procedure" entry although no renaming procedure is explicitly mentioned in the source.

- ADA DS. - COMMON -

KPR #: 4000056341 Product: ADA DS. - COMMON ADA-DSA

03.25

Keywords: ADA

One-line description:  
AdaFormat abnormal early line folding in col 60 of proc body w/no parms

Problem:

-----  
The REFORMATTER (pretty printer) tool incorrectly begins line folding in column 60 (although page width is 80) on a procedure body without parameter.

KPR #: 4000056465 Product: ADA DS. - COMMON ADA-DSA

03.25

Keywords: ADA

One-line description:  
AdaFormat produces ugly list of identifiers in multiple declaration

Problem:

-----  
Output produced by the REFORMATTER (pretty printer) tool for a list of identifiers in a single declaration statement is unsightly (i.e. not pretty).

KPR #: 4000057919 Product: ADA DS. - COMMON ADA-DSA

03.00

Keywords: ADA

One-line description:  
Compiler crash when large unit w/generics compiled with "-k" option

Problem:

Compiler crash "VCM internal table (AIL\_SAVE) overflow" when a large compilation unit containing generics is compiled with the save internal representation option ("-k").

Fix information:

May be corrected in a future release.

KPR #: 4000070896 Product: ADA DS. - COMMON ADA-DSA

03.25

One-line description:

RENAMING of a component of a transient record causes compiler abort

Problem:

If a component of a "transient" record object is RENAMED, the compiler aborts with a message indicating that compilation stopped in DAT due to a compiler limitation.

A transient record is a record type which

- has a defaulted discriminant, and
- whose size depends on discriminants value, and
- is potentially greater than 4096 bytes.

The typical example is:

- ADA DS. - COMMON -

KPR #: 4000070896 \*\*CONTINUED\*\*

type TRANSIENT\_RECORD(D:POSITIVE:= 80) is record  
C : STRING(1..D);  
end record;

Fix information:

May be fixed in a future release.

KPR #: 4000071258 Product: ADA DS. - COMMON ADA-DSA

04.35

One-line description:

AdaProbe's STEP fails on exceptions raised via SIGILL, SIGSEGV or SIGFPE

Problem:

AdaProbe's EXEC.STEP command incorrectly interprets exceptions raised via SIGILL, SIGSEGV, or SIGFPE as a fatal termination condition. The only recourse is to restart the debugging session with the EXEC.RESTART command.

Temporary solution:

The workaround for this defect is to avoid using EXEC.STEP on statements known to raise one of the above exceptions. Instead set breakpoints with BREAK.NEW and step through the statement with the EXEC.CONTINUE command.

KPR #: 4000071957 Product: ADA DS. - COMMON ADA-DSA

03.25

One-line description:

AdaProbe VIEW.NEW incorrectly omits construct statements (eg exceptions)

Problem:

If I have a program fragment like:

```
with TEXT_IO;
procedure EXCP is
IT: exception;
begin
raise IT;
exception
when IT =>
TEXT_IO.PUT_LINE (...);
end EXCP;
```

And then I use VIEW.NEW (CURRENT, SAME, DECREMENT, GLOBAL), the result is:

```
with TEXT_IO;
procedure EXCP is
IT: exception;
begin
raise IT;
when IT =>
end EXCP;
```

Notice that the line that contains "exception" has improperly gone away.

- ADA DS. - COMMON -

KPR #: 4000071423 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe does not detect abnormal termination in interfaced code.

Problem:  
In the case where program behavior is incorrect for example when an exception was raised in interfaced code, the message window indicates that "program normally completed". This is definitely not accurate and misleading. Strongly suggest that the wording be changed (possibly to "program terminated"). If AdaProbe can detect abnormal behavior then append "abnormally" to the message, otherwise be silent, and let the user determine if the termination was abnormal or not, it is bad to tell the customer that normal completion occurred when it clearly did not.  
The EXEC.WHERE command exhibits similar behaviour.

KPR #: 4000071431 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
System can lock-up when keys are pressed too rapidly in AdaProbe (X11).

Problem:  
If keys are pressed too rapidly while an action is being undertaken by AdaProbe as a result of previous keypresses, the system can become locked up. The display screen may indicate some UNIX signal received and the terminal is then locked up. On a workstation with only a single display this will require rebooting the system in order to regain control since the keyboard is remapped, and reset from keyboard is not possible.

Duplicate Service Requests: 4000089664 4000071647

KPR #: 4000072603 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe INTERNAL ERROR on OBJECT command of generic spec/body object

Problem:  
AdaProbe may generate an INTERNAL ERROR when attempting an OBJECT command (ASSIGN or EXAMINE) on an object within a generic specification or body.

Fix information:  
May be fixed in a future release.

KPR #: 4000082677 Product: ADA DS. - COMMON ADA-DSA 03.00

One-line description:  
DEFAULT command does not attempt to clarify ambiguous abbreviations

Problem:  
The Ada User's Guide states that the user will be notified of ambiguity when entering abbreviated unit or family manager commands. But the DEFAULT command does not thoroughly attempt to prevent ambiguous commands, rather executes them. For example, the command

- ADA DS. - COMMON -

KPR #: 4000082677 \*\*CONTINUED\*\*

unit manager command "d d YES" sets INVOKE.DISPLAY to YES and QUIT.DEFAULTS to "YES".

Fix information:  
May be corrected in a future release.

KPR #: 4000082727 Product: ADA DS. - COMMON ADA-DSA 03.00

One-line description:  
Compiler goes into an infinite loop on ambiguous overloading

Problem:  
In the following example, the array bounds could be either INTEGER or SHORT\_INTEGER. Since the compiler can not resolve this overload, the compiler should give an "ambiguous overloading" error message, but instead it goes into an infinite loop.

```
package DEFINE is
  function FFF (X: in integer) return integer;
  function FFF (X: in short_integer) return short_integer;
end DEFINE;
```

```
with DEFINE;
procedure BKEQ02_0M is
  type XX is array ( DEFINE.FFF(7) .. DEFINE.FFF(6) ) of integer;
begin -- BKEQ02_0M
  null;
end BKEQ02_0M;
```

Fix information:  
May be fixed in a future release.

KPR #: 4000082792 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
Incorrect error indicator position for infix or inlined function calls

Problem:  
The compiler incorrectly locates error position indicators for errors involving "infix" function calls or inlined function calls.

The following results assume the following declarations:

```
subtype SMALL is integer range 1..10;
function F (A, B: small) return integer;
function "&" (A, B: small) return integer;
function "and" (A, B: small) return integer;
pragma INLINE ("and");
```

The resulting error messages (note, these messages have been truncated):

```
61 I := F (I, 20); -- Position indicators are OK
```

- ADA DS. - COMMON -

KPR #: 4000082792 \*\*CONTINUED\*\*

```

1 : *COD 9004 CONSTRAINT_ERROR will always be raised here at executio
2 : *EXP 6009 CONSTRAINT_ERROR will be raised if executed.

62 I := F (20, I); -- Position indicators are OK

1 : *COD 9004 CONSTRAINT_ERROR will always be raised here at executio
2 : *EXP 6009 CONSTRAINT_ERROR will be raised if executed.

64 I := I & 20; -- EXP positions wrong

1 : *COD 9004 CONSTRAINT_ERROR will always be raised here at executio
2 : *EXP 6009 CONSTRAINT_ERROR will be raised if executed.

65 I := 20 & I; -- EXP positions wrong

1 : *COD 9004 CONSTRAINT_ERROR will always be raised here at executio
2 : *EXP 6009 CONSTRAINT_ERROR will be raised if executed.

```

Duplicate Service Requests: 4000092684

KPR #: 4000082909 Product: ADA DS. - COMMON ADA-DSA 03.00

One-line description:  
Compiler gets INTERNAL ERROR on fixed point with negative delta

Problem:  
The following test shows a problem with the declaration of fixed point types. RM 3.5.9 (3) says that "The delta ... must be positive (nonzero)". Therefore, these two declarations are clearly wrong. However, the compiler does not catch this error, and processes the declarations anyway, until the SNT table overflows. The error message is:

VCM Internal table (SNT) overflows: Compiler limitation

Example:  

```

procedure FIXD02_0M is
  type FIX is delta 0.0 range -1.0 .. 1.0;
  type FIX2 is delta -1.0 range -1.0 .. 1.0;
begin -- FIXD02_0M
  null;
end FIXD02_0M;

```

Fix information:  
May be fixed in a future release.

KPR #: 4000089011 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe does not allow EXEC.STEP command after a user interrupt

Problem:  
AdaProbe does not allow the EXEC.STEP command after a user interrupt. This is unacceptable because interrupting is usually motivated by the need to progress slowly by stepping.

Temporary solution:  
Single step control may be regained following a user interrupt by setting a breakpoint at any valid Ada codepoint and then continuing execution until the breakpoint is reached. After reaching the breakpoint, single step commands will work normally.

KPR #: 4000089037 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe's EXEC.RESTART command should signal when loading is complete

Problem:  
After executing AdaProbe's EXEC.RESTART command, the message "Loading program." is first displayed, but no other message appears when loading is complete. Users may keep on waiting. A message should signal when loading is complete.

KPR #: 4000089151 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe reverse video disappears when breakpoint set on current line

Problem:  
In dumb terminal mode on HP terminals, AdaProbe reverse video effects disappear when a breakpoint is set on the current line or stepping is performed.

Fix information:  
May be fixed in a future release.

KPR #: 4000089268 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
Inlining side-effect functions may affect normal program execution

Problem:  
Using compiler option "-0" or "+0 i" to inline subprogram calls may affect program execution when side-effect functions are involved.

Fix information:  
May be fixed in a future release.

KPR #: 4000089466 Product: ADA DS. - COMMON ADA-DSA

03.25

## One-line description:

No ambiguity detected in some cases involving overloaded operators

## Problem:

No ambiguity is detected in some cases involving overloaded operators in expressions with more than one operator.

## As in:

```

type T is range 1 .. 10;
Z : BOOLEAN;
function "+"(X, Y : T) return BOOLEAN;
function "(X : BOOLEAN; Y : T) return BOOLEAN;
Z := 1 + 1 + 1; -- Ambiguous expression

```

## Fix information:

May be fixed in a future release.

KPR #: 4000089789 Product: ADA DS. - COMMON ADA-DSA

03.25

## One-line description:

Suggestion: AdaProbe EXEC.WHERE cmd should display library unit name

## Problem:

The AdaProbe EXEC.WHERE command does not display the Library unit name of subprogram calls (on the call stack), but only the subprogram names, even though the documentation says it should do so.

## Fix information:

To be fixed in a future release.

KPR #: 4000089797 Product: ADA DS. - COMMON ADA-DSA

03.25

## One-line description:

AdaXref crashes when library mode file omits "use &lt;library&gt;" as 1st line

## Problem:

AdaXref crashes in library mode and issues wrong error message when the file containing library mode directives does not include the "use &lt;library&gt;" line as the first line.

KPR #: 4000089870 Product: ADA DS. - COMMON ADA-DSA

03.25

## One-line description:

CALENDAR functions TIME\_OF and SPLIT return wrong results for leap year

## Problem:

The CALENDAR functions TIME\_OF and SPLIT return wrong results for the 31st day of months which have 31 days during a leap year. The returned date is shifted one day.

## Fix information:

May be fixed in a future release.

- ADA DS. - COMMON -

KPR #: 4000089953 Product: ADA DS. - COMMON ADA-DSA

03.25

## One-line description:

Wrong generic subprogram parameter association for "=" and "/="

## Problem:

When the "/=" operator is substituted for a generic formal "=" parameter in an instantiation, the meaning of the "/=" operator within the instantiated unit is incorrectly not the equality.

## As in:

```

generic
  type T is limited private;
  with function "="(P1, P2 : T) return BOOLEAN;
function NE(X, Y : T) return BOOLEAN;
function NE(X, Y : T) return BOOLEAN is
begin
  return X /= Y;
end NE;

```

function F is new NE(INTEGER, "/="); -- Should have effect of EQUALITY

## Fix information:

May be fixed in a future release.

KPR #: 4000089979 Product: ADA DS. - COMMON ADA-DSA

03.25

## One-line description:

"-C" compiler option shouldn't affect code of all generic instantiations

## Problem:

The "-C" compiler option for suppressing runtime checks should be effective for the code of an inner generic instantiation only if the generic unit itself was compiled with this option. Otherwise, instantiations of generic IO packages inside units compiled with the "-C" option may behave erroneously.

## Fix information:

May be fixed in a future release.

KPR #: 4000093005 Product: ADA DS. - COMMON ADA-DSA

04.10

## One-line description:

Nested generic instantiation causes compiler to abort

## Problem:

-- This procedure shows a bug. The compiler aborts with the following -- message:

```

-- ***MAN H012 Compilation stopped in EXP at line 30 (at line 41 of
-- inlined or instantiated unit) due to a compiler limitation.
procedure NESTGEN is
  generic
    package FIRST is
      F: INTEGER;
    generic

```

- ADA DS. - COMMON -

KPR #: 4000093005 \*\*CONTINUED\*\*

KPR #: 4000093310 \*\*CONTINUED\*\*

procedure SECOND;  
end FIRST;

package body FIRST is  
G: INTEGER;  
procedure SECOND is  
begin

F := 1;  
G := 2;  
end SECOND;

F := 3;  
G := 5;  
end FIRST;

package INST\_FIRST is new FIRST;

procedure INST\_SECOND is new FIRST.SECOND;

begin -- NESTGEN  
INST\_SECOND;  
end NESTGEN;

KPR #: 4000093161 Product: ADA DS. - COMMON ADA-DSA 03.20

One-line description:  
Abnormal HLO effect for comparison of fixed types in an IF statement

Problem:  
Abnormal code elimination occurs during the high level optimizer (HLO) phase of compilation when the "-0" or "+0 e" option is used and an IF statement in the source includes a comparison of fixed type objects. A warning is issued that code will be removed and it is actually removed.

Fix information:  
May be fixed in a future release.

KPR #: 4000093203 Product: ADA DS. - COMMON ADA-DSA 04.10

One-line description:  
Wrong expression eval order when assigning overlapping array slices

Problem:  
Wrong expression evaluation order occurs when assigning overlapping array slices, one of them being a slice of a subprogram parameter.

KPR #: 4000093310 Product: ADA DS. - COMMON ADA-DSA 04.10

One-line description:  
Wrong HLO effect for variable tested after LOOP which may alter variable

Problem:  
Wrong high level optimizer (HLO) effect occurs during compilation (warning issued, no code generated) when the "-0" or "+0 e" option is used and a variable is tested after a loop which may alter its

Known Problem Reports as of 11/21/90

KPR #: 4000093310 \*\*CONTINUED\*\*

value. HLO incorrectly removes code when the value is not altered.

Temporary solution:  
Do not use the "-0" or "+0 e" options.

KPR #: 4000093328 Product: ADA DS. - COMMON ADA-DSA 04.10

One-line description:  
Wrong HLO effect when S'LAST is compared to 0, where S is a STRING param

Problem:  
Wrong effect of the high level optimizer (HLO) during compilation when S'LAST is compared to 0, where S is a STRING parameter. The case of a null string seems to be discarded and the corresponding code is removed.

Temporary solution:  
Do not use the compilation options "-0", "+0 e", or "+0 p".

KPR #: 4000093419 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Certain AdaProbe commands following an XTRA.INVOKE are not executed

Problem:  
When an AdaProbe QUIT, XTRA.INVOKE, or EXEC.CONTINUE command follows an XTRA.INVOKE command, they are not executed. Instead, AdaProbe returns in interactive mode.

Temporary solution:  
Use the XTRA.LEARN.READ and XTRA.LEARN.EXECUTE commands.

KPR #: 4000093435 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe XTRA.EDIT.FIND cmd has non-UNIX concept for regular expressions

Problem:  
In the AdaProbe XTRA.EDIT.FIND command with parameter MODE => REGULAR, the concept of a regular expression is not the same as the usual UNIX concept; the star convention does not allow zero repetitions (there must be at least one character).

KPR #: 4000093468 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
DISPLAY option of the AdaProbe XTRA.LEARN.EXECUTE cmd works improperly

Problem:  
When using the AdaProbe XTRA.LEARN.EXECUTE command with the default option DISPLAY=NO, the macro is incorrectly not considered as a black box. The EXECUTE result is displayed regardless of the value of DISPLAY.



KPR #: 4000094243 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
 FIX'BASE has incorrect values for attributes 'FIRST and 'LAST

Problem:  
 -----

In my examples I will use a delta value of 1.0 to simplify things. This allows the integer values used internally to represent a fixed point number to match the actual fixed point values used in the Ada source.

The first example that I will consider is the case of an 8 bit fixed point type.

```
type short_fixed is delta 1.0 range -120.0 .. 120.0;
```

The compiler will correctly represent the values of short\_fixed'first and short\_fixed'last as -120.0 and 120.0. However if the source code contains a reference of the form short\_fixed'base'first or short\_fixed'base'last the the compiler\_informs you that NUMERIC\_ERROR will be raised here at run time.

The compiler resisted all of the methods that I came up with for printing or assigning the value of "short\_fixed'base'first". In each attempt to assign or print the value, I was told that NUMERIC\_ERROR will be raised here at run time. I finally discovered that I could use a boolean expression to query the compiler about the specific value of "short\_fixed'base'first". I determined that the following values were used internally by the compiler:

```
sfbf: constant boolean := short_fixed'base'first = -129.0; -- TRUE
sfb1: constant boolean := short_fixed'base'last = 128.0; -- TRUE
```

-----  
 I believe that the correct values for fix'base'first and fix'base'last should be -128.0 and 127.0. In fact, as it is currently implemented the fix'base attribute returns a completely useless value, as the compiler will always try to coerce this value to the users fixed point type, and this always causes NUMERIC\_ERROR to be raised. The following example illustrates this:

```
type short_fixed is delta 1.0 range -120.0 .. 120.0;
type medium_fixed is delta 1.0 range -32000.0 .. 32000.0;
type my_float is digits 15;
m_fixed: medium_fixed;
```

- ADA DS. - COMMON -

KPR #: 4000094243 \*\*CONTINUED\*\*

```
l_float: my_float;
```

```
begin
```

```
  m_fixed := medium_fixed(short_fixed'base'first);
```

```
  1 *EXP 6005 This value is outside the range of the target type.
    NUMERIC_ERROR will be raised here at run time.
```

```
  l_float := my_float(short_fixed'base'first);
```

```
  1 *EXP 6005 This value is outside the range of the target type.
    NUMERIC_ERROR will be raised here at run time.
```

KPR #: 4000096149 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
 unchecked conversion of task access object raised PROGRAM\_ERROR

Problem:

A library level generic package has a task (or task access) parameter and elaborates the task in its body. The task access is uncheckedly converted to another task access type (with the same task profile). The generic is instantiated in a procedure. Calls to entries via the converted access value work for some time, but eventually fail with PROGRAM\_ERROR.

Fix information:  
 May be fixed in a future release.

KPR #: 4000096164 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
 Unchecked conversion as a function result cannot always be returned

Problem:

A function returning a constrained subtype of an unconstrained array type cannot directly return the result of an UNCHECKED\_CONVERSION to that constrained subtype, it must assign the conversion to a local and then return the local.

Fix information:  
 May be fixed in a future release.

KPR #: 4000096172 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
 Changing terminal characteristics using termio() with tasking fails

Problem:

In library package elaboration code, suspend tasking, get and save the current (original) terminal characteristics, change the terminal characteristics, change the terminal characteristics, and then

- ADA DS. - COMMON -

KPR #: 4000096172 \*\*CONTINUED\*\*

resume tasking. Later, while tasking is running, attempts to restore the original characteristics seem to "not take".

## Fix information:

May be fixed in a future release.

KPR #: 4000096230 Product: ADA DS. - COMMON ADA-DSA 04.34

One-line description:  
Dynamic in-out slice of bit packed boolean array uses wrong elements

## Problem:

-- This shows a bug, in the dynamic slice marked BUG  
-- On the outbound parameter assignment, the slice  
-- adds I in twice, to make the range 6..8  
-- I believe what is happening here is that the code  
-- calculates the address of the first bit in the slice.  
-- It uses this on the inbound assignment. Then, before  
-- the outbound assignment, it adds the first index  
-- to this pointer, which is incorrect.

```
with TEXT_IO;
procedure BIT_REP is
  type BOOL_ARR is array (INTEGER range <>) of BOOLEAN;
  pragma PACK (BOOL_ARR);
  A : BOOL_ARR (0..99) := BOOL_ARR' (0..99 => FALSE);
  I, J : INTEGER;
  procedure INNER (B : in out BOOL_ARR) is
  begin
    B := not B;
  end INNER;
begin
  I := 3;
  J := 5;
  INNER (A(I..J));
  -- BUG here. Input slice is 3..5, but on
  -- outbound parm assignment, slice used is 6..8.
  for X in 0 .. 10 loop
    TEXT_IO.PUT_LINE (INTEGER'IMAGE (X) & ' ' &
      BOOLEAN'IMAGE (A (X)));
  end loop;
end BIT_REP;
```

## Temporary solution:

Put the slice into a temporary object, pass the temporary, and then copy the temporary back into the slice.

## Fix information:

fixed in release A.05.35

- ADA DS. - COMMON -

KPR #: 4000096321 Product: ADA DS. - COMMON ADA-DSA 04.34

One-line description:  
Front end incorrectly folds constant mod expression.

## Problem:

The front end appears to be incorrectly folding constant mod expressions. The result looks like rem was used instead of mod. Test program follows.

with TEXT\_IO;  
procedure JUNK1 is

-- Test to ensure consistency between front end's constant  
-- folding of mod and evaluated mod.

```
NEG11 : integer;
POSS : integer;
COMPUTED_RESULT : integer;
CONSTANT_RESULT : integer;
begin
  NEG11 := -11;
  POSS := 5;
  CONSTANT_RESULT := -11 mod 5;
  COMPUTED_RESULT := NEG11 mod POSS;
  if CONSTANT_RESULT /= COMPUTED_RESULT then
    TEXT_IO.PUT_LINE("Failed");
    TEXT_IO.PUT_LINE("Computed result of (-11 mod 5) was => " &
      integer'IMAGE( COMPUTED_RESULT ) );
    TEXT_IO.PUT_LINE("Front end folded constant (-11 mod 5) to => " &
      integer'IMAGE( CONSTANT_RESULT ) );
  else
    TEXT_IO.PUT_LINE("According to 4.5.5 of LRM, result should be => 4");
  end if;
end JUNK1;
```

KPR #: 4000096339 Product: ADA DS. - COMMON ADA-DSA 04.31

One-line description:  
Setting TASK'SORAGE\_SIZE too small not detected

## Problem:

If you use a representation clause to set TASK'SORAGE\_SIZE to a value which is "too small" the error is not explicitly detected and the program behavior becomes unpredictable.

## Temporary solution:

The minimum size that can effectively be used in a TASK'SORAGE\_SIZE representation clause is 4096. Do not attempt to set the TASK'SORAGE\_SIZE value to a value smaller than this otherwise unpredictable behavior will occur.

## Fix information:

This problem will be corrected in the next release of the

- ADA DS. - COMMON -

KPR #: 4000096339 \*\*CONTINUED\*\*

Ada/300 product.

KPR #: 4000096347 Product: ADA DS. - COMMON ADA-DSA 04.30

One-line description:  
Two ada.mklibs of the same library at the same time can both fail

Problem:  
If two more or less simultaneous attempts are made to CREATE a library with the same name in a given family, both can fail. One can manage to create the library directory but find the family locked when trying to update the family. The other can fail to create the library directory because it already exists. An "incomplete" library will be the result; attempts to ERASE it will fail because it is not a valid library.

KPR #: 4700820555 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe decodes the PARAMETER string of EXEC.RESTART inconsistently

Problem:  
AdaProbe "decodes" the argument string of the EXEC.RESTART command. Due to the AdaWorld interface, this processing may make sense during the initial call to LOAD\_PROGRAM (protocol.adb), but when EXEC.RESTART is requested, the processing of the argument string should be suppressed (although code may be needed to transform the string to be compatible with the underlying C routine execv).

KPR #: 4700822056 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Assembly output shows misleading record alignment values

Problem:  
The output produced by the Ada -S option, is perhaps misleading when the actual representation of a record type is shown.

The record alignment value is displayed in bits whereas the user specifies it in storage units. While the value is "right" in that it represents the correct alignment, it is possible that a user will be confused. It would be better if the alignment value was displayed in the same units the user would use to specify it.

KPR #: 4700822106 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
Using the ESC key in AdaProbe key binding causes an INTERNAL ERROR

Problem:  
In dumb terminal mode, AdaProbe reports an INTERNAL ERROR when using the ESC key, within a key binding.

In addition, there may be problems with timing escape sequences to differentiate between an <ESC>P or F2.

- ADA DS. - COMMON -

KPR #: 4700822114 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:

Software line control chars used in AdaProbe key bindings cause problems

Problem:

Remove use of software line control characters from the predefined key bindings, (that is, ENG/ACK ^F and ^E, and XON/XOFF ^Q and ^S).

Depending on the terminal's configuration (see the v3.25 Ada Tools Manual pg 7-8), the terminal may intercept these keys.

KPR #: 4700822122 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:

Linked units removed or in locked libraries confuse AdaProbe

Problem:

For linked units either within a locked library or removed from the library result in the following defects:

- An INTERNAL ERROR on a progression selection of an object in the linked unit.
- A STEP into the linked unit reports that the unit is not compiled with debug.
- The UNIT.LIST command (silently) fails to list the linked unit.

KPR #: 4700822130 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:

The menu cursor does not trace AdaProbe's Up\_Key in dumb terminal mode

Problem:

In dumb terminal mode on 300h terminals, the menu cursor does not trace the Up\_key correctly. The menu underline and the menu cursor appear on different but adjacent menu items making it difficult to determine which item will be selected when entering Return\_Key.

This problem also occurs when using the Down\_Key to wrap from the bottom menu item back around to the top menu item.

KPR #: 4700822148 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:

AdaProbe's OBJECT.EXAMINE.QUALIFICATION does not detect invalid input

Problem:

The QUALIFICATION parameter to OBJECT.EXAMINE accepts predefined attributes like 'SIZE without a warning or error, but the object value rather than the attribute value is displayed.

AdaProbe gives no negative feedback that his QUALIFICATION request was ignored. This can seriously mislead the user if the OBJECT value reported looks like a reasonable value for the requested attribute.

The general problem is that NO error checking is being done when the QUALIFICATION parameter is not "required". OBJECT.ASSIGN

- ADA DS. - COMMON -

KPR #: 4700822148 \*\*CONTINUED\*\*

suffers from this same lack of error checking.

KPR #: 4700822155 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe's XTRA.VIEW.LIST incorrectly displays all possible line types

Problem:  
XTRA.VIEW.LIST displays the list of all possible line types in the Ada language rather than ONLY those line types available in the Ada source code of the specified window. Also, the list is displayed in no apparent order; specifically the order is different than Table 2-1 in the v3.25 Ada Tools manual.

KPR #: 4700822163 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe Windows incorrectly repositioned when main X window is resized

Problem:  
When running in X, the AdaProbe pop-up CONFIRM and ASSISTED commands windows may be incorrectly repositioned when the main AdaProbe window is resized with the mouse.

AdaProbe may partially reposition the CONFIRM window outside of the visible main window. This should be prevented since AdaProbe will refuse to process any user commands until the CONFIRM window is cancelled.

This defect is easily duplicated on the pop-up windows generated by the QUIT and OBJECT\_ASSIGN commands.

KPR #: 4700822171 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe's XTRA.LEARN.TEACH uses undocumented cursor movement commands

Problem:  
The cursor movement commands generated by XTRA.LEARN.TEACH need to be added to the documentation.

KPR #: 4700822189 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe does't detect if the program has been removed from the library

Problem:  
AdaProbe does not always recognize if the program has been removed from the Ada program library. Specific examples follow.

Compile and link a simple program with the -D option and then erase the main unit from the library with the unit manager erase command.

1) EXEC.STEP (MODE => INTO)  
AdaProbe incorrectly reports that the unit was not compiled with debug.

KPR #: 4700822189 \*\*CONTINUED\*\*

The pop-up error message reads,  
"Cannot STEP INTO, unit not compiled with debug, STEPPING OVER"  
The program terminates as if an EXEC.CONTINUE had been entered.

2) EXEC.STEP (MODE => OVER)  
AdaProbe incorrectly reports that the unit was not compiled with debug.  
The pop-up error message reads,  
"Cannot STEP INTO, unit not compiled with debug, STEPPING OVER"  
The program terminates as if an EXEC.CONTINUE had been entered.  
Note also that AdaProbe though we were executing step into.

3) UNIT.LIST

4) Executing EXEC.RESTART and continuing with the above will eventually result in an INTERNAL TOOL ERROR.

KPR #: 4700822197 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
XTRA.INVOKE within .ada.proberc results in deadlock or INTERNAL ERROR

Problem:  
Use of an XTRA.INVOKE command within the AdaProbe start-up file (.ada.proberc) results in a deadlock or INTERNAL ERROR  
Nested XTRA.INVOKE commands (XTRA.INVOKE within an invoke file) hang also.

KPR #: 4700822205 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe's online help should contain the same info as the manual.

Problem:  
There are some inconsistencies where the on-line help facility does not provide the "same" help information as the manual.  
The on-line help text should match the documentation.

The general problem is that the documentation and the help files are not well integrated. They should appear to the user as if they were written and reviewed by the same person(s).

Specific problem areas should be noted here and will be fixed during the documentation review cycles.

Areas where on-line help and documentation differ.

-----  
XTRA.VIEW.NEW.RULE  
XTRA.VIEW.NEW.RULE.DEF

KPR #: 4700822213 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:  
AdaProbe PROGRESS may move the cursor to a non-visible source area

Problem:  
Selection of a non-visible location (because of existing viewing rules) from the PROGRESS window moves the cursor to the "area" where the object resides. Why not refuse to move the cursor by reporting an error or make the destination line visible?

KPR #: 4700822247 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe's EXEC.STEP from a RETURN may jump to another RETURN point.

Problem:  
In the presence of multiple RETURN points (either RETURN statements or body completion points), EXEC.STEP from a return point may jump to another return point. For example, EXEC.STEP from the LAST\_STATEMENT in the following pseudo code will result in a jump to the RETURN statement denoted by the "RETURN #1" comment:

```

procedure X is
begin
  if (...) then
    if (...) then
      ...
    return; -- RETURN #1
  end if;
  elsif (...) then
    LAST_STATEMENT;
  end if;
end X;

```

KPR #: 4700822254 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe INTERNAL ERROR when INVOKE file command's strin parm > 85 chars

Problem:  
AdaProbe generates an INTERNAL ERROR when a string parameter of a command within an INVOKE file is greater than 85 characters.

Fix information:  
May be fixed in a future release.

KPR #: 4700822270 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe cannot OBJECT.EXAMINE/ASSIGN a separate package body object.

Problem:  
AdaProbe cannot OBJECT.EXAMINE/ASSIGN a separate package body object.

Fix information:

- ADA DS. - COMMON -

KPR #: 4700822270 \*\*CONTINUED\*\*

May be fixed in a future release.

KPR #: 4700822288 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe detects "Exec Error" at START\_RESET.1 on EXEC.RESTART.

Problem:  
Debug an Ada source that sets the exit status to a non-zero value. When in AdaProbe, set breakpoints on one or more lines, and use EXEC.RESTART. AdaProbe returns with the following error message:

```

Exec error raised at START_RESET.1
Status UNKNOWN

```

AdaProbe states the reason for this error is:  
GIVE\_ACCESS\_TO\_SAVE\_REGISTERS

To work correctly, the user must first remove all breakpoints, then EXEC.RESTART.

KPR #: 4700822304 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
CANCEL of online HELP is inconsistent with the other AdaProbe commands

Problem:  
The CANCEL\_KEY "^X" and right mouse button do not CANCEL AdaProbe's online HELP facility. HELP must be cancelled with the cancel option on the HELP menu. This is inconsistent with every other AdaProbe command.

Attempting to cancel HELP.APROPOS with the CANCEL\_KEY leaves the HELP.APROPOS.IIEM pop-up window visible. The user must explicitly select this window and cancel it. This is redundant, the pop-up window should automatically be deleted when help is cancelled.

KPR #: 4700822312 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

ADACOMP generates incorrect AdaProbe line codes for IF-ELSIF statements.

Problem:  
The Ada compiler generates incorrect AdaProbe line codes for IF ... ELSIF statements. Branches around ELSIF conditions are incorrectly associated with the ELSIF condition when they should be associated with the last statement in the previous sequence of statements.

This defect also shows up in CASE-WHEN statements with 3 or fewer WHEN clauses. This is because these get optimized into the equivalent IF-ELSIF sequence.

This causes the follow AdaProbe defects:

1. EXEC.STEP Defect.

- ADA DS. - COMMON -

KPR #: 4700822312 \*\*CONTINUED\*\*

AdaProbe appears to EXEC.STEP on unexecuted source statements and may mislead the user.

2. BREAK.NEW Defect.

Breakpoints on ELSIF (WHEN) statements will not be hit before the ELSIF (WHEN) condition is evaluated.

Duplicate Service Requests: 4700828327

KPR #: 4700822320 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
BREAK.RAISE (CURRENT) reacts differently after used with (INTERACTIVE)

Problem:  
AdaProbe's BREAK.RAISE command does not pop up the interactive menu when first invoked. However, after the command is used interactively, the menu always appears. Furthermore, when the command is used interactively, AdaProbe echoes the current setting of the most recently selected exception, but does NOT echo the current setting of any exception set interactively, to the message window

To reproduce this, do the following:

Position cursor on an exception

BREAK.RAISE with mode CURRENT => break set correctly. No menu  
BREAK.RAISE with mode INTERACTIVE => interactive menu pops up  
BREAK.RAISE with mode CURRENT => interactive menu now pops up.  
Message is echoed reflecting the current setting of the selected exception.

Now, any settings done with interactive mode ARE accepted, but no message is echoed to the message window.

KPR #: 4700822346 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe's XTRA.WINDOWS.WRITE incorrectly deletes blank source lines

Problem:  
AdaProbe's XTRA.WINDOWS.WRITE command deletes blank source lines. Therefore, source line numbers no longer match the unit window nor the original source text. No XTRA.VIEW.NEW commands were executed before writing the unit window.

KPR #: 4700822353 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Several AdaProbe commands overwrite existing files without warning

Problem:  
The following AdaProbe commands will overwrite existing files without prompting or warning the user:  
BREAK.SAVE, XTRA.LEARN.WRITE, XTRA.WINDOWS.WRITE.  
This is a defect not an enhancement request.

Adding the following OVERWRITE parameter with CONFIRM as the default would correct this defect and still allow the user to overwrite files without prompting when he really wants to.  
OVERWRITE => YES | NO | APPEND | CONFIRM  
-----

KPR #: 4700822379 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe's XTRA.LEARN.TEACH doesn't record mouse input

Problem:  
Any commands that are input via selection with the mouse, are not recorded when using XTRA.LEARN.TEACH. There are some commands, such as switching windows, that are logically done with the mouse (X11) when using XTRA.LEARN.TEACH, the user has to be especially careful not to use the mouse - which is a real nuisance.

KPR #: 4700822387 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe's EXEC.RESTART with incomplete parameters causes INTERNAL ERROR

Problem:  
AdaProbe's EXEC.RESTART command with incomplete parameters used within an XTRA.INVOKE or startup file may cause an INTERNAL ERROR. Reproduce by executing either of the following within an INVOKE or startup file:

```
EXEC.RESTART ;
EXEC.RESTART (MESSAGE => DIALOG);
```

KPR #: 4700822395 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe unable to restart after error termination in user program

Problem:  
When a program terminates in an error, AdaProbe gives the message:

After Continue, your program died of fatal error: Not owner

Then, if you try to EXEC.RESTART it, you get

```
Exec error raised at START_RESET.1
Reason :GIVE_ACCESS_TO_SAVED_REGISTERS,
```

KPR #: 4700822395 \*\*CONTINUED\*\*

System error occurred (No such process)  
Status: UNKNOWN

The only work-around is to exit AdaProbe and restart it.

KPR #: 4700822403 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
AdaProbe may display an extra box mark when the screen is resized in X11

Problem:  
AdaProbe may display an extra box mark when the screen is resized in X11

This defect can be easily demonstrated in the initial screen before opening any Ada units by clicking on the Message Window to generate the mark and then enlarging the AdaProbe screen. The box mark will be written on the new Message window and a ghost image will appear in its previous physical location on the screen.

KPR #: 4700822494 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
If AdaProbe fails to open an X window, it doesn't cleanup after itself.

Problem:  
If AdaProbe is unable to open a display on the X server, it aborts without resetting the terminal to its previous state.

KPR #: 4700822510 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Use of pseudo token EOFMARK in error message could be better

Problem:  
When error recovery inserts tokens before the "end of the source file" the syntax error messages mention that they were inserted before "EOFMARK". While the intended meaning can be deduced, it is perhaps not the best message for an average Ada user.

For example, this three line source file  
procedure BAD is

begin

yields this compiler output

3 begin

1

1 \*\*SYN 1056 "NULL" followed by ";" has been inserted before "EOFMARK".

2

2 \*\*SYN 1056 "END" followed by ";" has been inserted before "EOFMARK".

2 Errors detected. No warning issued. Compilation failed.

- ADA DS. - COMMON -

KPR #: 4700822510 \*\*CONTINUED\*\*

Fix information:  
May be fixed in a future release.

KPR #: 4700822528 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
"Too many indicators" message may be unclear and can be truncated

Problem:

When the compiler encounters "too many" errors on a single line it can produce a message that says

Too many indicators

The meaning of this message is probably not clear to the average Ada user, improving the message or changing the documentation might be appropriate.

In addition, the "Too many indicators" message is sometimes displayed with part of the message truncated. This happens when the message indicators are in a column less than the length of the "Too many indicators" message.

Fix information:

May be fixed in a future release.

KPR #: 4700822866 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:

Menu selected HELP from within an AdaProbe submenu is out of context

Problem:

Within a submenu, menu selection of the HELP command is not context specific, as documented. When invoking HELP with the Help\_key, AdaProbe displays help information with respect to the submenu, but a menu selection of HELP within a submenu results in main menu help information.

KPR #: 4700822874 Product: ADA DS. - COMMON ADA-DSA 03.25

One-line description:

AdaProbe ASSIGN/EXAMINE defect with register OBJECTS in unoptimized code

Problem:

In the following program, a register tracking defect was detected by setting a breakpoint on the first PUT\_LINE. EXEC.CONTINUE to the breakpoint, and then use OBJECT.ASSIGN to modify SSI. While stepping over this PUT\_LINE, the original value rather than the modified value of SSI is displayed.

The program was compiled with all optimizations disabled.

with TEXT\_IO;

use TEXT\_IO;

- ADA DS. - COMMON -



KPR #: 4700822874 \*\*CONTINUED\*\*

```

procedure INTEGERS is
  SSI : SHORT_SHORT_INTEGER := SHORT_SHORT_INTEGER'FIRST;
  SI  : SHORT_INTEGER        := SHORT_INTEGER'FIRST;
  I   : INTEGER              := INTEGER'FIRST;
  N   : NATURAL              := NATURAL'FIRST;
  P   : POSITIVE             := POSITIVE'FIRST;
begin
  PUT_LINE("SSI => " & SHORT_SHORT_INTEGER'IMAGE(SSI));
  PUT_LINE("SI => " & SHORT_INTEGER'IMAGE(SI));
  PUT_LINE("I => " & INTEGER'IMAGE(I));
  PUT_LINE("N => " & NATURAL'IMAGE(N));
  PUT_LINE("P => " & POSITIVE'IMAGE(P));
end INTEGERS;

```

KPR #: 4700822882 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
 Inconsistent AdaProbe handling of quoted strings w/in INVOKE file.

Problem:  
 Command parameters of type string must be quoted differently when using the INVOKE file mechanism (which includes the start-up file) as compared to the assisted command facility.

For example, the equivalent to entering the following to the ARGUMENTS parameter of the EXEC.RESTART command within the Parameter List window:

```
1 "name" 2
```

is the following when defining the ARGUMENTS parameter of the EXEC.RESTART command within an invoke file:

```
"1 "name" 2"
```

KPR #: 4700822957 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
 AdaProbe's OBJECT.EXAMINE gives wrong value for some record components

Problem:  
 OBJECT.EXAMINE gives wrong value on a float (or long float) component of a record with a representation clause.

Fix information:  
 May be fixed in a future release.

KPR #: 4700829911 Product: ADA DS. - COMMON ADA-DSA 04.31

One-line description:  
 Floating point I/O with illegal number causes program to hang

Problem:  
 with TEXT\_IO;  
 procedure clllov00906 is  
 use TEXT\_IO;

- ADA DS. - COMMON -

KPR #: 4700829911 \*\*CONTINUED\*\*

```

package LONG_FLOAT_IO is new FLOAT_IO(LONG_FLOAT);
use LONG_FLOAT_IO;

type BYTE is range 0..255;
for BYTE'SIZE use 8;

begin
  PUT_LINE("TEST START");
  declare
    X : LONG_FLOAT;
  begin
    PUT_LINE("Now attempting to print an uninitialized floating");
    PUT_LINE("point number, that just happens to have 8 bytes of");
    PUT_LINE("0xFF stored at it's location.");
    PUT("The value of X is ");
    PUT(X);
    NEW_LINE;
  end;
  PUT_LINE("TEST COMPLETE");
end;

```

KPR #: 4700831057 Product: ADA DS. - COMMON ADA-DSA 04.34

One-line description:  
 HLOPT incorrectly removes good code after FIXED'LARGE attribute.

Problem:

-- This procedure shows a bug in HLOPT.

-- On the line marked with asterisks, HLOPT thinks it will raise a  
 -- NUMERIC\_ERROR. HLOPT gives the error message:  
 -- \*HLO 4084 An argument of this expression cannot be correctly  
 -- represented in the base type. NUMERIC\_ERROR will be  
 -- raised at run time.

-- Unfortunately, HLOPT then removes the statements after that line,  
 -- to the end of block.

-- The line in question does not raise an error but instead gets  
 -- the correct answer, so the net effect is HLOPT has removed good  
 -- code.

with TEXT\_IO;  
 procedure FIXD09\_0M is

- ADA DS. - COMMON -



KPR #: 4700831057 \*\*CONTINUED\*\*

```

DEL : constant := 1.0/2**15;
type FIXED_16 is delta DEL range -1.0 .. +1.0-DEL;
LOW : FIXED_16 := -1.0;
HI : FIXED_16 := +1.0-DEL;
subtype FIXED_16 is FIXED_16 range LOW .. HI;
F_SMALL, F_LARGE, F_DELTA, F_SAFE_SMALL, F_SAFE_LARGE :
    FIXED := 0.0;

package F_IO is new TEXT_IO.FIXED_IO (FIXED);

begin -- FIXD09_0M

begin
  F_SMALL := FIXED_SMALL;
  F_IO.PUT (F_SMALL); TEXT_IO.NEW_LINE;
  F_LARGE := FIXED_LARGE;
  F_IO.PUT (F_LARGE); TEXT_IO.NEW_LINE;
exception
  when CONSTRAINT_ERROR => TEXT_IO.PUT_LINE ("CONSTRAINT_ERROR");
  when NUMERIC_ERROR => TEXT_IO.PUT_LINE ("NUMERIC_ERROR");
end;
F_IO.PUT (F_LARGE); TEXT_IO.NEW_LINE;
end FIXD09_0M;

```

Temporary solution:

Do not use the high level optimizer, which means do not use "-0", "+0 e" or "+0 p".

Note: the compiler has been changed to no longer remove the code, but it still gives the incorrect message.

KPR #: 4700831065 Product: ADA DS. - COMMON ADA-DSA 04.34

One-line description:

HLOPT incorrectly removes checks, causing bad results

Problem:

- This procedure shows a bug in HLOPT.
- The line marked with asterisks, without any optimization, raises NUMERIC\_ERROR. This test therefore prints: Starting... NUMERIC\_ERROR.
- When HLOPT handles this line, it incorrectly switches off the overflow check on the addition. It also assumes that the changed line will raise CONSTRAINT\_ERROR, and deletes the TEXT\_IO call that follows it as dead code.
- On Ada/300, with the overflow check switched off, the addition operates on 16 bits, and the true sum of 32768 wraps around and becomes the value -32768. Therefore, the constraint check succeeds, and no error is raised. Nothing further is printed, since the

- ADA DS. - COMMON -

KPR #: 4700831065 \*\*CONTINUED\*\*

```

-- following line has been removed. The test therefore prints:
-- Starting...
-- This is horrible, because no exception is ever raised, and the
-- non-exception code has been removed.
-- On Ada/800, with the overflow check switched off, the addition
-- operates in 32 bits, and the true sum of 32768 stays that way, so
-- the constraint check fails, and we raise CONSTRAINT_ERROR. The
-- test therefore prints:
-- Starting...
-- CONSTRAINT_ERROR.
-- This is not as bad, but still, HLOPT should not be changing the
-- exception raised.

with TEXT_IO;
procedure FIXD17_0M is
  -- fixed point type that maps fully into 16-bits
  DEL_16 : constant := 1.0/2**15;
  type FIXED_16 is delta DEL_16 range -1.0 .. +1.0-DEL_16;

begin -- FIXD17_0M

declare
  V1 : FIXED_16 := 0.50;
begin
  TEXT_IO.PUT_LINE ("Starting..."); -- *****
  V1 := V1 + 0.50;
  TEXT_IO.PUT_LINE ("No exception raised - 16-bit case 1");
exception
  when NUMERIC_ERROR =>
    TEXT_IO.PUT_LINE ("NUMERIC_ERROR");
  when CONSTRAINT_ERROR =>
    TEXT_IO.PUT_LINE ("CONSTRAINT_ERROR");
  when others =>
    TEXT_IO.PUT_LINE ("Wrong EXCEPTION raised");
end;

end FIXD17_0M;

```

Temporary solution:

Do not use the high level optimizer, which means do not use "-0", "+0 e" or "+0 p".

KPR #: 4700831073 Product: ADA DS. - COMMON ADA-DSA 04.34

One-line description:

HLOPT incorrectly thinks conversion will raise error

Problem:

- This procedure shows a bug in HLOPT.
- The line marked with asterisks, without any optimization, raises NUMERIC\_ERROR. This test therefore prints: Starting... NUMERIC\_ERROR.
- When HLOPT handles this line, it incorrectly switches off the overflow check on the addition. It also assumes that the changed line will raise CONSTRAINT\_ERROR, and deletes the TEXT\_IO call that follows it as dead code.
- On Ada/300, with the overflow check switched off, the addition operates on 16 bits, and the true sum of 32768 wraps around and becomes the value -32768. Therefore, the constraint check succeeds, and no error is raised. Nothing further is printed, since the

- ADA DS. - COMMON -

KPR #: 4700831073 \*\*CONTINUED\*\*

```
-- On the line marked with asterisks, HLOPT believes that the line
-- will raise NUMERIC_ERROR. HLOPT then attempts to delete the
-- TEXT IO call since it thinks it is dead code. This has been
-- disabled, but the error message still indicates that the code
-- will be removed.
```

```
-- In fact, there is no NUMERIC_ERROR in that line, since
-- 127 is in the range of the 8_bit integer. Therefore, at
-- runtime, no error is raised.
```

```
with TEXT_IO;
procedure FIXD24_0M is
begin -- FIXD24_0M
```

```
declare
type F1 is delta 0.125 range 100.0 .. 1900.0;
```

```
V2F1 : F1 := 127.34;
```

```
I2_8 : SHORT_SHORT_INTEGER;
```

```
begin
I2_8 := SHORT_SHORT_INTEGER ( V2F1 ); -- *****
```

```
TEXT_IO.PUT_LINE (SHORT_SHORT_INTEGER'IMAGE (I2_8));
exception
```

```
when others =>
```

```
TEXT_IO.PUT_LINE ("EXCEPTION RAISED");
```

```
end;
```

```
end;
```

```
Temporary solution:
```

```
Do not use the high level optimizer, which means do not use "-O",
"+O e" or "+O p".
```

```
Note: the compiler has been changed to no longer remove the code,
but it still gives the incorrect message.
```

KPR #: 4700831826 Product: ADA DS. - COMMON ADA-DSA 04.35

```
One-line description:
```

```
Creation of direct access file that exists doesn't delete old file
```

```
Problem:
```

```
Creation of a direct access file by giving an existing file
name abnormally doesn't delete the old file.
```

```
Test program follows:
```

```
with DIRECT_IO, IO_EXCEPTIONS, TEXT_IO;
```

```
use IO_EXCEPTIONS;
```

```
procedure Jpl1046 is
```

```
package DIR_IO is new DIRECT_IO(INTEGER);
```

```
FILE : DIR_IO.FILE_TYPE;
```

```
X : INTEGER;
```

```
begin
```

```
DIR_IO.CREATE(FILE, MODE => DIR_IO.OUT_FILE, NAME => "JPL1046.file");
```

```
-- ADA DS. - COMMON -
```

KPR #: 4700831826 \*\*CONTINUED\*\*

```
DIR_IO.WRITE(FILE, 1);
DIR_IO.WRITE(FILE, 2);
DIR_IO.CLOSE(FILE);
DIR_IO.CREATE(FILE, MODE => DIR_IO.OUT_FILE, NAME => "JPL1046.file");
DIR_IO.WRITE(FILE, 3);
DIR_IO.CLOSE(FILE);
DIR_IO.OPEN(FILE, MODE => DIR_IO.IN_FILE, NAME => "JPL1046.file");
DIR_IO.READ(FILE, X);
if X /= 3 then
```

```
TEXT_IO.PUT_LINE("Failed, bad read");
end if;
```

```
begin
```

```
DIR_IO.READ(FILE, X);
```

```
TEXT_IO.PUT_LINE("Failed, END_ERROR not raised");
```

```
exception
```

```
when END_ERROR =>
```

```
TEXT_IO.PUT_LINE("Passed, END_ERROR raised");
```

```
when others =>
```

```
TEXT_IO.PUT_LINE(
```

```
"Failed, others exception than END_ERROR raised");
end;
```

```
DIR_IO.CLOSE(FILE);
```

```
end jpl1046;
```

```
Temporary solution:
```

```
Delete the existing file before creating it the second time.
```

KPR #: 4700831875 Product: ADA DS. - COMMON ADA-DSA 04.35

```
One-line description:
```

```
FLOAT_IO.GET on STRINGS does not raise DATA_ERROR on INTEGER literal
```

```
Problem:
FLOAT_IO.GET on STRINGS reading an INTEGER string literal
("1234") abnormally does not raise DATA_ERROR (but rather,
interprets it as 1.234E-01). A test case follows:
```

```
with TEXT_IO;
```

```
procedure LTD2545 is
```

```
F : FLOAT;
```

```
P : POSITIVE;
```

```
package F_IO is new TEXT_IO.FLOAT_IO (FLOAT);
```

```
begin
```

```
F_IO.GET ("1234", F, P);
```

```
TEXT_IO.PUT ("F is ");
```

```
F_IO.PUT (F);
```

```
TEXT_IO.NEW_LINE;
```

```
exception
```

```
when TEXT_IO.DATA_ERROR =>
```

```
TEXT_IO.PUT_LINE ("DATA_ERROR raised.");
```

```
end;
```

```
Temporary solution:
```

```
-- ADA DS. - COMMON -
```

KPR #: 4700831875 \*\*CONTINUED\*\*

Make sure the string is a legal float, in other words, append ".0" to the end.

KPR #: 4700831891 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Non-blocking open for a terminal can block

Problem:

If you open a terminal device in non-blocking mode, either by default in a tasking program, or with the appropriate form parameter, the open itself will block if the terminal device has full modem control and there is no "carrier detected".

This behavior defeats the purpose of non-blocking I/O as the entire program will stop until the open completes (when a "carrier" is detected).

Temporary solution:

There is no workaround at this time other than to not open tty devices with full modem control unless you can afford to block on the open.

Fix information:

This defect has been repaired by HP in version 5.2 and later.

KPR #: 4700835306 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

Bad error message for conversion of string catenation.

Problem:

Compiler gives incorrect error message, indicating argument of an explicit conversion must not be a string literal, when the argument is OK (ie, not a string literal). The test program is:

```
package ERROR_PKG is
  type ERROR_RANGE is range 1..80;
  type ERROR_MESSAGE is array (ERROR_RANGE range <>) of CHARACTER;
end ERROR_PKG;
```

with ERROR\_PKG;

```
package MY_ERRORS is
  DUMMY_ERROR_MESSAGE: constant ERROR_PKG.ERROR_MESSAGE
    := ERROR_PKG.ERROR_MESSAGE ("1234567890" & "1234567890");
end MY_ERRORS;
```

The error message says:

```
**SEM 3125 The operand of a type conversion is not allowed to be
  a string literal.
```

Note that the operand of the conversion is a simple\_expression (RM 4.4), and is not a string literal, so this code should compile without error.

- ADA DS. - COMMON -

KPR #: 4700835306 \*\*CONTINUED\*\*

Temporary solution:

The workaround is to put a string qualification on the first argument of the type conversion, ie:  
:= ERROR\_PKG.ERROR\_MESSAGE (string ("1234567890") & "1234567890");

KPR #: 4700835397 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

Subunit incorrectly hides renaming declaration of derived function.

Problem:

In a subunit, we lose visibility of a renaming of a derived function. The following shows the problem:

```
package PACK1 is
  type Time_Type is record
    Seconds: INTEGER;
  end record;

  function "-" (Left: in Time_Type) return Time_Type;
end PACK1;
```

with PACK1;

package PACK2 is

```
-- Introduce derived "-" here:
  type Time_Type is new PACK1.Time_Type;
end PACK2;
```

with PACK2;

procedure TEST is

```
-- rename the derived subprogram
  function "-" (Left: in PACK2.Time_Type)
    return PACK2.Time_Type
    renames PACK2."-";
  procedure SUB_PROC is separate;
begin
  null;
end;
```

separate (TEST)

procedure SUB\_PROC is

```
T: PACK2.Time_Type;
```

begin

```
T := -T; -- GET ERROR MESSAGE HERE
```

end SUB\_PROC;

The error message says:

```
** IDE 2050 The type of this expression conflicts with the type
  TIME_TYPE imposed by the context.
```

It appears that in the process of handling the separate, the compiler loses the renaming of the derived subprogram.

- ADA DS. - COMMON -

KPR #: 4700835397 \*\*CONTINUED\*\*

Temporary solution:  
Put the separate unit back inline at the point of its body stub,  
or repeat the renaming declaration in the separate unit.

KPR #: 4700837781 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Library cannot be deleted with ada.rmlib when created previously

Problem:  
When an ada library is created with an older version of the ADS, and  
an attempt is made to use the ada.rmlib command from a newer ADS to  
remove the library, the error message says the library is not an  
Ada library. This is confusing to the novice user, since it is an Ada  
library, just not a current version of an Ada library. The error  
message should be more descriptive, and suggest that it might be an  
older version of a library.

Temporary solution:  
If the ada.rmlib command refuses to erase an Ada library, the user can  
type:  
rm -rf library name  
to remove the library from the file system, and free up disk space.

Fix information:  
May be fixed in a future release.

KPR #: 4700839605 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Instantiation of generic in package spec. raises PROGRAM\_ERROR

Problem:  
-- A generic instantiated in a package specification causes  
-- PROGRAM\_ERROR. Test program follows:

```
package genbug is
  generic
  procedure one;
  procedure two;
  procedure three is new one; -- Error: causes PROGRAM_ERROR
end genbug;

with text_io; use text_io;
package body genbug is
  procedure one is
  begin
    put_line("one called.");
  end one;
  procedure two is
  procedure four is new one; -- Info: Body of generic procedure
  begin
    put_line("one called.");
  end one;
  procedure four is new one; -- OK: no error here
  begin
```

- ADA DS. - COMMON -

Known Problem Reports as of 11/21/90

KPR #: 4700839605 \*\*CONTINUED\*\*

```
put_line("two called.");
  four;
end;
end genbug;
```

```
with genbug;
with text_io; use text_io;
procedure genmain is
begin
  genbug.two;
  genbug.three;
end genmain;
```

KPR #: 4700839696 Product: ADA DS. - COMMON ADA-DSA 04.10

One-line description:  
Predefined operator may incorrectly not be hidden by a later homograph

Problem:  
A predefined (derived) operator is sometimes abnormally not  
hidden by a later explicit homograph operator declaration.  
The predefined is still chosen when a further selected usage  
is made (like P.+.). This is wrong overloading resolution.  
Test program follows:

```
package pack is
  type int is range 0..5;
  function ">"(l,r:int) return boolean;
end pack;
---
package body pack is
  function ">"(l,r:int) return boolean is
  begin
    Return true;
  end;
end pack;

with text_io; use text_io;
with pack;
procedure SA3469 is
begin
  declare
    -- the following pack.">" is the wrong one !!
    x:boolean:=pack.">"(pack.int'(0),pack.int'(5));
  use pack;
  y:boolean:=">"(int'(0),int'(5));
  z:boolean:=int'(0) > int'(5);
  begin
    put_line(boolean'image(x));
    put_line(boolean'image(y));
    put_line(boolean'image(z));
  end;
  put_line("Test PASSED if it says : TRUE TRUE TRUE ");
end SA3469;
```

- ADA DS. - COMMON -

KPR #: 4700839696 \*\*CONTINUED\*\* Product: ADA DS. - COMMON ADA-DSA 04.30

Temporary solution:  
Do not use the selected notation in this case, use the simple name instead. This means that you need a "use" clause for the package.

One-line description:  
Library manager family information can be "out of date"

Problem:  
The library manager "reads in" information about the current family when it is started up and when the OTHER command is used.

It does not keep the family locked, nor "reread" the information, when performing other commands.

We will call this invocation of the library manager the "original" library manager.

Given this behavior, other users can modify the family with other instances of the library (or family) manager, and these changes would not be known to the "original" library manager.

The "original" library manager could then operate "incorrectly". This could range anywhere from "LISTING" libraries that no longer exist or have been renamed, to attempting to manipulate such libraries and failing with error messages that could be misleading to the user.

Since locking the family for the duration of a library manager invocation is probably not a good idea, at a minimum this behavior should be documented so that users are at least warned. But it would also be worthwhile to consider if there are other (longer term) solutions that would actually prevent "incorrect" library manager behavior (e.g. perhaps migrating the family/library model into a real data base management system).

KPR #: 4700839753 Product: ADA DS. - COMMON ADA-DSA 04.30

One-line description:  
Mend and Rename allowed with libraries locked, locks may be lost

Problem:  
The family manager can perform a MEND or RENAME operation on a family which contains libraries which are currently locked and such locks will be destroyed by the operation.

The behavior should at least be documented for the user, so that they can take appropriate precautions. In the longer term other options should be considered so the user does not need to take such precautions (such as migrating the family/library model into a true data base management system).

KPR #: 4700840561 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
Ada tasks that call interface code may behave incorrectly

Problem:

Ada tasks that call interface code may behave incorrectly if the interface code allocates too much space on the stack. Some routines in libc (e.g. sprintf) use nearly 8K of space on the stack. If an Ada task calls such a routine (either directly or indirectly) the task stack may overflow. The effect of this problem may be that the error "Global blocking situation detected" is produced. This problem is an unfortunate result of the fact that languages other than Ada do not do overflow checking on task stacks, so that when the stack overflows, it is not detected properly.

The compiler option "-w b,-t,<nnn>" may be used to change the size of the task stack. The default task stack size is 8K. Users of GKS/Ada binding and Starbase/Ada binding are advised to use stack sizes of at least 16K on the series 300 if calls are made from tasks to subprograms in the bindings. This should be documented in the manual.

Temporary solution:  
The workaround for this problem is to use the binder option to the ada command to specify a larger task size:  
-w b,-t,<nnn>

For users of the GKS or Starbase bindings, it is recommended that a minimum value of 16K be used, i.e.  
-w b,-t,16

Fix information:  
See KPR # 4700905174. It asks to have the default task stack size increased to 32K.

Duplicate Service Requests: 4700893149

KPR #: 4700842872 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:  
If two people try "ada.mklib" at same time, one may not finish

Problem:  
If two different people are doing ada.mklibs at the same time, even in different directories, one will proceed correctly, but the other may create an empty directory (and possibly give an error message). One has to use rmdir to get rid of the empty directory, as it isn't a valid library.

Temporary solution:  
Don't try multiple ada.mklib commands at the same time.

KPR #: 4700843672 Product: ADA DS. - COMMON ADA-DSA

04.35

One-line description:  
 Compiler aborts on invalid comparison involving renamed "="

Problem:  
 Comparisons involving incompatible operands and renamed "=" operators apparently cause the compiler to abort. The following source causes such a compiler abort. The offending statement is apparently the erroneous comparison in the body of TEST\_F00.

```
package F00 is
  type TYPE_ONE is new INTEGER range 1..10;
  type TYPE_TWO is new INTEGER range 2..11;
  THREE : constant TYPE_ONE := 7;
  function RESULT return TYPE_TWO;
end F00;

with F00;
procedure TEST_F00 is
  function "=" (RIGHT: F00.TYPE_ONE; LEFT: F00.TYPE_ONE)
    return BOOLEAN renames F00."=";
  function "=" (RIGHT: F00.TYPE_TWO; LEFT: F00.TYPE_TWO)
    return BOOLEAN renames F00."=";
```

```
begin
  -- This comparison should be illegal.
  if F00.RESULT = F00.THREE then
    null;
  end if;
end;
```

Temporary solution:  
 -- The following code gives 3 examples of workarounds for the  
 -- problem of renaming "=".

```
package F00 is
  type TYPE_ONE is new INTEGER range 1..10;
  type TYPE_TWO is new INTEGER range 2..11;
  THREE : constant TYPE_ONE := 7;
  function RESULT return TYPE_TWO;
end F00;

with F00;
procedure TEST_F00 is
  function EQ (RIGHT: F00.TYPE_ONE; LEFT: F00.TYPE_ONE)
```

- ADA DS. - COMMON -

Known Problem Reports as of 11/21/90

KPR #: 4700843672 \*\*CONTINUED\*\*

```
  return BOOLEAN renames F00."=";
  function EQ (RIGHT: F00.TYPE_TWO; LEFT: F00.TYPE_TWO)
    return BOOLEAN renames F00."=";
  function "=" (RIGHT: F00.TYPE_TWO; LEFT: F00.TYPE_TWO)
    return BOOLEAN renames F00."=";
begin
  -- The compiler can correctly reject this syntax error.
  if EQ (F00.RESULT, F00.THREE) then
    null;
  end if;
  -- This has just fully qualified the original "=" from
  -- package F00. It is correctly rejected.
  if F00."=" (F00.RESULT, F00.THREE) then
    null;
  end if;
  -- With correct Ada syntax, the equal can be redefined.
  if F00.RESULT = F00.RESULT then
    null;
  end if;
```

end;

Fix information:  
 This defect may be repaired in a future release.

KPR #: 4700857698 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

Listing process does not check for I/O errors, allows SIGPIPE to occur

Problem:

If you run the compiler and request either a compiler listing or an assembly listing (or both), which will be written to stdout, and you pipe the output into a process that terminates without reading all the listing, the ada(1) program will report, for example

```
ada: Warning: Signal 13 (write on a pipe with no one to read) while
compiling test.ada
```

This indicates that the ada(1) program saw the compiler terminate abnormally with a signal 13. It isn't "too wrong" for the compiler to terminate that way, it internally cleans up on that signal, but it may be disconcerting to the user to see that message (which is rarely seen from any other Unix utility).

- ADA DS. - COMMON -

KPR #: 4700857698 \*\*CONTINUED\*\*

## Fix information:

May be fixed in a future release.

KPR #: 4700857714 Product: ADA DS. - COMMON ADA-DSA 04.35

## One-line description:

The Unit Manager does not list desired units when library is large.

## Problem:

A library containing approximately 660 units was created.

When I said:

list (units =&gt; mac, detail =&gt; full)

the Unit Manager came back with a null response leading me to

believe that the unit MAC did not exist in the library. However,

if I said:

list (detail =&gt; full)

the resulting list of all units in the library DID contain MAC

(spec and body).

## Temporary solution:

If the unit manager doesn't find units specified with the "units=>" parameter of the list command, don't use that parameter, and let the unit manager default to listing all units in the library.

## Fix information:

May be fixed in a future release.

KPR #: 4700861740 Product: ADA DS. - COMMON ADA-DSA 04.31

## One-line description:

Time slicing seems to be ineffective in heavy I/O situations

## Problem:

If a task performs I/O it gets to to run for a longer period of time than the time slice value would seem to indicate it should.

## Cause:

The timer used to calculate time slices only counts process time spent in actual user code, it does not count the process time spent in HP-UX code on behalf of the process. As most I/O time is spent in HP-UX code the time slice runs out very slowly (very little non HP-UX code is being executed by the Ada process). Hence time slicing is "fair" for a program containing all compute bound tasks, but "unfair" as soon as an I/O bound task appears.

## Temporary solution:

Setting a very small time slice value will produce the most "fair" behavior, but then the process of task switching itself will begin to be a significant part of the CPU usage and the application will get less actual processing time.

## Fix information:

HP Ada version 5.35 has been modified such that the user can specify at

- ADA DS. - COMMON -

KPR #: 4700861740 \*\*CONTINUED\*\*

bind time the timer Aisys Ada uses for time slicing, it is not tied to any processor use time, it appears to time slice more fairly under heavy I/O, although it can in fact be unfair as the HP-UX kernel may not even run the Ada process during any particular real time interval, or 3) SIGPROF (the process profile timer), counts both user and system time in the slice, is the most fair in CPU time allocation, but may still appear to penalize heavy I/O because some I/O time is not counted by any timer (e.g. time from when the terminal or window driver gets the characters to the time the user sees them).

KPR #: 4700866459 Product: ADA DS. - COMMON ADA-DSA 04.35

## One-line description:

Paths that end with .+ or .+. may be reported by the NAME function

## Problem:

If an Ada program has a directory open as a file, and that directory is a CDF, and the program opened the directory with a path whose last component was .+ or .+. , the NAME function will return a path with the .+ or .+. intact.

The NAME returned is correct, but since appearances of . and .+ are "normalized" to explicit names, so .+ and .+. should be normalized as well.

## Temporary solution:

The NAME returned is a legal name that can be used to access the CDF directory object, it is simply not consistent with similar names which involve . and .+ components. Such names can simply be avoided, in favor of the explicit name without the .+ or .+. , if desired.

## Fix information:

The path name resolution code was modified to properly resolve path names that end with the component .+ or .+. such that the result returned by the NAME function will not end with .+ or .+. (the returned path will be "normalized" to reflect the effect of the .+ or the .+.).

KPR #: 4700866475 Product: ADA DS. - COMMON ADA-DSA 04.35

## One-line description:

Working directory not restored after error when it could be

## Problem:

When the Ada I/O code is resolving the fully rooted path to a file (e.g. during an OPEN or CREATE call for later use by the NAME function) it changes the current working directory during the process. Normally it restores the correct when directory when it is done resolving the path. However, on rare occasions, if the path resolution fails, it sometimes fails to restore the correct working directory. With the working directory not correctly restored, subsequent name resolution calls tend

- ADA DS. - COMMON -

KPR #: 4700866475 \*\*CONTINUED\*\*

to also fail even though there is nothing actually wrong with the subsequent names (and so subsequent OPEN and CREATE calls tend to raise NAME\_ERROR or USE\_ERROR when in fact no such error has actually occurred). In addition, the program could easily fail without doing any subsequent OPEN or CREATE operations, because it will be operating with a different working directory than the one it believed it was in.

This is known specifically to happen when any directory in the fully rooted path of a file being OPENed or CREATED has search (x) permission for the effective user/group, but does not have read (r) permission for the effective user/group. The Ada I/O will fail to resolve the rooted path to that file, and will fail to restore the correct working directory.

Temporary solution:

Make sure that all directories in the paths to files that will be accessed by Ada programs have both read (r) and search (x) permission for the effective user/group of the users of the Ada programs.

Fix information:

This defect is repaired in HP versions 5.2 and later.

KPR #: 4700875286 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: COMPILER

One-line description:

Compiler gives incorrect error on 'SIZE clause for a private type

Problem:

-- The following text gets an inappropriate compiler error.

```
package MY_RECORDS is
  type PRIV_TYPE is private;
  type REC_TYPE is record
    FIELD_1: PRIV_TYPE;
  end record;
  private
  type PRIV_TYPE is record
    FIELD_2: SHORT_SHORT_INTEGER;
  end record;
  for PRIV_TYPE'SIZE use 8;
  for REC_TYPE'SIZE use 8; -- ERROR HERE
end MY_RECORDS;
```

-- The error indicates:

```
-- **SEM 3291 The type REC_TYPE must have a static constraint, and
-- if it has subcomponents, they too must have static constraints.
--
-- This is inappropriate, since everything is static. The compiler
-- seems confused by the private type.
```

Temporary solution:

The workaround to this is to comment out the 'SIZE representation clause. On this compiler, the size is set by the record representation clause, and the 'SIZE clause is basically an assertion, in that it

- ADA DS. - COMMON -

KPR #: 4700875286 \*\*CONTINUED\*\*

just gives an error if the size doesn't match what the compiler already knows.

For safety, in the package body, insert code to (at run time) take the 'SIZE attribute and compare it with the expected value. If it doesn't match, abort the program.

Another workaround would be to remove the private part, and make all types involved non-private.

Fix information:

May be fixed in a future release.

KPR #: 4700880245 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

Improve Appendix F so that it describes how to use RECORD\_SIZE FORM parm

Problem:

The Appendix F manual does not clearly describe the size needed for the RECORD\_SIZE part of the FORM parameter. It describes in detail the structure of the data in the file, ie:

```
[ HEADER ] OBJECT [ UNUSED_PART ]
```

But it never says that the RECORD\_SIZE you specify must include enough space for the HEADER and the OBJECT. I thought it was enough to include space just for the OBJECT, but this is not the case. This affects both the S300 and the S800. In the S300 manual, this information should go into section F 8.2.9.2.

Fix information:

The Reference Manual for the Ada Programming Language, Appendix F has been modified to properly describe the use of the RECORD\_SIZE form parameter.

KPR #: 4700882134 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

Ada compiler gives meaningless diagnostic and aborts.

Problem:

Attempting to compile a file named 'pascal\_to\_ada.ada', which is symbolically linked to 'pascal\_to\_ada.ad' results in:

```
ada: Path name exceeds file system length limit.
ada: pascal_to_ada.ada
ada: Please specify the actual name.
```

The compiler then aborts.

The filesystem is an hfs filesystem configured for long filenames.

Fix information:

The ada(l) program was corrected to properly handle symbolic links and to not produce an incorrect truncation diagnostic under the indicated conditions.

- ADA DS. - COMMON -



KPR #: 4700882142 Product: ADA DS. - COMMON ADA-DSA

04.35

One-line description:  
If the environment variable ENV is set some ada.xxx commands may fail

Problem:

Some of the ada.xxx (like ada.mkllib) style commands are implemented as ksh scripts. A "feature" of ksh is that it will "source" the contents of the file which is the value of the ENV environment variable when it begins execution, even if it is executing a script (i.e. is not interactive).

Since such a file can "do" anything, it can cause the Ada command script to fail. Specifically if the file defines aliases for standard commands or performs an operation that changes the values of the positional parameters, the ada commands may fail or may perform unexpected actions.

Temporary solution:

The standard technique for working around this problem is to set up ENV so that it is only the name of a file when the shell being started is interactive. Hence ENV is empty for non-interactive invocations of ksh and so the ada.xxx commands do not cause an ENV file to be read. The traditional incantation for that, which usually resides in the file \$HOME/.profile is

```
export START=$HOME/.kshrc
export ENV='${START[_$-1]+(_=0)-(_$-!=${-%%*i*})}'
```

where you define START as whatever file you do want "sourced" for interactive ksh invocations. Don't worry too much about how it works, it does (I believe it is explained in Korn's book on ksh).

You can also

1. Unset ENV before running Ada commands.

or

2. Unset ENV at the end of the file that it (ENV) specifies. The first interactive ksh will then reads ENV but no subsequent ksh will (interactive or not).

but the magic incantation above is the most convenient.

Fix information:

Supermom now sets the ENV environment variable to null before exec'ing any of the ada commands.

KPR #: 4700883488 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

Compiler gives variety of incorrect errors on too many units in library

Problem:

The compilers detection of "Too many units in library" is not very good.

- ADA DS. - COMMON -

KPR #: 4700883488 \*\*CONTINUED\*\*

The following test fails on Ada/300, and is assumed to fail on Ada/800 as well.

Test procedure:

1. Create a new library (it will contain only the 13 predefined link units).
2. Compile this spec:  
package UNITS is  
end UNITS;
3. Compile this body with varying values of N (i.e. various numbers of the separate procedures):

```
package body UNITS is
  procedure P1 is separate;
  .
  .
  .
  procedure PN is separate;
begin
  null;
end UNITS;
```

4. Go back to step 1 for a different value of N (i.e. always start with a new library to there are no random units in the library to perturb the results).

5. The following results are observed (note that most of the PROGRAM\_ERROR failures are at varying places [except where noted], there is no obvious consistency in the tracebacks):

- 1 <= N <= 1022 - Compilation succeeds
- N = 1023 - Compilation fails with no error message (or sometimes with a PROGRAM\_ERROR and an empty traceback)
- N = 1024 - Compilation succeeds
- N = 1025 - Compilation fails with PROGRAM\_ERROR [at varying places, but not where it is noted as occurring for N >= 4075]
- N = 1026 - Compilation fails with segmentation violation (but compiler does not report it).
- 1027 <= N <= 1030 - Compilation fails with PROGRAM\_ERROR [at varying places, but not where it is noted as occurring for N >= 4075]
- 4075 <= N <= 4080 - Compilation fails with PROGRAM\_ERROR [always in unit CTXM.INSERT\_UNIT in scope

- ADA DS. - COMMON -

KPR #: 4700883488 \*\*CONTINUED\*\*

RECORD\_DEP\_LIST at line 92]

4081 <= N <= 4085 Compilation fails with MAN H002 Compilation stopped in IDE at line 4082 due to a compiler limitation.

6. There are 15 "fixed" units in this test, the 13 links to the predefined unit and the spec and body of the package. Note that the MAN H002 error appears at 4081+15=4096 total units. So the front end apparently traps that case (although MAN H002 doesn't tell the user much, an error that said too many units/separates for library would be better).

However, long before that, at 1023+15=1038 total units it fails to compile with an internal error (although 1039 units does compile for some reason) and then presumably for 1040 through 4095 total units it also fails to compile with an internal error. It would appear that a limit check is missing, or is present but is checking for a higher limit than the internals of the compiler can actually support.

Temporary solution:

Keep the number of units in a library low. The actual limit is not clear, and seems to depend on a number of factors, including how many are library units and how many are subunits.

Fix information:

This particular defect was not a problem with too many units in a library, it was a problem with too many dependencies in a unit (in this case "separate" dependencies but there are several kinds of dependency overflow conditions that could cause this behavior).

The compiler was modified at revision A.05.35 to detect the overflow condition and report an error rather than causing harm to the internal data structures that led to the unpredictable compiler failure modes.

The error message that will now be produced will be of the form (with the <> items filled in appropriately):

```
**CTX E022 The number of <kindofdependency> dependencies in the unit
<nameofunit> exceeds the capacity of the compiler. A maximum
of <numberofdependencies> such dependencies are supported.
```

KPR #: 4700887711 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: COMPILER

One-line description:  
Size of record component that is mutant record cannot exceed 8192 bytes

Problem:  
Compilation fails on a record with a component which is itself a

- ADA DS. - COMMON -

KPR #: 4700887711 \*\*CONTINUED\*\*

unconstrained discriminated record with default discriminant values. The compiler message is:

```
**SEM 3279 COMPILER CAPACITY EXCEEDED: The component FIELD is a record
with defaulted discriminants; the size of such a component cannot
potentially exceed 8192 storage units - Appendix F.
```

Temporary solution:

There is a patch available, to replace the limited version of the ada compiler with a version that allows up to 24K records. The patch is too big to put on the Fort Collins SE machine (hpfscse). If you want a copy, call the HP Response Center (the standard HP support channel), (Response Center engineers can call STD Languages Support for details).

KPR #: 4700899278 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: TOOLS

One-line description:  
ada.make incorrectly does not compile units dependent on invalid link

Problem:  
Ada.make utility does not issue compilation of unit that depends on an invalid link.

Example: you have two files, as follows:

```
File "packa.ads":
```

```
package A is
  I: integer;
end A;

with A;
procedure MAIN is
begin
  A.I := 3;
end MAIN;
```

Create two libraries: "rel" and "dev". Compile packa.ads into "rel". Run: "ada.make -s rel dev main.adb" and execute the result. This makes a link from dev to rel for unit A and compiles MAIN into dev. Next, touch packa.ads, and recompile it into "rel". Run: "ada.make dev". The result re-establishes the link to A, but incorrectly DOES NOT issue a compile command for MAIN.

Temporary solution:

There is a patch available for Ada/300, to replace the faulty version of the ada.make tool with a working version. The patch is on the Fort Collins SE machine (hpfscse) directory ~ftp/unsupp-patches/300-7.0/Ada. The file README in that directory explains the patch. If you want a copy, call the HP Response Center (the standard HP support channel).

KPR #: 4700900720 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: RUNTIME

One-line description:  
TEXT\_IO.SET\_INPUT on closed file can cause STATUS\_ERROR on re-OPEN

- ADA DS. - COMMON -

KPR #: 4700900720 \*\*CONTINUED\*\*

Problem:  
If I use text\_io.set\_input on a closed file, then re-open it, I get STATUS\_ERROR. The following code shows the problem, it gets STATUS\_ERROR on the OPEN on the second time through the loop.

```
with text_io; use text_io;
procedure fileit is
  file_handle : file_type;
  C: character;
begin
  for I in 1..3 loop
    put_line ("IN LOOP");
    open (file => file_handle, mode => in_file, name => "arith.dat");
    set_input (file_handle);
    get_(C);
    close (file_handle);
    set_input (standard_input);
  end loop;
end fileit;
```

Temporary solution:

One possible workaround is change the order of the close/set\_input to be "set\_input (standard\_input);" followed by "close (file\_handle);". If you make this change, it works fine.

Fix information:

The bug is fixed 5.32 compiler.

KPR #: 4700903591 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: RUNTIME

One-line description:

Input from FIFO pipes incorrectly reads to far ahead, causing blocking

Problem:

Using TEXT\_IO to read a FIFO pipe with FORM->"NON\_BLOCKING", it incorrectly attempts to read part of the next line before processing the current line. If you have one program writing lines to the pipe, and another reading lines, they get out of sync, because the reader tries to read too far. Should treat pipes like terminals, and not read ahead past the end of the line.

Temporary solution:

This only occurs with TEXT\_IO, so if the data is such that you can use SEQUENTIAL\_IO, the problem will not occur.

Fix information:

I modified "bufferio.adb", "filmgtio.adb" and "textio.adb" to treat a file associated with a FIFO special file the same as a terminal file. This fixes the problem that was associated with the read-ahead causing a blocking on a FIFO but not on a terminal.



KPR #: 4700904516 Product: ADA DS. - COMMON ADA-DSA

04.35

Keywords: COMPILER

One-line description:

Compiler needs "-u" to avoid infinite loop on too many generic instances

Problem:

An attempt to compile a unit with many generic instantiations causes compiler to get into an infinite loop and never terminate. If I use the "-u" compiler option, it works fine, so there is an easy workaround. The example program has 17 instantiations of DIRECT\_IO with different complex record and string types.

Temporary solution:

Use the compiler option "-u" to compile the generics as separate compilation units. This avoids the problem.

KPR #: 4700905174 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

Change default task stack size to 32K.

Problem:

Currently, the default for the size of a task stack is 8K. This is too small for many applications. This should be changed to 32K.

Temporary solution:

Use the binder option "-w b,-t,mnn" to over-ride the default.

KPR #: 4700905182 Product: ADA DS. - COMMON ADA-DSA 04.35

One-line description:

AdaProbe can't display FOR variables

Problem:

AdaProbe has difficulty displaying variables introduced by the FOR statement. This maybe because the variable is temporary, has a scope limited to the loop, and is probably promoted to a register. In any case AdaProbe doesn't seem to have enough information about this variable to display it properly when you request an object examine. The following test program was used to exhibit AdaProbes behaviour on the 300 and 800:

```
with TEXT_IO;
procedure LOOP_VAR is
begin
  for I in 'A'..'Z' loop
    TEXT_IO.PUT_LINE ("I = " & CHARACTER'IMAGE (I));
  end loop;
  for I in 1..26 loop
    TEXT_IO.PUT_LINE ("I = " & INTEGER'IMAGE (I));
  end loop;
```

KPR #: 4700905182 \*\*CONTINUED\*\*

end LOOP\_VAR;

If you set a break point on the first TEXT\_IO statement, and try to Object Examine I, AdaProbe displays I => <Unknown>. This happens on both the 300 and the 800. If you reset your break point to the second TEXT\_IO and Object Examine I again you will see I => 0 on the 300 and the correct value on the 800. I have not tried any other types of loop variables such as integer subtypes, derived types and the like.

Temporary solution:  
In the program being debugged, copy the "for" variable into a regular variable at the beginning of the loop. Then in ada.probe, examine the regular variable.

KPR #: 4700910489 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: COMPILER

One-line description:  
Bad error message on library exceeding max size of 33,553,408 bytes

Problem:  
If an Ada library exceeds a size of 33553408 bytes, the compiler gives strange error messages, of the form:  
\*\*\* MAN H004 Compilation stopped in SEM due to a compiler limitation.  
No line number is available.

Temporary solution:

Instead of one big library, split your application into multiple libraries. You can have the necessary links built automatically using the "ada.make" command.

Fix information:  
The root 5 based product has been enhanced so that the library file size can grow larger than 33,553,408 bytes.

Theoretically a library can hold 4096 units and the information stored in the library for any single unit can be at most 67,108,864 bytes, for a maximum library size of 274,877,906,944 bytes (plus library and unit header overhead).

However the library file remains limited to a maximum size of 2,147,483,647 bytes by the file system.

KPR #: 4700929570 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: COMPILER

One-line description:  
Error not detected when subunit matches wrong overloaded subprogram

Problem:  
The following program should produce a compiler error, since the subunit does not match the profile of its stub. However, the compiler does not

KPR #: 4700929570 \*\*CONTINUED\*\*

detect an error, and at runtime, execution hangs:

```
-----
package EXAMPLE is
  function BUG return BOOLEAN;
  function BUG return INTEGER;
end EXAMPLE;
-----
package body EXAMPLE is
  function BUG return BOOLEAN is separate;
  function BUG return INTEGER is
  begin
    return 0;
  end BUG;
end EXAMPLE;
```

```
separate (EXAMPLE)
function BUG return INTEGER is
begin
  return 0;
end BUG;
-----
with EXAMPLE;
procedure MAIN is
begin
  null; -- the main program does nothing
end MAIN;
```

Fix information:  
May be fixed in a future release.

KPR #: 5000535146 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: TOOLS

One-line description:  
ada.mklib needs read&search perms on all dirs in paths of libs in family

Problem:

Ada.mklib will fail, unless it has read (r) and search (x) permissions on all directories involved in the full path names of all libraries in the family specified (or the default public family, if used).

Temporary solution:

Make sure that all directories in the paths to libraries in the family have both read (r) and search (x) permission for the effective user/group of the ada.mklib command.

To find the list of libraries in the family, use the "ada.lslib" command.

Fix information:

The algorithm used to create Ada libraries has been modified such that it does not need to examine the directory paths to other libraries in the same family, when creating a new library in that family. Hence a

KPR #: 5000535146 \*\*CONTINUED\*\*

user creating a library in a family no longer needs access to any other libraries already present in the family (nor do they need access to any of the directories in the paths to any of those other libraries).

KPR #: 5000558130 Product: ADA DS. - COMMON ADA-DSA 04.35

Keywords: RUNTIME

One-line description:  
 FLOAT\_IO.PUT incorrectly raises LAYOUT\_ERROR on large negative number.

Problem:  
 This problem can be shown by the following:

```
with text_io; use text_io;
procedure test is
package F_IO is new float_io (float);
a: float := -2.0;
begin
-- This works fine for awhile, then aborts when A is -20000000.0
-- According to LRM 14.3.8, this should work.
loop
F_IO.PUT (A, fore => 2, aft => 2, exp => 0);
new_line;
A := A * 10.0;
end loop;
end test;
```

Temporary solution:  
 Change the value of the parameter "fore" to be 3, and the problem will not occur.

Fix information:  
 Increased the image string length to print large negative numbers as the original string length was not large enough.

KPR #: 4700890939 Product: ADA SOFTBENCH COMMON ADA-SBA 00.00

One-line description:  
 Resizing of FLU Managers may corrupt window layout

Problem:  
 After reducing the window size of a Family, Library, or Unit Manager such that window regions are "lost", this state is not corrected once you enlarge to the original size.

Cause:  
 In the FLU encapsulations, each vertical row of widgets resides in its own pane. We wanted to have sashes only on those panes that it makes sense to resize (the list panes and results area panes). The only way to do this is to set the Min and Max resources to the same value on the pane that you do not want to have a sash. Unfortunately, the Encapsulator team found a bug (I believe it was in the X toolkit) that caused something to go wrong when a pane was sized very small. They implemented a workaround in the Encapsulator, which is to always set the value of Min to 3. Once this has been set, there is no way to change the value from the encapsulation.

Because of this, it is not possible to selectively use sashes in an Encapsulation. We decided that rather than have many sashes, most of which were useless, we would have no sashes at all and let the user set the size of the list and results area panes in their Xdefaults file. They can still change the size of the bottom pane (the "results" area) interactively. We later found, however, that if the window is made very small (for example, so that all panes are reduced to their minimum size), that when the window is later expanded panes are not reasonably vertically resized. Since there are no sashes, the user cannot correct this situation.

Temporary solution:  
 There is currently no workaround for this problem.

Fix information:  
 This problem may be corrected in a future release.

KPR #: 4700890947 Product: ADA SOFTBENCH COMMON ADA-SBA 00.00

One-line description:  
 FLU encapsulations may not run on remote data

Problem:  
 The Family, Library, and Unit Managers do not start when the host context is set to a remote machine.

Cause:

KPR #: 4700890947 \*\*CONTINUED\*\*

The problem is due to differences in how "encapsulate" searches for the .edl file and how "encaprun" searches for the .cedl file. "encaprun" is doing it wrong. In addition, it seems that it is doing it wrong in such a way that the -searchost and -searchpath command line options have no effect.

Temporary solution:

The workaround is to start the tool with data context set to the local machine, and then change context to the remote machine using the "File: Set Context" menu.

Fix information:

This problem will be fixed in the next release.

KPR #: 4700890962 Product: ADA SOFTBENCH COMMON ADA-SBA 00.00

One-line description:  
Dev. Mgr. incorrectly identifies Ada Static Analysis files as executable

Problem:

Static Analysis File Sets for Ada sources have the file name pattern: \*.ad?g

Development Manager should recognize these files as Static Data files and not as executables. This error prevents the user from selecting the Show Functions action on an Ada Static Analysis file type.

In particular, it would be nice if when such a file was selected, the Static Analyzer were invoked on this file.

Temporary solution:

In order to perform Static Analysis on Ada source files within a directory, do the following:

- a) Choose the desired source file which is to be analyzed.
- b) Select the menu item "Actions: Show Functions".

or:  
---

- a) Choose the menu item "Directory: Static Analysis->Current Directory"

Using either of these methods enables you to statically analyze your Ada source files.

Fix information:

This defect may be fixed in the next release.

KPR #: 4700890970 Product: ADA SOFTBENCH COMMON ADA-SBA 00.00

One-line description:  
Program Builder may not recognize references to Ada Ref. Manual

Problem:

KPR #: 4700890970 \*\*CONTINUED\*\*

Compilation errors when compiling an Ada source file are normally selectable for browsing by the user. If the error contains a reference to the Ada Language Reference Manual, selecting such an error results in the Reference Manual Browser being invoked and positioned at the appropriate section.

When two or more errors occur on the same line, and the first one contains a reference to the Language Reference Manual, Program Builder does not detect this reference.

Temporary solution:

There is no workaround to this problem.

Fix information:

This defect may be fixed at the next release.

KPR #: 5000195735 Product: AGP/DGL - MU 98600B 06.50

One-line description:  
ZIDRW incorrectly interprets current window coordinates

Problem:  
Customer found that the zidrw routine, in DGL, does not work properly on a s200 running hpux 5.1. Zidrw does not seem to correctly interpret the current window coordinates, as specified with a zwind call. The problem can be worked around by using zdraw instead.

Temporary solution:  
Use zdraw.  
Update S200 to 5.22 AGP/DGL

Fix information:  
Will not be fixed.

KPR #: 4700826735 Product: COBOL/HP-UX S300 35322B 01.06

One-line description:  
Repeated calls to X"82" consume memory

Problem:  
Repeated calls to X"<anything>" consumes memory.  
Cause:  
Not all memory is being properly released

Fix information:  
Fixed in B.02.01

Signed off 05/25/90 in release B02.01

KPR #: 4700879395 Product: COBOL/HP-UX S300 35322B 01.50

One-line description:  
bcheck does not work with lowercase names

Problem:  
9/28) problem caused by bcheck checking for a file extension of .dat, which used to be used for the data portion of the file. (now it has no extension.)

KPR #: 4700880062 Product: COBOL/HP-UX S300 35322B 01.08

One-line description:  
Numeric move does not move correct value

Problem:  
Moving a numeric value from a data item with usage comp to a data item with usage display produces the wrong value. This problem appears in native code programs.

Fix information:  
In order to receive this fix: All native code must be recompiled

KPR #: 4700884635 Product: COBOL/HP-UX S300 35322B 01.08

One-line description:  
Signed numeric decimal move does not move the correct value

Problem:  
Moving a numeric value from a data item declared as signed numeric with an assumed decimal point to a signed numeric data item without a decimal point moves the wrong value. This problem appears in native code programs.

KPR #: 5000522854 Product: COBOL/HP-UX S300 35322B 01.06

One-line description:  
Compiler option ODOOSLIDE causes native code program to abort

Problem:  
Compiler option ODOOSLIDE causes error 153 "Subscript out of

KPR #: 5000522854 \*\*CONTINUED\*\*

Range" when used with an OCCURS clause.  
Only occurs with native code, intermediate code is correct.

Fix information:

In order to receive this fix: All native code must be recompiled  
All code must be re-linked  
A new animator must be used

KPR #: 4000033357 Product: COMMON LISP DEVELOPMT HP98678A

01.00

Keywords: NMODE

One-line description:

File search indexes allow dup. names and leading/embedded spaces.

Problem:

File search indexes allow dup. names and leading/embedded spaces.  
Detailed instructions for duplicating problem:  
It is possible to create two (or more) search indexes with the same name. It should work the same way as code indexes (i.e. second create should put user in existing index with same name.)  
There is a separate bug that applies to all three types of file index browsers. It is legal to create a browser with a name that is all blanks, but the browser commands for moving up and down in a list of indexes will ignore blank lines even when those lines are for normal items. There should probably be a requirement that index names contain at least one printing character.

Fix information:

Will not fix.

KPR #: 4000033373 Product: COMMON LISP DEVELOPMT HP98678A

01.00

Keywords: NMODE

One-line description:

Find file on read protected file creates an empty buf. & new file msg.

Problem:

Find File on read protected file creates an empty buffer & new file message.

Detailed instructions for duplicating problem:

When the Find File command (C-X C-F) is given for a file that is read protected, an error message should be displayed. Instead, the command treats this case the same as an attempt to read a non-existent file, by creating an empty buffer and displaying a "(New File)" warning message.

Fix information:

Will not fix.

KPR #: 4000033381 Product: COMMON LISP DEVELOPMT HP98678A

01.00

Keywords: NMODE

One-line description:

Left locator button clicks above browser items beep; clicks below don't.

Problem:

Left locator button clicks above browser items beep; clicks below don't.

Detailed instructions for duplicating problem:

Left locator clicks which attempt to move the browser current item highlight above the pickable browser areas cause the top line to be highlighted and beep. Clicks below the pickable browser area high-



KPR #: 4000033381 \*\*CONTINUED\*\*

light the bottom line but do not beep. A second click in either case does not browse but continues to beep or not beep. This is not consistent.

Fix information:  
Will not fix.

KPR #: 4000033399 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Command line of editing buffer sometimes erroneously shows C-M-L.

Problem:  
Command line of editing buffer sometimes erroneously shows C-M-L . Detailed instructions for duplicating problem:  
In an Editing buffer, sometimes the promptline contains C-M-L to quit when C-M-L results in a no previous location message. This can be caused by directly browsing a series of buffers then deleting one of the previously browsed buffers.

Fix information:  
Will not fix.

KPR #: 4000033407 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
It's not possible to customize (bind keys to commands) all keyboard keys

Problem:  
It is not possible to customize (bind keys to commands) all keyboard keys, since shifted numberpad alpha keys have same key code as main keyboard keys.  
Detailed instructions for duplicating problem:  
When running Nmode in a HPWindows/9000 fastalpha graphics window, the following applies:

- Keys in the numberpad region of the IIF keyboard can be divided into 2 groups:
1. the 4 unlabeled function keys plus Enter and Tab
  2. all the others

Keys in group 2 (above) exhibit this bug:

The cause of the bug is in the window product.

Fix information:  
Will not fix.

KPR #: 4000033415 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Buffers can be accidentally killed if they have long filenames.

Problem:  
When buffer name is > 120 characters long, Selecting NO to popup menu confirmation of KILL BUFFER will kill buffer.  
Detailed instructions for duplicating problem:  
Rename a buffer so name is > 120 chars. Use popup menu in buffer browser to kill it. Confirmation popup menu has title missing!  
Select NO item. Buffer gets deleted anyway!  
Workaround:  
Shorten the buffer name or use the keyboard.

Fix information:  
May be corrected in a future release.

KPR #: 4000033423 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

One-line description:

With term0 window, shift left/right arrow key's not decoded

Problem:

In Term0, shift left/right arrow key's escape sequences are not decoded, causing Nmode to enter garbage into a text buffer when pressed.  
Detailed instructions for duplicating problem:  
Term0 sends ESC & r 1 L for left and ESC & r 1 R for right.  
Pressing these keys in a text buffer results in everything but the ESC being stored in the buffer.

Fix information:  
Will not fix

KPR #: 4000033431 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Undocumented behavior with cmd-argument to C-X O.

Problem:  
Undocumented behavior with cmd-argument to C-X O.  
The command argument selects the next pane in sequence and displays in it the same buffer that is displayed in the pane just left, independent of the sign or magnitude of the command argument given.

Fix information:  
Will not fix.

KPR #: 4000033449 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
Command functions do not follow M-X conventions.

Problem:  
There are many command functions in the system which do not follow the convention of -command at the end and match the M-X command name.

Fix information:  
Will not fix.

KPR #: 4000033456 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
LISP specific commands do not completely parse all CL syntaxes.

Problem:  
The LISP specific commands (eg move-forward-form, kill-next-form, indentation) don't completely parse all Common Lisp syntaxes, eg. all reader macros and reader syntax for arrays, etc. For example, parenthesis matching in Lisp Mode isn't smart enough to know about all the Common Lisp escapes.  
Detailed instructions for duplicating problem:  
The escape characters that NMODE doesn't consider when matching parens are "|" and the combination of "#|" and "#.". For instance, on the line

((foo) | x)

the right paren in the symbol foo) gets matched with the opening left paren.

Similarly, in

(foo #| This is a comment )|# x)

the right paren in the comment gets matched with the opening left paren.

These escape characters also need to be considered in other NMODE commands, such as the ones for killing forms.

Fix information:  
May be corrected in a future release.

KPR #: 4000033464 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
M-) command isn't consistent with indentation done by other commands.

KPR #: 4000033464 \*\*CONTINUED\*\*

Problem:

M-) command isn't consistent with indentation done by other commands. Detailed instructions for duplicating problem:  
The M-) command works weird. It's very useful for breaking up long one-liners (like macroexpansions, etc.), but ... For example, if you M-) this line repeatedly,

```
(let ((a b) (c d)) (cond (((a) b) ((c) d) (t e))))
```

..you get...

```
(let ((a b)
      (c d)
      )
  (cond (((a)
         b)
         ((c)
         d)
         (t e)
         )
        )
)
```

Fix information:  
Will not fix.

KPR #: 4000033472 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
White space at the end of a sentence is treated as another sentence.

Problem:  
Forward sentence will treat trailing white space at the end of paragraph as a sentence.

Fix information:  
Will not fix.

KPR #: 4000033480 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
In auto fill, + text modes Nmode doesn't keep left margin in view.

Problem:  
In auto fill, text modes, Nmode doesn't try to keep left margin in view.

Detailed instructions for duplicating problem:  
If I'm in text mode, auto fill, and I have a long word at the end of a line which forces the left margin out of view, auto fill will force the word onto the next line. The problem is, as long as point is visible, the window will not be resrolled to show the left margin.

KPR #: 4000033480 \*\*CONTINUED\*\*

KPR #: 4000033514 \*\*CONTINUED\*\*

Fix information:  
Will not fix.

KPR #: 4000033498 Product: COMMON LISP DEVELOPMT HP98678A 01.00

Keywords: NMODE

One-line description:

Receiving input from more than 27 file descriptors causes error.

Problem:

Receiving input from more than 27 file descriptors causes error.  
Detailed instructions for duplicating problem:

If you reconfigure your HP-UX kernel such that it supports more than 20 open file descriptors per process and increase the process per user count, you can create enough windows and HP-UX Access shell buffers to cause Nmode's input loop to fail. It isn't capable of receiving input from a file descriptor greater than 27. The easiest way to clean up the situation is to exit and reenter Nmode or kill off any extra windows or shells.

Fix information:  
Will not fix.

KPR #: 4000033506 Product: COMMON LISP DEVELOPMT HP98678A 01.00

Keywords: NMODE

One-line description:

Hitting [Break] while creating nmode shells causes loss of shell access.

Problem:

Hitting the [Break] key while creating Nmode shells cause loss of all future access to that shell during the current Nmode session.  
Detailed instructions for duplicating problem:  
If you hit the BREAK key while creating shells, in the most likely case it will just cause lack of access to that shell and may leave an extra (empty) buffer lying around. Because it cannot deallocate the broken resource, it also means you will have one less shell available for use (your total limit decreases).

Fix information:  
Will not fix.

KPR #: 4000033514 Product: COMMON LISP DEVELOPMT HP98678A 01.00

Keywords: NMODE

One-line description:

HP-UX command softkey is confusing and may cause garbage.

Problem:

HP-UX Command softkey is confusing and may cause garbage screen when used in terminal mode or without HPWindows/9000 when the HP-UX Access

- COMMON LISP DEVELOPMT -

KPR #: 4000033514 \*\*CONTINUED\*\*

Facility has not been loaded.

Detailed instructions for duplicating problem:

After invoking Nmode as "nmode -t hp" or invoking it without HPWindows/9000, and without loading the HP-UX Access facility, hit HP-UX Command softkey. Answer the prompt with "date" RETURN.

HP-UX executes date, and sends the results to stdout which in the window case is the term0 window and the other case is wherever the cursor was on the screen before Nmode was invoked. The output is sometimes difficult to read (it disappears with the next screen refresh) and sometimes creates a messy screen until the next refresh.  
Workaround:

When using Nmode without HPWindows/9000 or as a terminal, load the HP-UX Access facility first. Output will then be integrated into the appropriate Nmode buffer.

Fix information:  
Will not fix.

KPR #: 4000033522 Product: COMMON LISP DEVELOPMT HP98678A 01.00

Keywords: LISP

One-line description:

C-M-Return doesn't work in the middle of a shell-buffer.

Problem:

C-M-Return (HP-UX Execute and Delete Command) doesn't work in the middle of a shell-buffer, only at the bottom.

Detailed instructions for duplicating problem:

The key sequence C-M-Return, the HP-UX Execute and Delete command, will only work if you are typing on the last line of a shell-buffer. If used elsewhere, it may delete your last line if you have specified use of the prompt-end-character option.

Fix information:  
Will not fix.

KPR #: 4000033530 Product: COMMON LISP DEVELOPMT HP98678A 01.00

Keywords: NMODE

One-line description:

Shell buffers are not correctly named according to options.

Problem:

In the HP-UX Options browser: if you specify an existing buffer for the shell-buffer name option, creating a shell-buffer will make a new buffer based on the system's default name for shell-buffers (HP-UX.SHELL) instead of based on the name you specified.  
Detailed instructions for duplicating problem:

Currently, if you specify a name of a buffer that already exists, the algorithm will use the default name (HP-UX.SHELL) as a base to determining the name of the new buffer to create. It should instead use the name you specify at least as the base name of the new buffer. For example, if you specify "SHELL" for the name and a buffer named

- COMMON LISP DEVELOPMT -

KPR #: 4000033530 \*\*CONTINUED\*\*

SHELL already exists, it should create a new shell-buffer named SHELL-1 and not HP-UX.shell-?.  
 Workaround:  
 Always specify a buffer that doesn't already exist, or use the default name, or use M-X Create Shell-Buffer which allows you to specify the name.

Fix information:  
 Will not fix.

KPR #: 4000033548 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Keyboard and locator inputs not always processed in order entered.

Problem:  
 Keyboard and locator inputs not always processed in order entered. Detailed instructions for duplicating problem:  
 When keyboard and locator (mouse) inputs are both queued up, the inputs may not be processed by the system in the same order that they were entered. This is because the keyboard queue is emptied before the locator queue is read.

Fix information:  
 Will not fix.

KPR #: 4000033555 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Locator buttons may be missed during switching of windows.

Problem:  
 Locator buttons may be missed during switching of windows. Detailed instructions for duplicating problem:  
 If you do the following sequence as fast as possible, nmode misses the right button click:  
 select a different nmode window  
 bring up the Windows/9000 menu (left button on desktop)  
 abort it  
 try and bring up the nmode menu

The button is only missed if pressed during the window switch.  
 Workaround:  
 Don't give commands while the windowing system is switching windows.

Fix information:  
 Will not fix.

KPR #: 4000033563 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Mouse clicks can cause keystrokes to be ignored.

Problem:

In rare cases, mouse clicks occurring simultaneously with keystrokes will cause the keystrokes to be ignored.  
 Detailed instructions for duplicating problem:  
 If you have more than one Nmode window and try to do something like select the hidden window, then sometimes your subsequent keystrokes have no effect and other times (eg. when typing into a buffer) they will be processed but also force the hidden window to the top.

If you attempt to select a window at approximately the same time you hit a key on the keyboard with all of the following true:  
 - the mouse selection signal is actually "heard" before the key stroke  
 - you do this at "precisely" the right moment (at a time that the input path cannot detect it)  
 you can manage to get Nmode in a state whereby it is waiting for input from the "wrong" window (the fact that you have selected the other window has not yet been recognized).

This behavior is due to the single process nature of Nmode, and that signal events (the action as opposed to the recognition) are queued for processing in a synchronous manner. There exist critical sections in the input path, during which a signal could occur, that will not be processed immediately, causing Nmode to believe it is reading from the wrong device. The requirements necessary to produce such behavior occur within a very narrow window of time and are extremely hard to reproduce.  
 Checks have been added wherever possible.  
 Workaround:  
 If you get into such a situation you can just hit another mouse click to recover. Your data will not be lost.

Fix information:  
 Will not fix.

KPR #: 4000033571 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Changing C block begin/end chars in C Edit Options breaks C-M-F/B.

Problem:

Changing C block begin/end chars in C Edit Options breaks C-M-F/B. Detailed instructions for duplicating problem:  
 In C Edit Options, changing the block begin/end characters causes M-X Move Forward/Backward Block (C-M-F, C-M-B) to not match the new character strings.

Fix information:

KPR #: 4000033571 \*\*CONTINUED\*\*

Will not fix.

KPR #: 4000033589 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Template placeholders can be lost during template edit when CR inserted.

Problem:  
 Template placeholders can be lost during template edit when CR inserted.  
 Detailed instructions for duplicating problem:  
 While filling in a template in C, Pascal or Fortran mode, inserting a CR before a template in the same line causes the system to lose track of the remaining placeholders in the template. A good example is the C Case Template. While positioned on the first placeholder, insert a CR, and subsequent placeholders will be ignored.

Fix information:  
 May be corrected in a future release.

KPR #: 4000033597 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 BREAK key typed during load of tutor disables Load command for tutorial.

Problem:  
 BREAK key typed during load of tutor disables Load command for tutorial.  
 Detailed instructions for duplicating problem:  
 If the break key is typed during loading of the NMODE tutorials, further loading attempts of the tutorial will be ignored. When an attempt is made, a warning is displayed in the output buffer.  
 Workaround:  
 The current work around is to continue loading via the Lisp-C command instead of quitting from the break loop(s). If beyond this point, Nmode must be brought down and brought back up in order to load the tutorial.

Fix information:  
 Will not fix.

KPR #: 4000033605 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 The Restore key in the NMODE tutorial does not restore all situations.

Problem:  
 The Restore key in the NMODE tutorial does not restore all situations.

- COMMON LISP DEVELOPMENT -

KPR #: 4000033605 \*\*CONTINUED\*\*

Detailed instructions for duplicating problem:

If the View One Pane command is give while in the NMODE tutorials, the two pane configuration of the tutorial cannot be restored. Also, the NMODE tutorial does not allow a recursive call to itself.

Workaround:

Leave the tutorial via the f8 command, then return to the tutorial, or use the f4 softkey to return to the Tutor browser.

Fix information:  
 Will not fix.

KPR #: 4000033613 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Where-Am-I for Directories specifies "directories" instead of files.

Problem:  
 Where-Am-I documentation for Directories specifies "directories" where "files" should be specified.  
 Detailed instructions for duplicating problem:  
 Get into a directory browser. Do a Help Where-Am-I. Look at the command list under Utility. Notice that for Move, Copy and Rename the explanation speaks of directories rather than files. Should be only files or both files and directories.

Fix information:  
 May be corrected in a future release.

KPR #: 4000033621 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Help Where-I-Am lists a non-existent function.

Problem:  
 Help Where-Am-I for Error index has an error under Options: it lists a non-existent function.  
 Detailed instructions for duplicating problem:  
 Get into an error index. Do a Help Where-Am-I. Look down in the command list under Options. You will see that it lists a Lisp sub command. This command does not exist.

Fix information:  
 May be corrected in a future release.

KPR #: 4000033639 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Tutorial keys are changed if a breakloop entered while in the tutorial.

- COMMON LISP DEVELOPMENT -

KPR #: 4000033639 \*\*CONTINUED\*\*

Problem:  
 Tutorial keys are changed if a breakloop entered while in the tutorial.  
 Detailed instructions for duplicating problem:  
 When a break loop is entered, the four right tutorial keys are overwritten with no way to restore them.  
 Workaround:

Work around for this problem is to execute the command "M-X Leave Tutor Module" or press the List Tutors softkey to return to the Tutorial browser. The keys will be replaced.

Fix information:  
 Will not fix.

KPR #: 4000033647 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Evaluating a form in customize tutorial will overwrite the instructions.

Problem:  
 Evaluating a form in customize tutorial will overwrite the instructions.

Detailed instructions for duplicating problem:

Evaluating a form in Customize tutorial will bring up the output buffer over the tutorial instruction text.

Workaround:

The problem is that the any output will overwrite the instruction text. The workaround for this problem is to use C-X C-E command to evaluate the needed forms instead of evaluating the forms in the .moderc file. If the user is passed this point already, and the output has already overwritten the instructions, use the command C-X 0 to go to the instruction pane and execute C-M-L to remove the output buffer. Then return to the practice area (C-X 0).

Fix information:  
 Will not fix.

KPR #: 4000033654 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Online help for C-] L does not describe fully what the command does.

Problem:  
 Online help documentation for C-] L does not describe fully what the command does.

Detailed instructions for duplicating problem:

Look at the description of the C-] L command. The command is M-X Exit To Lisp.

Workaround:

In reality Nmode retains it state and you can come back right to where you left off. Think of this command as an "Exit to Lisp

- COMMON LISP DEVELOPMENT -

KPR #: 4000033654 \*\*CONTINUED\*\*

Listener".

Fix information:  
 Will not fix.

KPR #: 4000033662 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:

Documentation of Defuns in any of the online-help info needs further desc

Problem:

The documentation of Defuns in any of the online-help information needs further descriptions.

Detailed instructions for duplicating problem:

The on line documentation for Lisp-D is incorrect. It states that the current defun is executed when in reality it is only the current top level form (ie. open paren in col. one) that is executed.

The documentation as well as some of the functionality of NMODE (e.g. code browsers for lisp source files) considers top level functions as forms that starts in column 1.

Fix information:  
 Will not fix.

KPR #: 4000033670 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:

Help frame on Upcase-digit needs description of effective range.

Problem:

Help frame on Upcase-digit needs description of effective range.

Detailed instructions for duplicating problem:

Upcase-digit-command works only if at least one digit is found from the start of last line to the point.

Fix information:  
 Will not fix.

KPR #: 4000033688 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:

Softkeys can not be used with prefixed commands.

Problem:

Softkeys can not be used with prefixed commands eg C-X, M-X, Help

Detailed instructions for duplicating problem:

Bring up rkeys.

Hit the HELP softkey key. That works great. You see the Help menu.

- COMMON LISP DEVELOPMENT -

KPR #: 4000033688 \*\*CONTINUED\*\*

Hit the HELP softkey again. The result is an Undefined command.

Fix information:  
Will not fix.

KPR #: 4000033696 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Nmode -t Create window softkey exists even if window support does not.

Problem:  
nmode -t Create Window softkey exists even if window support is not available (e.g. from a terminal).

Fix information:  
May be corrected in a future release.

KPR #: 4000033704 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Softkeys for original window are reset.

Problem:  
The softkeys for the original window that nmode starts from are reset.  
Detailed instructions for duplicating problem:  
Define softkeys while in a window. Startup nmode. Stop nmode. The softkeys in the window where the nmode command was entered have been reprogrammed to produce ESC \ n where n is a digit corresponding to the key.

Fix information:  
Will not fix.

KPR #: 4000033712 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Windows in input mode cannot be killed with popup menu.

Problem:  
Window is not killed when using HPWindows/9000 popup to kill, and window is in input mode.  
Workaround:  
When this occurs, use the Kill Window M-X command to kill the window. The HPWindows/9000 popup menu will indicate that the window has already been killed so it cannot be killed again with the popup.

Fix information:  
May be corrected in a future release.

KPR #: 4000033720 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Lisp L gets errors when run from background.

Problem:  
Lisp L gets errors when run from background.

Temporary solution:  
Do not run NMODE from the background.

Fix information:  
Will not fix

KPR #: 4000033902 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
Package objects are accessible as normal vectors or arrays.

Problem:  
package objects are accessible as normal vectors or arrays  
Detailed instructions for duplicating problem:  
(in-package 'abc)  
(aref 'abc 0)  
returns a value, not an error

Fix information:  
Will not fix.

KPR #: 4000033910 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
Lamdas whose compiled code exceeds 32K bytes will not work.

Problem:  
Lamdas whose compiled code exceeds 32K bytes will not work.  
Detailed instructions for duplicating problem:  
Create a very large lambda and try to compile it.  
Workaround:  
Keep object code size less than 32K by breaking functions into pieces.

Fix information:  
May be corrected in a future release.

KPR #: 4000033928 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:  
 READ-CHAR-NO-HANG does not work with device files.

Problem:  
 READ-CHAR-NO-HANG does not work with device files.  
 Detailed instructions for duplicating problem:  
 If you open a stream to a device file and then try to do a  
 READ-CHAR-NO-HANG, it will hang if there is no data available.  
 Workaround:

Make the call to READ-CHAR-NO-HANG conditional upon a non-NIL value  
 returned by a call to LISTEN to the stream.

Fix information:  
 Will not fix.

KPR #: 4000033936 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:  
 Bare CL always prints system prompt even when user code doing READ.

Problem:  
 Bare CL always prints system prompt even when user code doing READ  
 Detailed instructions for duplicating problem:  
 Bring up CL, not NMODE.  
 Write and execute a function which contains a READ. The standard  
 prompt string will appear.

Fix information:  
 Will not fix.

KPR #: 4000033944 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
 Load of binary file with other than .b suffix gives unintelligible error

Problem:  
 Load of binary file with other than .b suffix gives unintelligible  
 error.  
 Detailed instructions for duplicating problem:  
 Assume that a file named example.l in the default directory contains  
 Common LISP source.  
 (compile-file "example.l" :output-file "code.example")  
 (load "code.example")  
 gives an error instead of loading the file.

Workaround:  
 If no :output-file option is given, compile-file will create a .b  
 file.

Fix information:

KPR #: 4000033944 \*\*CONTINUED\*\*

May be corrected in a future release.

KPR #: 4000033951 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:  
 System not observing restriction of call-arguments-limit (p108 CLtL)

Problem:  
 System not observing restriction of call-arguments-limit (p108 CLtL)  
 Call-arguments-limit is 254.  
 (vector 1 2 3 4 ... 299 300) will return a simple-vector of 300  
 elements, will not give an error.

Fix information:  
 Will not fix.

KPR #: 4000033969 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
 Save-world doesn't unwind bindings, save break state, update open files.

Problem:  
 Save-world does not unwind bindings or save break state or update  
 open files  
 Detailed instructions for duplicating problem:  
 While paused in a break loop, do a save-world. Later, from HP-UX,  
 execute the file named in the save-world. The state will not be  
 exactly what it was before the save-world, and some data written to  
 files oa{ will be lost.  
 Whenever possible, close all open files, exit break loops, and  
 return to the top level before executing save-world.

Fix information:  
 Will not be fixed.

KPR #: 4000033977 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:  
 Disassemble output is not compatible with either LAP or UNIX assembler.

Problem:  
 Disassembled output is not compatible with either LAP or UNIX  
 assembler.

Fix information:  
 Will not fix.



KPR #: 4000033985 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:

pp-expand does not preserve SPECIAL declarations in locally (and let).

Problem:

pp-expand does not preserve SPECIAL declarations in locally (and let).

Detailed instructions for duplicating problem:

```
(pprint (extn:pp-expand ,
```

```
  (let (a) (locally (declare (special a))) (foo a))
```

```
))
```

returns (LET ((A NIL)) (LET () NIL) (FOO A)) where the A after FOO

is not special.

pp-expand does not preserve ANY declarations except SPECIAL, and those only when there are specially bound variables.

In fact, its method is only heuristic; it may print special

declarations when none were originally given!

Workaround:

Use speed 0 where necessary to avoid preprocessor optimizations.

Fix information:

May be corrected in a future revision.

KPR #: 4000033993 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:

Bothtime functions (e.g. proclaim, in-package) take only constant args.

Problem:

bothtime functions (e.g. proclaim, in-package) take only constant args

Detailed instructions for duplicating problem:

When functions such as PROCLAIM or IN-PACKAGE occur as top-level forms in a compile-file, they are eval'ed at compile time.

This is necessary in most cases in order to either get correct

semantics (as with IN-PACKAGE or PROCLAIM SPECIAL) or to derive the

benefits (as with PROCLAIM optimizations).

However, since these functions evaluate their arguments, if the

arguments are not constants, they may not evaluate correctly at

compile time.

E.g. (PROCLAIM X) ==> Error: The symbol X has no value.

Fix information:

Will not fix.

KPR #: 4000034009 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:

File names containing '\$' are not handled correctly.

KPR #: 4000034009 \*\*CONTINUED\*\*

Problem:

File names containing '\$' are not handled correctly

Detailed instructions for duplicating problem:

1. Attempting a C-X C-F command and specifying a file that begins with a \$ (I used \$test) causes the system to display the message:

File <directory>/\$test is a directory; use a command argument to force a read. When I used a command argument the system brought

up a buffer that had garbage in it.

2. Attempting a C-X C-F on an existing file named test\$test nmode put the system into a new buffer that it said contained a new file.

3. I created a file with the name "\$\$(CC) \$(CFLAGS)". When I subsequently tried to do a C-X C-F on the file and typed in \$(CC) and

a space to do file completion the system erased all that I typed and replaced it with "\$HOME/". Also when I try to execute the form

```
(=> (make-nmode-file-name "$$(CC) $(CFLAGS)" :true-namestring)
```

```
)
```

The system gets a lisp error:

An attempt was made to use '-12' as an index in IMPL:SUBSEQ .....

Condition signalled in NMODE::TRUEST-NAMESTRING

To create these files with \$ in the name. I did the following from

cs:

```
vi \ $test
```

```
<entered text and quit file saving changes>
```

```
cp \ $test 'test$test'
```

```
cp \ $test '$$(CC) $(CFLAGS)'
```

forward-info Forward to lisp.kernel:

Since (truenamestring "foo\$fee") evals to defaultdir/foo when

\$fee cannot be expanded, there is no way for the nmode user to

specify a filename which contains a "\$".

Fix information:

May be corrected in a future release.

KPR #: 4000034017 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:

(defun nil {} nil) works interpretively, not compiled.

Problem:

(defun nil () nil) works interpretively, not compiled

Detailed instructions for duplicating problem:

```
(defun nil () nil)
```

works interpretively. You can't (compile 'nil) due to the definition

of compile. If you put the defun in a file, compile it, and load it

the system will reset whenever you call (nil). It goes back to

the beginning of top-loop as near as I can tell. The banner is

reprinted and the listener sequence numbers get reset to nil. In

trying to debug this I found that our system can't handle a function

- COMMON LISP DEVELOPMENT -

KPR #: 4000034017 \*\*CONTINUED\*\*

named nil. #'nil (symbol-function 'nil) (disassemble 'nil) ...  
all give errors.

Fix information:  
Will not fix.

KPR #: 4000034025 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
Preprocessor does not handle &key and &rest in the wrong order

Problem:  
Preprocessor doesn't gracefully handle &key and &rest in wrong order.  
Detailed instructions for duplicating problem:  
(defun bar (&key b &rest c)  
c)

(bar :b 3)

(defun bum ()  
((lambda (&rest c &key b) c) :b 3))

(defun bum ()  
((lambda (&key b &rest c) c) :b 3))

; (Two bugs demonstrated: )

; call to BAR complains of too many arguments passed  
; 1st definition of bum works fine  
; 2nd definition of bum blows away preprocessor with some strange  
; error

Fix information:  
Will not fix.

KPR #: 4000034033 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Sys:\*break-level-limit\* & Sys:\*break-limit-exceed-limit can work incorr.

Problem:  
The variables system:\*break-level-limit\* and  
system:\*break-limit-exceeded-limit\* do not work right when you set  
them to a non-integer value.  
Detailed instructions for duplicating problem:  
(setq system:\*break-level-limit\* 5.0)  
Then evaluate (/ 1.0) more than 5 times. Instead of printing a  
warning and exiting to the error handler, the system ignores the  
limit and goes deeper and deeper into breaks.

KPR #: 4000034033 \*\*CONTINUED\*\*

Fix information:  
Will not fix.

KPR #: 4000034041 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
Preprocessor error from an eval shows as eval on stack; not the pp fn!

Problem:  
Preprocessor error from an eval shows as eval on stack; not the pp fn!  
Detailed instructions for duplicating problem:  
Doing a (setq a b c) causes a preprocessor error signalled in a  
preprocessor function. doing a backtrace shows this function on  
the stack. Wrapping an eval around this also causes the break, ie,  
(eval '(setq a b c)), but the backtrace shows only eval on the  
stack. It should also show the pp function.

Fix information:  
May be corrected in a future release.

KPR #: 4000034058 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:

Attempt to trace method on undefined type gives meaningless warnings.

Problem:

Attempt to trace method on undefined type gives extraneous  
meaningless warnings.

Detailed instructions for duplicating problem:

Evaluate (trace (:method horse :color)) when horse is not a defined  
instance type. This gives the following four warning oessages, only  
the first of which is meaningful, the rest should be ignored:

!!! Warning: (:METHOD HORSE :COLOR) method specifier ignored in  
TRACE. HORSE is not a defined instance type.

!!! Warning: unrecognized option :METHOD--option ignored.

!!! Warning: unrecognized option HORSE--option ignored.

!!! Warning: unrecognized option :COLOR--option ignored.

Fix information:

May be corrected in a future release.

KPR #: 4000034066 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
(... &key) causes spurious compiler warning.

KPR #: 4000034066 \*\*CONTINUED\*\*

Problem:

(... &key) causes spurious compiler warning  
Detailed instructions for duplicating problem:  
(defun foo (&key)  
...)  
(compile 'foo)

Will give warning message that the variable PREPROCESSOR:  
\*\*KEYARGS\*\* is unnecessary.

Fix information:  
May be corrected in a future release.

KPR #: 4000034074 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
Outer eval-when specs don't control inner ones.

Problem:  
Outer eval-when specs don't control inner ones.  
Detailed instructions for duplicating problem:  
(eval-when (load)  
(defmacro foo (  
...  
)))

Will define foo at eval and compile times, too. This is because  
defmacro will expand into an '(eval-when (eval compile load) ...)',  
and nested eval-whens are not handled correctly.

Fix information:  
Will not fix.

KPR #: 4000034082 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
DIRECTORY pathname can't read LAN root directory.

Problem:  
(DIRECTORY pathname) where pathname specifies another system on the  
same Local Area Net can't read the root directory!

Fix information:  
May be corrected in a future release.

KPR #: 4000034090 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Documentation discrepancy on listener-abort/quit/-continue.

- COMMON LISP DEVELOPMENT -

KPR #: 4000034090 \*\*CONTINUED\*\*

Problem:  
Documentation discrepancy on listener-abort/-quit/-continue.  
Detailed instructions for duplicating problem:  
According to documentation, any listener invoked with the parameter  
top-level? true will catch a listener-abort. Listener-abort, in  
fact, always throws all the way out to lisp-top-level-loop.

Fix information:  
Will not fix.

KPR #: 4000034108 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
After !step, XM starts afresh on each new form, losing history.

Problem:  
After !step, XM starts afresh on each new form, losing history.  
Detailed instructions for duplicating problem:

Example:  
(defun foo (  
(let ((x 3))  
(break)  
(+ x x)  
(let ((y 4))  
(values x y))))

Evaluating (foo), and then !step from break, the stepper properly  
steps the form (+ x x). Then, however, when it starts with the  
inner let, XM makes it the new top level form, and discards the  
history information about (+ x x).

Fix information:  
Will not fix.

KPR #: 4000034116 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
Misleading error message in stepper when aborting the computation.

Problem:  
Misleading error message in stepper when aborting the computation.  
Detailed instructions for duplicating problem:  
When in the stepper, and you elect to abort the computation, the  
prompt window has the message "... abort the computation and exit  
the browser? default yes..." BUT the new behavior of the stepper is  
NOT to exit the browser (the expected behavior, anyway...), so the  
message is misleading.

Fix information:  
Will not fix.

- COMMON LISP DEVELOPMENT -

KPR #: 4000034124 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
Exec Monitor mismaps the i and v keys.

Problem:  
Exec Monitor mismaps the i and v keys.  
Detailed instructions for duplicating problem:  
Run nmode -t hp on term0  
Browse Additional Facilities, Execution Monitor  
Do meta-slash on "i"  
Do meta-slash on "v"  
At least one of these is a bug. :-)  
When I did it, one was unmapped & one was mapped to BELL which was not defined. At least one of these characters was the abbreviation for one of the commands in the "alphabet soup" line at the bottom.

Fix information:  
Will not fix.

KPR #: 4000034132 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
When ExMon is active, Lisp-a from 2nd window pops up ExMon in 2nd window

Problem:  
When ExMon is active, Lisp-a from 2nd window pops up ExMon in 2nd window.

Fix information:  
Will not fix.

KPR #: 4000034140 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
Stack overflow makes nmode window the bottom window.

Problem:  
Stack overflow makes nmode window the bottom window  
Detailed instructions for duplicating problem:  
From nmode in a window, I typed in and evaluated the following function:  
(defun f (n)  
 (f 0)  
)

It eventually got a stack overflow error. It seems that when the stack overflow occurs, the window is made the bottom window.

Fix information:  
Will not fix.

- COMMON LISP DEVELOPMENT -

KPR #: 4000034157 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:  
PP does not check declare name for symbolp; causes error in printing.

Problem:  
PP does not check declare name for symbolp; causes error in printing.  
Detailed instructions for duplicating problem:  
Example:  
(defun foo ()  
 (declare (extn:name (foo)))  
 'foo)  
#'foo

This sequence results in

!!!! Error: Argument (FOO) to IMPL:SYMBOL-PACKAGE is not a symbol.  
Condition signalled in: IMPL:SYMBOL-PACKAGE.

When the printer tries to print the fundef's lambda name.

Fix information:  
Will not fix.

KPR #: 4000034165 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
Exec. Monitor does not allow changing the number of function return val.

Problem:  
Execution Monitor allows the changing of individual return values from a function, but not the number of return values.  
Detailed instructions for duplicating problem:  
Create the function two-values: (defun two-values () (values 1 2 3)), then evaluate (step (two-values)). In the Execution Monitor, single step until getting the line  
| (TWO-VALUES) = 1 2 3

Then type V, for V(iew) V(values-and-args). By positioning on one of the value lines, using V S it is possible to change the 2 to a 5, for example, but it is not possible to make the function return exactly 2 values.

Fix information:  
Will not fix.

KPR #: 4000034173 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: NMODE

One-line description:  
Error in on-line help text for Exec. Mon.

- COMMON LISP DEVELOPMENT -

KPR #: 4000034173 \*\*CONTINUED\*\*

KPR #: 4000034207 Product: COMMON LISP DEVELOPMNT HP98678A 01.00

## Problem:

Error in on-line help text for Exec. Mon.  
Detailed instructions for duplicating problem:  
The on-line help text for the Execution Monitor says if there are more than 3 return values from a form that the fourth and succeeding forms are replaced by the string "Etc.". They are actually replaced by the string "...". The actual behavior is preferable, the help-text should be changed.

## Fix information:

Will not fix.

KPR #: 4000034181 Product: COMMON LISP DEVELOPMNT HP98678A 01.00

## Keywords: NMODE

## One-line description:

Meaningless warning msg from Execution Monitor.

## Problem:

When entering the Monitoring Options browser of the Execution Monitor, it gives a meaningless warning message that there are 'No options in group "rare".'  
Detailed instructions for duplicating problem:  
From the Execution Monitor type "OM" to invoke the monitoring options browser. The warning message will be displayed at the bottom of the screen.

## Fix information:

Will not fix.

KPR #: 4000034199 Product: COMMON LISP DEVELOPMNT HP98678A 01.00

## Keywords: NMODE

## One-line description:

Additional facilities prints incorrect message when loading xs browser.

## Problem:

Additional facilities prints incorrect message when loading xs browser.

## Detailed instructions for duplicating problem:

Upon loading the execution monitor the execution monitor was marked with an "L", but the execution stack was not. I then browsed into the execution stack. A message was displayed asking if I would like to load the facility. I hit return for "yes" and a message was displayed saying that I had already loaded the facility. An "L" was then displayed next to the facility name.

## Fix information:

Will not fix.

- COMMON LISP DEVELOPMNT -

KPR #: 4000034207 Product: COMMON LISP DEVELOPMNT HP98678A

01.00

## Keywords: NMODE

## One-line description:

Execution Monitor signals error that a form is not an identifier.

## Problem:

Execution Monitor signals error that a form is not an identifier. Detailed instructions for duplicating problem:  
When positioned on the line which says "Monitored form: ...", type V C (for View Code), and the following error is signalled:

```
!!!! Error: An attempt was made to do IMPL:ID2STRING on
(:MONITORED-FORM ...) which is not an identifier.
```

Error message is erroneous and misleading. No error should be signalled, the Execution Monitor should merely point out that there is no browsable code represented by this form.

## Fix information:

Will not fix.

KPR #: 4000034215 Product: COMMON LISP DEVELOPMNT HP98678A 01.00

## Keywords: NMODE

## One-line description:

Restoring default Breakpoints in XM options browser bad warn message.

## Problem:

Restoring default Breakpoints in XM Options browser gives bad warn message.

## Detailed instructions for duplicating problem:

Typing R, for restore-default, when on Breakpoints line in Execution Monitor. Monitoring Options browser gives warning message that an internal XM variable (DEBUG::\*FS-STOP-FNS\*) is ignored in breakpoint specification because it has no function definition.

## Fix information:

Will not fix.

KPR #: 4000034223 Product: COMMON LISP DEVELOPMNT HP98678A 01.00

## Keywords: LISP

## One-line description:

Execution Monitor reqs symbol to have function definition to set brkpt.

## Problem:

Execution Monitor requires that a symbol have a function definition to set a Breakpoint on it.

## Detailed instructions for duplicating problem:

I cannot set a breakpoint on an undefined function in the Execution Monitor, even though I know it is going to be defined and and invoked later in my stepping. This is because the Execution Monitor requires a valid function definition before it will add an element

- COMMON LISP DEVELOPMNT -

KPR #: 4000034223 \*\*CONTINUED\*\*

to the breakpoints list. For the same reason it is not possible to break on a named closure.  
 Workaround:  
 For ordinary functions, create a temporary function definition and let it be redefined by program execution. If, however, correct operation of the program requires the function be undefined, there is no work-around. There is also no workaround for the case of a named closure.

Fix information:  
 Will not fix.

KPR #: 4000034231 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 When XM not loaded, (step <form>) EVALs <form>, then says step undefined

Problem:  
 When XM not loaded, (step <form>) EVALs <form>, then says step undefined.

Fix information:  
 Will not fix.

KPR #: 4000034249 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 Fletting a constant folded function gives wrong results.

Problem:  
 Fletting a constant folded function gives wrong results  
 Detailed instructions for duplicating problem:  

```
(proclaim '(optimize (speed 2))) ; to get constant folding
(flet ((car (x) (cdr x))
      (cdr (x) (car x)))
  (cdr (car '(1 2 3))))
```

Will give an error message, because CAR and CDR are constant folded at speed 2, and this constant folding is not overridden by the flet definitions.

Fix information:  
 May be corrected in a future release.

KPR #: 4000034256 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
 Function reported in "Condition signalled in ..." msg not consistent.

KPR #: 4000034256 \*\*CONTINUED\*\*

Problem:  
 Function reported in "Condition signalled in ..." msg not consistent  
 Detailed instructions for duplicating problem:  
 Interpretively define a function foo which calls BREAK. Step foo.  
 The break message will say that the condition was signalled from APPLYHOOK rather than from foo.

Fix information:  
 Will not fix.

KPR #: 4000034264 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 XM pauses at evaluation of closed var in function call.

Problem:  
 XM pauses at evaluation of closed var in function call.  
 Detailed instructions for duplicating problem:  
 For most function calls where the arguments are all variable evaluations, the stepper first shows the call "as written", then on the next Step, it evaluates and displays all argument values and redisplay the calling form with the actual values substituted in the form. If, however, any of the variable arguments is closed, the stepper stops before evaluating it, and then forces the user to hit the S key once to see the value and a second time to continue evaluating the remaining arguments. Other closed arguments in the list will make similar stops. If remaining arguments are simple local or special variables, though, the evaluation will proceed for all of them as it should.

Fix information:  
 Will not fix.

KPR #: 4000034272 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 Execution Monitor limits maximum indentation to 50.

Problem:  
 Execution Monitor limits maximum indentation to 50. Any limit, even no limit, should be OK.  
 Detailed instructions for duplicating problem:  
 Enter the Monitoring options browser and try to set the maximum display indentation to a number greater than 50.

Fix information:  
 Will not fix.

KPR #: 4000034280 Product: COMMON LISP DEVELMNT HP98678A

01.00

Keywords: NMODE

One-line description:

In xm, quit acts like an inefficient run (changes modes, run does not).

Problem:

In xm, quit acts like an inefficient run (changes modes, run does not).

Fix information:

Will not fix.

KPR #: 4000034298 Product: COMMON LISP DEVELMNT HP98678A 01.00

Keywords: LISP

One-line description:

Can't redefine interpreted fn just before call in XM.

Problem:

Can't redefine interpreted fn just before call in XM.

Detailed instructions for duplicating problem:

When stepping a function call the Execution Monitor "stops" at two different times on forms representing the call. The first time it reconstructs the "source" of the call, complete with the forms which will be evaluated to produce the arguments to the function. The second time, it shows the actual argument values in a list with the function name that is about to be invoked. One would expect that if the function about to be called were redefined at the second suspension point, that the new definition would be invoked. In fact, if the function about to be called is compiled at the time the second suspension point is reached, the new definition does take effect. If, however, the function about to be called is interpreted when the second suspension point is reached, the new definition does NOT take effect. In the compiled case, if the new definition is interpreted, it also has the unfortunate side effect of showing the call twice.

Fix information:

Will not fix.

KPR #: 4000034306 Product: COMMON LISP DEVELMNT HP98678A 01.00

Keywords: NMODE

One-line description:

Stepper resets debug::\*step-size\* when preferred value is set.

Problem:

Stepper resets debug::\*step-size\* when I have my preferred value set

Detailed instructions for duplicating problem:

Whenever quit or abort are used to exit the stepper

\*step-size\* is set to nil. When the next step form is

evaluated it is then reset to all evaluations.

KPR #: 4000034306 \*\*CONTINUED\*\*

Fix information:

May be corrected in a future release.

KPR #: 4000034314 Product: COMMON LISP DEVELMNT HP98678A 01.00

Keywords: NMODE

One-line description:

Stepper does not gracefully accept bad input when in input mode.

Problem:

Stepper does not gracefully accept bad input when in input mode.

Detailed instructions for duplicating problem:

In the stepper, when I want to walk or run thru a computation, I am prompted for a function to break at. If I input a series of blanks, the system goes into a break loop and I get "unexpected end-of-file encountered. Condition signalled in lisp::read-preserving-whitespace-aux.

Fix information:

Will not fix.

KPR #: 4000034322 Product: COMMON LISP DEVELMNT HP98678A 01.00

Keywords: NMODE

One-line description:

XM signals non-continuable error if call an undefined function.

Problem:

XM signals non-continuable error if call an undefined function.

Fix information:

Will not fix.

KPR #: 4000034330 Product: COMMON LISP DEVELMNT HP98678A 01.00

Keywords: NMODE

One-line description:

V(value) cmd on env item in stack br signals error--should ignore instead.

Problem:

V(value) cmd on env item in stack br signals error--should ignore instead.

Fix information:

Will not fix.

KPR #: 4000034348 Product: COMMON LISP DEVELMNT HP98678A 01.00

Keywords: NMODE

One-line description:

Compile-file creates .b with wrong permissions (should use umask).

KPR #: 4000034348 \*\*CONTINUED\*\*

Problem:  
 Compile-file creates .b with wrong permissions (should use umask).  
 Detailed instructions for duplicating problem:  
 Files created by compile-file seem to be created with permission 666  
 regardless of the umask.  
 Workaround:  
 Change permission after compilation.

Fix information:  
 May be corrected in a future release.

KPR #: 4000034355 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 Codegen gives "wrong number of arguments" error.

Problem:  
 codegen bug with optional parameters  
 Gives wrong number of arguments error if called compiled  
 with one argument. Only happens when the optional has  
 an init form which is an integer 0..255.  
 Detailed instructions for duplicating problem:  
 (defun foo (a (&optional (b 23))) (print a) (print b))  
 (compile 'foo)  
 (foo 5)

Workaround:  
 Compile the function at speed 3.

Fix information:  
 Will not fix.

KPR #: 4000034363 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 Optimization bug with (equal 3.0.0).

Problem:  
 Optimization bug with (equal 3.0 0)  
 Detailed instructions for duplicating problem:  
 A bug exists in one of the optimizations of EQUAL and EQL. The  
 conditions in which it is manifest are as follows (will generate an  
 illegal instruction trap):

- 1) Running on a Series 9000 Model 310
- 2) Compiling at speed 1
- 3) Function EQUAL or EQL used
- 4) One argument is the fixnum 0
- 5) the other argument is a non-fixnum constant

This is a fairly close approximation of the conditions causing this

KPR #: 4000034363 \*\*CONTINUED\*\*

problem but may not be exact.  
 Workaround:  
 The workaround is to compile with some other speed than  
 1 for this particular function call.

Fix information:  
 Will not fix.

KPR #: 4000034371 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 Defmacro destructuring does not always initialize correctly.

Problem:  
 defmacro destructuring does not always initialize correctly.  
 Detailed instructions for duplicating problem:  
 (defmacro mac (&rest (arg)) arg)

Fix information:  
 Will not fix.

KPR #: 4000034389 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 Printing of floats inaccurate if number has large or small abs. value

Problem:  
 Printing of floats is inaccurate when the number is large or small  
 in absolute value.  
 Detailed instructions for duplicating problem:  
 (setq x 1.0E-300) causes 1.00000000000000006E-300 to be printed.  
 The internal representation is correct.

Fix information:  
 Will not fix

KPR #: 4000034397 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
 Subtypep does not work on types created by defstruct.

Problem:  
 Subtypep does not work on types created by defstruct.  
 Detailed instructions for duplicating problem:  
 (defstruct a)  
 (defstruct (b (:include a)))

(subtypep 'a 'b) should return (T). The current subtype  
 mechanism ignores all user defined types, including those created



KPR #: 4000034397 \*\*CONTINUED\*\*

by defstruct.

Fix information:  
Will not fix.

KPR #: 4000034405 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:

User initiated read of #, syntax evaluates at read-time.

Problem:

User initiated read of #, syntax evaluates at read-time.  
Detailed instructions for duplicating problem:  
(read-from-string "#gromek"); where gromek is unbound  
produces an error since gromek is unbound.

Fix information:

May be corrected in a future release.

KPR #: 4000034413 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:

PPRINT does not work on circular structures.

Problem:

PPRINT does not work on circular structures  
Detailed instructions for duplicating problem:

```
(pprint '(block fred
  (if q (mapcar #'(lambda () (return-from fred)) X)
  (:return-from fred))))
```

(BLOCK FRED

```
(IF Q
  (MAPCAR (FUNCTION (LAMBDA () (RETURN-FROM FRED)))) X)
  (RETURN-FROM FRED)))
```

GOOD:

```
(pprint '#1=(block fred
  (if q (mapcar #'(lambda () (return-from fred)) X)
  (return-from fred #1#)))
)
```

#30=(BLOCK FRED #31=(IF Q (MAPCAR (FUNCTION (LAMBDA () (RETURN-FROM FRED))) X) #32=(RETURN-FROM FRED #30#)))

BAD:

Fix information:

Will not fix.

KPR #: 4000034413 \*\*CONTINUED\*\*

Duplicate Service Requests: 4000034736

KPR #: 4000034421 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:

Double-float-epsilon needs to be different on 881.

Problem:

Double-float-epsilon needs to be different on an 881!!  
Workaround:  
Define and use your own constant instead of double-float-epsilon  
when running on a model 320.

Fix information:

Will not fix.

KPR #: 4000034439 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:

Special-form-p of multiple-value-call returns nil.

Problem:

Special-form-p of multiple-value-call returns nil.

Fix information:

Will not fix.

KPR #: 4000034447 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:

Read suppress not working with escaped symbols.

Problem:

Read suppress is not working with escaped symbols  
Detailed instructions for duplicating problem:  
'|foo,bar| ;; evaluates OK

```
#-hp ;; shouldn't get evaluated, but blows up with
'|foo,bar| ;; Error: Comma not inside a backquote.
```

Fix information:

Will not fix.

KPR #: 4000034454 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:

pprint seems to print certain forms incorrectly.

KPR #: 4000034454 \*\*CONTINUED\*\*

Problem:  
 pprint seems to print certain forms incorrectly  
 Detailed instructions for duplicating problem:  
 (pprint '((bbbbbbbbb...56 b's...bbbbbb) (define-method 4))  
 prints as

```
((bbbbbbbbb...bbbbbbbbb)
  ((bbbbbbbbb...bbbbbbbbb) (define-method 4))
```

which just isn't right. A symbol 55 characters long won't fail.  
 The total length of what should be printed is 78 characters.  
 The symbol define-method must be there and the bbb's must be at  
 least 2 levels down.

Fix information:  
Will not fix.

KPR #: 4000034462 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: NMODE

One-line description:  
y-or-n-p and yes-or-no-p should prompt.

Problem:  
 y-or-n-p and yes-or-no-p should prompt  
 Detailed instructions for duplicating problem:  
 The functions Y-OR-N-P and YES-OR-NO-P should prompt the user. For  
 example: "Delete file? (Y or N)" and "Delete directory? (Yes or No)"  
 Currently, they only tell the user what to say after the user first  
 says something wrong. There is no way for the user to distinguish  
 between these two cases based on the message printed.

Fix information:  
Will not fix.

KPR #: 4000034538 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

One-line description:  
Editing switches to PLS mode not LISP mode.

Problem:  
 Problem description:  
 Editing the file \$LISP/config/nmode.init with NMODE the system  
 switches to "PSL" minor mode. It should be in "Lisp" minor mode.  
 Workaround:  
 M-X Lisp Mode

Fix information:  
Will not fix.

KPR #: 4000034710 Product: COMMON LISP DEVELOPMENT HP98678A

01.00

Keywords: LISP

One-line description:  
Format bug: ~@\* directive fails inside ~{...~}.

Problem:  
Format bug: ~@\* directive fails inside ~{...~}

The ~@\* (absolute goto) format directive does not work properly when  
 used inside a ~{...~} (list iteration) directive. The proper  
 function is to use the elements of the list as the argument list that  
 the ~@\* directive refers to. Instead, the ~@\* continues to refer to  
 the top level argument list. [See Steele, p. 399; pp. 403f.] The  
 relative skip (~\*) seems to work correctly inside iteration  
 directives.

Examples:

(format nil "~1{~0@\*~A~}" '(1 2 3)) => "(1 2 3)" Correct: "1"

(format nil "~2@\*~A~}" '(1 2 3)) =>  
 !!! Error: In call to FORMAT:  
 Illegal to go to non-existent argument  
 ~2@\*~A~}

Condition signalled in: FORMAT.

Correct: "3"

(format nil "~{~\*~A~}" '(1 2 3 4)) => "24" O.K.

(format nil "~1{~2\*~A~0@\*~A~}" '(1 2 3 4)) => "3 (1 2 3 4)"  
Correct: "3 1"

Fix information:  
Will not fix.

KPR #: 4000034744 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

Keywords: LISP

One-line description:  
GENSYM message refers to extraneous init forms

Problem:  
 Compiler Warning Message Problem  
 The compiler generates a warning message about extraneous init forms  
 when these are encountered. Unfortunately, the error message is  
 somewhat garbled. The value that it displays in the error message is  
 the print name of a GENSYM, rather than any indication of the form  
 that caused the error. It looks as if the message constructor does  
 not evaluate an internal compiler symbol (the GENSYM), but prints its  
 name instead.

KPR #: 4000034744 \*\*CONTINUED\*\*

This only occurs with COMPILE-FILE, not with COMPILE (the latter produces no such warning).

Example: Compile a file containing the following:

```
((lambda (x)
  (setq x 'foo)
  (symbol-name x)
  )
 nil)
-----
```

Temporary solution:

Try: (PROCLAIM '(WARN NIL))

This turns off all warnings!

Fix information:  
Will not fix

KPR #: 4000036616 Product: COMMON LISP DEVELOPMENT HP98678A 01.01

One-line description:  
Lisp should load required modules automatically.

Problem:

The LISP modules loaded to the lisp-loader kernel with the make-nmode script should be "orthogonal" in the sense that none of them requires any other module to be present when loaded. If one module needs another one to be present it should execute a (require <module>) by itself.

However, when I tried to just execute (require "nmode") from the bare lisp-loader kernel, I got the error message "undefined function: load-of-ile". When I tried to execute (require "external") (require "nmode")

the function "debug::add-to-visibility-class" was not defined. This means: whenever you want to (require "nmode") you need to (require "debug") and (require "external") first.

Workaround:

Load the required modules with (require <module>).

Fix information:  
May be fixed in a future release.

Duplicate Service Requests: 4000046136

KPR #: 4000046110 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

One-line description:  
If a Q-Prolog is loaded, output can go to the wrong window

Problem:  
If Q-PROLOG is loaded from a Lisp listener, the output will continue to go to the listener window instead of the output buffer.

Bring up an NMODE with Z-PROLOG in it. Execute a Lisp-L and evaluate the form (q-prolog). Then exit q-prolog with a ^D and return to nmode with (nmode:nmode). Upon returning, Q-PROLOG will continue to output to the listener window instead of the output buffer.

Workaround:

Don't load Q-PROLOG for the first time while in the Lisp listener. It will work correctly, as long as it is not loaded while in the Lisp-L.

Fix information:  
Will not fix

KPR #: 4000046128 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

One-line description:  
Current language can get out of sync with mode of buffer

Problem:

There are certain conditions in which the listener (current language) can get out of sync with the mode of the buffer in NMODE. The circumstances are described in Prolog Users guide.

Do a Lisp-L while in a Lisp buffer. Then evaluate the function (z-prolog). Inside Z-PROLOG, do a (lisp-eval ?x (nmode:nmode)) to return to NMODE without leaving the Z-PROLOG language. The buffer you return to will be in Lisp mode but in the Z-PROLOG language (the listener will be in Z-PROLOG).

Workaround:

Simply cycle through the language modes until you return to the mode you want. The listener will be correct by then.

Fix information:  
Will not fix

KPR #: 4000046433 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

One-line description:  
Emacs menu "MODES" not complete.

Problem:

Emacs popup menu "MODES" only contains Lisp, Text, and Auto Fill. It should also contain C, Pascal, Fortran, Z-Prolog and Q-Prolog if these facilities are loaded.

KPR #: 4000046433 \*\*CONTINUED\*\*

Fix information:  
May be fixed in a future release.

KPR #: 4000046441 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

One-line description:  
When loading files, cannot determine use of old or new entry points

Problem:

If you try to load-offile at some entry point which already exists in the system it is not easy to tell whether you are getting the existing entry-point or a new one.

For example, Nmode always has the Windex (hp-ux\_3w) libraries. This contains an entry point named "wmove". If you want to use the curses junk and use that "wmove" you will not have an error on the load-offile but will get one when you think you are calling curses and end up calling windex.

Workaround:

You can push the symbol of the entry point onto the \*protected-entry-points\* list and then use the :redefining keyword in the load offile to redefine during the load the entry point in question.

We should include a specific explanation of this phenomena in the documentation.

Fix information:  
Will not fix

KPR #: 4000046771 Product: COMMON LISP DEVELOPMENT HP98678A 00.00

One-line description:  
lisp sometimes hangs, this is aggravated by prolog

Problem:

It is possible to get the PROLOG system into such a state that the BREAK key will not ever be processed. In other words, the system hangs. This generally will not happen unless BREAK is not hit for at least a couple minutes after a predicate starts looping.

Define the following predicate in Z-PROLOG and evaluate the second call (the one in the comment below). Wait several minutes (I waited 8) and hit BREAK. It will not respond.

```
(defpred reverse
  ((reverse ?list1 ?list2)
   (rlist ?list1 () ?list2)))
(defpred rlist
  ((rlist () ?list1 ?list1)
   (rlist ?list1 ?list1 ()))
```

- COMMON LISP DEVELOPMENT -

KPR #: 4000046771 \*\*CONTINUED\*\*

```
((rlist (?a . ?b) ?c ?r)
 (rlist ?b (?a . ?c) ?r))
;(reverse (a b c) (c b a))
;(reverse ?X (a b c))
```

Workaround:

Hit BREAK earlier in the process. If this happens and it does not return, then you must restart NMODE/PROLOG. Note that this never interferes with the correct operation of correct programs.

Fix information:  
Will not fix.

KPR #: 5000170167 Product: COMMON LISP DEVELOPMENT HP98678A 01.01

One-line description:  
Setq & setf combination results in system termination.

Problem:

Common Lisp bug:  
(setq a (make-array '(2 3)))  
(setf (apply #'aref a' (1 1)) 1)  
Bombs the system, the following works:

```
(setq a (make-array '(2 3)))
(setq z '(1 1))
(setf (apply #'aref a' z) 1)
```

Fix information:  
Will be fixed in a future release.

KPR #: 5000193656 Product: COMMON LISP DEVELOPMENT HP98678A 01.00

One-line description:  
inquire\_hit function not included in HPUX\_3g package for LISP

Problem:

The customer has tried to use the Inquire Hit function which is a new feature with version 5.12 of the Starbase Graphics but this was not available through the HPUX\_3g package from Lisp 1.01. She wants this feature to be added. She knows that she can write a foreign function call from Lisp that will allow the use of this but she wants it in the HPUX\_3g package.

Temporary solution:

Make a file with the following things in it:

```
{in-package 'hp-ux_3g}
(export '(inquire hit))
(extn:defexternal inquire-hit ...)
```

It appears that you already have the defexternal defined. This file can be compiled and the binary can be loaded in your .lisprc or .nmoderc. It could also be put in your make-rmode.

- COMMON LISP DEVELOPMENT -

KPR #: 5000193656 \*\*CONTINUED\*\*

Fix information:  
Will not be fixed.

KPR #: 5000272898 Product: COMMON LISP DEVELOMNT HP98678A 01.01

Keywords: DOCUMENTATION LISP

One-line description:  
Error in lisp application note example.

Problem:  
The "Window smart example" in Chapter 5 "Term0 Windows" of "Lisp Application Note" (part# 98678-90010 p71) causes "file stream error".

When we evaluate "(query-usr wmfid "Jimi" "Hey Joe, where you going with that pizza in your hands?")", a window is successfully made but after displaying the message "Hey Joe, ..... your han", an error occurs. The error message is:

```
!!!! Error: Unknown file stream error with stream #<<File Stream
/dev/screen/Jimi^@>
Condition signalled in :LISP::FILE-OUT
```

\*\*\* System \*\*\*  
9000/350, HP-UX 5.5, Common Lisp 1.01

Temporary solution:  
In the function query-user, change the call set-canonical to set-raw. You will have to handle echoing and backspacing yourself.

Fix information:  
Will not fix.

KPR #: 1650041749 Product: COMMON LISP EXECUTION HP98679A

01.00

One-line description:  
Order of FORTRAN function parameters effects calc.when called from LISP.

Problem:  
Example in Lisp programmer's guide p.141 fails when sequence of parameters in both Lisp program aswell as in Fortran routine are changed. Only the original sequence generates the right result.

Temporary solution:  
The workaround is a redefinition of two LISP macros. This fix should be referenced in the user's .nmoderc file.

Fix information:  
Will be fixed in a future release.

KPR #: 1650119883 Product: DOS COPROCESSOR SFTW 98531A

02.00

Keywords: DOS CO-PROCESSOR

One-line description:  
DOS Co-processor does not work correctly with 98549A

Problem:  
The wrong starbase driver (hp300h) was being used for this display type. Not all graphics planes were being manipulated properly, causing ghost planes to appear.

Cause:  
The wrong starbase driver (hp300h) was being used for the 98549 display.

Temporary solution:  
To avoid this problem, use dos.cga inside of Windows 9000, or use dos.ega, or use dos.x.

Fix information:  
This fix was made in DosCoproprocessor version 2.1.

Signed off 10/30/90 in release A02.10

KPR #: 4000058446 Product: DOS COPROCESSOR SFTW 98531A

01.05

One-line description:  
CTTY does not work with VIAC00PD loaded

Problem:  
CTTY is a MSDOS command that allows a character IO device to be substituted for the standard console. It does not work when Viacooopd is loaded.

Cause:  
This problem associates with the program, VIAC00PD.EXE, which has been obsoleted in version 2.00.

Temporary solution:  
Unload the Networking software by typing nocoopd at the MSDOS prompt. The HP-UX file system can not be accessed, however CTTY should work.

Fix information:  
not applicable any longer on 2.00+  
Signed off 10/30/90 in release A02.00

KPR #: 4000078683 Product: DOS COPROCESSOR SFTW 98531A

01.06

One-line description:  
Shell escape from DOS and try to start DOS again. Font's get trashed.

Problem:  
When a soft-reset is done in the ITE (shift-break key) it overwrites the offscreen memory in the display. The fonts stored by the DOS coprocessor get overwritten. The only workaround is to exit dos and re-start.

(Note that re-starting DOS from a shell escape fails. However the ITE is reset during that process, thus overwriting the original fonts)

Cause:  
Fonts get unloaded

Temporary solution:  
No workaround needed

Fix information:  
This problem fixed in version 2.1. But there are still a few rare instances where fonts can get trashed in dos.cga.

Signed off 10/30/90 in release A02.00

KPR #: 4000093401 Product: DOS COPROCESSOR SFTW 98531A

02.00

One-line description:  
If dosconfig used to disconnect & reconnect LPT1->spooler, fails errno32

Problem:  
This problem is due to a defect in the dosconfig script.

Cause:  
This is due to a defect in the dosconfig script.

Fix information:  
Will be fixed in release 2.10 of DOS Coprocessor Software.

Signed off 10/30/90 in release A02.10

KPR #: 4000093567 Product: DOS COPROCESSOR SFTW 98531A

02.00

One-line description:  
README.DOC doesn't mention REDIR when showing how to update AUTOEXEC

Problem:  
The README.DOC on the 2.0 release of the Dos Coprocessor does not fully explain how to update an AUTOEXEC.BAT file. The statement should read

To modify your old AUTOEXEC.BAT,  
remove these lines if they are present: xmemdrv  
viacooopd

KPR #: 4000093567 \*\*CONTINUED\*\*

KPR #: 5000456640 \*\*CONTINUED\*\*

add these lines if they are not ^M already there:

redir  
dosmount d:

Cause:  
The README.DOC file had incomplete information.

Temporary solution:

Follow the directions mentioned above under Problem: to make the changes to the autoexec.bat files.

Fix information:

This problem is fixed in version 2.11

Signed off 10/30/90 in release A02.10

KPR #: 5000429019 Product: DOS COPROCESSOR SFTW 98531A 01.20

One-line description:

dos subsystem ties up system when pressing extend/reset for long time

Problem:

The autorepeating flush key caused the DOS System to repeatedly fork/exec the lp process. These are costly operations in terms of compute time (lots of swapping) and the large number of requests generated by the autorepeat caused the system to grind to a halt.

Cause:

Getting autorepeat directly from X sometimes leads to too many key presses

Fix information:

This problem is fixed in version 2.1 and following.

Signed off 10/30/90 in release A02.10

KPR #: 5000456640 Product: DOS COPROCESSOR SFTW 98531A 02.00

Keywords: DOCUMENTATION

One-line description:

format not correctly documented

Problem:

The 2.0 DOS Coprocessor does not properly handle the /T:80 argument to the FORMAT command, when formatting 720k 3.5-inch media on a 1.44M drive. The FORMAT command fails when this argument is given, but the

Known Problem Reports as of 11/21/90

KPR #: 5000456640 \*\*CONTINUED\*\*

syntax is valid and should be handled correctly.

Cause:

The 2.0 DOS Coprocessor emulation code has a 2 defects in the 3.5" disk drive emulation code. Either of these defects cause the /T:80 argument to the FORMAT command to be incorrectly rejected.

Temporary solution:

In DOS Coprocessor revisions 2.0 and earlier, do not use the /T argument with the FORMAT command. To format a 720 kbyte floppy in a 3.5-inch 1.44 Mbyte drive, the "/N:9" argument will cause FORMAT to take the proper action.

Fix information:

This has been fixed in DOS Coprocessor Release 2.1. Starting with that revision, the FORMAT command will format 720 kbyte media in a 1.44 Mbyte 3.5-inch drive when the /N:9 and/or the /T:80 arguments are supplied.

Signed off 10/30/90 in release A02.10

KPR #: 5000479725 Product: DOS COPROCESSOR SFTW 98531A 01.20

Keywords: DOS CO-PROCESSOR

One-line description:

pop up menu under dos.x hangs the dos window

Problem:

X Library changes made in 6.5 made some implementation assumptions no longer valid. The 6.2 libraries did not exhibit this problem. Version 2.00 of the DOS Coprocessor software was developed on 6.2.

Cause:

The X libraries changed for HP-UX 6.5 causing DOS to fail.

Fix information:

Changed the user interface for 2.1

Signed off 10/30/90 in release A02.10

KPR #: 1650042044 Product: HP PROLOG 1.0 79232U 01.00

Keywords: PROLOG

One-line description:  
PROLOG goes into infinite loop on certain predicates.

Problem:  
HP9000/350 with 16Mbyte ; HP-UX 5.22 ; CommonLisp and HP-Prolog

1. Define the following two predicates:

```
(defpred fibonacci
  ((fibonacci 1 0 ))
  ; ((fibonacci 1 1 ))
  (+ ?n -1 ?n-1)
  (fibonacci ?fn ?n)
  (+ ?n -2 ?n-2)
  (fibonacci ?fn-1 ?n-1)
  (+ ?fn-1 ?fn-2 ?fn)))
```

2. Prove  
(fibonacci ?res 5)

It is not possible to abort the evaluation of this endless loop using the break key.

Fix information:  
Will not be fixed.

KPR #: 1650059014 Product: HP SQL/300 79725A 01.05

One-line description:

Computing COUNT over an empty set returns no row instead of zero

Fix information:

This problem has been resolved on HP-UX 3.0 on the series 800 machine. When resyncing of HP SQL between 300 and 800 series machines is complete, it will contain the necessary fix for this SR.

Signed off 12/29/89 in release A02.00

KPR #: 4700441717 Product: HP SQL/300 79725A 00.00

One-line description:

we need to raise the minimum number of log pages allowed

Problem:

A user can specify a minimum of 120 log pages on HP SQL/300 while HP SQL on the Series 840 has a minimum of 136 log pages. For compatibility, these numbers should be the same.

Cause:

A constant needs to be redefined from 120 to 136. In reality, for the latest A.B2.00 ALLBASE release on the Series 840, the minimum number of log pages has been set at 144 pages.

Temporary solution:

On HP SQL/300 specify a minimum of 136 log pages. To be compatible with the latest Series 840 A.02.00 HP SQL release (ALLBASE A.B2.00.00) specify a minimum of 144 log pages.

Fix information:

The problem will be fixed in resync 300 base code.

Signed off 03/09/89 in release A06.05

KPR #: 4700451161 Product: HP SQL/300 79725A 00.00

One-line description:

'unload to external..' from cmd file requires all params on one line

Problem:

When doing an ISQL 'unload to external' from a command file, a single character on one line causes a problem to occur. The error returned is #47 - Missing parameters from command file.

Cause:

None at this time.

Temporary solution:

When using 'unload to external' from a command file, put all required parameters on a single line.

Fix information:

To be fixed by resync in 6.5 release.



KPR #: 4700451161 \*\*CONTINUED\*\*

Signed off 03/07/89 in release A02.00

KPR #: 4700455444 Product: HP SQL/300 79725A 00.00

One-line description:

illegal syntax error generated due to bigfile processing

Problem:

Due to the 255 bytes limitation on strings, large queries are sometimes incorrectly recalled from big file processing. When these are run through ISQL, a syntax error is returned.

Cause:

HP SQL was incorrectly concatenating lines every 256 bytes rather than the 2048 bytes found on the Series 840 HP SQL version.

Temporary solution:

Limit the length of large queries to less than 256 bytes.

Fix information:

To be fixed by the resynch in 6.5 release. David Ai

Signed off 03/07/89 in release A02.00

KPR #: 4700481937 Product: HP SQL/300 79725A 00.00

One-line description:

installation module size not compatible with that of hp sql/800

Problem:

There is an alignment difference in the sizes of HP SQL/300 and HP SQL (Series 840) ISQL install modules. This causes some porting problems for HPToday and HP SQL users who want to transfer these modules between different 300, 500, and 800 series hardware.

Cause:

An alignment difference exists between HP SQL/300 and HP SQL on the Series 840. The HP SQL/300 length is 498 bytes while HP SQL/840 is 500 bytes for a module. The extra 2 bytes (filler) needs to be added to HP SQL/300 module size.

Temporary solution:

No temporary workaround exists for porting modules.

Fix information:

Will be fixed by the resynch in 6.5 release. David Ai 9/1/88

Signed off 03/07/89 in release A02.00

KPR #: 4700539148 Product: HP SQL/300 79725A 00.00

One-line description:

BULK FETCH bug. Can only retrieve a certain number of rows.

Problem:

The problem exists as Charlie stated it. Tony found the bug in a piece of assembly code that reads a word instead of a longword from the length register so only a certain number of rows can ever be fetched.

There is a workaround. Only 65535 bytes can be fetched at a time, so divide by the number of bytes per tuple and that will be the max number of rows that can be fetched at a time.

No error message was ever returned. gk

Cause:

As identified by Tony, the problem is in a piece of assembly language routine inside SQLCore. I am transferring this to May's group that handles SQLCore. David Ai 9/1/88

The assembly code that reads a word instead of a longword from the length register so only a certain number of rows can ever be fetched.

Only 65535 bytes can be fetched at a time.

No error message was ever returned. gk

Fix information:

This problem has been fixed in release version 1.01 or later.

Signed off 05/23/89 in release A02.00

KPR #: 4700552232 Product: HP SQL/300 79725A 00.00

One-line description:

LOAD command failing when pattern matching specified

Problem:

version 1.0

There is a problem with the LOAD command. Try loading from an external file using a pattern to a relation. EG:

LOAD FROM EXTERNAL extern TO TEST

SERLN 1 10 #

END

YES 1 a;

isql will still prompt you for the starting location and the pattern even though you've given it. After specifying these values, nothing is loaded even though some tuples qualify. Specifying an uppercase A instead of a lowercase a will cause qualifying tuples to be loaded.

Cause:

This problem was caused by an ISQL defect.

Fix information:

To be fixed by the resynch in release 6.5. David Ai 9/1/88

Signed off 03/07/89 in release A02.00

KPR #: 4700579508 Product: HP SQL/300 79725A 00.00

One-line description:  
negative numbers improperly sorted by ORDER BY

Problem:  
DMCCD (column compare) does not work correctly on the 300 code.

Cause:  
See problem text.

Fix information:  
This will be fixed on the 300 6.5 release.

Signed off 03/09/89 in release A06.05

Duplicate Service Requests: 5000296913

KPR #: 4700590638 Product: HP SQL/300 79725A 00.00

One-line description:  
multi-table joins may cause memory allocation failures

Problem:  
The problem was in the optimizer, which was using an unnecessary large amount of memory for a multi-table join. Memory utilization was large enough to cause queries to fail with "HP SQL memory allocation failed" error during optimization.

Cause:  
Some memory no longer needed by the optimizer was never being released. Thus, with multi-table joins which involve many join orders and index plan possibilities, available memory would be exhausted.

Fix information:  
A fix was made to release memory no longer needed.  
Fixed in Release 1.01.

Signed off 12/21/89 in release A20.00

KPR #: 4700594275 Product: HP SQL/300 79725A 00.00

One-line description:  
incorrect error msg when using isql from directory w/bad permissions

Problem:  
rev 1.0 When trying to select from within isql and the permissions are incorrect in the current working directory, the error msg needs to be cleaned up. A pascal runtime error is output along with a hp-ux system error 13. What should be output is 'security violation, permission denied (DBERR 220)' gk 3/22

Cause:  
This problem was caused by ISQL's not interpreting HP-UX return code.

KPR #: 4700594275 \*\*CONTINUED\*\*

Fix information:  
Will be fixed on 6.5 release. David Ai 9/1/88

Signed off 03/07/89 in release A02.00

KPR #: 4700594309 Product: HP SQL/300 79725A 00.00

One-line description:  
unload command with embedded select stmt causes syntax error

Problem:  
Lines from the SELECT clause of the ISQL UNLOAD command are concatenated without the insertion of a blank. This results in an error for the SELECT clause when it is parsed.

Temporary solution:  
This problem can be worked around by inserting a blank at the beginning of every line within the doubly quoted SELECT clause.

Fix information:  
Will be fixed on 6.5 release. Linda Spilo 11/3/88

Signed off 03/07/89 in release A02.00

KPR #: 4700664219 Product: HP SQL/300 79725A 00.00

One-line description:  
internal error msg returned for < minimum log pages on start db

Signed off 05/23/89 in release A02.00

KPR #: 4700687905 Product: HP SQL/300 79725A 00.00

One-line description:  
C compiler cannot resolve symbols when linking more than 1 object file.

Problem:  
When an application contains two or more program source files and after preprocessing these source files, at linking time the linker complains 'sqlmodname' and 'sqlowner' as multiple defined symbols.

Cause:  
This problem is caused by the C Preprocessor in HP300 system defined 'sqlmodname' and 'sqlowner', as global variables in each corresponding type file for each program source file which has been preprocessed, and after compiled by C compiler these global have been into each object file, therefore when linker tried to link these object files it detected two identical global variables in each object file and issued warning messages.

Fix information:

KPR #: 4700687905 \*\*CONTINUED\*\*

The problem was fixed by recompiling the fixed C preprocessor module (generating both 'sqlmodname' and 'sqlowner' as static variables instead of global variables) and recreating a new C Preprocessor.

Signed off 03/07/89 in release A02.00

KPR #: 4700688226 Product: HP SQL/300 79725A 00.00

Keywords: ISQL

One-line description:  
ISQL exhibits transaction errors when loading large table from external.

Problem:  
ISQL gives the user multiple (~12) duplicate error messages indicating a transaction is not in progress when the user tries to commit work (DBERR 2102) after loading a large number (3477) row of data into a table. This seems to occur only when the database has been loaded with a fair amount of data (it does not occur when the data is initially loaded). This problem does not seem to be dependent on a particular table (any large table will do).

Cause:  
This problem is caused by loading large amounts of data at a time into a database that already contains a fair amount of data.

Temporary solution:  
Use LOAD PARTIAL to load smaller amounts of data at a time.

Fix information:  
This problem will be fixed for release 2.00.

Signed off 12/19/89 in release A02.00

KPR #: 4700712463 Product: HP SQL/300 79725A 01.01

One-line description:  
FORTRAN preprocessor doesn't allow underscore in variable names

Problem:  
The Fortran/300 preprocessor does not allow underscore in variable names.

Cause:  
This problem is caused by the Fortran/300 preprocessor not allowing underscore in variable names. The Fortran/800 preprocessor allows underscore. The problem will be fixed upon completion of the 800/300 code resync.

Fix information:  
This will be fixed in the resync (release 6.5).

KPR #: 4700712463 \*\*CONTINUED\*\*

Signed off 03/07/89 in release A02.00  
Duplicate Service Requests: 5000433540

KPR #: 4700713743 Product: HP SQL/300 79725A 01.01

One-line description:  
Incorrect and nonexistent error msg (DBERR 3045) output

Problem:  
Described in Submitter Text.

Cause:  
Described in Verifier Text.

Fix information:  
Fixed in HP SQL/300 Release 2.0 on 6.5 which is the re-synced code.

Signed off 12/21/89 in release A20.00

KPR #: 4700714352 Product: HP SQL/300 79725A 01.01

One-line description:  
select while in unwritable directory causes abort from isql

Problem:  
ISQL gives a cryptic error message and aborts when the user tries to do a SELECT after invoking ISQL from a directory that is not writable.

Cause:  
ISQL tries to create a temporary file when doing a SELECT. When the directory is not writable, ISQL is not able to do this. This error condition should be handled better by ISQL by giving the user a better error message and not aborting.

Fix information:  
This will be fixed for the 6.5 release.

Signed off 03/07/89 in release A02.00

KPR #: 4700720177 Product: HP SQL/300 79725A 01.01

One-line description:  
ER to keep daemon from outputting errors to /dev/console

Problem:  
The 1.01 software had this problem. With the 6.5 software, one can do a 'mesg -n' to disable writing to the console. The daemon will then write its messages to /tmp.

Cause:  
On 1.01 the daemon would abort if it did not have write permission

KPR #: 4700720177 \*\*CONTINUED\*\*

on the console. With 6.5, if it can't write to the console, it will simply write its message to /tmp.

Fix information:

This will be fixed in release 6.5 on the 300s.

Signed off 03/09/89 in release A06.05

Duplicate Service Requests: 4700720169

KPR #: 4700740589 Product: HP SQL/300 79725A 01.01

One-line description:

Internal error occurs in a query with 2 aggregates in an expression.

Cause:

The bug was due to two factors:

1. Internally, only enough space for the number of select items was allocated, not for the number of columns referenced within the select items.
2. The count distinct required a sort. Since the sort list is allocated right next to the select list internally, when the select list was lengthened due to items referring to more than one column, the new items were written over when the sort list was generated (in the space allocated for it)

Fix information:

To fix this problem, sufficient space was allocated for the select item list to handle the case when more than one column is named in a single select item.

This fix will appear in the HP-UX/300 7.0 release.

Signed off 12/27/89 in release A02.00

KPR #: 4700743401 Product: HP SQL/300 79725A 01.01

One-line description:

For certain decimal type fields, negative numbers are stored as positive

Problem:

When inserting negative decimal values into decimal columns, if the number of digits after decimal point matches exactly the scalar of the column defined, and the precision is bigger than 7, then the negative sign will be lost:

e.g. Column defined as: Decimal (9,2)  
 Value entered : -12.50  
 Result : 12.50

Cause:

This is due to a problem in HP SQL that at runtime the minus sign is lost if:

KPR #: 4700743401 \*\*CONTINUED\*\*

- 1) The input format has the same scalar as the column definition;
- 2) the input value takes a smaller storage space than the column e.g. decimal (9,2) takes 8 bytes but -2.45 takes 4 bytes.

Fix information:

The fix is in HP SQL so that it references the correct sign bit location.

The work around is to enter data where scalars between the entered value and the column definition are different.

Signed off 12/29/89 in release A02.00

Duplicate Service Requests: 4700748301

KPR #: 4700747246 Product: HP SQL/300 79725A 01.01

One-line description:

4053 on an update of a table with multiple indexes

Cause:

The problem appeared because in attempting to locate the update column(s) in the index column list(s), the search continued past the end of the list(s).

Fix information:

The fix will appear in HP SQL/300 release 7.0.

Signed off 12/27/89 in release A02.00

KPR #: 4700748368 Product: HP SQL/300 79725A 01.01

One-line description:

DBCORE 285 caused by application with CS (or RC) and ORDER BY clause.

Problem:

BEGIN WORK CS;  
SELECT ... ORDER BY ...;

The above sequence returns a DBCore error 285.

Cause:

IS-Level CS or RC is not supported on list scan since there is no concurrency issue on temp table (temporary table is owned by only one user). SQLCore should be using RR whenever it scans a temporary table.

Temporary solution:

Build an index on the order by column would be one work around. Another way is doing the query in RR IS-Level.

Fix information:

The fix involved making sure that the correct isolation level was used on the sorted data.

KPR #: 4700748368 \*\*CONTINUED\*\*

This fix will be in HP SQL/300 Release 7.0.

Signed off 12/27/89 in release A07.00

KPR #: 4700753293 Product: HP SQL/300 79725A 01.01

One-line description:  
With NEQ operator, tuples w/ unknown search condition value are returned

Problem:

When a factor containing an NEQ operator is evaluated at the DBCore level, tuples for which the value of the search condition is unknown will be returned, violating ANSI SQL1.

Cause:

When a factor containing an NEQ operator is evaluated at the DBCore level, SQLCore fails to AND a null test with the factor, causing the incorrect results.

Temporary solution:

A temporary workaround is to explicitly include a null test in the query. For example,

c1 <> 10

would become:

(c1 <> 10) and (c1 is not null).

Fix information:

This defect will be fixed in release 7.0.

Signed off 12/29/89 in release A07.00

KPR #: 4700768077 Product: HP SQL/300 79725A 01.01

One-line description:  
Query with 13 between clauses fails with DBCore Internal Error 216.

Problem:

Dbcore was issuing bus error (error number 216) when a query had more than 13 'and' conditions. The stack size in one of the Dbcore module was not sufficient enough and a null pointer was referenced. This problem was only on 300.

Cause:

Please see problem text.

Fix information:

This problem has been fixed in release 7.0 IC2.

Signed off 01/02/90 in release A07.02

KPR #: 4700768416 Product: HP SQL/300 79725A

Keywords: SFK ISQL

One-line description:  
UNLOAD EXTERNAL using SELECT on a Japanese database aborts ISQL with (0)

Problem:  
ISQL aborts when the user who is using a multi-byte language (such as Japanese) enter an UNLOAD EXTERNAL command that contains a SELECT clause.

Cause:

This problem is caused by ISQL not properly handling the UNLOAD EXTERNAL SELECT clause properly in the case on multi-byte languages.

Temporary solution:

To work around this problem, create a view with the desired SELECT clause and then UNLOAD the data from the view.

Fix information:

This problem will be fixed in release 7.00 IC1.

Signed off 12/19/89 in release A07.00

KPR #: 4700776633 Product: HP SQL/300 79725A 01.01

One-line description:

ISQL help text examples should display the semicolon at end of command.

Problem:

The examples in the online HELP text should contain semicolons. Some currently do, but most do not.

Cause:

Not all examples in the ISQL HELP text end with a semicolon. All examples should contain semicolons.

Temporary solution:

Always add a semicolon to the end of all queries entered through ISQL.

Fix information:

Semicolons ';' have been added to the examples of help text. This will go out on Rel 7.00 IC2.

Signed off 12/19/89 in release A07.00

KPR #: 4700776641 Product: HP SQL/300 79725A 01.01

One-line description:

Incorrect error msg from ISQL when ran out of disk space for tmp file.

Problem:

ISQL prompts the user to mount another tape when it runs out of space in the directory. It should give the user a better error

KPR #: 4700776641 \*\*CONTINUED\*\*

message when this happens and not prompt them for another tape.

Cause:

The HP-UX operating system returns the same error message when it has reached the end of the tape as when it has used all the available disk space within the directory. ISQL needs to determine what device is causing the error before deciding whether to prompt the user for another tape or tell the user there is no more space in their directory.

Fix information:

The error message has been updated to take into consideration for both the tape and disk storage devices. In addition, a DBWARN message is issued when the device is full. This will go out on REL 7.00 IC2.

Signed off 12/19/89 in release A07.00

KPR #: 4700777813 Product: HP SQL/300 79725A 01.01

One-line description:  
Problem with using ISQL on 700/43 terminals

Problem:  
ISQL uses HP Escape characters to clear the screen, highlight text and underline text. Two new terminals, the 700/41 and 700/43 do not support these escape characters. As a result the screen is not cleared when ISQL is invoked and the SELECT output is displayed. It also causes problems when displaying HELP text, since highlighting and underlining are done regularly when displaying this text.

Cause:  
Two new terminals. the 700/41 and 700/43 do not support the HP escape characters. ISQL uses these when displaying HELP text, clearing the screen for SELECT output and clearing the screen when invoking ISQL.

Temporary solution:

It is not critical that the screen get cleared when invoking ISQL or displaying the SELECT data. The main problem is in using the HELP text. To work around this problem, the ISQL and SQL Reference Manuals should be used instead of the online HELP facility within ISQL. Note that there is a summary of ISQL and SQL syntax in appendices A and B of the ISQL Reference Manual.

Fix information:

All control characters have been replaced by special characters. (eg. '=' '-'). The should be out on Rel 7.00 IC2.

Signed off 12/19/89 in release A07.00

KPR #: 4700778951 Product: HP SQL/300 79725A 01.01

One-line description:  
hpdbdaemon dies on CONNECT (error 1067) on S300 w/ floating pt accel.

Problem:

The hpdbdaemon was not passing a properly sized buffer in a system library call on the 300 which caused other variables to be overwritten. One of these variables was the DBCon name which then caused the 1067 error. Only users running on 300 hardware including the floating point co-processor and the floating point accelerator would potentially hit this problem.

Cause:

Please see problem text.

Fix information:

The buffer size on the 300 for the library call has been corrected. This problem will be fixed in release 7.0

Signed off 01/02/90 in release A07.01

KPR #: 4700793570 Product: HP SQL/300 79725A 01.01

One-line description:

After update or delete, opened cursor reads old data within transaction.

Cause:

There is a problem with cursor sensitivity in HP SQL within a transaction. If a cursor is defined and opened, and within this transaction updates or deletes are performed which effect the result of the cursor, these changes are not reflected when using the cursor.

So if a delete is performed for example by the user within the same transaction as the cursor, a fetch from the opened cursor may still retrieve tuples which were deleted.

KPR #: 4700794388 Product: HP SQL/300 79725A 02.00

One-line description:

HP SQL is utilizing a large amount of swap space.

Problem:

HP SQL is utilizing a large amount of swap space.

Cause:

The scheme for attaching shared memory was preallocating heap space causing the system to wastefully allocate swap space.

Fix information:

A new scheme was developed for attaching shared memory which was not dependent on preallocation of heap space. This fix is available in a patch (HP SQL rev. 2.00, NET rev. 1.01)

Signed off 12/20/89 in release X07.03

KPR #: 4700795872 Product: HP SQL/300

79725A 02.00

One-line description:  
DBCORE reports "out of disc space" even though entire file is avible.

Problem:  
When the temporary relation is dropped and a new transaction is started, Dbcore was generating the same transaction id. This was causing the problem of out of space.

Cause:  
See problem text.

Signed off 01/08/90 in release A07.01

KPR #: 4700795898 Product: HP SQL/300 79725A 02.00

One-line description:  
2060, 2066 during load, select - following large delete.

Problem:  
The problem here is that in situations where a user deletes a large number of the highest keys from an index the index gets corrupted causing errors such as 2066 and 2080.

Cause:  
The cause of the problem is that DBCORE depends on special high value entries being the last entry on all non-leaf levels of a btree index. When enough of the highest entries in an index are deleted to delete a highest page at a non-leaf level then we are left with a level which does not have a high value entry.

A possible work around would be to keep record with an index key higher than any real record in the database at all times.

Temporary solution:  
This problem causes corruption in the index, but not in the data. A workaround is to drop the index and recreate it, if this problem is encountered.

Signed off 01/08/90 in release A07.01

KPR #: 4700795914 Product: HP SQL/300 79725A 02.00

One-line description:  
DBERR 4008 on query with BEGIN WORK RC or CS and involving sort.

Signed off 01/02/90 in release A07.02

KPR #: 4700803395 Product: HP SQL/300 79725A 01.01

One-line description:  
Data corrupted on 2048 byte when entering char string > 2048 bytes

Problem:  
There was a problem obtaining memory for an internal buffer



KPR #: 4700803395 \*\*CONTINUED\*\*

when the first allocation is greater than 2k. Therefore, the value would be corrupted after the 2k offset.

Cause:  
Only 2k bytes was being allocated for the value.

Fix information:  
Fixed in the 7.0 HP SQL Release.

Signed off 12/20/89 in release A07.00

KPR #: 4700820704 Product: HP SQL/300 79725A 01.01

One-line description:  
Query result was sorted in ASC order although DESC was specified.

Problem:  
A query where an descending order was specified may come out in ascending order if it involves a join with an equal predicate and indexes are available on the table.

Cause:  
A new sort merge join algorithm is incompatible with a sort optimization algorithm using indexes. If the optimizer chooses to employ both algorithms, the results may not come out in the specified order.

Fix information:

A fix was made to disallow both sort merge join and index sort optimization at the same time. This fix will be available in UX release A.07.00.13.

Signed off 11/15/89 in release A70.00

KPR #: 4700829655 Product: HP SQL/300 79725A 01.01

One-line description:  
The bugcatcher on the 300 aborts with segmentation violation

Problem:  
The bugcatcher on the 300 aborts with segmentation violation.

Cause:  
There was a bug in one of the 300-specific debug include files.

Fix information:  
Fixed in a post pass 15 IC3 D.0 version. This version does not exist as yet (as of 10/6/89 0900 HRS), but when it does, the version will be A.07.03.16 (UX) and A.20.03.16 (XL).

Signed off 12/18/89 in release A07.03



KPR #: 4700829952 Product: HP SQL/300 79725A 07.00

One-line description:  
An ALTER TABLE section in a 2.0-migrated 7.0 database fails for FLOATs.

Problem:  
MDD is attempting to run an application compiled on 6.5 UK/300, with a database which was created on 2.0 SQL and then migrated to 7.0 using SQLMigrate. This means they will have old (2.0) stored sections in the database, which HP SQL should be detecting and correcting for automatically. It also means that the program was linked with 2.0 libsql.a, which will cause any prepare or execute immediate statement to also build 2.0 stored sections for execution. So, whether they execute an alter table directly as in:

```
EXEC SQL ALTER TABLE t1 ADD c1 FLOAT;
```

or do it with a prepare:

```
EXEC SQL PREPARE MOD1 FROM 'ALTER TABLE t1 ADD c1 FLOAT';
```

they will be using 2.0 input structures to SQLCore.

This problem will also appear in the CREATE TABLE command, when the command defines a FLOAT column, in the 2.0 -> 7.0 migration path (2.0 stored sections in a 7.0 database).

Cause:

The cause of the problem is that we were not correcting an input node which should have been automatically upgraded. When we added FLOAT precision specification, this altered the structure for defining columns in tables. This structure should have been marked as needing SQLCore migration, but it was not. So the old structure was used unchanged. That structure did not declare a precision for FLOAT columns, but left it 0. Since 0 is now an invalid FLOAT precision (the range 25 - 53 is valid in HP SQL Release 7.0), the error message is generated. If the node had been corrected properly, the precision would have been set to 53 (the default).

Temporary solution:

A workaround which will remove the old 2.0 input structures is to recompile the application on 7.0. Then, the new (corrected) 7.0 input structures will be generated and the problem will not appear.

Fix information:

This problem will be fixed in the 300 7.0 patch and will be available for a 800 7.0 and XL 2.0 patch. It will also be fixed in the XL 2.1 and UK 8.0 releases.

The fix will cause a low-priority problem described in SR # 4700-833590. This bug allows FLOAT(0) to be accepted and processed as a FLOAT(53) in CREATE and ALTER TABLE. This was the only way to efficiently and properly fix this bug in a release without impacting future releases. That SR will be fixed in a future release.

KPR #: 4700829952 \*\*CONTINUED\*\*

Fixed in HP SQL Patch Release A.07.00.17 on HP/UX, and A.20.17 for MPE/XL.

Signed off 01/11/90 in release A07.17

KPR #: 4700835561 Product: HP SQL/300 79725A 07.00

One-line description:

Incorrect query results for OR predicate with null indicator set.

Problem:

HP SQL may return incorrect query results when the predicate includes an OR operator and null indicators.

Cause:

When the predicate includes parameters (host variables) that may be null (have null indicators), SQLCore generates code to test for null parameters at runtime. If any parameter is null, no tuples will be returned. However, when the predicate includes one or more OR operators, one or more parameters may be null, but there may still be a result.

Temporary solution:

A temporary workaround is to make the source reference an arithmetic expression (e.g., multiply column by 1). This will force evaluation at the SQLCore level.

Fix information:

This defect will be fixed in the 8.0 and later releases. It is also available for a 7.0/2.0 patch.

Fixed in HP SQL Patch A.07.00.18(HP/UX), and A.20.18(MPE/XL).

Signed off 01/11/90 in release A07.18

KPR #: 4700837666 Product: HP SQL/300 79725A 07.00

One-line description:

While testing FIPS, a particular query hangs.

Problem:

The problem is in the processing of the BETWEEN clause in the grammar and the HAVING clause in the linearizer. The BETWEEN clause is transformed into the equivalent comparison (LHS >= V1 and LHS >= V2); the HAVING clause attempts to transform this predicate, and when it pulls out the second copy of the LHS, it corrupts an internal structure.

Fix information:

The fix is for the HAVING linearization to check that an item is not already in the internal structure before attempting to place it there. No where else does the processing of BETWEEN cause this problem.

This will be fixed in the 9000/800 and 9000/300 UX Release 7.0



KPR #: 4700837666 \*\*CONTINUED\*\*

patch, and in the XL 2.1 release.  
Fixed in HP SQL Patch Release A.07.00.17 on HP/UX, and  
A.20.17 for MPE/XL.

Signed off 01/10/90 in release A70.16

KPR #: 4700839928 Product: HP SQL/300 79725A 70.00

One-line description:  
Backend process core dump due to unable to allocate free page buffer.

Problem:  
The problem was that DBCore could not find a free page buffer and  
then a core dump was generated for the query mentioned on the lab  
text.

- Jenny Shieh

Cause:  
There were two reasons for this bug. The core dump was caused directly  
by the invalid value of NOP (number of parameter) in an instruction  
which was not in the range of a case statement in JTRUN. The further  
reason for the invalid value of NOP was caused by the inner block.  
When the inner block encountered error 261, it did not switch  
the code buffer pointer back to the original one for the outer  
block before popping out to the system. So when the outer block  
executed the next fetch, it used the wrong code buffer pointer of the  
inner block to execute its op codes. Unfortunately the NOP value  
was invalid, the core dump was generated.

- Jenny Shieh

Fix information:

This fix will be available in XL release A21.05 and UX release  
A08.00.00. It will also be available in a patch release for UX 7.0  
as version A07.00.18.

Signed off 01/11/90 in release A70.18

KPR #: 4700842989 Product: HP SQL/300 79725A 07.16

One-line description:  
Pascal runtime error returned from ISQL processing Japanese input > 2k

Problem:  
ISQL returns pascal runtime error in certain cases of NLS input > 2k.

Cause:  
A previous fix to a non-NLS problem caused this. String routines in  
the non-NLS fix spanned across NLS code, as a result (because NLS string  
routines are different) we may get a pascal runtime abort.

Temporary solution:

There is no temporary solution to this problem. It all depends on the

- HP SQL/300 -

KPR #: 4700842989 \*\*CONTINUED\*\*

type of NLS data you use.

Fix information:

This problem has been fixed and will go out with rel 7.0 patch and rel  
8.0.

This problem also occurs in rel ux03.01.07 and will be fixed in rel  
ux03.01.08.

KPR #: 4700849927 Product: HP SQL/300 79725A 01.01

One-line description:  
ISQL is not checking for overflow on a 4 byte FLOAT.

Problem:  
The ranges of a 4 byte float is not checked when loading through ISQL.

Cause:

Overflow checking on Unix is only reported for double precision floats,  
a 4-byte float will never get an overflow error.

Temporary solution:

Check through the input file for 4 byte float values manually.

Fix information:

The problem has been corrected and will go out with rel ux 8.0.

KPR #: 4700852574 Product: HP SQL/300 79725A 07.00

One-line description:

Internal error on join query including OR and ORDER BY, GROUP BY, DISTINCT

Problem:

An internal error may occur when a join query includes both an  
OR operator in the predicate, and an ORDER BY, GROUP BY or  
DISTINCT clause.

Cause:

The internal error occurs because the internal optimization tree  
is not maintained correctly in certain cases.

Fix information:

This fix will appear in a 2.0/7.0 patch, and in releases 3.0  
and 8.0.

KPR #: 4700855932 Product: HP SQL/300 79725A 07.18

One-line description:

Changing the select list on a 5 table join query returns fewer rows.

Fix information:

Fixed in HP SQL HP/UX PATCH for 7.0.

- HP SQL/300 -

KPR #: 4700857938 Product: HP SQL/300

79725A

70.00

One-line description:

Integer Overflow on Operation Convert when inserting min integer value.

Problem:

On the 300 only, HP SQL will not accept an INSERT of the minimum integer value allowed. A DBERR condition is generated, overflow on operation convert.

Cause:

HP SQL is reading the value in as a decimal, and converting it to an integer. The convert routine blindly converts the positive value to an integer, which is greater than the maximum positive integer allowed. Thus an error condition arises. The convert routine must check if it is converting the smallest integer allowed before blindly converting it as a positive value, and then setting the sign at the end of the convert.

Fix information:

Will be fixed in HP/UX 8.0.

KPR #: 4700858837 Product: HP SQL/300

79725A

07.00

One-line description:

Sort is returning bad data on select on >16 col table with index.

Problem:

A SORT operation (on any column > #16 in the projection list of the table) is returning bad data for that column.

Cause:

The bug is very simple. A SORT projection list can never exceed 16 columns (we know that). A table projection list can have as many as 255 columns (we know that too).

The way we create a SORT projection list is as follows. We take the table projection list and create a subsetted inversion of it into the SORT projection list.

For that reason, although the SORT projection list will NEVER have more than 16 active elements, it needs to be as big as 255 elements - just because of the implementation. Well, it was only 16 elements long. Consequently, we were corrupting the local variables on the stack immediately following the SORT projection list declaration.

What follows can be anybody's guess. It is a surprise the user query was not aborting.

Fix information:

Fixed in D.0 DBCORE versions A.07.03.17/A.20.03.17).

Signed off 02/20/90 in release A70.17

KPR #: 4700859488 Product: HP SQL/300

79725A

07.00

One-line description:

INSERT of REAL number outside of legal negative range is not trapped.

Problem:

Insert of a REAL number outside of the range is not trapped as pointed out in the submitter text. DBERR 1022 should be generated.

Cause:

Instead of error 1022, the value 0.0 would be inserted. The cause was that recover logic for aborts(underflow/overflow of numeric data) was not checking the right escapecode for the 300. Instead of generating the DBERR 1022, processing of the INSERT would continue with a value of 0.0.

Fix information:

Fixed in HP SQL HP/UX 8.0.

KPR #: 4700859660 Product: HP SQL/300

79725A

07.00

One-line description:

Arithmetic computation results in an integer underflow condition.

Problem:

An arithmetic operation on that would result in a integer underflow condition (minint/2.0) was not being trapped with an error condition(DBERR 2600) at run time.

Cause:

A case statement for RECOVERY of such an abort did not include the 300 integer underflow case.

Fix information:

Fixed in HP SQL HP/UX 8.0.

KPR #: 4700863472 Product: HP SQL/300

79725A

08.03

One-line description:

"DBCon File invalid-DBERR 3066" expected but DBERR 3078 reported on 300.

Problem:

On HP SQL HP/XU 300 only, DBERR 3078 is not being reported but instead DBCon File invalid-DBERR 3066.

Cause:

A fix was made for this mapping in a section of compiler option code for the 800, but was never applied to the 300 specific code. Thus, the incorrect mapping of the return code occurs.

Fix information:

Fixed in HP SQL HP/UX 300 Release 8.0.

KPR #: 4700869537 Product: HP SQL/300

79725A

00.00

One-line description:  
DBERR 8207 returned by SHOWDBE command in SQLUTIL.

Problem:  
While executing a SHOWDBE command of SQLUTIL under another user's directory, DBERR 8207 "Operation not performed; illegal capability" was received. However, the command was executed without problem.

Cause:  
Redundant checks are performed in SQLUTIL, causing the incorrect error message.

The real cause of the problem is when SQLUTIL tries to obtain the maintenance word for the current user. If this fails, the error message 8207 will appear. But only for that attempt. The rest of the command will continue to execute.

Temporary solution:  
Ignore the DBERR 8207 if you didn't enter a maintenance word.

Fix information:  
Code has been changed so that if the user made no attempt to get the maintenance word, they will not get the error.

This will be fixed in Ux 8.0.

KPR #: 4700875468 Product: HP SQL/300 79725A 00.00

One-line description:  
Missing tuple in a multi-user KC test

Problem:  
This problem can manifest in 2 ways:

1. Error 2060 is generated when a tuple (record) is updated or deleted.
2. In a SQL command where an index scan is used, a key may not be found where it actually exists.

An index scan may be used on a SELECT, FETCH, UPDATE, or DELETE. When a key is not found, no error is returned. The problem can occur with heavy updates on a b-tree index. In other words, the b-tree keys need to be updated heavily where b-tree pages will be deleted and created.

If a SQL application updates index keys, then the index's integrity should be checked, regardless of having an error returned or not. The best way to check a b-tree index integrity is to use a fast tool. Until such a tool is available, there is a work around to check a b-tree index integrity.

KPR #: 4700875468 \*\*CONTINUED\*\*

TEMPORARY WORK AROUND FOR INDEX INTEGRITY CHECK:

The temporary work around may be slow especially with a large table. Simply issue the following command:

```
DELETE * from TABLE;
ROLLBACK WORK;
```

The delete command will consume log space. Log should be large enough to allow the delete to complete successfully. Note that a rollback command is issued after the delete because the intent is not to delete but to check the integrity of the index.

In a manufacturing environment, the integrity of indexes may be checked one at a time during slow hours.

HOW DELETE CHECKS THE INTEGRITY OF THE INDEX:

To delete all the rows in a table, a table scan is executed. For each row, we will search for the corresponding key in each of the table indexes. If the delete command returns no error, then each index for the table is good. If an internal error (2060, 2060) is returned, then one of the table's indexes is bad. This index should be dropped and recreated. It is highly recommended to drop all the indexes and recreated.

CAUSE TEXT:

The handling of page free and page add (split) was incorrect. Heavy updates to the index can cause a key to be inserted in the wrong place.

FIX INFORMATION:

Once an index is checked and is found good, the fixed software will ensure that the discussed type of corruption will not reoccur. With recreated indexes, the fixed software provides the same insurance. By attempting to keep existing indexes good, a local space problem may occur where an error (1025) may be returned. In such a case, the index should be dropped also, and recreated.

Fix information:  
Fix available in:

UX	XL
A.07.03.23	A.20.03.23
A.71.02.11	A.21.02.11
A.08.01.05	A.30.01.05

KPR #: 4700875468 \*\*CONTINUED\*\*

Note that with the D.0 fix, there will also be the possibility that newly created indexes (or index uncorrupted so far) may generated a "no space" condition. This is a real corner case, and will force users to drop and recreate their indexes when it happens. But ALLBASE is guaranteed NEVER to corrupt indexes because of this bug any more.

Signed off 02/21/90 in release A70.23

KPR #: 4700876060 Product: HP SQL/300 79725A 01.01

One-line description:  
DBERR 13262 and RC 196 on SELECT w/ IN predicate during regression test

Problem:

A query containing an IN predicate with host variables and null indicators, and three or more values in the list may fail with an internal error.

Cause:

This defect results because the parse tree built is not in the form required for OR optimization, and the predicate tree size is calculated incorrectly.

Fix information:

This defect will be fixed in the XL 3.0 and UX 8.0 releases, and will be available for a 7.0/2.0 and 2.1 patches.

KPR #: 4700876128 Product: HP SQL/300 79725A 02.00

One-line description:  
SQL may choose force index plan when standard plan is better.

Problem:

Non-optimal performance may be observed for some queries containing ORDER BY, GROUP BY, and/or DISTINCT.

Cause:

The SQL optimizer may sometimes choose a force index plan (i.e. use an index scan instead of performing a sort), when the standard plan would be better.

Fix information:

This fix will be in release 8.0.

KPR #: 4700876516 Product: HP SQL/300 79725A 00.00

One-line description:  
DBCORE error 2060 from aci\_fetchc (reproducible through Info Access)

Problem:

Corrupted DBEFILE0 in an application where the parent process is constantly being killed and restarted.

KPR #: 4700876516 \*\*CONTINUED\*\*

Cause:  
The parent application is closing and reopening the 3 STD files before and after connecting to the DBE. We have a problem with HP SQL in that it writes to STDLIST and STDERR (i.e. fds 1 and 2) all the time. If the parent is closing these files before forking hpsqlproc, the fds 1 and 2 may correspond to some DBE files. That will do it.

Problem is UX specific.

Fix information:  
This fix will be available in UX 8.0 and following releases as well as patch releases for UX 3.1 and UX 7.0.

KPR #: 4700877282 Product: HP SQL/300 79725A 70.00

One-line description:

HP SQL internal error (MPE-XL Error 16) occurred: nested query testing

Problem:

The problem for this SR is the query got an underflow value so that the system cannot continue to finish the query.

Cause:

The problem is caused by an uninitialized CS2 value in a join plan. The system uses a garbage value in the memory to represent CS2. If the value is extremely small, then the query gets underflow.

Fix information:

The fixed is on XL 2.1 release, and UX 8.0 release.  
Fixed in HP SQL Patch Release A.07.00.17 on HP/UX, and A.20.17 for MPE/XL.

Signed off 05/07/90 in release A70.17

KPR #: 4700878447 Product: HP SQL/300 79725A 70.00

One-line description:

Error 139 may be returned with Read Uncommitted during a timing window.

Problem:

Error 139 may be generated if Read Uncommitted is used with a reverse table scan.

CAUSE TEXT:

The RU latch was not requested on reverse relation scan.

FIX INFORMATION TEXT:

Fixed available in:

UX XL

E.0 A.80.06 A.30.06

KPR #: 4700878447 \*\*CONTINUED\*\*

This defect will not be fixed for D.0 (XL 2.0, UX7.0) or XL 2.1 due to the low probability of its occurrence.

KPR #: 4700882936 Product: HP SQL/300 79725A 00.00

One-line description:  
Large variable index keys do not work correctly.

Problem:  
Sometimes, the INSERT/UPDATE of a large key (about 990+ bytes) generates an internal error 2080.

Cause:  
Currently, the way index page splits work, if a new key value comes along and there is not enough room on its candidate page, the index manager will split this page, put one half of the current tuples in one page, the remainder in the second one, and then try to insert this new value.

It is totally possible that even after this split, we do not manage to fit the new tuple in its (new) candidate page. At this point, respitting this page is a problem. Here is where the index manager was getting confused.

Fix information:  
Fix available in:

D.0	UX	Exists, not fixed	XL	Exists, not fixed
D.1		Exists, not fixed		Exists, not fixed
E.0		A.08.01.06		A.30.01.06

KPR #: 4700882951 Product: HP SQL/300 79725A 07.00

One-line description:  
Error 1058 result on update after no more tuples code is returned.

Problem:  
Error 1058 is generated on a KEEP CURSOR test with CS.

Cause:  
The cause is currently under investigation. It seems that if an UPDATE is issued after the most recent FETCH returns a "no more tuples", DBCORE acquires a latch (which latch?) and does not release it before getting back to the command manager.

Fix information:  
Problem will be fixed for E.0, but not for D.0 or D.1:

D.0	UX	Will not be fixed	XL	Will not be fixed
D.1		Will not be fixed		Will not be fixed

KPR #: 4700882951 \*\*CONTINUED\*\*

E.0 A.08.01.06 A.30.01.06

KPR #: 4700882985 Product: HP SQL/300 79725A 07.00

One-line description:  
KEEP CURSOR scans can proceed with no system relations locks

Problem:  
A low level test showed that a KEPT scan, upon COMMIT WORK, maintains relevant locks on user tables and indexes, but releases locks on DBCORE directory tuples.

This makes it possible for another application to DROP the table or index being used by this KEPT scan.

Cause:  
We have discovered a not too complex, but basic problem with the way KEEP CURSOR handles locks on DBCORE directory objects. Please see lab text if you can for details. Otherwise, the following high level explanation should suffice.

The basic theme is that the problem is caused by the same user transaction that deals with multiple cursors. Further, there HAS to be some overlap between the objects locked by these two cursors.

The following facts should clarify the issue:

1. An OPEN SCAN on a table will always lock the following low-level DBCORE objects:
  - a. The table tuple in the low level directory (S lock)
  - b. The page in which this tuple resides (IS lock)
  - c. The low level directory table (IS lock)

And of course, if this is an index scan, the same a,b,c set is acquired for the index tuple (and associated page and table).

2. The sequence in which locks are acquired are a,b,c.

3. At any point in the sequence, if a lock is found to be already acquired by the transaction, the scan manager will assume that all higher locks are also held, and will try no further.

This is the right thing for us to do. However, with cursor stability and KEEP CURSOR etc, every scan needs to be individually aware of EVERY lock that is associated with it WHETHER or not this lock was explicitly acquired by this OPEN CURSOR.

4. Every lock is aware of "how many cursors depend on it". But this awareness is limited only to the cursor that explicitly obtained the lock.

KPR #: 4700882985 \*\*CONTINUED\*\*

5. If the cursor that explicitly acquired the lock(s) now does a CLOSE CURSOR, and the transaction now COMMITS, these locks will be released. However, there may still be a KEPT CURSOR that indirectly acquired the lock, and still needs the lock for the next implicit transaction.

6. Now this KEPT CURSOR that is still alive continues on to FETCH more records from the table/index, and all along, this transaction is missing some key directory locks.

7. Now, some other user comes along and drops this table on which this active cursor is running. But the cursor is merrily running, reading what it thinks is valid data.

The reason why the DROP TABLE will succeeds is that it only checks to see if the table tuple in the DBCORE directory is locked. That alone will tell it if it is okay to DROP TABLE.

Fix information:

We have decided that while this is a pretty bad bug, (a) it can only happen when there is destructive DDL going on.

(b) to fix this bug, new routines need to be added. Do we really want to fix it for UX 7.0/XL 2.0 and XL 2.1?

At this point, we feel that we will fix it for E.0, and nothing else.

UX XL

E.0 A.80.01.08 A.30.01.08 (Proposed)

KPR #: 4700883009 Product: HP SQL/300 79725A 00.00

One-line description: DBCORE existence not being verified in rollforward recovery

Problem: HPIMAGE basically uses the extend chunk feature during rollforward recovery. DbcCore w &dBas not replaying the pages for the extend &@ chunk and thus the recovery wasnot completed.

Cause:

Dbcore was reinitialising the pages to the newest version at the time of recovery. And this didnot allow the recovery to replay the pages.

To fix the problem, we reinitialised the pages to lowest version number. The file affected was "dtfoch".

Temporary solution:

KPR #: 4700883009 \*\*CONTINUED\*\*

At this point, we do not allow rollforward recovery through a CREATE DBEFfile command. The temporary workaround would be for the user to perform all the CREATE DBEFfiles and then do a STORE of the entire environment.

We will seriously investigate fixing this bug in the very near future.

7/19/88

KPR #: 4700883033 Product: HP SQL/300 79725A 00.00

One-line description: DBCore Internal Error 1057 returned when log full during SORT.

Problem:

Yet another case of attempting to exit DBCORE without unpinning all pinned pages.

Cause:

After a SORT operation fails on a normal error (out of space etc) this may happen.

Fix information:

Fix available in:

UX XL  
D.0 Not to be fixed Not to be fixed  
D.1 Not to be fixed Not to be fixed  
E.0 A.80.00.03 A.30.00.03

KPR #: 4700883280 Product: HP SQL/300 79725A 01.01

One-line description: "HPSQL not running" appears twice for commands after TERMINATE USER

Problem:

If after issuing a TERMINATE USER command for himself/herself the user issues a SELECT command they will be the message "HP SQL not running (DBERR 2100)" twice. Only one occurrence of this message is necessary.

Cause:

The SELECT command will cause ISQL to issue multiple "HP SQL not running (DBERR 2100)" messages after a TERMINATE USER operation is done.

Temporary solution:

Ignore the extra message.

Fix information:

Fixed in ALLBASE/SQL HP/UX release 8.0.

KPR #: 4700883306 Product: HP SQL/300 79725A

01.00

One-line description:  
Must enter EXIT; a few times to exit ISQL when user #2 does a STOP DBE

Problem:

When in multi-user mode and another user issues a STOP DBE, ISQL does not correctly recognize that the DBE has been stopped and requires the user to enter multiple EXIT commands to EXIT from ISQL.

Cause:

ISQL does not correctly test for a STOP DBE being done by another user. As a result, when a DBCORE error is encountered when trying to EXIT from ISQL, ISQL simply reports the error back to the user and aborts the command. It is not till several errors are encountered does ISQL realize that no database is connected to and it allows the user to exit ISQL.

Temporary solution:

Proceed with entering EXIT and ignore the extra messages.

Fix information:

This problem will be fixed in Rel 8.0.

KPR #: 4700883322 Product: HP SQL/300 79725A 01.01

One-line description:

ISQL: Entering 'non-existent' command gives DBERR 2102

Problem:

ISQL does not give consistent error messages for single letter commands entered after a connect is done. Since a transaction should automatically be started for the user, then all the commands should get the DBERR 2214 error message.

Cause:

ISQL does not correctly handle all unknown commands (i.e. single letter commands) consistently. Note that some single letter commands, such as "C" and "U", are valid abbreviations for ISQL commands (see CHANGE and UNLOAD).

Temporary solution:

Ignore the message if the command entered is not valid.

Fix information:

This problem has been corrected in Rel 8.0. A more appropriate message will be issued.

KPR #: 4700883330 Product: HP SQL/300 79725A 07.00

One-line description:

PASCAL preprocessor fails to preprocess SELECT COUNT(\*) FROM T1 command

Problem:

The SQL statement "SELECT COUNT (\*) FROM ..." is not processed correctly by the Pascal preprocessor. It treats (\*) as the

KPR #: 4700883330 \*\*CONTINUED\*\*

beginning of a Pascal comment block.

Cause:

The Pascal preprocessor treats comment symbols for Pascal before it scans for other tokens. Therefore when it encounters the syntax SELECT COUNT (\*) ... it assumes the two symbols (\* mean the beginning of a comment block.

Fix information:

Fixed in ALLBASE/SQL HP/UX release 8.0.

KPR #: 4700883413 Product: HP SQL/300 79725A 00.00

One-line description:

ISQL does not allow > 255 when SELECT includes joined tables

Problem:

SELECT's with greater than 255 columns in SelectList will result in DBERR 3008 using ISQL.

Cause:

ISQL calls SQL to fetch 255 columns whenever the SelectList contains more than 255 columns. ISQL has a bug on the DESCRIBE call to SQL.

KPR #: 4700883959 Product: HP SQL/300 79725A 07.00

One-line description:

Internal error 52 occurs in a joined nested query

Problem:

In a correlated nested query, the subquery is executed for each value of the outer query. If the first value of the outer query is NULL, a DBERR 4053 might occur.

Cause:

The DBERR 4053 is a result of a system bus error which occurred in trying to dereference a bad pointer.

Fix information:

This fix will be put available through a UX 7.0 patch as well as XL 2.1 and all subsequent releases.

KPR #: 4700883975 Product: HP SQL/300 79725A 07.00

One-line description:

Subquery with EXISTS hangs

Problem:

Any nested query with a subquery which makes three or more outer references may cause a hang to occur.

Cause:

The cause of the problem was an endless loop which is only hit when you have three or more outer references in a subquery.



KPR #: 4700883975 \*\*CONTINUED\*\*

Fix information:

This fix will be put available through a UX 7.0 patch as well as XL 2.1 and all subsequent releases.

KPR #: 4700886796 Product: HP SQL/300 79725A 00.00

One-line description:

HPDBDAEMON needs to be more robust in its error handling

Problem:

There are many cases where the daemon needs to shut down the environment, or just simply, report an error condition.

Under normal circumstances, the daemon's messages that go to the console are cryptic, unfriendly and not very communicative.

Cause:

The only inhibitor to doing anything about this SR was the fact that the daemon, while it does read the message catalog, does not go the extra inch of putting in parameter substitution as well. If it did, it would report the error code (at least) along with the message text.

We will fix this problem for ux 8.0 definitely. By the way, the problem is for the 800 and 300 alike.

Fix information:

Fix is UX specific. We hope to put in a fix quickly for the daemon. There is also an overall issue of friendly error trapping for DBCORE as a whole. That is a subject for a future SR.

Version numbers will be supplied as soon as they are known.

KPR #: 4700890228 Product: HP SQL/300 79725A 07.00

One-line description:

Doubly defined error for SQLCODE at compile time - ANSI conform. issue.

Problem:

If user defines a variable SQLCODE explicitly, after preprocessing the application program will have another SQLCODE variable defined, causing a "doubly defined symbol" error at compile time.

Cause:

With the SQLCode enhancement in UX 7.0 and XL 2.0, the preprocessors will insert the definition for a variable SQLCODE into the user's application. If the user already has the same variable defined (as demanded by the ANSI Level 2 standard) there will be a direct conflict.

Temporary solution:

The workaround is to not define the variable SQLCODE explicitly in the user code.

Known Problem Reports as of 11/21/90

KPR #: 4700890228 \*\*CONTINUED\*\*

Fix information:

Fixed in ALLBASE/SQL HP/UX 8.0 release.

KPR #: 4700892448 Product: HP SQL/300 79725A 07.00

One-line description:

User session waiting for a page can not be aborted due to a hang

Problem:

A user process was found hung inside an RU transaction.

Cause:

Please see lab text (if you can) for details. This hang was caused by an RU user process waiting on itself. In summary, a certain flag is set by an RU reader when it attempts to FETCH the next row from a table. If this FETCH operation fails for a valid reason (in this case, the reason was DBERR 4008 - could not allocate shared memory), this flag should be reset BEFORE attempting the internal abort-transaction.

Fix information:

Fix available in the following releases:

	UX		XL
UX 7.0/XL 2.0	A.07.03.29	A.20.03.29	
XL 2.1	A.71.02.14	A.21.02.14	
UX 8.0/XL 3.0	A.80.01.08	A.30.01.08	

Signed off 07/27/90 in release A07.29

KPR #: 4700892612 Product: HP SQL/300 79725A 01.00

One-line description:

Preprocessing "C" application with LANG=korean gives DBERRs 10908/11014.

Cause:

The cause of this problem is resulted from passing the incorrect parameter value to 'NLJUDGE' in the Preprocessor command line handling routine 'SOPTGETU' (a common routine for all Preprocessors).

The 'SOPTGETU' routine uses "sizeof()" to pass the length of the data buffer without cleaning up the buffer first. Since the buffer is declared as a packed array the "sizeof" always passes the fixed size of the buffer (from its declaration) which does not reflect the true length of the data string in the buffer, 'NLJUDGE' interprets the 'garbage' data in the buffer and returns this error!

The reason why it does not happen to LANG=japanese is that 'maybe' the 'garbage' data can be interpreted by 'japanese' collate8 table but not by 'korean' collate8 table.

Fix information:

The problem has been fixed by replacing the 'sizeof' with 'strlen'



KPR #: 4700892612 \*\*CONTINUED\*\*

to pass the data buffer length to 'NLJUDGE' in 'SOPTGETU' module.  
The fix has been submitted to Rel7.0 Pass30 (patch) release.

KPR #: 4700896944 Product: HP SQL/300 79725A 70.00

One-line description:  
Query returns DBERR 4053

Problem:  
An internal error (DBERR 4053) may occur on a query including both an aggregate distinct and a group by.

Cause:  
The internal error was due to a segmentation violation caused by accessing an array of pointers with the incorrect index variable.

Fix information:  
This defect will be fixed in the 8.0 release. A patch will be available for the 7.0 release.

KPR #: 4700899815 Product: HP SQL/300 79725A 03.00

One-line description:  
START DBE NEW should clean up ALL files in case of failure.

Problem:  
ALLBASE/UX does not clean up completely after a START DBE NEW fails for whatever reason.

Cause:  
This is just a minor bug in the code. We clean up DBECON, DBELOG1 (and DBELOG2 if there is one), but we are neglecting to clean up DBEFILE0.

Fix information:  
Target fix versions:

UX 8.0/XL 3.0 A.80.52.01 A.30.52.01

This issue will not be addressed for already released versions.

KPR #: 4700901470 Product: HP SQL/300 79725A 01.01

One-line description:  
C preprocessor appears to cause byte alignment problems with application

Cause:  
The problem is caused from the inconsistency of the alignment schemes between C (and Pascal) Preprocessor(s) and C (and Pascal) compiler(s). for building the host variable format nodes on the UX300 system.

Fix information:  
The fix is done by modifying the C (and Pascal) Preprocessor(s)'s

Known Problem Reports as of 11/21/90

KPR #: 4700901470 \*\*CONTINUED\*\*

alignment handling modules to following the relevant UX300 compiler alignment algorithm.

The fix has been submitted into rel7.0 pass34.

KPR #: 4700902122 Product: HP SQL/300 79725A 01.01

One-line description:

ALLBASE is not catching the error when Long Field output device too long

Problem:  
ALLBASE is not generating the correct error message when Long Field file path length is too long (DBERR 3204). Instead the Long Field file access error (DBERR 3205) is reported.

Cause:  
ALLBASE is not checking the length of the output path before copying the name to a local variable. If the path length is greater than 46 bytes, it will overwrite another local variable, which is used to check if the output path is for file access. Because of the overwritten, the check condition will always fail and check on path length will not be performed. It will then go ahead and will try to open the file, which doesn't exist. This will return the error indicating the file access fail.

Fix information:

This SR will be fixed on 300 in Release 8.0

Duplicate Service Requests: 4700902130

KPR #: 4700905877 Product: HP SQL/300 79725A 20.33

One-line description:

Optimizer may choose sort merge join when nested loop join is faster

Problem:

The optimizer may choose a sort merge join plan when a nested loop join plan would be faster. Also, for sort merge join, we may perform a sort even if an index is available on the join column.

Cause:

Currently, when a sort merge join is performed, we do not consider doing an index scan on a join table in order to eliminate the sort. Also, our calculations tend to underestimate sort costs.

Duplicate Service Requests: 4700914382 1650132670

KPR #: 4700906263 Product: HP SQL/300 79725A 70.00

One-line description:

Start db newlog accepts 'logx and logy' without using Dual log command.

Problem:

KPR #: 4700906263 \*\*CONTINUED\*\*

HPSQL accepts the specification of two logs in the START DBE NEW and START DBE NEWLOG commands even when DUAL LOG is not specified. This should be an error condition. It simply ignores the the second log specification.

Cause:  
This condition was not being check for. If DUAL LOG was not specified, it was treating it as if only one log was specified.

Fix information:  
This problem will be fixed for HP/UX release 8.0 and MPE/XL release 3.0. This fix will be to return a DBERR 1074 in this case.

KPR #: 4700908137 Product: HP SQL/300 79725A 00.00

One-line description:  
ISQL sometimes returns DBERR 49 when not recognizing ';' in START file

Problem:  
ISQL fails to recognize ';' at the end of some START files, causing a "Last command not terminated in command file - ignored (DBERR 49)" warning.

Cause:  
ISQL fails to recognize the last ';' in a command file.

Temporary solution:  
Users are advised to ignore the DBERR 49 message.

Fix information:  
This problem is fixed in rel 8.0 ux.

KPR #: 4700908251 Product: HP SQL/300 79725A 00.00

One-line description:  
Problems: Literals with '--' and parameter prompt in ISQL is ;

Problem:  
Two problems: 1) ISQL treats '--' as special SQL comment delimiter, even in quotes as in INSERT...VALUES 'a--z';

2) ISQL doesn't re-prompt correctly when the first prompt for a command file parameter receives only a ,;

Cause:  
The first problem is caused by ISQL enforcing an incorrect order of precedence. Comments should be stripped out, but not so when within quotes. The second problem is caused by a coding error.

Temporary solution:  
For the first problem, users should avoid using two dashes in a row in literals. For instance, when inserting data, they are advised to use host variables in an application to pass the data containing the two dashes to SQL.

KPR #: 4700908251 \*\*CONTINUED\*\*

For the second problem, avoid entering empty strings to the prompt for parameters when evoking command files.

Fix information:  
The problem has been fixed so that ISQL will recognize when -- is withing quotes.

The problem will be fixed in Rel 7.0 pass 34.

Note : this only addresses the first problem, the second will addressed in SR #4700911537

KPR #: 4700908285 Product: HP SQL/300 79725A 00.00

One-line description:  
HPSQL Alignment error(DBERR 4200) when using column of type DATETIME.

Problem:  
For a Date/Time column referenced in a query, user gets "HP SQL alignment err on column x in buffer 5 (DBERR 4200)" at preprocessing time.

Cause:  
The calculation of offsets for Date/Time columns involves some re-adjustments due to the mapping of an internal type (Date/Time) to an external type (character array) that have different sizes. This calculation of these offsets in the buffer is incorrect in some cases, causing the out of alignment error.

Temporary solution:  
It was suggested by the response center that the table be defined with all columns NOT NULL, then the Date/Time column selection seems to work. This workaround hasn't been thoroughly tested yet.

Fix information:  
The fix has been done by correctly calculating the Date/Time and non Date/Time format information, including alignment adjustments.

KPR #: 4700908319 Product: HP SQL/300 79725A 00.00

One-line description:  
C Preprocessor truncates .c filenames when using -i option.

Problem:  
C preprocessor truncates long file names supplied with -i option on the invocation line. In the example given, the submitter has a file name with its full path that's 45 characters long.

Cause:  
There is a current limit of 29 bytes for the file name processed by the C preprocessor.

Temporary solution:  
Use relative paths to shorten the file name supplied.

KPR #: 4700909168 Product: HP SQL/300 79725A 00.00

One-line description:  
 DBCORE gets a file open error when the number of files open exceeds limit

Problem:  
 On Unix, file open may fail if system-wide open file limit is exceeded (not per-process limit).

Cause:  
 Cause is overflow of System File table.

Fix information:

Fix goes in:  
 Unix: 80.10.01  
 XL : not applicable

KPR #: 4700911537 Product: HP SQL/300 79725A 00.00

One-line description:  
 ISQL doesn't prompt correctly when user enters ';' for command file parm

Problem:  
 2) ISQL doesn't re-prompt correctly when the first prompt for a command file parameter receives only a ,;

Temporary solution:

For the second problem, avoid entering empty strings to the prompt for parameters when invoking command files.

Duplicate Service Requests: 4700911529 4700915280

KPR #: 4700912998 Product: HP SQL/300 79725A 00.00

One-line description:  
 Corner case found with PAGE ALLOCATION log recs where rolloff may fail.

Problem:  
 In one of our internal online backup tests, we found a rather rare corner case where rolloff recovery (strictly archival rolloff recovery, not warmstart redo) could fail.

Cause:  
 This relates to PAGE ALLOCATE (DA) log records. Please refer to lab text (if you can).

Fix information:  
 Fix info will be updated when available. For now, we do not plan to fix this bug for UX 7.0/XL 2.0 OR XL 2.1 ALLBASE.

Fix update 8/24/90

Fix available in:

UX XL

KPR #: 4700912998 \*\*CONTINUED\*\*

UX 7.0/XL 2.0 Not fixed Not fixed  
 XL 2.1 Not fixed Not fixed  
 UX 8.0/XL 3.0 A.80.55.01 A.30.55.01

KPR #: 4700915462 Product: HP SQL/300 79725A 70.00

One-line description:  
 Nested query resulted in TRAP 13

Problem:  
 A floating point exception may occur when executing subqueries that depend on floating point values from outer queries. This is likely to result in a DBERR 4053 or DBERR 4054.

Cause:  
 A correlated subquery was executed before the outer query had any valid data for it to use. The subquery picked up an invalid floating point number from where it expected to find its outer reference value.

Fix information:

This problem will be fixed in HPUX 8.0 and MPEXL 3.0. It will also be fixed on a patch release available for HPUX 7.0.

KPR #: 4700921429 Product: HP SQL/300 79725A 70.00

One-line description:

PSQLCOB does not allow assigning integer values > 2,147,483,647

Problem:  
 Integer variables outside of the SQL declaration section generate DBERR 10925 "Integer value too large" when they are assigned values within the legal range of the compiler. Specifically, variables of type PIC S9(10) can't receive values > 2,147,483,647.

Cause:

SQL parser incorrectly checks syntax outside SQL declaration section.

Temporary solution:

A workaround is to assign values greater than 2,147,483,647 using a compute statement.

Fix information:

This fix will appear in ALLBASE/SQL version 3.0 for MPE/XL and version 8.0 for HP-UX.

KPR #: 4700923268 Product: HP SQL/300 79725A 07.26

One-line description:

Declare Cursor with 'LIKE' returns DBERR 4051 from JGEFMT(1)

Problem:

An HP SQL query involving 'LIKE' predicate, connected by about 20 ANDs/ORs gives DBERR 4051 (an internal error encountered

KPR #: 4700923268 \*\*CONTINUED\*\*

KPR #: 4700923300 \*\*CONTINUED\*\*

at routine JGEFMT(1) at preprocessing time).

Cause:

This problem is due to HP SQL failing to adjust predicate tree correctly after Conjunctive Normalization Process. The improper nodes gets detected in later phase of preprocessing and causes HP SQL internal error.

Fix information:

Fix in a MPE/XL Release 2.0 Patch, and HP/UX 7.0 Patch.

KPR #: 4700923284 Product: HP SQL/300 79725A 07.26

One-line description:

Complex query with OR predicate runs out of memory and returns TRAP 68

Problem:

The customer query has a very complicated WHERE clause with 53 AND's and 13 OR's. This query runs for over an hour then aborts with a data memory protection trap. (TRAPS 68)

Cause:

For MPE/XL Release 2.0 and HP/UX Release 7.0, ALLBASE/SQL was enhanced to optimized OR predicates. As part of the implementation for OR optimization, the predicates must be normalized in order for optimization to be taken advantage of.

For this complicated query, the normalization process is taking over an hour, and also running out of memory.

Checks should be made before normalization starts to see if it is feasible time wise. If the query is too complicated, OR's would not be optimized but run similar to previous releases.

Fix information:

Fix in a MPE/XL Release 2.0 Patch, and HP/UX 7.0 Patch.

KPR #: 4700923300 Product: HP SQL/300 79725A 07.00

One-line description:

Null Indicator set to 4 on select of dec(4,0) into S9(4) COMP-3 field.

Problem:

The NULL indicator was set to 4 on the FETCH, even though the columns were numeric.(DECIMAL) Setting of the indicator variable for truncation should only occur on non-numeric data types.(CHAR/VARCHAR/DATE/TIME/DATETIME/INTERVAL and any future non-numeric types)

In this instance, the appropriate host variable was used in the COBOL application, but it consumed only 3 bytes

Known Problem Reports as of 11/21/90

KPR #: 4700923300 \*\*CONTINUED\*\*

of storage, whereas HP SQL stores decimal columns in 4 or 8 bytes. HP SQL detected the length difference, and incorrectly set the indicator variable. It should not be set for numeric types. Numeric types would cause run time underflow/overflow conditions if the precision is loss due to the target host declaration.

Cause:

HP SQL was not checking the source data type when generating code for setting the indicator variable for data truncation.

Fix information:

Fixed in HP SQL/XL 2.1 Release.

KPR #: 4700923318 Product: HP SQL/300 79725A 07.00

One-line description:

Packed decimal overflow on operation CONVERT. (DBERR 2605

Problem:

A UNION of three queries returned DBERR 2605 'Packed Decimal overflow on operation CONVERT'. 2 columns of type char(16) and decimal(10,2) are being projected. In the first two queries, the char column doesn't allow null values, but the decimal column does. The third query allows nulls in the char column, but not the decimal column.

This forces a conversion for the UNION operation since the projected columns do not match identically.(data type, length, and null length)

When the query was executing, DBERR 2605 was returned.

Cause:

The run time routine for UNION was executing the convert code when a source was at end of scan on a NEXT call. It would not execute the compare or move code, but this execution of convert code on what-ever is in the buffer could cause overflow/underflow conditions on numeric data types.

The fix is not to execute convert code on a NEXT call, if a source is at end of scan.

Fix information:

This fix should go into a 7.0 patch for HP SQL version A.07.00.17. Fixed in HP SQL Patch Release A.07.00.17 on HP/UX, and A.20.17 for MPE/XL.

KPR #: 4700923326 Product: HP SQL/300 79725A 07.00

One-line description:

Random DBERR 2605 errors with UNION commands.

Problem:

Even though the same error was being returned as in SR 5000574418, this problem was distinct in itself and different.

The queries that failed after a certain repetition, had NULL values returned in the result for some DECIMAL fields. There was a problem with the executable tree built when conversions were necessary to perform a UNION command. In NTL's case, 29 columns were involved in the UNION and there were 2 sources to the UNION. The 29 columns were not exactly the same data types, as the result of the UNION. Thus some conversions were necessary to perform the UNION.

The problem was that the code generated for the conversion was not correct. If a NULL is returned, a conversion should not be done, but rather setting the NULL indicator. While executing a convert on a decimal column which was NULL, a DBERR 2605 was generated when the value was garbage enough to cause a decimal overflow. (The value is not set in the case of a NULL, but only the NULL indicator. Therefore it was random when the query would get DBERR 2605)

Cause:

At preprocess time, the run tree for the UNION command, which involved conversions, was not built correctly. Convert instructions would be executed at run time even in cases when the field value was NULL. This could result in overflow/underflow conditions for NUMERIC data types.

Fix information:

Fixed in an ALLBASE/SQL Patch to HP/UX 7.0 and MPE/XL 2.0.

KPR #: 4700923334 Product: HP SQL/300 79725A 07.00

One-line description:  
DBERR 2413 returned with large number of OR INDEX predicates.

Problem:

It is possible that existing queries that ran prior to HP/UX 7.0 or MPE/XL 2.0, would fail with DBERR 2413. A patch was made to resolve 4700566666, but 1 situation was not taken care of.

This situation is when an index column is OR'ed more than 15 times or so. This situation will result in DBERR 2413.

Cause:

The fix made to 4700566666 did not take into account this situation.

KPR #: 4700923334 \*\*CONTINUED\*\*

Fix information:  
Fixed in a PATCH for ALLBASE/SQL for HP/UX 7.0 and MPE/XL 2.0.

KPR #: 4700923342 Product: HP SQL/300 79725A 07.00

One-line description:  
"Invalid decimal precision error" on UNION command with decimal data.

Problem:

It is probable to get a DBERR 2430 "Invalid decimal precision" - Allowed range is 1-15. When performing a UNION on decimal columns. ALLBASE/SQL is to compute the result data types. If column n is a decimal data type being projected in a UNION, the result data type is to be computed based on the merged data types of all columns in the nth position of the SelectList.

Cause:

When ALLBASE/SQL is computing the merged result format of two decimal columns, it would determine the result precision and scale of the result based on the two decimal columns precision and scale. The problem is that it would not verify the result precision was not greater than the maximum precision allowed 15.

Fix information:

Fixed in a PATCH for ALLBASE/SQL HP/UX 7.0, and MPE/XL 2.0.

KPR #: 4700923367 Product: HP SQL/300 79725A 07.00

One-line description:

Two COMMIT WORK with DDL disabled and KEEP CURSOR in effect causes hang.

Problem:

With DDL off, and KEEP CURSOR in effect, two COMMIT WORK statements with no SQL statements in between cause a hang on the next BEGIN WORK.

Cause:

The process gets hung when it is attempting to allocate memory off of the free memory list. This list was corrupted by the re-use of sections (saved due to DDL off) of a KEEP CURSOR. The first time the section is used, the KC makes a shadow heap. When done, it frees that heap, but (before the fix) does not reset the pointer to it. When the next KC reuses the section and needs to create the heap, it starts by re-freeing the heap (since the pointer is not nil). Thus, the same memory gets freed twice and corrupts the free memory list, causing the next allocation to fail.

The fix is to make sure to reset the KC heap pointer to nil after it is freed.

KPR #: 4700923367 \*\*CONTINUED\*\*

Fix information:  
This fix will appear in a patch release of ALLBASE/SQL XL 2.0 and UX 7.0.

KPR #: 4700926865 Product: HP SQL/300 79725A 00.00

One-line description:  
DBERR 4050 internal error in JBIREF(1) when selecting from a view.

Problem:  
When using a correlation name in a SELECT from a VIEW which contains a DISTINCT node in the SelectList, DBERR 4050 "HP SQL internal error in JBIREF(1). (Node DISTINCT out of context)" is returned when executing the SELECT.

Cause:  
When binding the SELECT statement, a flaw in logic in binding the correlation name generated the error condition. The code didn't expect to ever see a DISTINCT, but as the example shows, it is possible.

Temporary solution:  
The error can be avoided by removing the DISTINCT from the view and putting the distinct in the SELECT statements on the view, or by not using correlation names when selecting data from a view which has a DISTINCT in the SELECTLIST.

Fix information:  
Fixed in ALLBASE/SQL Release HP/UX 8.0 and MPE/XL 3.0.

KPR #: 4700929679 Product: HP SQL/300 79725A 07.00

One-line description:  
DBERR 4053 may be returned when optimizer not detecting over/underflow

Problem:  
There are many cost calculations in the optimizer that have could result in float underflow/overflow conditions. The code was written to nicely trap these conditions and not abort back to the user with DBERR 4053. For the 300 only, the code would always return a DBERR 4053 when an abort occurred in the optimizer.

Cause:  
The code was not checking against 300 abort codes when determining the type of abort that occurred. Thus the code wasn't handling any 300 aborts, but rather escaping back to the user with a DBERR 4053 abort error.

Fix information:  
Fixed in an ALLBASE/SQL PATCH for HP/UX 7.0.

KPR #: 4700929687 Product: HP SQL/300 79725A 70.00

One-line description:  
Over/underflow may result due to incorrect cost computation in optimizer

Problem:  
The optimizer was computing one of the plan values (number of sort rows) with an uninitialized and incorrect plan. The results could lead to inaccurate best plan calculation. On the 300, DBERR 4053 could also occur as a result of another problem with this one. (see 4700929679)

Cause:  
A calculation within the optimizer was using an incorrect variable in a calculation. The variable was uninitialized, and could be equal to almost anything at run time.

Fix information:  
Fixed in an ALLBASE/SQL PATCH for HP/UX 7.0 and MPE/XL 2.0.

KPR #: 4700933028 Product: HP SQL/300 79725A 20.29

One-line description:  
BULK FETCHES WITH KEEP CURSOR WITH NOLOCKS cause DBCORE Internal err 184

Problem:  
The problem is when user is doing the bulk fetch to the end of scan, if he does another fetch, he get a DBCORE internal error 184 instead of tuples not found which he's supposed to get.

Cause:  
The cause of this problem is when the end of scan is reached when executing the fetch, there is a internal field at the scan control not reset back to its valid value.

Fix information:  
Fixed in an ALLBASE/SQL PATCH for HP/UX 7.0 and MPE/XL 2.0.

KPR #: 4700933788 Product: HP SQL/300 79725A 70.00

One-line description:  
NEW and DISPOSE called a lot while executing an SQL program.

Problem:  
Every execution of a section when running an application program would cause ALLBASE/SQL preprocessor code to call NEW and DISPOSE which is a performance issue.

Cause:  
The logic in the preprocessor run time module which calls ALLBASE to execute a section was using NEW and DISPOSE.

KPR #: 4700933788 \*\*CONTINUED\*\*

This code was reworked not to call NEW and DISPOSE which improves performance.

Fix information:

Fixed in ALLBASE/SQL Release HP/UX 8.0, and MPE/XL 3.0.

KPR #: 4700937037 Product: HP SQL/300 79725A 08.55

One-line description:

FORTRAN preprocessor generates syntax error for valid compiler options.

Problem:

The FORTRAN SQL preprocessor generates error messages DBERR 10944 (Unrecognized syntax encountered. Parse aborted.) or DBERR 10994 (Syntax error in option specification.) for valid compiler options which follow documented syntax rules.

Cause:

The FORTRAN SQL preprocessor handles dollar signs '\$' incorrectly. Code is checked following syntax rules for the Pascal compiler instead of the FORTRAN compiler.

Temporary solution:

There is no temporary fix except to delete the affected compiler option line from the source code.

Fix information:

This fix will be made available in ALLBASE/SQL released on HP-UX version 8.0

KPR #: 4700938225 Product: HP SQL/300 79725A 07.00

One-line description:

DBCORE abort (internal error 3822) in a KEEP CURSOR application.

Problem:

Several problems were noticed in this single-user application. Most of them were not reported by the customer.

- a. A KEEP CURSOR application aborted inside the LOCK allocation code in ALLBASE.
- b. Following that, this process kept going on (i.e. the PIN was still alive).
- c. Subsequent to this, other processes started hanging on locks held by this (technically) dead process.

Now, we also found other internal errors like 1058 and 1049 in dump files on disk. But surprisingly, the customer did not report these errors. Clearly, the exception handling in the application is not trapping all these errors (especially on the RELEASE command). This needs further investigation.

KPR #: 4700938225 \*\*CONTINUED\*\*

Cause:

So far, what we have found is that a lock control block is partially orphaned. If you can see the LAB TEXT, please do, otherwise it is perhaps enough to say that there is internal corruption in the lock linked list.

This is WHAT is happening. We do not know WHY as yet.

CAUSE TEXT update 9/19/90

There is an optimization in DBCORE where it always keeps track of the "current" scan that is being operated on. If there is a current scan, then any locks acquired will be associated with this scan. (Note also that locks were never associated with scans before CS/RC and KC came along. They were always associated with the transaction only). In other words, you will not see this problem in RR.

When we have a SORT operation (ORDER BY, GROUP BY, DISTINCT), we open a scan on the base table, call the sort manager to perform the SORT operation, and close the scan on the base table. But we were not setting the "current scan pointer" to NIL. Now, the only types of locks we can acquire without having another scan opened are low level directory locks. If we do that, these locks will now get associated with a scan that has been closed (but its control block is still hanging around in the heap somewhere).

Now, someone else comes along and opens a scan on some other table, gets the same control block from the heap etc etc. The count fields in the block are all messed up at this point. At the time of releasing these locks, KEEP CURSOR selectively keeps some locks across transactions. It will now keep some extra "orphan" locks that can simply not be accounted for.

Fix information:

The fix is simple. At the end of a SORT operation, we should just set the current scan pointer to NIL.

Fix available in:

UX	7.0/XL 2.0	UX	XL
	XL 2.1	A.07.03.44	A.20.03.44
UX	8.0/XL 3.0	A.80.57.01	A.21.24
			A.30.57.01

The XL 2.1 version number is tentative.



KPR #: 4700939512 Product: HP SQL/300 79725A

70.00

One-line description:  
A potential undetected deadlock with RU application in a loaded system.

Problem:  
Potential undetected deadlock in a very loaded system.

CAUSE TEXT:

RU transaction still get system locks. May run into a deadlock.  
The fix will make the transaction abort and not hang the system.

FIX TEXT:

fixed                    XL                    UX  
                         A.30.00                    A.80.00

KPR #: 4700941633 Product: HP SQL/300 79725A 70.00

One-line description:  
Migrating a DBE with DDL disabled caused DBCore error 134 in CREATE FILE

Problem:  
If DDL is disabled for a DBEnvironment, then the SQLMIGRATE  
CREATE DBEFILE command will fail with the following messages:

\*\*\* DBCore error. (FNC 34, RC 134, 200220, ...)

Attempt to CREATE DBEFILE in <DBEnvironmentName> failed.

Cause:  
The CREATE DBEFILE command is a DDL operation. If DDL is disabled,  
then the command will fail.

The CREATE DBEFILE command in SQLMIG is provided in case the PREVIEW  
command indicates that more space must be added to the SYSTEM  
DBEFILESET. A CREATE DBEFILE command must be issued followed by  
an ADD DBEFILE comand to add space.

Normally, the customer would use SQLUTIL to enable DDL mode before  
adding space to a dbfilesset. In the migration process, it cannot  
be guaranteed that the new SQLUTIL will work against an old  
DBEnvironment. So, the SQLMIGRATE CREATE dbefile command should  
enable DDL mode, if necessary, in order to guarantee that the  
command will succeed.

Fix information:

The fix is to temporarily enable DDL. After the CREATE DBEFILE  
command is complete, the DDL-mode will be restored to the value  
that existed before the command was issued.

The fix is in the HPUX 8.0 and MPEXL 3.0 releases.

KPR #: 4700941799 Product: HP SQL/300 79725A

02.00

One-line description:  
COBOL PP inserts 1-byte filler for variables outside DECLARE SECTION.

Problem:

The COBOL preprocessor inserts 1-byte fillers in record  
declarations which appear outside the SQL DECLARE SECTION.  
The filler byte is inserted before odd-byte decimal data  
declarations. The insertion of filler bytes should not  
occur outside the SQL DECLARE SECTION.

Cause:

This problem is caused by a defect in the COBOL preprocessor  
which does not recognize the scope of the SQL DECLARE SECTION  
when scanning variable declarations. The preprocessor must  
recognize when it is scanning inside/outside the SQL DECLARE  
SECTION.

Temporary solution:

A temporary fix can be made by manually removing the preprocessor-  
inserted filler bytes from the modified source file generated by  
the preprocessor. Remove only those filler bytes which appear  
outside the SQL DECLARE SECTION. Do not remove the filler bytes  
which are inserted within the SQL DECLARE SECTION.

Fix information:

This fix will be made available on HP-UX version 7.0

KPR #: 4700942342 Product: HP SQL/300 79725A 07.00

One-line description:

DBCORE error 181 is returned on fetch from a keep cursor

Problem:

DBCORE internal error 181 in KC NOLOCKS test case.

Cause:

Since all SQLCORE-DBCORE fetches are BULK in nature, it is  
possible for DBCORE to get end-of-scan during a single  
FETCH. DBCORE does remember that fact for this scan, but  
if SQLCORE makes the next FETCH call, DBCORE will attempt  
to position itself on the tuple following the last tuple  
fetched.

However, after the end-of-scan, the last tuple id known to  
DBCORE contains garbage.

Fix information:

Fix consists of checking the end-of-scan indicator before going  
on with the FETCH call.

Fix available in:

UX

XL

UX 7.0/XL 2.0

A.07.00 45

A.20.00.45



KPR #: 4700942342 \*\*CONTINUED\*\*

XL 2.1  
 UX 8.0/XL 3.0 A.80.57.01 A.30.57.01 TBD

KPR #: 4700945683 Product: HP SQL/300 79725A 70.00

One-line description:  
 Slow performance on Join of tables

Problem:  
 Customers may experience poor performance on queries when the predicate involves columns with non-uniform data distribution.

Cause:  
 Currently, the SQLCore optimizer assumes uniform distribution of data values in columns. When this assumption is not justified, estimates of selectivity, and therefore those of the sizes of intermediate results, may be inaccurate. A non-optimal access plan (especially a non-optimal join order) may be chosen, resulting in poor performance.

KPR #: 4700946400 Product: HP SQL/300 79725A 00.00

One-line description:  
 Need to increase the SQLUTIL max runtime control blocks constant.

Fix information:  
 PASS 47 for D.0 will include this fix.(10/23/90 is the expected build date)

KPR #: 4700946715 Product: HP SQL/300 79725A 08.56

One-line description:  
 Incorrect error message (DBERR 2910) when OPEN CURSOR is used.

Cause:  
 When the same host variable names are used in the USING CLAUSE, they are treated as one which caused the problem.

Fix information:  
 The problem will be fixed in the release E.1 '80.57.00'.

KPR #: 4700946814 Product: HP SQL/300 79725A 07.00

One-line description:  
 DBERR 4000 with five LIKE predicates separated by logical OR.

Problem:  
 A SQL query with more than 4 OR'ed LIKE predicates aborts with a DBERR 4000 HP SQL code buffer overflow. LIKE predicates are expanded with boundary checkings, and OR-AND predicates are further normalized to conjunctive form. Many predicates are added to the query. Lots of code need to be generated to handle LIKE and other predicates operations. With a limited amount of code buffers, code buffer overflow occurs for this query with table scan.

KPR #: 4700946814 \*\*CONTINUED\*\*

Cause:  
 This is due to the LIKE predicates are expanded with boundary checkings, and the OR-AND predicates are further normalized to conjunctive form. Many predicates are added to the query. Lots of code need to be generated to handle LIKE and other predicates operations. With a limited amount of code buffers, code buffer overflow occurs for this query with table scan.

Fix information:  
 Fixed in a MPE/XL Release 2.0 Patch and HP/UX 7.0 Patch.

KPR #: 4700948133 Product: HP SQL/300 79725A 00.00

One-line description:  
 HPIMAGE/DBCORE pass 34 page corruption bug during B-tree migration

Problem:  
 B-Tree corruption was detected in an HP IMAGE PCR (this happened on ALLBASE/7.0 Pass 34).

Cause:  
 The earlier fix to this B-Tree corruption was done first in UX 7.0/XL 2.0. Please refer to the following SR numbers:

4700-853066 (800) B-Tree corruption in parent key updates  
 4700-871806 (900) Same as above  
 4700-875468 (300) Same as above

The above fix was made available in ALLBASE/7.0 Pass 25. But that fix did not take care of tuple migration across B-Tree pages. This is what caused the new problem.

Fix information:  
 Fix available in:

UX 7.0/XL 2.0 A.07.00.46 A.20.00.46 XL

KPR #: 4700949016 Product: HP SQL/300 79725A 70.00

One-line description:  
 CURRENT\_DATEIME function is not accurate as its format requires.

Problem:  
 Function CURRENT\_DATEIME is not as accurate as required by format. The precision is not down to milliseconds as specified.

Cause:  
 The function always puts zeroes in the FFF field which displays the thousandths of a second. The code to get the current datetime value calls OS dependent intrinsic calls which do not return milliseconds. A fix will be made to call intrinsics which return the accurate precision required.

KPR #: 4700949685 Product: HP SQL/300

79725A

70.00

One-line description:  
incorrect result from retrieving a default value from varbinary column

Problem:  
The test case here actually puts 708 byte character string into a varbinary column as a default value. After a insert with c1 the value of c2 should be 708 byte default value, but it is not.

Cause:  
There are two buges revealed by the test case. The first one is fixed at SR#4700942623, the number of the tuples is not calculate correctly when putting a character string into varbinary column. The second bug is caused by not enough space allocated when the default value is fetching from the system catalog.

Fix information:  
The fix for this SR will be in HPUX8.0, MPE/XL3.0

KPR #: 4700949701 Product: HP SQL/300

79725A

70.00

One-line description:  
Incorrect char string is displayed when it's a default val to varbin col

Problem:  
A character string is assigned to a varbinary column as its default value, the character string is not stored correctly.

Cause:  
Internaly one byte binary in hex takes two byte ascii to represet, however, if assign character string to binary no coversion needs to be done. One char goes to one byte storage. There is a miscalculation at the storage size for assigning char to binary type.

Fix information:  
The fix will go to HP-UX 8.0 and MPE/XL 3.0

KPR #: 5000260547 Product: HP SQL/300

79725A

01.00

One-line description:  
wrong user used by sql for authorization after an su was done

Problem:  
Wrong user used by SQL for authorization after an "su" was done.

Cause:  
The authorization routines were using 'userid' from the system library to check who the current user is. 'userid' actually tries to check who they logged on as.

Fix information:  
The authorization routines now use 'getuid'.

Signed off 05/23/89 in release X00.00

KPR #: 5000484352 Product: HP SQL/300

79725A

01.10

One-line description:  
Data or Index space exhausted in DBEFIELD (DBERR 2502).

Problem:  
There was a problem with HP SQL with re-issuing transaction id's. SQL would not free up temporary space in the system dbfileset, with a scenario as described in the submitter text. Error 2502 would result.

Cause:  
As described in the problem text.

Fix information:  
Fixed in HP SQL/300 Release 2.0.

Signed off 12/21/89 in release A20.00

KPR #: 5000566836 Product: HP SQL/300

79725A

07.00

One-line description:  
DBERR 4104 - shared memory failure on S300 series

KPR #: 5000566851 Product: HP SQL/300

79725A

00.00

One-line description:  
SQLUTIL STORE command truncates storefile names longer than 44 chars.

Temporary solution:  
STORE command in SQLUtil truncates the file name when it's longer than 44 characters, forcing the user to look for the file after a successful STORE operation. A warning or even error message should be generated to alert the user to the limit.

Fix information:  
Fix scheduled for UX 8.0. Exact versions will be provided when the fix is available.

Duplicate Service Requests: 5000562322 5000562330 5000558155

KPR #: 5000568196 Product: HP SQL/300

79725A

00.00

One-line description:  
SQLUTIL STORE gives confusing message with write-protected directory.

Problem:  
When trying to perform a STORE in SQLUtil to a directory that's write-protected, the user gets messages that are misleading.

Cause:  
The error condition handling should be enhanced to give more meaningful data.

Temporary solution:  
When trying to perform a STORE in SQLUtil to a directory that's

write-protected, the user gets messages that are misleading.

Known Problem Reports as of 11/21/90

Page: 181

KPR #: 5000568196 \*\*CONTINUED\*\*

write-protected, the user gets messages that are misleading.

Fix information:

This problem will be fixed in UX 8.0. The correct system error no. will be returned.

Known Problem Reports as of 11/21/90

Page: 182

KPR #: 4700685560 Product: HP SQL/300 C APG 79725-90014 88.02

One-line description:  
Compilation statement specifies libraries in incorrect order.

Problem:  
In chapter 1 the order of libraries in the compilation statement is incorrect.

Fix information:

The order of libraries will be changed to:  
"cc.source.c -lsql -lheap2 -lportnls -lpc"  
This change will be made in the next edition for release 7.0, where the information for the Series 800 and Series 300 can be found. The part number is 36217-90014.

Duplicate Service Requests: 1650079939 1650079954 4700503664

KPR #: 4700879403 Product: HPC++ COMMON HPCPLUSPLUSA 00.01

One-line description:  
Can't compile with <starbase.c.h>. Undefined c\_draw2d(), c\_move2d().

Problem:  
The <starbase.c.h> header file does not define c\_draw2d() and c\_move2d().

Fix information:  
Fixed in A.02.10

KPR #: 4700879411 Product: HPC++ COMMON HPCPLUSPLUSA 00.00

One-line description:  
sys/ns\_ipc.h file not converted for HP C++.

Problem:  
The <sys/ns\_ipc.h> include file not converted for HP C++

Fix information:  
Fixed in A.02.00

Signed off 04/12/90 in release A02.00

KPR #: 4700880393 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
unnamed bit fields are initialized, even in ANSI mode (+a1).

Problem:

According to the ANSI Draft Standard for the C language (December 7, 1988, Section 3.5.7), unnamed structure members are ignored during initialization. Cfront, even in its ANSI mode (+a1), ignores this and applies initializers to fields, one-for-one, unnamed or not.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700880401 Product: HPC++ COMMON HPCPLUSPLUSA 00.04

One-line description:  
DNMT\_LABEL's address field not set correctly

Problem:

Due to a bug in the series 800 C compiler, if a label is put on a block (i.e. just before the opening "{" of the block) then the debug information for the label is incorrect.

Temporary solution:

This problem is not severe ; the only manifestation is that one cannot set a breakpoint on the said label by using the "b #label" syntax. A simple workaround is to set the breakpoint using the line number that the label appears on: "b 4".

- HPC++ COMMON -

KPR #: 4700880401 \*\*CONTINUED\*\*

Fix information:  
Will be fixed in A.03.00

KPR #: 4700880419 Product: HPC++ COMMON HPCPLUSPLUSA 00.04

One-line description:  
passing function pointer as parameter causes internal error

Problem:  
passing function pointer as parameter causes internal error  
3058 ; bus error

Fix information:  
Fixed in A.02.10.

KPR #: 4700880427 Product: HPC++ COMMON HPCPLUSPLUSA 00.00

One-line description:  
no include file for net\_aton or net\_ntoa(3N)

Problem:

There is no include file for net\_aton or net\_ntoa(3N).

Fix information:  
Fixed in A.02.00.

Signed off 04/12/90 in release A02.00

KPR #: 4700883066 Product: HPC++ COMMON HPCPLUSPLUSA 00.04

One-line description:  
cfront creates this pointer for static member function

Problem:

Incorrect value was printed when the base class defines succor as non-static and the derived class declares it as static.

Fix information:  
Fixed in A.02.10.

KPR #: 4700884270 Product: HPC++ COMMON HPCPLUSPLUSA 00.00

One-line description:  
merger is zapping out SRCFILE entries that should not be zapped

Problem:

Functions with #includes inside their bodies cannot be debugged properly, because the debug merger tool discards the source file information inside the function bodies.

Temporary solution:

On the series 800, use compiler mode (i.e. do not use the +T flag).

- HPC++ COMMON -

KPR #: 4700884270 \*\*CONTINUED\*\*

Fix information:  
Will be fixed in A.03.00

KPR #: 4700885749 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
Compile time for HPC++ is 2-3 times slower than bare cfront

Problem:  
The compile time for HPC++ is 2 to 3 times that of a straight port of the AT&T translator.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700886598 Product: HPC++ COMMON HPCPLUSPLUSA 00.00

One-line description:  
Need to build libc.ansi.a and add this file to the file set

Problem:  
An ANSI version of libc.a needs to be built and submitted to the HP C++ product, so that people who compile with +a1 can link and run their programs.

Fix information:  
Fixed in A.02.00

Signed off 04/11/90 in release A02.00

KPR #: 4700887976 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
CC +a1 generates bad C code -- cc fails

Problem:  
The problem is that in +a1 (ANSI C) mode, cfront tries to put out full prototypes for external functions declarations, \*including parameter names\* (when it has no need to, and indeed should not). Sometimes, it ends up putting out some garbage characters instead of the name, which causes C syntax errors.

Temporary solution:  
Don't use +a1 mode in your application if you get this problem.

Fix information:  
Fixed in HP C++ A.02.10.

KPR #: 4700888925 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
CC doesn't cast 0 to an array type

Problem:  
CC automatically casts the constant 0 to the NULL pointer of the appropriate type for assignments and function calls where the argument is a pointer. However, if the argument is an array, CC fails to make the cast.

Fix information:  
Will be fixed in AT&T cfront 2.1

KPR #: 4700889394 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
Struct member w/in struct not declared in generated C code.

Problem:  
Struct member within struct results in member not being declared in the generated C struct.  
No complaints issue from cfront, but C compiler complains about the missing struct member.

Fix information:  
Fixed in A.02.10

KPR #: 4700890368 Product: HPC++ COMMON HPCPLUSPLUSA 00.00

One-line description:  
Cfront core dumps in making a long signature name

Problem:  
Cfront aborts when the mangled name that it creates for a function would be greater than 255 characters long.

Temporary solution:  
Shorten the name of the function, and/or the class of which it is a member.

Fix information:  
Will be fixed in HPC++ A.03.00.

KPR #: 4700890392 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
passing a float const arg with a cast to inline func is botched.

Problem:  
Passing an argument to an inline function which consists of a floating-point constant with a cast cause incorrect code to be generated.

KPR #: 4700890392 \*\*CONTINUED\*\*

Temporary solution:  
After including <math.h>, undef and redefine MAXFLOAT  
as follows:

```
#include <math.h>
#undef MAXFLOAT
#define MAXFLOAT 3.40282346638528860e+38
```

Fix information:  
Fixed in HPC++ A.02.10.

KPR #: 4700890830 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Pointers to members cannot always be assigned the constant zero.

Problem:  
Cfront does not allow constant expressions that evaluate to zero to be assigned to pointer to members which is in violation of section 4.8 of the reference manual.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700890848 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Cfront allows a const object to not be passed to non const member func.

Problem:  
\* Description:  
\* Cfront does not catch a call to a non-const function using a constant object. Essentially the example from the language reference manual found in section 9.3.1.  
\* Executable example: \*/

```
// A member function that is non-const has a call from it from an
// object that is declared const, which is an error. By the way,
// this example is essentially the same as the one in 9.3.1 of the
// reference manual
struct s {
    int a;
    int f() const;
    int g() { return a++; }
};
int s::f() const { return a; }
```

```
void foo() {
    s x;
    const s y;
    x.f();
}
```

KPR #: 4700890848 \*\*CONTINUED\*\*

```
x.g();
y.f();
y.g(); // error.
}
```

```
/* Current result:
   * successful compile
   * Expected result:
   * compile time error messages
   *
   * *****/
```

Fix information:  
Fixed in A.02.10

KPR #: 4700891754 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Bad debug info if only the enum tag from a class is referenced

Problem:  
The current algorithm for determining when a class is referenced does not include the reference to a tag defined in a class. This results in an unresolved DNTPOINTER, because an enum tag belonging to a class is only dumped when the class itself is dumped.

Fix information:  
Fixed in HPC++ A.02.00.

Signed off 08/08/90 in release A02.00

KPR #: 4700891762 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Forward struct references in inner scopes cause problems

Problem:  
If an incomplete type is referenced in an inner scope, and another incomplete type is declared in an outer scope, then the reference to the inner incomplete type causes problems when emitting debug information.

```
///
somefunc() {
    struct S* ptr = 0;
}
//If this line is commented, things will work
//This causes a new incomplete type to be declared
struct S;
///
```

KPR #: 4700891762 \*\*CONTINUED\*\*

If the above example is compiled with debug on, you will get the following message:

warning: Debug info may be corrupt. (1 unresolved reference)

Fix information:  
Fixed in A.02.10.

KPR #: 4700891796 Product: HPC++ COMMON HPCPLUSPLUSA 00.00

One-line description:  
scope of names redeclared in inner scope sometimes leads to surprise

Problem:  
The scope of variable names in the debugger mirrors the scope of variables in the emitted C code, instead of the scope of variables in the original C++ code. This may occasionally confuse the user.

For example:

```
void somefunc() {
    int j;
    j = 1; //Point A
    int i;
    i = 1;
}
```

In the emitted C code, both "i" and "j" are declared at the beginning of the function; consequently in the debugger, if you are at "Point A", the variable i is visible. If you attempt to print "i" at this point, you will get the local "i", even though there may be a global "i" visible at this point.

Temporary solution:  
There is a simple workaround for \*this\* problem: simply

```
p ::k
```

and you'll get the global.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700891804 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
warning, not error, given for item declared as both signed and unsigned

Problem:  
cfront does not give an error if both "signed" and "unsigned" are specified on the same type.

Fix information:

- HPC++ COMMON -

KPR #: 4700891804 \*\*CONTINUED\*\*

Will be fixed in A.03.00.

KPR #: 4700891846 Product: HPC++ COMMON HPCPLUSPLUSA 00.01

One-line description:  
cannot find function symbols for nameless class

Problem:  
If a class has no tag, the debug information produced for the class may be incorrect. This happens because the name mangling algorithm used by the code that emits debug information does not match the name mangling algorithm used by cfront when it emits C code.

Temporary solution:  
Avoid the use of classes which have no tags. If you have such a class, make up a dummy tag name for the class.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700891853 Product: HPC++ COMMON HPCPLUSPLUSA 00.02

One-line description:  
names are given to nameless classes in debug information

Problem:  
If a user has a class without a tag, cfront will make up a tag name (e.g. \_C1). This tag name will be visible in the debugger when doing stack tracebacks and so on. This may confuse the user.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700891879 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
Should be error to init const pointer to non-const data with const data

Problem:  
Should be error to init const pointer to non-const data with const data. Lippman pg. 38 states that it is a compile-time error to assign the address of a symbolic constant to a pointer.

Fix information:  
Fixed in A.02.10.

KPR #: 4700891887 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
demangler does not handle leading \_ correctly on s300s

Problem:

- HPC++ COMMON -

KPR #: 4700891887 \*\*CONTINUED\*\*

The demangler still does not handle s300 symbols correctly. The s300 linker always generates an extra leading " " character. The demangler MUST strip this before trying to demangle anything.

Fix information:

On the s300 systems external symbols in an object file or executable have a " " prepended to the external name. This only occurs in object or executable files. C++ mangled names occur in the resulting C source and the object files. The C source code names do not have a leading " " .

A fix on the s300 systems requires the demangling tool to handle both situations. Because of this c++filt has been enhanced on the s300 systems to take an option, '-x', to handle mangled names in object files. Refer to the c++filt man page. nm++ is a simple shell script which calls c++filt with the '-x' option.

When using libdemangle.a, the leading " " needs to be removed before the name is unmangled.

Having the demangler handle virtual table names would be useful and has been resubmitted as an enhancement request.

fixed in A.02.00.

KPR #: 4700891911 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
incorrect debug info emitted for local static cfront temps

Problem:

Under certain circumstances, cfront creates temporary variables which start with the name "F". The debug information for such variables may be incorrect. Use caution when printing out the values of such variables in the debugger.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700891945 Product: HPC++ COMMON HPCPLUSPLUSA 00.06

One-line description:  
assignment to data member overwrites virtual base class pointer

Problem:

When calling a member function whose access has been changed using an access modifier, the proper address arithmetic to obtain a pointer to the correct base class is not performed, sometimes leading to data corruption.

This is only a problem when multiple inheritance is used, and the function whose access was modified belongs to the second or subsequent base class in a multiple-inheritance declaration.

- HPC++ COMMON -

KPR #: 4700891945 \*\*CONTINUED\*\*

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700891952 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
Compiling with +d and -g is ~60% slower than just -g

Problem:

When the translator is given the +d option, it will take some extra time because many extra function bodies will be emitted when inlining is turned off; this also means that the -g option will take longer, since we need to emit debug information for all of these extra functions.

Fix information:  
Fixed in A.02.10.

Some improvements have been made. However, the very nature of the +d option means that much more information is being output into the intermediate code, so more time is required to compile and generate debug information for it.

KPR #: 4700891978 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
CC +w: cc warning for virtual function call

Fix information:

Fixed in A.02.00 version. CC does not pass +w to C compiler anymore and thus avoids spurious warnings from cc.

Signed off 04/11/90 in release A02.00

KPR #: 4700892992 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:

member function call returns wrong value if access declaration used.

Problem:

Member function of derived class returns wrong value for field of base class whose visibility was modified via access declaration.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700893008 Product: HPC++ COMMON HPCPLUSPLUSA 00.01

One-line description:  
initialization not required for const non-external struct

Problem:

Cfront allows declaring an uninitialized non-external const of a

- HPC++ COMMON -



KPR #: 4700893008 \*\*CONTINUED\*\*

struct type either at file or function scope

Fix information:  
Fixed in A.02.10

KPR #: 4700893016 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
pointer to the virtual table is being copied when it should not be

Problem:

The pointer to the virtual table is being copied when an object is passed by value to a function. This results in wrong behavior of the object in the called function (it should behave like an object of the formal parameter type).

Fix information:  
Fixed in HPC++ A.02.10.

KPR #: 4700893057 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
typedef of unsigned long within func does not work.

Problem:

typedef of unsigned long within func does not work.

```
#include <stdio.h>
void function () {
    typedef unsigned long Ulong;
    Ulong l = 0;
    int s = sizeof (Ulong);
}
```

/\* line 5: error 1588: "Ulong" undefined \*/

Fix information:  
Fixed in HPC++ A.02.10.

KPR #: 4700893065 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
Destructor cannot delete pointer to class returned by inline func.

Problem:

Class B's destructor unable to delete pointer to Class A when that pointer was returned by an inline member function and when Class A has a virtual destructor.

KPR #: 4700893065 \*\*CONTINUED\*\*

Fix information:  
Fixed in A.02.10.

KPR #: 4700893073 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
cfront crashes when calling static function inherited from virtual base

Problem:

1. in find\_in\_base in find.c if the base is found to be virtual, they set the ll field in the expr node to 1.
2. Later on in call\_fct in expr.c, they check the value of e1, and e1 is in the same union as ll. Since they find e1 to be non zero, they try to dereference it and of course you get a segmentation violation because the pointer value is 1.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700893081 Product: HPC++ COMMON HPCPLUSPLUSA 00.02

One-line description:  
array of class objects containing const enum causes bus error

Problem:

array of class objects containing const enum causes internal error 3058: bus error (or something nasty like that)

Fix information:  
Fixed in A.02.10

KPR #: 4700893099 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
cfront puts out incorrect warnings about integral type compatibility.

Problem:

Cfront puts out incorrect messages about type compatibility between integral types.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700893107 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
The debugger does not understand the void data type

Problem:

If you use a void type (e.g. a function returning void), the debugger will incorrectly assume that it is "long".

KPR #: 4700893107 \*\*CONTINUED\*\*

Fix information:  
Will be fixed in A.02.10.

KPR #: 4700893206 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
bogus error message for implicit conversion to int for unary op.

Problem:  
Cfront does not seem to recognize the existence of a conversion operator "operator int()" for a class when a unary operator is applied to an object of that class.

Temporary solution:  
Use an explicit cast on the object, as in:

- int(object)

Alternatively, for a unary "-", use the expression

0 - object.

KPR #: 4700893487 Product: HPC++ COMMON HPCPLUSPLUSA 00.01

One-line description:  
cfront allows user to define body for pure virtual function!

Problem:  
CC doesn't give a compile time error when a body is defined for a pure virtual function.

Cause:  
CC doesn't give a compile time error when a body is defined for a pure virtual function.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700893503 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Wide string literals are unimplemented

Problem:  
Wide string literals have not been implemented in Cfront.

Fix information:  
Will be fixed in A.03.00.

Duplicate Service Requests: 4700930289

KPR #: 4700893511 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Enum's aren't scoped properly

Problem:  
Enum's are not scoped properly. Enum's defined in one function are accessible in another function.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700893529 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Cfront allows duplicate declarations of enum's

Problem:  
Cfront allows enum declarations to be duplicated within a function, even to differing values.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700893537 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Incorrect handling of redefinition of classes in blocks

Problem:  
Cfront does not handle redeclaration of classes within blocks. If a class is defined both inside and outside a block, the definition that is used is the one in the outside block, even when used inside the block.

Cause:  
Declaring a class in an inner scope with the same name as one in an outer scope does not work properly.

The cause of this defect has not been diagnosed.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700893545 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:

Cfront does not catch calls to main, violation of sec. 3.4 in ref manual

Problem:  
// Section 3.4 in the reference manual states that main () is not // callable from any portion of the program. Cfront does not tag this // as an error

main () {

KPR #: 4700893545 \*\*CONTINUED\*\*

```
main();
}
```

Cause:  
Cfront does not detect a call of main within main itself. This problem has not been diagnosed further.

Fix information:  
Will be fixed in A.03.00.

KPR #: 4700893552 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Cfront does not correctly mangle member funcs. for tagless classes

Problem:  
Member functions of tagless structs, classes or unions are not encoded correctly in the C intermediate output, causing them to potentially link up incorrectly with other existing functions.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700893578 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
reference to type void should get error

Problem:  
Function of type `reference to type void' is accepted by cfront. It should get an error.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700893586 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
redefinition of enum tag name in inner scope not allowed

Problem:  
an enum tag name is defined at file scope. Attempting to redefine it (again as an enum tag) within a function elicits the error message:

```
error: enum <tag_name> defined twice
```

Fix information:  
Will be fixed in A.03.00

KPR #: 4700893610 Product: HPC++ COMMON HPCPLUSPLUSA 00.01

One-line description:  
CC gets internal error on abstract virtual operator declaration.

Problem:  
CC gets internal error on abstract virtual operator declaration.

Fix information:  
Fixed in A.02.10

KPR #: 4700893628 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
cfront using +d option works incorrectly.

Problem:  
When using the '+d' option which prevents the inlining of inline functions, bad C code is generated.

Temporary solution:  
Do not use '+d'. The program will give the same results when functions are inlined.

Fix information:  
Will be fixed in A.02.10

KPR #: 4700893651 Product: HPC++ COMMON HPCPLUSPLUSA 00.02

One-line description:  
incorrect warning given for overloading based on enum vs. int.

Problem:  
When two overloaded functions are differentiated in their parameter list by an int versus an enum, an incorrect warning message is displayed at compile time specifying that the enum was converted to an int, implying that the function with the int is called. However, the code that is generated is correct and the function that specifies an enum is called.

Cause:  
When two overloaded functions are differentiated in their parameter list by an int versus an enum, an incorrect warning message is displayed at compile time specifying that the enum was converted to an int, implying that the function with the int is called. However, the code that is generated is correct and the function that specifies an enum is called.

Fix information:  
Fixed in HP C++ A.02.10.

KPR #: 4700894113 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
cfront does not complain about anon member and local var with same name

Problem:  
cfront occasionally allows an anonymous union member to have the same name as a local variable.

```
main()
{
  union {
    int yell;
    char *yodel;
  };
  yell = 37;
  char yodel = 'A'; //This should not be allowed
}
```

Duplicate Service Requests: 4700891788

KPR #: 4700894121 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
cfront does not handle static anonymous unions properly

Problem:  
cfront generates bad code for static anonymous union as data member of a class.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700894139 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Variable with the same name as a label is not emitted.

Problem:  
If a variable and label in the same scope have the same name, cfront may incorrectly ignore the variable declaration when it is emitting C code.

Cause:  
// The variable "label" will not be emitted. This is caused by the // emission routines not checking the n\_list field for the variable // declaration.

```
void foo ()
{
  label:
  int label;
  label = 1;
  goto label;
}
```

KPR #: 4700894139 \*\*CONTINUED\*\*

}  
Fix information:  
Fixed in A.02.10 by AT&T.

KPR #: 4700894147 Product: HPC++ COMMON HPCPLUSPLUSA 00.02

One-line description:  
redefinition of default argument not caught as error by cfront

Problem:  
CC doesn't give a compile time error when a default argument for a function is redeclared.

Cause:  
CC doesn't give a compile time error when a default argument for a function is redeclared.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700894154 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Invalid code generation for pointers to static members.

Problem:  
Normal pointers to members contain the offset + 1 from the base of an object. When the code generation for a pointer to a static member is done, the value of the address of the static member is used since it is not attached to any object. When an access is made, the address of the object is added to the address of the static member decremented by 1 which will produce unpredictable results.

Fix information:  
Fixed in A.02.10 by AT&T.  
Pointers to static members are now disallowed.

KPR #: 4700894162 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
link-time unsat for derived class ptbl when using +e0/+e1 facility

Problem:  
When using the +e0/+e1 options, you may sometimes encounter unresolved symbols at link time. These symbols will start with the string "\_\_ptbl". Update by dcc 8/29. While this problem is fixed for 2.1 in the translator (+T option) in the compiler we sometimes have unresolved symbols starting with "\_\_vtbl".

Temporary solution:  
Do not use the +e0/+e1 options. cfront 2.0 does a much better job than 1.2 in determining when to emit virtual tables. The only time cfront obeys the +e0/+e1 option is if you have a class in which all

KPR #: 4700894162 \*\*CONTINUED\*\*

the virtual functions are declared inline. Avoid having such classes; add a dummy non inlined virtual function to such classes, and provide a dummy body for this function.

Fix information:  
Will be fixed in A.03.00

Update 8/29/90. Fixed in A.02.10 for translator (by AT&T) and for new compiler.

KPR #: 4700894188 Product: HPC++ COMMON HPCPLUSPLUSA 00.02

One-line description:  
like-named classes in two different functions disallow ptr to member

Problem:  
Declaring two classes with the same name inside different functions causes cfront to use the wrong type information when processing the uses of the second class, causing spurious errors (or worse, generation of incorrect code).

Fix information:  
Will be fixed in A.03.00

Duplicate Service Requests: 4700942011

KPR #: 4700894204 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
spurious error for initialized array parms

Problem:  
If a function is declared with a default initializer for an array parameter, a later definition of the function gets a spurious error "bad initializer for array".

Fix information:  
Will be fixed in A.03.00

KPR #: 4700894535 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
xdb may print the incorrect value for members of a virtual base class

Problem:  
If a virtual base class is inherited directly and indirectly, xdb may print incorrect values when printing the directly inherited base class.

Fix information:  
This has been fixed in the A.02.10 release.

KPR #: 4700897009 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
allows declaration of uninitialized const structs, classes, & unions

Problem:  
Defining an uninitialized non-external const struct, class, or union using a previously declared tag name is incorrectly allowed (cf. AT&T C++ 2.0 Reference Manual, Section 7.1.6).

Fix information:  
Fixed in A.02.10

KPR #: 4700897017 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
member function declared volatile treated same as const

Problem:  
A volatile member function, which changes a private member, elicits the message:

error : increment of member <class>::<member> of const struct.

Fix information:  
Fixed in A.02.10, with a reasonable error message (not implemented: volatile member functions).

KPR #: 4700898460 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
initialization of union unimplemented

Problem:  
initialization of union using brace-enclosed initializer is not supported.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700898478 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
line numbers not monotonic for inlined constructor

Problem:  
Occasionally, the debug information generated for inline functions has out-of-sequence line numbers, causing the debugger to get confused about the corresponding code locations.

Typical symptoms of this are the inability to set breakpoints on certain statements or functions in a compilation unit, or confusing messages from the debugger when it thinks it is inside a different function than where it actually is.

Fix information:

KPR #: 4700898478 \*\*CONTINUED\*\*

Fixed in A.02.10

KPR #: 4700898734 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
 Typedef altered by cfront that invalidates future declarations

Problem:  
 When a typedef which is a multi-dimensional array is used as a formal parameter to a function, subsequent uses of that typedef outside the function result in spurious error messages.

Fix information:  
 Will be fixed in A.03.00

KPR #: 4700899401 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
 Initialization of AUTO struct (using +a1) gets bus error.

Problem:  
 /\*  
 An automatic struct (but not an array, the other type of aggregate) which is initialized in ANSI mode (using +a1), causes cfront to emit  
 CC: "foo.c", line 6: internal error 3058: bus error (or something nasty like that)

The command used was CC +a1 -c foo.c  
 \*/

```
void foo()
{
    struct St {
        int i, j;
    } s = { 100, 200 };
}
```

Fix information:  
 Will be fixed in A.03.00

Duplicate Service Requests: 4700931659

KPR #: 4700900100 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
 Stream operator<< occasionally appends garbage to output string.

Problem:  
 operator<< on streams occasionally append garbage characters at the end of the string.

KPR #: 4700900100 \*\*CONTINUED\*\*

Fix information:  
 Fixed in A.02.10

KPR #: 4700900118 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
 cfront does not catch access violation when accessed mem is overloaded.

Problem:  
 cfront gets lost when checking access restrictions on overloaded member functions, and as a result, allows incorrect accesses to protected or private member functions.

Fix information:  
 This has been fixed in the next release (HP C++ A.02.10).

KPR #: 4700906339 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
 Misleading message when a break occurs within {} in a switch statement.

Problem:  
 If the code after a case label contains a block with a declaration for a variable with a constructor, and there is a "break" within the block, the message about "statement not reached" (actually talking about the call to the destructor for the local variable) points to the wrong line (usually the first statement after the end of the block).

Fix information:  
 Will be fixed in A.03.00

KPR #: 4700906347 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
 Generated code jumps to address 0 instead of to virtual function.

Problem:  
 When the first non-inlined function of a class with virtual member functions is not defined, the program normally should not link (since the virtual table will never be generated).

However, when the program is compiled with symbolic debug, the compiler accidentally creates a garbage virtual table and links that in, resulting in a silently successful link, but execution errors at runtime when the object tries to use the virtual table.

Temporary solution:  
 The workaround is to define the bodies of all the member functions of a class.

Fix information:  
 Fixed in A.02.10. (The program as described will not link).

KPR #: 4700906347 \*\*CONTINUED\*\*

KPR #: 4700908491 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
not implemented 2012: general initializer in initializer list

Problem:  
Cfront is not able to handle addresses of globals as initializer values for other global variables.

Fix information:  
Fixed in A.02.10.

KPR #: 4700908509 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Bad C code generated with +d for class declared within a class

Problem:  
The declaration of a class within another class can cause CC +d to generate bad C code. The +d flag causes cfront to create C functions for the nested class's methods as soon as they are encountered; if they refer to the containing class's members, an error results, since the containing class's structure has not yet been defined.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700908517 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
garbled error message 1227 and internal error 3058 and bus error

Problem:  
This file looks correct to me.Yet it generates a garbled error message, and a bus error.

Note that the following error message has been shortened and broken up over several lines for STARS consumption.

```
CC -c bug.c
CC: "bug.c", line 14: error 1227: cannot deduce type for
overloaded"bug.c", line 14: CC: "bug.c", line 14:
internal error 3058: bus error (or something nasty like that)
Error code 1
Stop.
```

Fix information:  
Will be fixed in A.02.10

KPR #: 4700908525 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Internal error 3058: bus error for simple syntax error

Problem:  
A simple syntax error (mistyping the name of a constructor) causes a bus error in cfront (causing it to crash).

Fix information:  
Fixed in A.02.10

KPR #: 4700908533 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
not implemented 2020: cannot expand inline function with static var

Problem:  
CC is unwilling to expand an inline function that has a static variable. That being the case, CC should go ahead and make the function non-inline, rather than generate a fatal error.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700908541 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
no "arg not used" warning for array args

Problem:  
CC gives a warning if an argument to a function is not used. Unless the argument is an array type. In this file, both "x" and "y" are unused arguments, but only "y" is flagged with a warning.

Fix information:  
Fixed in A.02.10

KPR #: 4700908558 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
internal error 3111: can't find vptr for some nested class definition

Problem:  
This file has a nested class definition in which the inner class calls a member function for an instance of the outer class. CC gives an internal error "can't find vptr".

Fix information:  
Will be fixed in A.03.00

KPR #: 4700908566 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
unclear constructor-argument error messages for normal errors

Problem:  
Some of the messages given for illegally declared constructors are meaningless or unclear.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700908574 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
phrase "struct A" can't be used in a type cast in struct A definition

Problem:  
The phrase "struct A" can't be used in a type cast in the same statement in which the structure is defined. The error message

"bad initializer... ( struct A \* expected)" is particularly confusing, since "struct A \*" is what was typed.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700908582 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
xdb++ -- empty classes show a member "\_\_w1"

Problem:  
The debug information generated for classes contain entries for some internally-generated symbols which are meaningless to the user.

Fix information:  
Will be fixed in A.03.00

KPR #: 4700916627 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Bad function prototype for stats: 2nd param should be struct stats \*.

Problem:  
The header file <sys/vfs.h> contains an incorrect prototype for the function stats(). The second parameter should be a struct stats \*, not a struct stats.

Fix information:  
Fixed in A.02.10

KPR #: 4700917161 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:

Math.h lacks decls for abs(int) and abs(double), incompatible with ATT

Problem:  
The /usr/include/CC/math.h header file is missing some declarations from the original AT&T source (in particular, declarations for abs(int) and abs(double)).

Fix information:  
Fixed in A.02.10

KPR #: 4700919837 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
CC +p -g: c++merge terminated with signal 11

Problem:  
Certain small files, when compiled with symbolic debug (-g), cause a backend process (c++merge) to abort, leaving behind a truncated object file.

Temporary solution:  
Compile this compilation unit without "-g".

Fix information:  
Fixed in A.02.10

KPR #: 4700921759 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
debuger prints name of local class member function incorrectly

Problem:  
The debugger's "lp" command prints out the wrong information for a member function of a local class, when "+d" is turned on.

Fix information:  
Fixed in A.02.10

KPR #: 4700921767 Product: HPC++ COMMON HPCPLUSPLUSA 00.04

One-line description:  
Conditional operator takes wrong path.

Problem:  
When returning an object with a constructor from a const member function, if the return expression uses a (?:) expression, a lot of extra garbage is generated in the C code, a side effect of which is to always cause the ?: to evaluate to the false half.

Temporary solution:  
Instead of a (?:) expression, use an if-then-else expression to store the value into a temp, and return the temp.



KPR #: 4700921767 \*\*CONTINUED\*\*

Fix information:  
Will be fixed in A.03.00

KPR #: 4700927459 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Several func. prototypes missing from <X11/XHPlib.h>.

Problem:

The include file /usr/include/CC/X11/XHPlib.h is missing function prototypes for many of the HP extension routines, e.g. XHPConvertLookup(), XHPKeysymToRoman8(), XHPSetKeyboardMapping(), etc.

Fix information:  
Fixed in A.02.10

KPR #: 4700927467 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
<CC/dir.h> header has indented #defines, which affects /lib/cpp.

Problem:

The file <dir.h> has #define's that are indented from the left column, which is handled properly by the default preprocessor, but cannot be handled by the K&R preprocessor (invoked by the CC option -Ac).

Temporary solution:

Do not use the -Ac option when compiling a source file which includes <dir.h>.

Fix information:  
Fixed in A.02.10

KPR #: 4700928325 Product: HPC++ COMMON HPCPLUSPLUSA 00.03

One-line description:  
Union initialization in +a0: -- bad C code is generated, cc fails

Problem:

The declarataion of a variable whose type is a structure containing a union causes CC to generate code that gets an error from /bin/cc. CC evidently generates a C declaration of the variable that includes a (normally no-op) initialization to { 0 }. However, a structure containing a union may not be initialized in K&R C.

Fix information:  
Fixed in A.02.10

- HPC++ COMMON -

KPR #: 4700931188 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
compiler puts out bad debug info for members of type static anon. union

Problem:

When a local class (i.e. a class declared inside a function) with a static anonymous union as a member is compiled with -g, the debug information will be slightly corrupt (an attempt to display that particular class will result in an internal error message from XDB).

Fix information:  
Fixed in A.02.10

KPR #: 4700931626 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
xdb++ -- "l" gets confused with breakpoint (using +d): bad debug info.

Problem:

When using +d, cfront occasionally emits bad debug information for one-line inline member functions, like the following:

```
class ex {
  mem1() { /*body*/ }; // one-line function
  mem2() { /*body*/ }; // one-line function
  ...
};
```

The result of this bad debug information is that the user examine the local variables of mem2() with "l" or "p".

Temporary solution:

The workaround is twofold:

- Break up the function definitions, and
- Insert blank lines between the function definitions,

as follows:

```
class ex {
  mem1()
  { /* body */
  }
  mem2()
  { /* body */
  }
  ...
};
```

Fix information:  
Fixed in A.03.00.

- HPC++ COMMON -

KPR #: 4700931634 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
CC gens questionable C code; cc warning "Redeclaration of identifier"

Problem:  
For a class with a static member, if the initialization declaration for the static member outside the class is done without an explicit initializer value, as in

```
class A { static int mem; }; // missing initializer value
int A::mem;
then the translator generates somewhat questionable code (which happens to work under HP C, but gets a warning at compile time).
```

Temporary solution:  
On the 800 only: don't specify the +T flag: this is a problem only with the intermediate C code generation.

Fix information:  
Fixed in A.03.00.

KPR #: 4700931642 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Int. error on array initializers for classes with user-def. constructors

Problem:  
Cfront dies on array initializers for classes with user-supplied constructors. This seems to be sensitive to the actual user program: some cause cfront to abort, and some get away.

Temporary solution:  
The workaround is not to initialize the array at the point of declaration, but instead to initialize it at run-time (program startup time).

Fix information:  
Fixed in A.03.00.

KPR #: 4700931667 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
HP C++ error messages should be in 'standard' (/bin/cc) format

Problem:  
Error messages from HP C++ are slightly confusing, in that the error number and line number are in close proximity to each other, leading to confusion.

Fix information:  
Fixed in A.02.10.

KPR #: 4700931675 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
c++merge does not detect /bin/cc 'static' information

Problem:  
If the environment variable CCOPTS (for the C compiler driver) is set, and contains the flag "-y" (for C static analysis information), the C++ compiler produces garbaged debug information.

Temporary solution:  
Unset the CCOPTS environment variable, or remove the "-y" flag from CCOPTS.

Fix information:  
Fixed in A.02.10

KPR #: 4700934240 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
'sizeof variablename' as dimension in array decl. gets spurious errors.

Problem:  
When "sizeof variablename" is used as a dimension for declaring an array, CC gets a variety of spurious errors.

Temporary solution:  
Instead of using "sizeof variablename", use "sizeof(type)", where "type" is the actual type of the variable.

Fix information:  
Fixed in A.02.10

KPR #: 4700936260 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
xdb fails to indicate that a member function has been declared "const"

Problem:  
When printing a class definition (by using a \t or \T), xdb fails to indicate when a member function has been declared "const".

Fix information:  
Fixed in A.02.10.

KPR #: 4700942466 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Cfront crashes when a non-member function is declared as const.

Problem:  
If the user declares a non-member function as "const" (i.e. with the const keyword between the argument list and the body), then cfront crashes with a "bus error, or something nasty like that", instead of catching the semantic violation and printing an error message.

Fix information:

KPR #: 4700942466 \*\*CONTINUED\*\*

Fixed in A.02.10

KPR #: 4700945311 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
cfront doesn't always detect creating an instance of an abstract class

Problem:

If a base class is abstract, and if a derived class of this base does not redefine any of the abstract base's virtual functions, then cfront does not catch an attempt to instantiate an object of this derived class (which is also abstract, because it did not redefine its parent's pure virtual).

Attempts to call a virtual function through such an object result in a core dump.

Temporary solution:

Redefine any of the parent's virtual functions, especially the pure virtual functions.

KPR #: 4700945386 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Duplicate enumerators not caught in presence of a label

Problem:

Cfront does not complain about the same enumeration constant being used illegally in different enumerated types, if the two type declarations are separated by a label.

KPR #: 5000595447 Product: HPC++ COMMON HPCPLUSPLUSA 02.00

One-line description:  
Yacc stack overflow

Problem:

A function with a very large number of consecutive "else if (...)" constructs can cause the compiler to overflow its parse stack.

This is typically seen when trying to emulate a "string switch"-type construct (i.e. comparing a string against a few hundred string values).

Temporary solution:

For a string switch, the easy workaround is to do a real "switch" on the first character of the string, and then doing strcmp()'s against the subset of string values that start with that character.

For other huge cascaded-if constructs, the workaround is to try to break it up as follows:

```
if (conditional) {
    /*statements*/
    goto done;
```

- HPC++ COMMON -

KPR #: 5000595447 \*\*CONTINUED\*\*

```
}
if (condition2) {
    /*statements*/
    goto done;
}
/*... other conditions ...*/
done:
/* with cascaded if-then-else-if */
```

- HPC++ COMMON -

KPR #: 4700902734 Product: HPC++ S300

B1691A

02.00

One-line description:  
<stdarg> macros don't work on the 300 if the last parm is a reference.

KPR #: 4700905216 Product: OV NM SERVER 300 DEV 36985A

01.00

One-line description:  
sieve manager is not deleting obsolete sieves

Problem:

The event sieve manager does not delete obsolete local sieves since it doesn't find out when a local destination address in a sieve is not longer valid.

If an application creates a sieve containing its local destination address, and then exits without deleting the sieve, the sieve becomes obsolete. However since the event sieve manager gets no errors when it sends unconfirmed events to that sieve, it does not know that the sieve is obsolete so it doesn't delete it.

The sieve will continue to exist until it is explicitly deleted, or until the event sieve manager is restarted.

Fix information:

This defect will be fixed in release A.02.00.

KPR #: 4700907592 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:

Unable to compile a managed object class with filter syntax attribute

KPR #: 4700907600 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:

Misspelling of domainName field for CmotSystemID in the database.

Problem:

The DMS database is preloaded with a syntax definition for CmotSystemID in the Internet module. The domainName field of CmotSystemID was misspelled.

KPR #: 4700907618 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:

A sequence or set syntax can only have 1 field with an identified value.

KPR #: 4700907915 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:

Failure occurs on version access of instance with many attributes.

KPR #: 4700908079 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:

Getting scoped versioned data fails if parent instance does not exist

KPR #: 4700908921 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:  
OveCnvAddr () always return -63001 even if input address is valid

Problem:  
OveCnvAddr() always returns an Ove\_ERR\_CONVERTADDRESS\_UNKNOWN\_TAG error, even if the tag of the input OvcAddress structure is valid.

Temporary solution:  
Most OveEventSieve objects that are created will not have to have a destination address attribute converted with OveCnvAddr() and specified in the attribute list of the OvcCreateReq() call. If no destination address is specified, a default destination address is used which is the address of the requester of the create request. So applications can still create local sieves that send events to the application, and sieves on remote nodes that send events to the local node, without having to use OveCnvAddr() or specify a destination address attribute.

Even if an application wants to create a sieve with a specific destination address, it can do this without using OveCnvAddr(). Instead of specifying the address as an OvcAddress structure and using OveCnvAddr() to convert it to an OvcValue structure, the application can directly specify the destination address in the OvcValue structure using the following OvcAddress template.

```
OvcAddress ::= SEQUENCE {
tag          INTEGER {
nodeName     (1),
networkAddress (2),
localAddress (4)
},
union        OvcAddressChoice,
}
OvcAddressChoice ::= CHOICE {
octetString  OCTET STRING,
networkAddress NetworkAddress,
integer       INTEGER
}
```

Fix information:  
This defect will be fixed in release A.01.03

KPR #: 4700913459 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:  
op blocks not cleared when association is aborted

KPR #: 4700913467 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:  
On rose, rosy fatal errors, the association is not aborted or cleared.

KPR #: 4700917179 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:  
wrong type of results accepted (delete result is accepted for an event)

KPR #: 4700917476 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:  
request id's are non-negative, man pages say they are positive

Problem:  
The man pages for the Ovc\*Req() say

RETURN VALUE  
Upon successful completion, this call returns a positive integer, to be used as a request id.

However, 0 is also a valid request id. The documentation should say that the functions return a non-negative integer to be used a request id.

Fix information:

Ovc API man page for Ovc\*Req have been updated.

RETURN VALUE  
Upon successful completion, this call returns a non-negative integer, which is used as request id.

KPR #: 4700917500 Product: OV NM SERVER 300 DEV 36985A 01.00

One-line description:  
if dopSdata decodes an invoke w/o args, data struct is never freed

KPR #: 4700933580 Product: PHIGS DEV. ENVIRON. BI759A

02.00

One-line description:  
Cursor in wrong position when doing picking in Genesis window.

Problem:

Cursor is in the wrong position when doing picking or using default locator pet in 98736 X window.

Screen behavior is that the PHIGS cursor does not appear on the screen and the X cursor flashes in four positions on screen. The four positions form a rectangle with one corner set to the position where the PHIGS cursor should be and the other corner offset from that position by a distance equal to the distance between the upper-left corner of the window and the upper-left corner of the display. After the flash, the cursor is displayed at the latter position.

PHIGS and X are both competing for the 98736 hardware cursor due to a driver defect.

Temporary solution:

The drivers use check for an environment variable named, SB\_NO\_HW\_ECHO. The workaround is to set this variable after X has been started but prior to starting a PHIGS application.

```
set SB_NO_HW_ECHO=1 ; export SB_NO_HW_ECHO
```

Fix information:

The 98736 driver needs to be modified to not use the hardware cursor when running to an X window. No code change for the rest of the PHIGS library are necessary.

KPR #: 4700933598 Product: PHIGS DEV. ENVIRON. BI759A

02.00

One-line description:

Events are not flushed from queue when a workstation is closed.

Problem:

Events are not flushed when a workstation is closed.

If the PHIGS event queue has events pertaining to a workstation, when that workstation is closed, the events are not flushed. Later, when await event is called, the events are returned with potentially invalid information. Any of the 3 return parameters may have invalid values.

Cause:

The events were inadvertently not being removed at workstation close time. The code has been modified to do so now.

Temporary solution:

A simple workaround is to call pflush (Flush Device Events) for each logical device that was in event mode prior to calling pciwk (Close Workstation).

KPR #: 4700933598 \*\*CONTINUED\*\*

Fix information:

fix is to modify PHIGS internal code to pass the correct parameters.

```
_hp_INP_close_workstation in inp_intern.c calls
_hp_INP_flush_device_events((Generic_WSL_dev_Type *)&device);
and should call it as follows
_hp_INP_flush_device_events(wsl_dev_entry);
```

The internal routine uses the parameter's address to compare to another pointer to see if it is the same device. The cause of the problem is that the code currently passes the address of a local variable and it should pass a pointer to a global data structure.

The fix will likely show up in HP-PHIGS 3.0.

KPR #: 4700942490 Product: PHIGS DEV. ENVIRON. BI759A

02.00

One-line description:

PSCMR handles the definition of zero pseudo colours incorrectly [4,3,-1]

Problem:

Execute Summary:

When zero pseudo colours are specified as a colour mapping representation table entry of type pseudo colour is defined, two erroneous error messages are reported. A colour mapping representation must be immediately defined to avoid leaving colour mapping in an undefined state.

Detailed Summary:

Routine SET COLOUR MAPPING REPRESENTATION (pscmr) is used to define colour mapping representation table entries. One of the fields of each entry is the colour mapping method. When the pseudo colour mapping method is selected, the application must also define a number of pseudo colours, the pseudo colours themselves, and a weight vector. It should be acceptable to define zero pseudo colours. The application might want to do this to effectively delete pseudo colours from the colour mapping table since the number of pseudo colours defined across all entries of the colour mapping table is limited to the depth of the colour representation table.

HP-PHIGS erroneously reports two errors when zero pseudo colours are defined in this way. However the colour mapping representation table entry is defined correctly with zero colours. The error messages are as follows:

```
HP-PHIGS on HP-UX: Error 904 was detected in function 227
Input/Output error has occurred while sending data to a
workstation
PSCMR
```

KPR #: 4700942490 \*\*CONTINUED\*\*

Starbase error 2049: Could not allocate memory.

Procedure name: sbcheck

File descriptor: 8

Device file name: /dev/screen/0phigs

Library location: PHIGS color (0)

System errno: No such file or directory

HP-PHIGS on HP-UX: Error 125 was detected in function 227 Ignoring function, the total of the colour range fields in all the table entries is too large PSCNR

The application should immediately define a colour mapping representation table entry (not necessarily the same entry as was "zeroed") to leave colour mapping in a defined state.

Temporary solution:

There is really no getting around the extraneous error messages. The application also must define a colour mapping representation table entry immediately after defining an entry with zero pseudo colours in order to restore the colour mapping state.

One thing the application can do is to use its own error handler to hide the two extraneous messages from the user. If this is done, it must be recognized either error can legitimately be reported by routine SET COLOUR MAPPING REPRESENTATION (pscmr) in situations other than when zero pseudo colours are being defined.



KPR #: 4700933606 Product: PHIGS FORTRAN MNL. B1759-90001

One-line description:  
Cannot access reset\_rawdev man page on-line

Problem:

Problem Description:

The man page for reset\_rawdev (1) cannot be accessed on-line. This is because the filename /usr/man/man1.Z/reset\_rawdev.1, has 12 characters before the suffix. The filename must have 11 or less characters before the suffix.

Temporary solution:

Workaround:

The man page can be accessed through the Reference Manual hardcopy.

Fix information:

Proposed Fix (to be done in the future):

Rename the file to reset\_rawde.1. This file will be accessed even if the user accesses through "man 1 reset\_rawdev".

KPR #: 4000090860 Product: PROGRAMMERS DOC SET 98794A

06.02

One-line description:  
Sys Admin Manual says do gettools with floppy 8, should be floppy 3

Problem:  
The System Administrators Manual, in the section that talks about Floppy update (page 334) says to use floppy 8 when doing the update. It should say floppy 3.

Temporary solution:  
The S300 6.2 System Administrators Manual, in the section that talks about Floppy update (page 334) says to use floppy 8 when doing the update. It should be changed to read, use floppy 3.

Fix information:  
Has been fixed at the 6.5 release.

Signed off 01/26/90 in release A06.50

KPR #: 4000091702 Product: PROGRAMMERS DOC SET 98794A

06.02

Keywords: DOCUMENTATION

One-line description:  
system admin manual misname device bit

Problem:  
On page 164, the manual says that direct connect terminals should be named ttydxx and dialin ports should be named ttyxx. On page 166, the manual reverses these names.

Temporary solution:  
The workaround is to use the names consistently. The /etc/reconfig command defaults to ttydxx for a direct connect and ttyxx for a dialin. Just remember to use the names in this manner.

Fix information:  
Was fixed at the 7.0 release.

Signed off 12/18/89 in release A07.00

KPR #: 4000094342 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
missing aclentrystart(3C) link to strtocall(3C) manual entry (oops)

Problem:  
aclentrystart not linked in on-line manual files at 7.0.

Temporary solution:  
Link strtocall.3c to aclentrysta.3c in directory /usr/man/man3.2 on 7.0 systems and Series 300 6.5 systems.

KPR #: 4000094342 \*\*CONTINUED\*\*

Fix information:  
Has been fixed for release 8.0. However, Access Control Lists may be deleted at 8.0 or later based on industry trends.

KPR #: 4000094615 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
truncate(2) still contains an invalid BUGS section;

Problem:  
truncate(2) manpage contains invalid BUGS section.

Temporary solution:  
Ignore BUGS section in truncate(2) manual entry. Kernel does not behave as indicated.

Fix information:  
Has been fixed at 7.0.

Signed off 12/18/89 in release A07.00

KPR #: 4000094623 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
open(2), close(2) (and others?) don't mention behavior w.r.t. sockets

Problem:  
open(2), close(2), and others do not describe behavior with respect to sockets.

Cause:  
Enhancement request. Sockets treated same as files.

Fix information:  
No fix planned at present time.

KPR #: 4000094631 Product: PROGRAMMERS DOC SET 98794A

06.06

One-line description:  
Missing asterisks in sigsetops(3C) manual entry in SYNOPSIS

Problem:  
Asterisk missing in source file for sigsetops(3C) manual entry.

Temporary solution:  
Add asterisk in front of set in lines that resemble the following in SYNOPSIS:

sigset\_t \*set;

Fix information:  
Has been fixed at Release 7.0.

Signed off 12/18/89 in release A07.00



KPR #: 4000094656 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
typo, affect should be effect

Problem:  
Typo.

Temporary solution:  
Change affect to effect.

Fix information:  
Fixed at 7.0.

Signed off 12/18/89 in release A07.00

KPR #: 4000094664 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
Man page: "b" command shows wrong syntax for [count] [should be [\count]

Problem:  
Missing \ in various locations in xdb(1) manual entry.

Temporary solution:  
Change [count] to [\count] for b, bb, bx, bu, bt, and ba commands.

Fix information:  
Fixed in release 7.0.

Signed off 10/30/90 in release A07.00

KPR #: 4000094938 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
iomap man page example contains /n instead of \n

Problem:  
Typo. / should be \.

Temporary solution:  
Change /n to \n in example

Fix information:  
Fixed at 7.0.

Signed off 10/26/89 in release 207.00

KPR #: 4000095190 Product: PROGRAMMERS DOC SET 98794A

06.50

One-line description:  
man pages on AXE are missing, and don't work anyway

Problem:  
User on preliminary system with known defects. Ignore.

Temporary solution:

KPR #: 4000095190 \*\*CONTINUED\*\*

None needed. Problem version no longer exists (preliminary software).

Fix information:  
Fixed in release 7.0.

Signed off 10/31/90 in release A07.00

KPR #: 4000096115 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
mount(IM) manpage example options not in same order as SYNOPSIS

Problem:  
Inconsistency of option positions between SYNOPSIS and examples.

Temporary solution:  
None needed. Options position-independent.

Fix information:  
Options are position independent. Manual changed at 7.0 to clearly state this fact.

Signed off 12/18/89 in release A07.00

KPR #: 4000098293 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
group(4) should be linked to loggingroup(4)

Problem:

loggingroup missing from NAME line in group(4) manpage, also no link to loggingroup(4).

Temporary solution:  
None available. Fixed for future releases.

Fix information:  
Added loggingroup to group(4) manpage and added link to database.

Signed off 01/26/90 in release A06.50

KPR #: 4000098301 Product: PROGRAMMERS DOC SET 98794A

06.05

One-line description:  
setmask(2) Manual entry refers to signal(5) Does not exist!

Problem:  
6.5 brick signal(2) entry has SEE ALSO to signal(5) which does not exist.

Temporary solution:  
No workaround. Get 7.0 HP-UX Reference.

Fix information:  
Added signal(5) at 7.0.

KPR #: 4000098301 \*\*CONTINUED\*\*

Signed off 01/26/90 in release A07.00

KPR #: 4000098327 Product: PROGRAMMERS DOC SET 98794A 00.00

One-line description:  
Documenting "lpadmin -g" as setting print job priority.

Problem:  
-gpriority description does not explain what priority (job or fence) is being set.

Temporary solution:  
-gpriority sets job priority as nearly as can be determined at the present time. HP-UX Reference will be updated to correct this problem at next printing after Release 7.0 edition.

Fix information:  
Manpage updated for 8.0 to show correct information.

KPR #: 4000098343 Product: PROGRAMMERS DOC SET 98794A 06.05

One-line description:  
Doesn't document "-a" option

Problem:  
-a option missing on lifcp(1) manpage prior to 7.0.

Temporary solution:  
None available. Replace HP-UX Reference with 7.0 edition (09000-90013).

Fix information:  
-a option description added at 7.0 in HP-UX Reference lifcp(1) entry.

Signed off 01/26/90 in release A07.00

KPR #: 5000420307 Product: PROGRAMMERS DOC SET 98794A 06.02

Keywords: FIND

One-line description:  
The find(1) manual entry does not warn about Context-Dependent Files.

Problem:  
find(1) manual entry does not state that the -hidden option is required to detect context-dependent files for backups, so files are not copied to the backup device.

Temporary solution:  
Prior to 7.0 release, -hidden option must be specified with find(1) to ensure proper backup of CDFs.

Fix information:  
-hidden option added at 7.0 and documented in HP-UX Reference.

KPR #: 5000420307 \*\*CONTINUED\*\*

Signed off 12/18/89 in release A07.00

KPR #: 5000430165 Product: PROGRAMMERS DOC SET 98794A 06.02

Keywords: STARBASE

One-line description:  
the README FIRST for 6.02 incorrectly documents Pdriver

Problem:  
The documentation in the readme for axe 6.02 swapless for users tells the load all filesets. This is incorrect in that the PDRIVER set should not be installed as per the SE readme for axe.

Temporary solution:  
The workaround is to not load all filesets. Instead, Load all filesets except the PDRIVER fileset.

Fix information:  
The fix is to use the information for the workaround. Future releases of HP-UX had (or have) their own, unique README documents. Fixed in release 6.5

Signed off 10/30/90 in release A06.05

KPR #: 5000461467 Product: PROGRAMMERS DOC SET 98794A 06.02

Keywords: DOCUMENTATION

One-line description:  
Explain the difference between symbolic links and hard links.

Problem:  
ln(1) manual entry does not clearly explain the difference between hard links and symbolic links.

Temporary solution:  
The following text was placed in the HP-UX Reference for 7.0 to explain symbolic links:

-S Cause ln to create symbolic links instead of the usual hard links. A symbolic link contains the name of the file to which it is linked. The referenced file is used when an open(2) operation is performed on the link. A stat(2) on a symbolic link returns the linked-to file; an lstat(2) must be performed to obtain information about the link. A readlink(2) call can be used to read the contents of the symbolic link. Symbolic links can span file systems and can refer to directories.

Fix information:  
Fixed in release 7.0.

KPR #: 5000461467 \*\*CONTINUED\*\*

KPR #: 5000462242 \*\*CONTINUED\*\*

Signed off 10/30/90 in release A07.00

Temporary solution:  
The erroneous lines were removed. To copy files from one disk to another, use the following command:

Keywords: DOCUMENTATION

One-line description:  
System admin. manual documents checklist wrong.

Problem:  
I looked at both the manuals and found that both mention about bckup\_frequency first and pass\_number as second ( in the text) but in the example is where the discrepancy lies.  
The example in sys admin manual has pass# first and bckup\_frequency second, therefore the discrepancy.  
Whereas the Section 4 of HPUX reference manual is consistent with text and its example i.e. the bckup\_frequency first and pass\_number second.

Customers look at the example in both the manuals to set up their /etc/checklist and get confused.  
The /etc/checklist at the RC 300 system tallies with the section 4 of Ref. manual.

Temporary solution:

In the 7.0 release, the wording for /etc/checklist was changed to agree with the wording in the HP-UX Reference manual entry for checklist.

Fix information:  
Was fixed in the 7.0 release.

Signed off 10/26/89 in release 207.00

KPR #: 5000462242 Product: PROGRAMMERS DOC SET 98794A 06.05

Keywords: DOCUMENTATION

One-line description:  
Incorrect command for copying from one root disk to another.

Problem:  
The HP-UX commands:

```
cd/
find 'ls|grep -v disc' -print|cpio -pdum /disc
on page 6-28 of the HP-UX Systems Administrator's Manual Vol. 1 part number 98594-90060 revision 6.5 and page 433 of the HP-UX Systems Administrator's Manual Vol. 1 part number 98597-90060 revision 6.2 are incorrect for copying the contents of one root disk to another. This command will not copy any linked files or device files due to the omissions of the l and x options. A correct command to copy all files is:
find 'lsx- ll|grep -v disc' -print|cpio -pdlumx /disc
```

KPR #: 5000462242 \*\*CONTINUED\*\*

Temporary solution:  
The erroneous lines were removed. To copy files from one disk to another, use the following command:

```
cd /
find . -hidden -depth -print | cpio -pdlumx /target
```

Fix information:  
Fix occurred in the 7.0 release.

Signed off 12/18/89 in release A07.00

KPR #: 5000467480 Product: PROGRAMMERS DOC SET 98794A 06.02

Keywords: DOCUMENTATION

One-line description:  
Peripheral guide recommends wrong cable for use with built-in RS232

Problem:

The peripheral installation guide says to use the 9222ip cable with the laserJet. If you use this cable on the built in RS-232 port you will find that the casing is too big to fit.

Temporary solution:  
You need to use the 98561-61604 cable in order to clear the sides of the connector.

Fix information:  
Will be fixed in a future release.

Signed off 10/30/90 in release A07.00

KPR #: 5000475186 Product: PROGRAMMERS DOC SET 98794A 03.01

Keywords: DOCUMENTATION

One-line description:  
Change man page entry and HP-UX Reference Vol2 Sec5 from /usr/lib/term

Problem:

term(5) manpage refers to /usr/lib/term. Should be /usr/lib/terminfo.

Temporary solution:

None. Updated in next release after 7.0. Minor inconvenience.

Fix information:  
Fixed for 8.0.

KPR #: 5000484360 Product: PROGRAMMERS DOC SET 98794A 06.05

Keywords: CHECKLIST

One-line description:  
Sys Admin Manual contains incorrect example of editing checklist file.

Problem:  
/etc/checklist example for swap device incorrect:

The example for /etc/checklist in the 6.5 system admin. manual volume 1 (98594-90650) on page 4-77 for the swap device is incorrect. All the fields need to be included even if not used, so that swapon -a in /etc/rc can operate.

Temporary solution:  
The workaround for /etc/checklist, for example, on a 370 file server with five 340 diskless nodes is to have an entry such as the following one:

/dev/dsk/ls0 /users2 swap default 3 0 # 2nd swap  
Also, the checklist(4) man page shows a correct example for adding a swap device.

Fix information:  
The manual for the 7.0 release has new examples that were taken from a working system.

Signed off 10/12/89 in release A07.00

KPR #: 5000489187 Product: PROGRAMMERS DOC SET 98794A 06.05

Keywords: CU

One-line description:  
the suspend feature of cu is not completely documented

Problem:  
Documentation unclear: Return required after lines beginning with tilde.

Temporary solution:  
Press Return after all cu input lines that start with tilde, including the ~suspend sequence. While not specifically stated, this is implied in the descriptive text since the section in question deals with "lines that begin with a tilde", and all lines in the UNIX/HP-UX environment must be terminated by a new-line character (Return key).

Fix information:  
Added clarification to cu(1) entry for 8.0.

KPR #: 9999004824 Product: RJE/300 31447A 04.01

Keywords: OS

One-line description:  
Problem W/RJE -Configured for 2780 emulation s/be no space compression.

Problem:  
Question missing for Set Options script.

Cause:  
Incorrect data type.

Fix information:  
Fixed in 10/06/80 version.

KPR #: 9999004825 Product: RJE/300 31447A 04.01

Keywords: RJE300

One-line description:  
First 15 bytes of message not transmitted.

Problem:  
Send message loses text.

Cause:  
Only the last char string was kept. This is a problem in the praise routine.

Fix information:  
Fixed in future version.

KPR #: 9999004826 Product: RJE/300 31447A 04.01

Keywords: RJE300

One-line description:  
Unreasonable errors occur with Edit Commands softkey.

Problem:  
Edit commands creates the temporary file on the wrong pack.

Cause:  
Files on volumes other than the current one should not be allowed.

Fix information:  
Fixed in 10/06/80 version.

KPR #: 9999004848 Product: RJE/300 31447A 04.01

Keywords: RJE300

One-line description:  
Executive command receive error.

Problem:

KPR #: 9999004848 \*\*CONTINUED\*\*

RUI closes line.

Cause:  
Improper processing of RUI.

Fix information:  
Fixed in 10/06/80 version.

KPR #: 9999004961 Product: RJE/300 31447A 04.01

Keywords: RJE300

One-line description:  
The S in SELECT SOFTKEY truncated from message window.

Problem:  
When softkey is pushed, the "s" in "Select a softkey" is command.

Cause:  
TMCLEAR was not called. TMCPUTN was called with a blank line.

Fix information:  
A call to TMCLEAR was added.

KPR #: 9999004997 Product: RJE/300 31447A 04.01

Keywords: RJE300

One-line description:  
Error 'Automatic Receive, on Receive file invalid'.

Problem:  
Receive softkey is invalid. RJE thinks auto receive is on.

Cause:  
Also receive was turned off.

KPR #: 9999005048 Product: RJE/300 31447A 05.02

Keywords: RJE300

One-line description:  
Command file from workstation causes crash after SIGNON.

Problem:  
Posting a TAM listen request twice caused a crash.

Fix information:  
Check for a double post, don't post a previously posted request. Fix to QA 11/13/80.

KPR #: 9999005097 Product: RJE/300 31447A

04.01

Keywords: RJE300

One-line description:  
Crash during file transfer from 250 to 300.

Problem:  
CP'KILL'TIMER problem patch to QA 11/13/80.

KPR #: 9999005225 Product: RJE/300 31447A 05.02

Keywords: COMMANDS

One-line description:  
RJE USING "commandfile" does not work.

Problem:  
RUN using "CMDFILE" does not work, RJE aborts.

Cause:  
RJE tried to clear a non existant window.

Fix information:  
Window is now cleared only when RJE is in interactive mode.

KPR #: 9999005230 Product: RJE/300 31447A 05.02

Keywords: SF18

One-line description:  
RJE Using "commandfile" causes crash.

Problem:  
RJE using "Commandfile" causes \*Crash\* TCB=14EA CST=150 Deltap=156  
Bounds Violation Code=18 Parm=44 #-1 #20236 #88 [TM=12, Deltap=6NBB  
of task RJECON]

KPR #: 9999005359 Product: RJE/300 31447A 04.01

Keywords: COMM

One-line description:  
System crash while doing a send message

KPR #: 9999005459 Product: RJE/300 31447A 05.03

Keywords: COMM

One-line description:  
Crash when receive null block from IBM

Problem:  
2780-IBM. Receive null block from IBM and  
\*CRASH\* TCB=13FA CST=150 DELTAP=1120  
DSEG bounds violation CODE=11C PARMS=44 #-11 #-8767 #0

KPR #: 4000027565 Product: RJE/300 50967A 01.00

KPR #: 4000093039 \*\*CONTINUED\*\*

One-line description:  
If the background process cannot access rje\_joblog, user waits 90 sec.

The problem was caused by using the fgets() library function to read the binary file length within the queue file.

Problem:  
If rje\_init cannot open rje\_joblog, the user is notified immediately that rje cannot open rje\_joblog, however, it may be 30-90 seconds before the "link terminated abnormally" message appears to stdout. During this time the link is down and idle. Users should not attempt to initiate any new processes during this time, but just wait 30-90 sec.

fgets() terminates on linefeed characters (Hex 0A). Thus, some of the length bytes may be ignored if one of the bytes in the length happens to be a linefeed.

The problem has been corrected by using fread() instead of fgets() to read the file length. The fix will be incorporated in the next release.

Fix information:  
May be corrected in a future release.

Signed off 06/21/90 in release A02.00

KPR #: 4000084970 Product: RJE/300 50967A 01.00

KPR #: 4000093492 Product: RJE/300 50967A 01.00

One-line description:  
RJE/300 does not work with long file names

One-line description:  
rje\_bg or rje\_router can hang writing job notification to PTY terminal

Problem:  
rje\_send will hang for any long path, not just paths containing long file names. The longest path that may be safely used is 24 characters. (RD)

Problem:  
rje\_bg and rje\_router may hang under some circumstances. This may happen when these programs try to write to a terminal to inform a user of some change in a job's status. This happens only if the user is logged in to HP-UX on a PTY port (i.e. via the LAN) and the same user has previously been logged in to a lower numbered PTY port and no other user has logged in to that lower numbered PTY port.

Fix information:  
The path is copied into a data structure which was too small.

This will be fixed in RJE 2.0. The data structure will be expanded to accommodate paths of 1024 bytes. (RD)

Signed off 06/21/90 in release A02.00

Here is an example:

1. rjeuser logs in via /dev/pty/ttyp4
2. rjeuser logs in a second time via /dev/pty/ttyp5
3. rjeuser logs out from the session on ttyp4
4. rjeuser sends a job with rje\_send from ttyp5
5. the job has a usr card that causes rje to attempt to write some notification message to rjeuser's terminal.

One-line description:  
Binary files of certain lengths sent incorrectly using ~ control lines

Problem:  
Some binary files may be transmitted incorrectly if the length of the file falls within certain ranges and the binary file is sent using a control line beginning with ~.  
For example, if the input to rje\_send is  
~! -b cat datafile  
and datafile is 2700 bytes long, then the problem will occur.

The file sizes that are affected are:

- Hexadecimal XXXX0AXX: {2560-2815, 68096-68531, 133632-133887, etc}
- Hexadecimal XX0AXXXX: {655360-720995, 17432576-17498111, etc}
- Hexadecimal 0AXXXXXX: {167772160-184549375}

Temporary solution:  
The problem can be avoided by using rje\_send -b instead of using the ~ control lines within the rje\_send input file.

Fix information:

Temporary solution:  
Here are some workarounds for this problem:

1. Avoid choosing notification options in the usr card that write to the terminal.
2. Avoid logging in via a pty port.
3. Avoid logging in more than once at any one time.
4. If one of these programs does hang, it is possible to "unhang" it by opening the master pty file that it is waiting on. To determine which port is involved, use who -d to get a list of "dead" ports. Any ports that were last used by the same rje user who submitted the job should be opened.

For the example given in the submitter text, the following line would "unhang" the rje software.  
cat </dev/ptym/ptyp4

Fix information:  
May be fixed in a future release.

KPR #: 1650040139 Product: S300 GENERAL HPUX 98680B

KPR #: 1650040139 \*\*CONTINUED\*\*

Keywords: CSH

Keywords: MAN

One-line description:  
Csh(1) documentation in error about some features.

KPR #: 1650040147 Product: S300 GENERAL HPUX 98680B 05.50

Problem:  
THE BUILT IN CSH-COMMAND 'alloc' DOES NOT WORK.  
GIVES 'command not found' MESSAGE WHEN INVOKED.  
THE COMMANDS 'bye' AND 'gd' BOTH EXISTS IN CSH.  
AS BUILT-INS, BUT ARE NOT DOCUMENTED!!  
COMMAND 'history -h' WORKS BUT IS NOT DOCUMENTED!!

One-line description:  
"man -t" gives core dump.

Problem:  
IF YOU PRESS 'man -t' ACCIDENTLY THIS GIVES YOU SEGMENTATION  
FAULT, CORE DUMPED!!

Cause:  
This defect report contains several problems:

Cause:  
At this point (Aug, 1990), the cause of the original problem is unknown.

1. The alloc built-in does not work.
2. The history -h built-in works but is not documented.
3. The gd built-in works but is not documented.
4. The bye built-in works but is not documented.

The alloc built-in does not work because it is only compiled into csh when a 'Debug' compiler directive is used to build the shell. This compiler directive is not used to build release bits for csh.

Temporary solution:

The csh manual page has been changed for release 8.0 to include documentation about the 'gd' and 'bye' built-ins, along with a related built-in, 'rd'. The 'gd' and 'rd' built-ins are synonyms for 'pushd' and 'popd', respectively, and 'bye' is similar in function to 'logout' (the only difference being that it works for sessions which are not login shells). These built-ins are documented with their standard counterparts ('pushd', 'popd', and 'logout'), but their use is discouraged since they are not part of the standard BSD csh and may not be supported in future releases.

The 'history -h' built-in was documented in the manual page for release 7.0.

The 'alloc' built-in is only present if a 'DEBUG' compiler directive is used to build csh. This is not done for released versions of csh. Therefore this built-in will not be supplied in the HP-UX version of csh.

Fix information:

The csh manual page has been changed for release 8.0 to include documentation about the 'gd' and 'bye' built-ins, along with a related built-in, 'rd'. The 'gd' and 'rd' built-ins are synonyms for 'pushd' and 'popd', respectively, and 'bye' is similar in function to 'logout' (the only difference being that it works for sessions which are not login shells). These built-ins are documented with their standard counterparts ('pushd', 'popd', and 'logout'), but their use is discouraged since they are not part of the standard Berkeley csh and may not be supported in future releases.

The 'history -h' built-in was documented in the manual page for

Known Problem Reports as of 11/21/90

KPR #: 1650040139 \*\*CONTINUED\*\*

Keywords: MAN

KPR #: 1650040147 Product: S300 GENERAL HPUX 98680B 05.50

One-line description:  
"man -t" gives core dump.

Problem:  
IF YOU PRESS 'man -t' ACCIDENTLY THIS GIVES YOU SEGMENTATION  
FAULT, CORE DUMPED!!

Cause:  
At this point (Aug, 1990), the cause of the original problem is unknown.

Fix information:  
Fixed in release 6.0.

Signed off 11/07/90 in release B06.00

KPR #: 1650041160 Product: S300 GENERAL HPUX 98680B 05.21

Keywords: XARGS

One-line description:  
Xargs(1) of more(1) doesn't work as documented.

Problem:  
The xargs command does not function consistently. For example you get different responses for the two following uses of the command.  
execute # cd /usr/include

```
then
or # ls *.h | xargs -i -p cat {}          - this works as expected.
  # ls *.h | xargs -i -p more {}         - this does a more of all
                                         of the args, and than a
                                         more of the last arg.
```

Cause:

The default action for more is to first read standard input and then process file arguments. In the case of:

```
ls *.h | xargs -i -p more {}
```

both more and xargs share the same standard input. Hence, when a file is selected by xargs, more reads the rest of the standard input (i.e. the output from ls \*.h) and then processes the selected file. After returning, xargs finds that it has no more input, so it exits.

Fix information:

Fixed in HP-UX release 8.0.

KPR #: 1650050294 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: SH

One-line description:  
Report of shell script that results in unexpected logout when run

Problem:  
The customer sent me the following program (script). With that program he compiles c programs redirection to a file. And the file will be printed to the screen. While the program runs type one or more backspaces after the small program is finished you will automatically logged out.  
Contents of the program : cc -c -g \$1.c 2>errfile  
cat errfile|more

Fix information:  
This defect will be fixed in HP-UX 9.0.

KPR #: 1650057828 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: TBL

One-line description:  
"tbl" doesn't produce proper looking boxes on laser jet printer

Problem:  
Steven is using the following command:-  
tbl -Tlj test|nroff -Tlj -ms |lp -nroff  
On the following file called test:-

```
.TS  
allbox center;  
C C C.  
Number Name Crossings  
1 James 3  
2 Dave 4  
3 Alex 5  
4 Murdo 8
```

.TE  
Using 330 HPUX Rev6 (Diskless) with a Laserjet II. The output table has vertical lines that are jagged, that is they drift to the right then left by one or two pixels.

-----  
The command pipe of "tbl <file> | nroff -Tlj | lp -onroff" was producing incorrect results when sent to a Laserjet printer. The vertical lines would be seen at the bottom of the table, gradually drifting to the right of the page.

Cause:  
The problem was not with tbl nor nroff, but instead with the filter program /usr/lib/lprpp, which was munging the characters and escape sequences being output by the -Tlj option of nroff. This filter has been modified to leave the output untouched so that it displays correctly on Laserjet printers.

Temporary solution:

KPR #: 1650057828 \*\*CONTINUED\*\*

A possible workaround is to use:

```
tbl test | nroff -Tlj -ms | lp -oraw
```

instead. Note that tbl does not have the -T option as stated in the .submitter file.

Fix information:  
The fix will be in Release 8.0.

KPR #: 1650070474 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: KERNEL

One-line description:  
HPiB printer driver does not handle graphics properly

KPR #: 1650074385 Product: S300 GENERAL HPUX 98680B 02.01

One-line description:  
lint false errors on missing library entries mkdir(2) and rename(2)

Problem:

The problem was that the mkdir(2) and rename(2) entries were missing from the lint library.

Cause:  
The cause is missing lint library entries.

Fix information:  
Was fixed in HP-UX 7.0.

Signed off 10/30/90 in release B07.00

KPR #: 1650076091 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: FDB

XDB

One-line description:  
fdb has problems with formal arguments to CHARACTER\*(\*) subroutines

Problem:

Given this program:

```
PROGRAM X  
IMPLICIT NONE  
CHARACTER*5 Str1  
DATA Str1 /'Test'/  
CALL Sub1(Str1)  
END  
SUBROUTINE Sub1 ( Char1 )  
IMPLICIT NONE  
CHARACTER*(*) Char1  
PRINT *,Char1  
CALL Sub2(44)
```



KPR #: 1650076091 \*\*CONTINUED\*\*

KPR #: 1650082529 \*\*CONTINUED\*\*

```

RETURN
END
SUBROUTINE Sub2 ( Int1 )
IMPLICIT NONE
INTEGER Int1
PRINT *, Int1
RETURN
END
    
```

Fix information:  
Code was fixed for 7.0 as part of POSIX cleanup.

Signed off 11/07/90 in release B07.00

KPR #: 1650085514 Product: S300 GENERAL HPUX 98680B 06.02

Execute:

```

>S
>S
>S
>T
0 sub1 (char1 = '') [x.f: 15] <---- char1 = 'Test' !!!
1 MAIN () [x.f: 6]
  str1 = 'Test'
  2 main + 0x20 (0x1, 0xffeffe84, 0xffeffe8c, 0xffeffecc, 0)
    
```

Cause:  
Any access to a FORTRAN parameter of type CHARACTER(\*) on the series 300 will return an incorrect value.

Fix information:  
Fixed in B.08.00.

KPR #: 1650076422 Product: S300 GENERAL HPUX 98680B 03.00

One-line description:  
Using cu over 37212B at 2400 baud results in loss of banner if CCITT.

Temporary solution:  
No known workaround at this time.  
This problem is currently being investigated.

6-29-89

KPR #: 1650082529 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: LINT

One-line description:  
lint Gives unexpected error messages

Problem:  
The code was not bracketed with #ifdef KERNEL as it should have been.

Cause:  
Header file should have been #ifdef'ed properly. POSIX changes have addressed many similar problems.

Temporary solution:  
The fixed version of types.h will be shipped with 7.0, but people can delete the problem line from their local

- S300 GENERAL HPUX -

Keywords: CATMAN

One-line description:  
/usr/lib/mkwhatis script sometimes produces memory fault errors.

Problem:  
When working in some directories with a large number of manpages, too long an argument list was being constructed for for deroff. It responded ungracefully.

Cause:

The cause was too long an argument being passed to one of the commands in the mkwhatis script.

Fix information:  
Fixed in Release 8.0.

KPR #: 1650088997 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: FDB

One-line description:  
FDB does not handle array parameters correctly

Problem:  
When a statically initialized int array is passed to as an argument, the values are not correctly accessed by the parameter name in the called routine, in some cases. Here's an example program that shows the

```

problem:
program gm
integer abc(3,3),n,ar
data abc/1,2,3,4,5,6,7,8,9/
n = ar(abc,3)
end
integer function ar(ap,nr)
integer nr,ap(nr,3)
ar = 10
return
end
    
```

Changing the declaration of ap to

- S300 GENERAL HPUX -

KPR #: 1650088997 \*\*CONTINUED\*\*

integer.ap(3,3)  
fixes the problem.

KPR #: 1650090753 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: C

One-line description:  
value of boolean expression goes on stack correctly but does not return

Fix information:  
Fixed for 7.40

KPR #: 1650093328 Product: S300 GENERAL HPUX 98680B 05.02

Keywords: VI

One-line description:  
PROBLEM WITH UNDO FOR GLOBAL CHANGES IN MACROS IN VI

Problem:  
When the command like ":1,\$g/xx/s/xxx/yyy/" is used as a macro in vi(1), the first execution of it succeeds, but if 'u' command is used and after that the macro is used again, only two top lines are changed and the error "Can't undo in global commands" occurs.

Cause:

In executing the macro which causes the large change like "g/xx/s/xxx/yyy/", vi(1) reconstructs the state for the undo operation by using the undo facility in executing "s" command. But basically, the undo facility is inhibited in the global command, so the error occurs. And the state to undo "g" command is saved first of all then the reconstruction in executing "s" command is unnecessary. Before the commands related to the macro ( in this case, 'u' command ) are used, the state is set the special value, so "g/xx/s/xxx/yyy/" command works well unexpectedly.

Fix information:  
Will be fixed in the 8.0 release of HP-UX for the Series 300 and 800.

KPR #: 1650093351 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: UPDATE

One-line description:  
/ETC/MAGIC ALWAYS GETS OVERWRITTEN DURING AN UPDATE

Problem:  
When a system is updated, a tailored /etc/magic is overwritten, since the update media directly stores the new magic file in /etc/magic. This causes customer modifications to /etc/magic to be lost.

02/28/90

Cause:

- S300 GENERAL HPUX -

KPR #: 1650093351 \*\*CONTINUED\*\*

The /etc/magic file is supplied on the update tape as /etc/magic instead of /etc/newconfig/magic.

02/28/90

Temporary solution:

A workaround to this problem is to save your modified /etc/magic file in a temporary place before updating to the 7.0 release. After the update, merge your changes into /etc/magic.

This workaround will not be necessary when updating to 8.0, the 8.0 update will not overwrite a customized /etc/magic file.

02/28/90

Fix information:

Fixed in the 8.0 release of HP-UX on the Series 300 and 800.

02/28/90

KPR #: 1650100172 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: CU

One-line description:  
there is no environment passed when using ~! and cu

Problem:

The users environment was being completely destroyed by cu.

Cause:

An error in the design for cleaning the environment of setuid programs caused all environment variables to be reset

Temporary solution:  
none

Fix information:

Code was added to preserve the users environment at program entry and restore it after the uid's are reset in the fork routine.

Fixed in 8.0.

KPR #: 1650100230 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: COL

One-line description:  
tbl | nroff | col gives box with staggered line on Laserjet

Problem:

/usr/lib/lprpp filter attempts to shift char2 in the sequence "<char1>\<char2>" in an attempt to get the laserjet to embedden text. tbl|nroff produces table box character sequences like "\_\| " to form

- S300 GENERAL HPUX -

KPR #: 1650100230 \*\*CONTINUED\*\*

intersecting lines. lprpp shifts the '|', like it would a second ', in  
 "\_b", to attempt emboldening. On lines with "\b" the vertical bar  
 does not line up with those on lines with just "I".

Cause:  
 lprpp was not designed with tbl output in mind.

Temporary solution:  
 Use "tbl file\_name | nroff -Tlp | col -b | lp".

Fix information:  
 Fixed in the 8.0 release. Revision 66.1.

The nroff command should be used with the -Tlp option in this  
 application.

KPR #: 1650101147 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: CDB

One-line description:  
 cdb(1) only reports first value of local variable on stack

Problem:  
 Given this program:

```
main()
{
    int i;
    {
        int i;
        i = 4;
    }
    i = 5;
    return 0;
}
```

Execute:  
 >9 b  
 >r  
 >(i)

The value printed is 4 instead of 5.

Cause:  
 If more than one variable has the same name in C (due  
 to nested blocks), it is possible that the wrong one will  
 be referenced when specifying its name in an expression.  
 For example, the variable actually accessed is one in a  
 more deeply nested block than the current viewing location.

Fix information:  
 Fixed in B.07.06

Signed off 11/16/90 in release B07.06

KPR #: 1650101246 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: ACCOUNTING

One-line description:  
 acctcom(1M) shows time one hour earlier than -e or -s option specified

Problem:

The problem was that acctcom was incorrectly handling times passed as  
 parameters. It was subtracting an hour when it should not and thus the  
 output was wrong when selecting records based upon time.

Cause:  
 The problem was a line of code changed at level 62.1 where the hour  
 specifier was decremented by one before multiplying it by 3600 in order  
 to convert it to seconds.

Fix information:  
 This is fixed in 8.0.

KPR #: 1650102194 Product: S300 GENERAL HPUX 98680B 03.01

One-line description:  
 Special handling needed for SR #1650102194. See labtext.

KPR #: 1650130989 Product: S300 GENERAL HPUX 98680B 05.02

Keywords: LIFCP

One-line description:  
 lifcp from a floppy begins with a wrong header and cannot be read

Problem:  
 PASCAL workstation changed their implementation of lif files, adding a  
 "ws header" which contains information not available to lifcp.  
 Therefore, lifcp can not create "ws header" information. Lif\*(1) is  
 only intended as an interchange format to get data from one system to  
 another. It is therefore reasonable to assume that it will be converted  
 into a meaningful and useful format on the target system by the user.

Temporary solution:  
 Use RMB/UX, BASIC or PASCAL workstation to copy the files from lif disk  
 to the HP-UX system.

Fix information:  
 The lifcp(1) documentation was changed to show an example of the copy of  
 a bdat file. An example from the HP-UX 8.0 Release manual page follows:

```
lifcp -r -T 0xffff961 -i 0x20200080 bdat lifvol:BDAT
```

Copy a BDAT file, without a password, from a BASIC WorkStation to an  
 HP-UX LIF volume lifvol. Note that -i controls protection and record  
 size attributes. The file type for a BDAT file is -5791 (or 0xffff961)  
 and its record size is 256 bytes per record.

Known Problem Reports as of 11/21/90

Known Problem Reports as of 11/21/90

KPR #: 1650134353 Product: S300 GENERAL HPUX 98680B

KPR #: 4000003756 \*\*CONTINUED\*\*

Keywords: KERMIT

This may be demonstrated if you have two getty lines, one of them marked as "once", the other as "respawn".

One-line description:  
Kermit's automatic naming only works once, then overwrites file

Problem:

Kermit was not reading a long filename directory correctly. In ckufio.c, function "traverse", kermit was using a simple read on a file descriptor to obtain the file names. I modified the read so that directory(3C) statements were made. All changes were qualified with a "#ifdef HPUX".

Cause:

Kermit was not reading a long filename directory correctly. In ckufio.c, function "traverse", kermit was using a simple read on a file descriptor to obtain the file names. I modified the read so that directory(3C) statements were made. All changes were qualified with a "#ifdef HPUX".

Temporary solution:

Contact an SE to obtain the available patch.

Fix information:

Fixed in 8.0.

KPR #: 4000003756 Product: S300 GENERAL HPUX 98680B

KPR #: 4000003830 Product: S300 GENERAL HPUX 98680B

Keywords: LOGIN

One-line description:

People may appear logged in when they are not.

Problem:

Login only logs user IN to the logging files /etc/utmp and /usr/adm/wtmp. Getty is the only way to log someone OUT. If you let a user log in but then do not start another getty for their line when they log out, they continue to be "logged in".

Cause:

This problem was caused by a design flaw in /etc/init as derived from the original ATT System V.2 code.

When /etc/init handles the SIGCLD signal as the result of a death of one of its children, /etc/init records the fact that the child is dead along with its exist status in an internal data structure. However, it doesn't update the /etc/utmp entry for that child until it wishes to spawn another child. For "respawn" entries, this ends up being immediately, but if the child from a "once" entry terminates, the /etc/utmp entry for that child isn't updated until the next time /etc/init spawns a child (which might not occur for a long time).

03/16/90

Temporary solution:

Manage inittab carefully; never bring down the system until all users have logged out and have "login:" prompts from getty on their terminals.

Fix information:

Fixed in the 7.0 release of HP-UX on the Series 300 and 800.

03/16/90

Signed off 11/16/90 in release B07.00

Keywords: LOGIN

PASSWD

One-line description:

Very long fields in /etc/passwd mess up login.

Problem:

Very long fields in /etc/passwd (see the manual page for particulars) cause unpredictable things to happen to the login command.

Cause:

The login command does not limit the field lengths to the size of the space allocated, so other variables are overrun. This is a System III feature

Temporary solution:

Avoid overly-long /etc/passwd fields.

Fix information:

Fixed in HP-UX release 8.0

KPR #: 4000017020 Product: S300 GENERAL HPUX 98680B

04.00

Keywords: NROFF

One-line description:  
NROFF does not support any printers except the obsolete 2631B.

Problem:  
NROFF does not support any HP printer, except for the obsolete 2631B. Clever printers like the 2934A/2686A etc are supported by the op. sys., but not by relevant utilities like nroff.

KPR #: 4000019570 Product: S300 GENERAL HPUX 98680B

00.00

Keywords: DOCUMENTATION

DD

One-line description:  
Problem with dd with seek and mag tape

Problem:  
The manual entry for the "dd" command lists a "seek" option. (It allows skipping "n" records into the OUTPUT file before writing. The "seek" option doesn't have any effect when the output file is a 9-track mag tape. This is the way the code is written. We need to update the reference page to explain that the "seek" option has no effect on mag tape. [Perhaps an example with explanation would be sufficient.] See dd(1) and lseek(2), and the source code for "dd".

Temporary solution:  
Added following into the dd(1) manual page.

before modify:  
seek=n Skip n blocks from beginning of output file before copying.  
-----  
after modify:  
seek=n Skip n blocks from beginning of output file before copying;  
this option is ignored on a raw magnetic tape device. See  
mt(1) for information about operations on raw magnetic tape  
devices.

Fix information:  
Will be fixed in the 8.0 release of HP-UX.

KPR #: 4000092437 Product: S300 GENERAL HPUX 98680B

05.20

Keywords: LIBM

C

One-line description:  
Math routine, pow, does not handle overflow correctly.

Problem:  
The pow() function doesn't handle overflow properly when given a  
small value:

pow(3.3e-308,2)

KPR #: 4000092437 \*\*CONTINUED\*\*

returns: 1.79e+308  
When multiplication of 3.3e-308 by itself produces 0.0.

Fix information:  
Has been fixed for HPUX 8.0.

KPR #: 4000094060 Product: S300 GENERAL HPUX 98680B

06.05

One-line description:  
Invalid form in recognize\_array: During reg alloc because of common sub.

Problem:  
The compiler aborts with the following message:

C1 internal error in <routine>: invalid form in recognize\_array  
Temporary solution:  
This problem occurs when one type of optimization, specifically common subexpression elimination, creates a state in the internal data structure that a later phase of the optimizer is unable to handle.

The workaround is to use a special option to the optimizer that disables the first optimization:

-Wg,-d

Include this option in the cc command line:

cc -O example.c -Wg,-d

This will turn off common subexpression elimination for the entire file example.c. Another option is to turn off optimizations for the routine that was indicated in the error message:

cc -O example.c -Wg,-padd\_pn

(The routine name is add\_pn. -paddpn tells the optimizer to 'pass' the input through unoptimized for routine addpn.)

Fix information:  
Will be fixed for HP-UX release 7.40.

KPR #: 4000096487 Product: S300 GENERAL HPUX 98680B

06.05

One-line description:  
cc -O chokes on the appended code.

Problem:  
This defect is due to the fact that the code generator was loading pointer differences which were being used to index into an array, into address registers rather than data registers as would have been appropriate. The pointer type of the "index" operand was incorrectly

KPR #: 4000096487 \*\*CONTINUED\*\*

```

leading codegen to load an address (.vs. data) register.
Cause:
If you are not the correct group, please forward.
cc -c -O -DHPUX -DOS=HPUX search.c
- results in -
search.c, line 35: compiler error: no table entry for op REG.
If I invoke without optimization, it compiles.
SOURCE FILES:
<----->
#include "runtest.h"
Search(Pattern,PatLen,EndBuff, Skip1, Skip2, Desc)
char Pattern[];
int PatLen;
char *EndBuff;
int Skip1[], Skip2[];
struct PattDesc *Desc;
{
    register char *k, /* indexes text */
                *j, /* indexes Pattern */
                *PatBegin; /* register pointing to char
                * before beginning of Pattern */
    register int Skip; /* skip distance */
    char *PatEnd,
            /* pointers to last char in Pattern and Buffer */
            *BuffEnd;
    BuffEnd = EndBuff;
    PatBegin = Pattern - 1;
    PatEnd = Pattern + PatLen - 1;

    k = Desc->Start;
    Skip = PatLen-1;
    while ( Skip <= (BuffEnd - k) ) {
        j = PatEnd;
        k = k + Skip;
        while ( j > PatBegin && *j == *k ) {
            /* while */
            if (j < Pattern) {
                /* found it. Start next search
                * just after the pattern */
                Desc -> Start = k + 1 + Desc->PatLen;
                return(1);
            }
            /* if */
            Skip =
            bm_max(

```

KPR #: 4000096487 \*\*CONTINUED\*\*

```

} /* while */
Desc->Start = k;
return(0);
} /* Search */
<----->
/* this is the file of global declarations for Scaffold+ runtest */
#if defined(OS2)
#define ARG_MAX 128
#define LOOP 249
#define INCL_DOS
#define INCL_ERRORS
#define INT_SLASH '\\'
#define PATH "\\."
#define SLASH "\\"
#include <os2def.h>
#include <bsedos.h>
#include <baseerr.h>
#include <dos.h>
#include <stdlib.h>
#include <signal.h>
#include <stdio.h>
#include <fcntl.h>
#include <sys\types.h>
#include <sys\stat.h>
#include <ctype.h>
#include <malloc.h>
#include <errno.h>
#include <time.h>
#include <process.h>
#include <string.h>
#include <sys\utime.h>
#define BUF_SIZE 4*BUFSIZ
typedef unsigned short attribute;
typedef struct _dstruct {
    FILEFINDBUF *pBUFFER;
    HDIR handle;
    HDIR *pHANDLE;
    int f FIRST;
    USHORT searchcount;
    char *path;
    USHORT apirc;
    USHORT apiattrib;
} DSTRUCT;
char * getcwd();
#endif

```

KPR #: 4000096487 \*\*CONTINUED\*\*

```

- results in -
search.c, line 35: compiler error: no table entry for op REG.
If I invoke without optimization, it compiles.
SOURCE FILES:
<----->
#include "runtest.h"
Search(Pattern,PatLen,EndBuff, Skip1, Skip2, Desc)
char Pattern[];
int PatLen;
char *EndBuff;
int Skip1[], Skip2[];
struct PattDesc *Desc;
{
    register char *k, /* indexes text */
                *j, /* indexes Pattern */
                *PatBegin; /* register pointing to char
                * before beginning of Pattern */
    register int Skip; /* skip distance */
    char *PatEnd,
            /* pointers to last char in Pattern and Buffer */
            *BuffEnd;
    BuffEnd = EndBuff;
    PatBegin = Pattern - 1;
    PatEnd = Pattern + PatLen - 1;

    k = Desc->Start;
    Skip = PatLen-1;
    while ( Skip <= (BuffEnd - k) ) {
        j = PatEnd;
        k = k + Skip;
        while ( j > PatBegin && *j == *k ) {
            /* while */
            if (j < Pattern) {
                /* found it. Start next search
                * just after the pattern */
                Desc -> Start = k + 1 + Desc->PatLen;
                return(1);
            }
            /* if */
            Skip =
            bm_max(

```

KPR #: 400096487 \*\*CONTINUED\*\*

```
#if defined(DOS)
#define ARG_MAX 128
#define ELOOP 249
#define INT_SLASH '\\\
#define PATH "\\\"
#define SLASH "\\"
```

```
#include <dos.h>
#include <os2.h>
#include <stdlib.h>
#include <signal.h>
#include <stdio.h>
#include <fcntl.h>
#include <sys/types.h>
#include <sys/stat.h>
#include <malloc.h>
#include <ctype.h>
#include <errno.h>
#include <time.h>
#include <string.h>
#include <process.h>
#include <sys\utime.h>
```

#define BUF\_SIZE BUFSIZ

```
typedef char attribute;
typedef struct dstruct {
    struct find_t buffer;
    int f FIRST;
    char *path;
    unsigned dosattrib;
    unsigned dosrc;
} DSTRUCT;
```

```
char * getcwd();
#endif
```

```
#if defined(HPUX)||defined(SUN)||defined(VAX)||defined(APOLLO)
#define _A_NORMAL 0x0000
#define _A_RDONLY 0x0001
#define _A_HIDDEN 0x0002
#define _A_SYSTEM 0x0004
#define _A_SUBDIR 0x0010
#define _A_ARCH 0x0020
#define INT_SLASH '/'
#define O_BINARY 0
#define O_TEXT 0
#define PATH ".\"
#define SLASH "\\"
```

```
#include <signal.h>
#include <stdio.h>
#include <sys\param.h>
#include <ndir.h>
```

- S300 GENERAL HPUX -

Known Problem Reports as of 11/21/90

KPR #: 400096487 \*\*CONTINUED\*\*

```
#include <fcntl.h>
#include <sys/types.h>
#include <sys/stat.h>
#include <malloc.h>
#include <ctype.h>
#include <errno.h>
#include <time.h>
#include <string.h>
#include <unistd.h>
```

#define BUF\_SIZE BUFSIZ

```
extern char **environ;
typedef unsigned short attribute;
typedef struct dstruct {
    struct direct *pBUFFER;
    DIR handle;
    DIR *PHANDLE;
} DSTRUCT;
#endif
```

/\* macros for accessing local routines.
\*/

```
#define Malloc(a) mymalloc( FILE, LINE, a)
#define Free(a) myfree( FILE, LINE, &a)
#define Realloc(a,b) myrealloc( FILE, LINE, a,b)
#define serror(a) myerror( FILE, LINE, a)
#define bexec(a) Bexec( FILE, LINE, a)
```

```
#if defined(MEM)
#include "memchk.h"
#endif
```

```
#define ON_PASS "on_pass"
#define ON_FAIL "on_fail"
```

```
#define FALSE 0
```

```
#define TRUE 1
```

```
#define MAX_PATH_LENGTH 256 /* find this out for HPUX, DOS */
```

```
#define MAX_ITERATIONS 60 /* maximum number of times to try and get
a unique testid */
```

```
#define MAX_TESTID_LENGTH 12 /* maximum length for an id is 12 -
considering the ?3 limitation
DOS */
```

```
#define DEFAULT_NOHANG 600
```

```
#define DATE_FORMAT "%a %h %d %T %z 19%y"
```

```
#define PROG "prog"
```

```
#define RUNTEST_ERROR 3 /* return code for runtest error */
```

- S300 GENERAL HPUX -

KPR #: 4000096487 \*\*CONTINUED\*\*

```

#define STDIN "stdin"
#define STD_IN "std.in"
#define INTERACTIVE ".it"
#define SUPERUSER ".su"

#define CURRENT_DIR "."
#define PARENT_DIR ".."

#define ADMIN "ADMIN"
#define BAD "BAD"
#define GOOD "GOOD"
#define SAVEDIR "savedir"
#define RESULTS "RESULTS"
#define LOCKDIR "lockdir"

#define STDOUT "stdout"
#define STD_OUT "std.out"
#define STDERR "stderr"
#define STD_ERR "std.err"
#define STD_FIL "std.fil"
#define STD_FIL "std.fil"
#define RES_OUT "res.out"
#define RES_ERR "res.err"
#define RES_ERR "res.err"
#define RES_FIL "res.fil"
#define XFAIL_OUT "xfail.out"
#define XFAIL_ERR "xfail.err"
#define XFAIL_ERR "xfail.err"
#define XFAIL_FIL "xfail.fil"
#define XFAIL_FIL "xfail.fil"

#define PASSMSG "_PASSMSG="
#define FAILMSG "_FAILMSG="

/*
 * these are used to indicate the type of a pathname as either a
 * directory or a file
 */
#define DIRECTORY 0x0010
#define FILE 0x0000

/*
 * these are search-orientation constants for passing to
 * find_paths routine
 */
#define TOP_DOWN 1
#define BOTTOM_UP 2
#define SORTED_3
#define FAIL 1
#define NOFAIL 0

```

KPR #: 4000096487 \*\*CONTINUED\*\*

```

/*
 * used to tell path_exists whether to do a stat, do it into
 * a passed buffer, or do it in a local buffer.
 */
#define NO_STAT 0
#define STAT_NO_BUF 1
#define STAT_BUF 2

/*
 * for return status from function exec_test
 */
#define KILLED -1

/*
 * for return values from function path_exists
 */
#define NOEXIST -1
#define WRONG_TYPE 0
#define OK 1
#define ERROR -1

/*
 * pseudo-signals to cleanup indicating whether the <testdir>
 * should be processed or not.
 */
#define PROCESS_TESTDIR -1
#define NO_PROCESS_TESTDIR -2

/*
 * structure for pathname lists that will hold modules and
 * funcdirs
 */
struct path_list_node {
    char *path_name;
    int path_type;
    struct path_list_node *next;
} *func_dirs, *module_dirs;

struct inode_element {
    struct inode_element *previous;
    struct stat buf;
    struct inode_element *next;
} inode_list;
struct inode_element *bottom;

extern char *env_vars;
extern char **env_tbl;
extern char *testid;
extern char *testdir;
extern char *funcdir;
extern char *original_dir;

```



KPR #: 4000096487 \*\*CONTINUED\*\*

```
extern char *results_file;
extern char *good_dir;
extern char *bad_dir;
extern char *pass_mess;
extern char *fail_mess;
extern char **originalenvIRON;
extern char *type;
extern char *testfile;
extern char *runfile;
extern char *killfile;
extern char *lockdir;
extern char *std_in;
extern char *std_out;
extern char *std_err;
extern char *pid;
extern char *scaffold;
extern char *home;
extern char *msgbuffer;
extern char *s_TESTID;
extern char *s_PID;
extern char *s_FUNCIDIR;
```

```
extern int buffer_size;
extern int prog_killed;
extern int prog_pid;
extern int csuccesses;
extern int cxfail;
extern int cfail;
extern int ctests;
extern int cfirst;
extern int su_flag;
extern int link_flag;
extern int shell_flag;
extern int run_flag;
extern int test_flag;
extern int ignoresu;
extern int first_time;
extern int f_PTY;
extern int bsavedir;

extern long nohang;

char * Getpwuid();
char * mktestid();
char * namedir();
char * bundle();
char * mymalloc();
char * myrealloc();
char * addtype();
char * Bexec();
void myerror();
void myfree();

extern long shell_nohang;
```

KPR #: 4000096487 \*\*CONTINUED\*\*

```
DSTRUCT * Opendir();

/* Boyer-Moore string search declarations.
 */
#define MAXCHAR 0377
#define bm_min(x,y) (x) < (y) ? (x) : (y)
#define bm_max(x,y) (x) > (y) ? (x) : (y)
struct PattDesc {
    int *Skip1, *Skip2; /* pointers to skip tables
    char *Pattern;      /* Pattern to search for
    int PatLen;        /* Pattern length
    char *Start;       /* Starting position of search Pattern[0]
    int Success;      /* Pattern found
};

Temporary solution:
This defect is due to the fact that the code generator was loading
pointer differences which were being used to index into an array, into
address registers rather than data registers as would have been
appropriate. The pointer type of the "index" operand was incorrectly
leading codegen to load an address (.vs. data) register.

To work around this problem, use a temporary variable of appropriate
scalar type (e.g. int or long). Pre-assign the pointer type index
expression to the temporary scalar, and use the temporary in the
original index operation which was encountering the defect.

Fix information:
This defect was corrected in the S300 HP-UX 7.40 C compiler release.
KPR #: 4000097428 Product: S300 GENERAL HPUX 98680B 06.05
Keywords: LP
One-line description:
"lost connection" with remote spooling makes file lpd.log fill up disk
Problem:
When rlpdaemon loses the connection to remote machine, rlpdaemon tries
to fill a disk with a lot of error message "lost connection".
Cause:
When there is something wrong with the connection between
rlp(IM) and rlpdaemon(IM), rlpdaemon(IM) wouldn't stop writing
error message to a logfile.
Fix information:
Will be fixed in the release 8.0
```

KPR #: 4000097451 Product: S300 GENERAL HPUX 98680B

05.05

One-line description:  
C1 internal error in "function": illegal leaf node 49

Problem:  
Compiler error message when the tree node table needs to be expanded twice.

Cause:  
The tree node table is being incorrectly coalesced.

Temporary solution:  
Use the +Ne option to increase the size of the initial tree node array. For example, cc +Ne,1000 file.c

Fix information:  
Fixed in release 7.01.

Signed off 10/30/90 in release B07.01

KPR #: 4000097865 Product: S300 GENERAL HPUX 98680B 03.00

One-line description:  
"type clash" error points to wrong production

Problem:  
In the following error message:

fatal error: default action causes potential type clash, line 1053  
the production in line 1053 was NOT the one at fault. In fact, the error was in the PREVIOUS production, which is not always very nearby because of intervening action lines.

Cause:

The scanner looks ahead to determine the next token in a rule or find the end of the rule. By the time it is known that the rule is ended and then the rule is processed the scanner has moved to the first token beyond the rule, and that is what the lineno reflects.

Fix information:

The "fix" was to reword the message to say  
"possible type clash in the preceding production"

Hopefully, this will direct the user to look from this line number backward.

This change is in release 8.0.

KPR #: 4000097865 \*\*CONTINUED\*\*

KPR #: 4700774497 Product: S300 GENERAL HPUX 98680B 03.01

One-line description:  
tset does not use is[123] to initialize (see terminfo(4))

Problem:  
tset should do:

```
is1
is2
set tabs with tbc and hts
cat if
run iprog
is3

it only sets tabs and cats if.
```

Cause:

The tset command has never used is[1-3], rs[1-3] or iprog. Though these are clearly documented in terminfo(4) as part of the expected means of initializing the terminal.

Temporary solution:

The workaround is to put the initialization string in 'is2', which is currently emitted after tabsetting and before 'if' is cat'ed.

Fix information:

The behavior has been changed to follow that described in terminfo(4). Fixed in 8.0.

KPR #: 4700801597 Product: S300 GENERAL HPUX 98680B 03.01

One-line description:  
SAM doesn't appear to be able to add fiber link disks.

Problem:

The problem was that SAM was not allocating sufficient storage for another variable that was being used. Between the time it set the interface and the time it was used, it wrote to this other variable, and overwrote part of the interface variable. Thus it always thought it was a CIO HPIB device, and would attempt to use an HPIB device file rather than an HPFL device file.

Cause:

The problem was that SAM was not allocating sufficient storage for another variable that was being used. Between the time it set the interface and the time it was used, it wrote to this other variable, and overwrote part of the interface variable. Thus it always thought it was a CIO HPIB device, and would attempt to use an HPIB device file rather than an HPFL device file.

Fix information:

Has been fixed for release 7.0 of HP-UX.

KPR #: 4700879924 Product: S300 GENERAL HPUX 98680B 06.05

One-line description:  
no table entry for op REG (unoptimized)

Problem:  
The following program will not compile.

```
struct qunode { struct qunode *qu_next,*qu_last; };
int f(pi) register int *pi;
{
    register int *a,*b,*c,*d;
    register struct qunode *af;
    (qf->qu_next = qf->qu_last)->qu_next = qf->qu_next;
}

```

The compiler aborts with the message "no table entry for op REG"

Cause:

There are a number of possible reasons why a program will not compile and will abort with the message "no table entry for op REG". There is no way to know if it is a duplicate of this problem without trying a fixed compiler.

Fix information:

Fixed in the 7.40 release of the HP-UX compilers for the Series 300.

KPR #: 4700901041 Product: S300 GENERAL HPUX 98680B 05.05

One-line description:  
'diff -e ... | ed -' results in 2-byte file ("?\n") -- unusual case

Problem:

With two versions of a particular file, the following sequence results in incorrect output:

```
(diff -e oldfile newfile; echo '1,$p') | ed - oldfile >result
```

The "result" file contains only "?\n".

I've attempted to isolate the problem, but I cannot. Deleting the top portion OR the lower portion of "oldfile" and "newfile" produces correct results (for those portions). The problem persists when a line is added to the top and/or bottom of either file.

I've also tried replacing "ed" with "ex", to no avail.

I use the above command sequence frequently. It fails on only on a few files.

I can provide a 131-Kbyte shar file on request which contains the files needed to reproduce the problem.

Because this procedure is the cornerstone of our repeated integration with external partners, we would very much appreciate a work-around or an identification of the what causes the problem so that we can look

- S300 GENERAL HPUX -

KPR #: 4700901041 \*\*CONTINUED\*\*

for and avoid it in the future.

Fix information:  
Fixed in release 8.0.

KPR #: 5000121756 Product: S300 GENERAL HPUX 98680B 03.11

Keywords: PASCAL BOOTSYS

One-line description:  
Special handling required for SR #5000121756. See labtext.

Problem:

S 0200 860312  
When powering up a 310 with a built in video board and display compatibility interface, boot up BASIC 4.0 off the SRM. Following, if you execute a sysboot command to load the VT100 (98791B with 200 series environment and 300 series vt100 Prog) to use with the compatibility interface, the cursor did not appear on the CRT after the vt100 came up. The same problem exists when HPLPLUS is re-boot with sysboot. A fix is to enable compatibility interface with CONTROL CRT,21:1 (or remove CRTB from BASIC 4.0) and then do a sysboot. The cursor then appears as it does if vt100 is booted in powerup with it.

Temporary solution:

Enable compatibility interface with CONTROL CRT,21:1 (or remove CRTB from BASIC 4.0) and then do a sysboot from BASIC. Alternatively, reboot by cycling power.

KPR #: 5000170340 Product: S300 GENERAL HPUX 98680B 05.01

Keywords: SCCS

One-line description:

Problems with sccs and files larger than 3.35 megabytes.

Problem:

SCCS will not accept a file larger than 3.35 megabytes.

admin -ifile s.file

goes fine. But

admin -h

returns the message "corrupted file".

get -e s.file

returns the message "format error at line 3 (co4)"

Cause:

SCCS can only handle file up to 99999 lines in length.

- S300 GENERAL HPUX -

KPR #: 5000170340 \*\*CONTINUED\*\*

Temporary solution:  
run wc -l on files to be administered by SCCS and assure that they start out well below 99999 lines so they can grow without exceeding that limit. The csplit(1) command may be used on program files to split them into reasonable chunks.

Fix information:  
This defect is fixed in 8.0.

KPR #: 5000178038 Product: S300 GENERAL HPUX 98680B 05.15

One-line description:  
jobs disappear from lp queue, but not printed

Problem:  
System Configuration: HP 9000 Series 300 running 5.15, with a 82906A printer on internal HPiB, with 9144 and ThinkJet also off same HPiB.  
Problem: queue up jobs on 82906A (hereafter printer) with printer online, prints out fine. If off-line, job is shown in queue, with lpstat for a few minutes but after 4 minutes goes away. If the printer is brought back online before queued job goes away, it prints out, otherwise the job is lost. The printer model that was used was 2631G per the Series 300 Configuration Reference Manual.

Fix information:  
Has been fixed in 6.0 release

KPR #: 5000184275 Product: S300 GENERAL HPUX 98680B 05.15

One-line description:  
line printer spooler can lose data if printer is off line

Problem:  
When using the line printer spooler on a 320 running HP-UX 5.17 with a HP-IB 256x (non-cipher) printer and the printer goes off line (e.g. runs out of paper, off line key pressed, etc.) the spooled file is released. That is the spooler does not hold the file until the printer is put back on line. THIS RESULTS IN A LOSS OF DATA FOR THE CUSTOMER. It also does not matter which spooler model is used.

KPR #: 5000192682 Product: S300 GENERAL HPUX 98680B 05.14

Keywords: NROFF

One-line description:  
problems using table for matting and interactive text together

Problem:  
TRYING TO USE BOTH TABLE FORMATTING AND INTERACTIVE TEXT WITH THE MM MAC ROS USING mm -t FILENAME. USING THIS COMMAND THE TABLES CONTAINED IN THE FILE ARE PROCESSED, BUT THE INTERACTIVE PORTION OF THE FILE (.RD COMMANDS) ARE NOT PROCESSED. THE WORKAROUND IS TO DO A TBL FILENAME > FILEOUT A ND THEN NROFF FILEOUT > FILEDONE.

KPR #: 5000198770 Product: S300 GENERAL HPUX 98680B 05.15

Keywords: VI

One-line description:  
Problem with terminfo and vi using 2392Sa

Problem:  
Using a 2392a HP terminal in ANSI mode with TERM=vt100, s300hpux. When in the vi(1) editor, having problems with the up and down arrow keys. If the down arrow was held down to scroll down several screens, the escape on the key escape sequence would not always be read. The down arrow in terminfo vt100 is kcudl=VE0A

When the escape was not seen while scrolling the "0" would act as a usual vi(1) open line above cursor command. This would happen intermittently

Fix information:  
May be fixed in a future release.

KPR #: 5000216697 Product: S300 GENERAL HPUX 98680B 05.15

Keywords: COMPRESS

One-line description:  
(un)compress may not retain modification time.

Problem:  
I have found what I consider a bug in the "compress" program in HP-UX 5.2. If I do a "compress" or "uncompress" on a file which I own, the resulting file still has the original owner, permissions, and modification date. However, if I do a "compress" or "uncompress" on a file which I do not own, the resulting file still has the original owner and permissions, but the modification date and time are changed to the current time.

My users and I store a great many sccs files in compressed format. It is convenient for all of us to be able to uncompress these files regardless of the last person (owner) to use them.

The retention of the last modification date is one of the features I preferred over "compact", which altered the modification date (as well as the ownership) of the file. This retention is useful to help identify the last update of the file, without having to use "prs" (on sccs files) or view the file itself.

Cause:

The owner and group file attributes were being set before the modification and access times were begin set. Because you did not own the file, the access and modification times were never set properly.

Fix information:  
Fixed in HP-UX release 8.0

KPR #: 5000219485 Product: S300 GENERAL HPUX 98680B 05.11

KPR #: 5000220160 \*\*CONTINUED\*\*

Keywords: ACCOUNTING

One-line description: accounting does not properly report users' connect time.

desired.

Lifcp(1) DOES NOT say to use the implementation option to get around this-- it should.

Problem:

Frank Stutzman, Santa Clara Response Center  
The accton command of the accounting package encounters a user name that contains a character that is other than an alphanumeric, a space or a \$, it marks that user as being invalid and does not properly report that users connect time in the prdally report.

Temporary solution:

The workaround to the problem is to create a file under Basic with the desired attributes, and then list the LIF file under HP-UX using lifls to get the implementation value, eg. lifls -l or lifls -i.

lifcp -r -T 0xffff961 -i 0x20200080 bdat\_hpux /dev/rfd:BDAT

Cause:

"acctoni.c" was checking for valid wtmp records. The checks were performed for any alphanumeric character, "\$", and space. "." is the only other legal character allowed in the password file. Since it was not checking for this, it complained that the record was a bad one which consequently gets printed out as an error message.

Fix information:

The lifcp(1) manual page was updated to support BDAT.

KPR #: 5000221259 Product: S300 GENERAL HPUX 98680B 05.20

Keywords: SH

Temporary solution:

The workaround for this bug is not to include a "." in the users field. If some special character has to be used, then it is recommended that a "\$" be used instead of a ".".

One-line description:  
cannot boot from 5.21 recovery system

Problem:

Bug in /bin/sh prevents booting from s500 hp-ux 5.21 recovery system. When trying to boot from the recovery tape the customer received the error,

Fix information:

/bin/-sh: Unexpected memory fault  
/bin/-sh: No more space

The latter message was repeated endlessly.

There is no workaround. /bin/sh should be fixed to correct the problem.

KPR #: 5000220160 Product: S300 GENERAL HPUX 98680B 05.03

Keywords: LIFCP

One-line description:  
Lifcp with BDAT files not properly documented.

Fix information:  
Fixed in Release 5.3.

Signed off 10/26/89 in release B05.30

Problem:

The HP-UX Reference, 09000-90009 December 1986 Update, under lifcp(1) attempted to copy a file from HP-UX to LIF using a file type of -5791 does not explain the relationship between implementation values and in raw mode, the resulting LIF file had a protection on it and the record sizes were wrong. For example, Basic. Hence, when the customer the protection and record sizes under Basic.

Keywords: MM

One-line description:  
MM ignores Bolding.

Problem:  
Nroff -mm will properly bold using a laserjet printer and .B command. MM will not, the bolding is ignored, no errors are Generated.

lifcp -r -T -5791 bdat\_hpux /dev/rfd:BDAT  
results in a file named BDAT on the LIF volume that is protected. Furthermore, the record size is 1 byte when 256 bytes/record was

Cause:

KPR #: 5000224683 \*\*CONTINUED\*\*

This defect is caused by inappropriate use of hp(1) in mm.

Fix information:

Fixed in the release 6.5.

Signed off 11/01/90 in release B06.05

KPR #: 5000225904 Product: S300 GENERAL HPUX 98680B 05.21

Keywords: MOUNT

One-line description:

Rev.5.2 mount(1) doesn't work with floppy discs.

Problem:

After an upgrade from 5.11 to 5.21 on a 9000 s/520 the use of the new version of mount on the integrated 5 1/4 " floppy generated the following message:

mount:/rdev/fd : no such file or directory  
warning: /dev/fd may not be clean

Temporary solution:

The workaround to this problem is to move floppy disks to the new disk device directories:

/dev/rfd --> /dev/rdisk/fd  
/dev/fd --> /dev/disk/fd

Although it was not necessary in releases prior to 5.2 to have a 'raw' device file for a disk, new features in 5.2 (specifically support of the fsclean byte) require that such a device exist. Mount, along with several other commands, assumes that the character and block device files are located in the /dev/rdisk and /dev/dsk directories, respectively, with a common basename, as described in the DISK(7) HP-UX Reference Manual.

Fix information:

Fixed in release 5.3.

Signed off 10/26/89 in release B05.30

KPR #: 5000228635 Product: S300 GENERAL HPUX 98680B 05.03

Keywords: DELTA

One-line description:

Delta(1) hangs when reading files with very long lines.

Problem:

Using SCCS. After checking out a file, editing and trying to check it back in with delta(1), delta will hang and never return if the edited file contains very long lines (greater than 720 characters)

Cause:

Line buffers were too short to hold lines read by stdio.

KPR #: 5000228635 \*\*CONTINUED\*\*

Fix information:

Line buffer size was changed to match stdio BUFSIZ in 6.5 release.

Signed off 11/06/90 in release B06.05

KPR #: 5000232702 Product: S300 GENERAL HPUX 98680B 05.03

Keywords: TSORT

One-line description:

Tsort(1) generates spurious output line when processing long file names.

Problem:

Using "lorder" and "tsort" to build a library from existing ".o" files. The file names (which include the full path name) are about 50 to 55 characters long. The output from "tsort" includes an extra line which has characters similar to "x.o" as the first line.

Cause:

Character arrays for the names were only 50 characters long.

Temporary solution:

Filenames to be tsort'ed should be shortened to less than 50 chars.

Fix information:

In 8.0 release.

KPR #: 5000233601 Product: S300 GENERAL HPUX 98680B 05.05

Keywords: LP

One-line description:

Slp(1) doesn't allow "--a" and "--d" options together.

Problem:

When using the "slp" command, you can't simultaneously change the default parameter setting and display the current settings. For example:

slp -i0 >/dev/lp #change indentation=0  
slp -d -a >/dev/lp #This doesn't work.  
line=66 columns=132 indent=0 # output generated by "slp" command.

Cause:

Because the lp(7) device driver doesn't any capability to read the default value of the printer, there is no way for slp(1) to get the default without close and reopen of the driver.

Fix information:

Will be fixed in HP-UX 8.0 release for S300 and S800.

KPR #: 5000236984 Product: S300 GENERAL HPUX 98680B

05.21

Keywords: CATMAN

One-line description:  
Running catman(1) at high priority (with "nice") causes system errors.

Problem:  
Executing catman with a nice -19 generates errors (catman by itself works fine). These errors are of the form ".\*: no such file or directory".

If this is not enough this also causes problems with the shutdown procedure. After the above is executed the following error messages alternately come from the shutdown script:  
init process termination; errno=4 errinfo=309, trapno=0  
and init process termination; errno=25, errinfo=320, trapno=0  
The shutdown does continue and the reboot seems to be fine.

Cause:  
The system error messages were a result of attempting to open directories that did not exist. Since it was normal for catman to attempt to open directories in order to find out if it needed to create them, the error messages have been eliminated.

Fix information:  
Fixed in release 7.0.

Signed off 11/07/90 in release B07.00

KPR #: 5000244236 Product: S300 GENERAL HPUX 98680B 05.02

One-line description:  
PAM does not work properly with 98700 stations.

Problem:  
9050 hp-ux 5.2 with 98700 display station. Pam(1) does not work properly when run on the 98700 display station.

When pam(1) is invoked it appears correctly on the display, but to invoke a command from the command line you have to type it twice hitting <cr> each time.

The output from the command does not fill the screen, as it should, despite the fact that the TERM variable is set to "98700". This worked properly under the previous release of hp-ux, hp-ux 5.1.

KPR #: 5000271213 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: KERNEL

One-line description:  
defect in terminal driver following multiple fopens and fcloses of a file

Problem:  
The following program is only used to illustrate the problem

- S300 GENERAL HPUX -

KPR #: 5000271213 \*\*CONTINUED\*\*

with the terminal driver somehow being confused, after multiple opens and closes of files using fopen and fclose.

If there are any questions about this please contact the submitter at (714) 758-5552

Keith W. Guerin  
Hewlett Packard Co.  
Fullerton, Calif 92631.

Cause:  
The open count on the ITE was not being incremented by ite\_open. When it was decremented by ite\_close, it caused the ttclose() (the line discipline close) routine to be called. This broke the tty affiliation, which in turn disables <BREAK> and the INTR keys.

Fix information:  
This defect has been present in the ITE since 5.0, and will be fixed in a future release.

KPR #: 5000280461 Product: S300 GENERAL HPUX 98680B 05.05

Keywords: CURSES

One-line description:  
CONFLICT BETWEEN CURSES, SIGVECTOR AND SETITIMER

Problem:  
SERIES 330 HPUX 5.5 ELEZA SMITH - SANTA CLARA RESPONSE CENTER  
There is a conflict when an application uses curses, sigvector, and slttimer. The application is using settimer and sigvector to refresh the screen on a periodic basis ( every second) . If an escaped key is pressed on the keypad, right arrow key for example, the curses routine does not replace the signal. The following code will reproduce the problem.

```
#include<urses.h>
#include<time.h>
#include<signal.h>
#define KEY_F1 0411
#define KEY_F2 0412
#define BLANK ""
int dis_val = 1;
int ch = 'a';
int done = 0;
char ch_str[200];
```

Fix information:  
May be fixed in a future release.

KPR #: 5000286476 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: SH

One-line description:  
problem with setting term variable

- S300 GENERAL HPUX -

KPR #: 5000286476 \*\*CONTINUED\*\*

Problem:  
I have discovered that if I do the following steps my screen locks up:  
with my TERM variable set to hp,  
enter vi  
q  
set term hp9837  
vi

and after that my 9837 is locked up. I believe that this is a bug. I have  
e  
6.0 on my 310.

KPR #: 5000290544 Product: S300 GENERAL HPUX 98680B 06.00

One-line description:  
"/seek " does not work on CTD character special file

Problem:  
"lseek" doesn't work on the character special file of CTD.

This may be the lack of manual description.

When we open the character device of CTD, "lseek" and then "read" data,  
unexpected data is read. If we use the block special file, there is  
no problem.

There is a note "Some devices are incapable of seeking" in HP-UX Ref.  
lseek(2), but there is no description about what devices are incapable  
of seeking.

KPR #: 5000298687 Product: S300 GENERAL HPUX 98680B 02.00

One-line description:  
Kermit do not handle long filenames correctly.

Problem:  
Kermit code uses read instead of directory(3C) library calls.

Cause:  
Current kermit code is not written with long filename  
support.

3-20-89

Temporary solution:  
No known workaround.

3-20-89

Fix information:  
Will be fixed in a future release of HP-UX for the 300/800.

3-20-89

KPR #: 5000298687 \*\*CONTINUED\*\*

\*\*\*\*\*

Fixed in 8.0

KPR #: 5000299735 Product: S300 GENERAL HPUX 98680B 06.01

One-line description:  
a sparse file causes kernel panic

KPR #: 5000396648 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: LP

One-line description:  
line printer hangs

Problem:  
Sometimes a cancel operation would cause a SIGTERM signal  
to be sent before the spool system was ready for it.  
caused the files /usr/lib/lp/FIFO and /usr/lib/lp/SCHEDULELOCK  
to be removed. This left lpsched running (reading from a  
pipe) but no way for lp to tell it to start a spool operation  
because it could not write to FIFO.

In the above text I believe /usr/lib should be changed to  
/usr/spool.

Fix information:  
Fixed in the 7.0 release of HP-UX for Series 300 and 800.  
Signed off 11/06/90 in release B07.00

KPR #: 5000397711 Product: S300 GENERAL HPUX 98680B 02.00

One-line description:  
Enhancement request to increase the number of files sort can handle

Problem:  
The problem is a system-imposed limitation on the number of open files  
a process may have at any one time. Although this is a limitation,  
there is an easy workaround provided. Increasing this limitation  
will have serious repercussions on the rest of the system.

Cause:  
HP-UX limits the number of open files a process may have. When a user  
tries to sort more than 58 files, the command bombs.

Temporary solution:  
As a temporary workaround you can sort some of the files into  
a temporary file, sort the rest into a different temporary file  
and then sort the two temporary files into the final result.

This script takes the same command line as sort and will sort



KPR #: 5000397711 \*\*CONTINUED\*\*

up to 2500 files. WARNING, it has had only cursory testing.

```

----- cut here
# This is a shell archive. Remove anything before this line,
# then unpack it by saving it in a file and typing "sh file".

```

# Wrapped by bstowell at hpiso6 on Fri Sep 23 15:22:17 1988

```

# This archive contains:
# SORT

```

```

# Error checking via wc(1) will be performed.
# Error checking via sum(1) will be performed.

```

LANG=""; export LANG

```

echo x - SORT
cat >SORT <<'@EOF'
: # sort up to 2500 files
# $Header: SORT,v 1.2 88/09/23 15:11:15 bstowell Exp $
td="/tmp" # directory for merge files
mx=50 # maximum files sort can handle
trap "/bin/rm -f $td/mf$$.*; trap 0; exit 1" 1 2 3 15
trap "/bin/rm -f $td/mf$$.*; exit 0" 0
opts="" # get options from command line
while [ 1 ] ; do
c= expr substr $1 1 1
if [ "$c" != "-" -a "$c" != "+" ] ; then
break
fi
opts="$opts $1" ; shift
done

```

```

sf=$# # number files to be sorted
i=1 ; j=0 ; sl="" ; mf=0 ; ml=""
while [ $i -le $sf ] ; do
sl="$sl $1" ; j= expr $j + 1 ; shift
if [ $j -eq $mx ] ; then
mf= expr $mf + 1 ; ml="$ml $td/mf$$.$mf"
sort $opts $sl >$td/mf$$.$mf
j=0 ; sl=""
fi

```

```

i= expr $i + 1
done
mf= expr $mf + 1 ; ml="$ml $td/mf$$.$mf"
sort $opts $sl >$td/mf$$.$mf
if [ $mf -gt $mx ] ; then
echo `basename $0` : too many files
exit 1
fi

```

```

sort -m $opts $ml
rm -f $td/mf$$.*
@EOF
set -- `sum <SORT` ; if test $1 -ne 62935
then

```

echo ERROR: SORT checksum is \$1 should be 62935

Known Problem Reports as of 11/21/90

KPR #: 5000397711 \*\*CONTINUED\*\*

```

fi
if test "`wc -lwc <SORT`" != ' 33 181 880'
then
echo ERROR: wc results of SORT are `wc -lwc <SORT`
echo \\t\\tshould be 33 181 880
fi

```

```

chmod 544 SORT
exit 0

```

Fix information:

Code change to support > 58 files... 1024.  
This change will be effective in HP-UX 8.0.

KPR #: 5000397737 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: KSH

One-line description:  
.sh history does not come up as default

Problem:

For user root, no history file is used unless the HISTFILE parameter is set in the .profile or \$ENV files. The ksh man page states that the default value is .sh\_history, but this is not the case for root.

Temporary solution:

In either root's .profile or root's \$ENV file, set the HISTFILE parameter to the name of the desired history file. Ksh will not turn on history for root unless HISTFILE is set (no default for root).

Fix information:

For the 8.0 release of HP-UX, the ksh(1) man page documents the behavior of shell history for the user root. See the section describing the HISTFILE variable.

KPR #: 5000400846 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: AXE

One-line description:  
axe system doesn't have tty command used by lp spooler scripts

Problem:

The command /bin/tty is used by some of the example LP spooling

KPR #: 5000400846 \*\*CONTINUED\*\*

scripts that is part of the AXE product. However, /bin/tty only exists in a fileset that is supplied as part of the PE product. This causes some of the LP spooling scripts to fail in certain situations.

02/28/90

Cause:  
This defect is really caused by the LP model scripts using a command when they could be using a builtin shell test. Rather than use:

```
if tty -s <&1 ; then
echo "its a tty"
else
echo "its not a tty"
fi
```

The scripts should have used:

```
if [ -t ]; then
echo "its a tty"
else
echo "its not a tty"
fi
```

Thus, the scripts would no longer be dependent on the 'tty' command, which is not necessarily available in the AXE product.

02/28/90

Temporary solution:  
The occurrences of "tty" in the LP model scripts may be changed from:

```
if tty -s <&1

to:

if [ -t 1 ]
```

This workaround is not necessary on HP-UX 7.0 or later releases, as the model scripts now use this method to determine if the output device is a tty.

02/28/90

Fix information:  
Fixed in the 7.0 release of HP-UX on the Series 300 and 800.

KPR #: 5000400846 \*\*CONTINUED\*\*

Signed off 11/16/90 in release B07.00

KPR #: 5000404012 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: NROFF

One-line description:  
nroff hangs on specific input file

Problem:

The nroff command hangs on a specific input file. The input file is incorrect however. The diversion to "T" starts at 10 lines before from bottom of page (.wh -10v ET) While in the diversion, page position is not increased therefore ".FT" is never invoked. So the diversion does not end.

KPR #: 5000410191 Product: S300 GENERAL HPUX 98680B 06.00

Keywords: LP

One-line description:  
LP -W SOMETIMES FAILS TO SENDS MAIL TO PROPER USER

Problem:

Lp -w sometimes fails to send mail to proper user in case that the user rlogin/telnet to the host and logout from the machine during printing his request. Instead of mailing to him, lpsched writes the message to the next user's terminal, who login to the host after the user logout.

Cause:

When lpsched check to see if the user login to the host, it does check only if the login name exists in the utmp file, not check the process status. Therefore, even if the user logout from the machine, his entry remains there, so lpsched gets a wrong port. Since the port can be used for the next login user, the next one may get the lpsched's message instead of the proper user.

Fix information:

Fixed already in HP-UX 7.0 S300/S800

KPR #: 5000410191 \*\*CONTINUED\*\*

KPR #: 5000419770 \*\*CONTINUED\*\*

Signed off 11/06/90 in release B07.00

/etc/mnttab file. If the umount fails for any reason, the temporary file is not removed.

KPR #: 5000417394 Product: S300 GENERAL HPUX 98680B 05.21

One-line description:  
NROFF STORAGE CAPACITY IS TOO SMALL.

Temporary solution:  
These files are always the /etc directory.

Furthermore, the file names always start with the characters /etc/umount. These files can be removed by directing cron to rm /etc/umount[a-z][0-9]\*.

Problem:  
Customer was getting "Out of temp file space" error messages and nroff was aborting early.

Fix information:  
umount(1M) uses the kernel's view of the mounted file systems rather than attempting to create a new file based on what the /etc/mnttab file states as mounted. The result is an accurate /etc/mnttab file using no temporary files. This repair is in release 8.0.

KPR #: 5000420117 Product: S300 GENERAL HPUX 98680B 06.00

One-line description:  
In SAM, need an optional field for passwd while setting up UUCP

Keywords: LP

One-line description:  
Lpr script doesn't correctly handle the -R option

Problem:  
lpr script doesn't handle the "-r" option properly.

Cause:  
The "remove" variable in the script haven't been addressed correctly.

Problem:  
This is an enhancement request to change the way SAM handles passwords f or UUCP.

Temporary solution:  
The temporary correction is to put a \$ in front of the REMOVE variable.

For example:

INCORRECT: CORRECT:  
IF [REMOVE = TRUE] IF [\$REMOVE = TRUE]  
THEN THEN

KPR #: 5000419770 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: UMOUNT

RM -F \$FILES RM -F FILES

One-line description:  
AMOUNT DOES NOT REMOVE TMP FILES

FI FI

Problem:  
umount(1M) makes a temporary file that will eventually replace /etc/mnttab. If the umount(1M) fails for any reason, the temporary file will be left in place.

Fix information:  
Fixed in the 6.5 release of HP-UX.

Signed off 11/06/90 in release B06.05

KPR #: 5000436899 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: UUCP

One-line description:  
the -j and -o options to uustat return an illegal option message

KPR #: 5000436899 \*\*CONTINUED\*\*

Problem:  
uustat manual page lists unsupported options

Temporary solution:  
Don't use any of the options listed as S300 only

Fix information:  
When H-P adopted HDB uucp, all of the S300 specific uustat options became obsolete. The manual was not updated to reflect these changes. It will be chagned for the 8.0 release.

KPR #: 5000437129 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: RMNL

One-line description:  
return code from "rmnl" is incorrect.

Problem:  
The command would exit and not return a value when everything worked fine.

Cause:  
The code would exit without returning a value when everything worked without error.

Fix information:

The rmnl command was fixed for HP-UX Rev. 8.0 for the s300 and s800 architectures. The fix involed a code change to return the correct status for no error. This fix is at level 66.1.

KPR #: 5000440180 Product: S300 GENERAL HPUX 98680B 02.01

One-line description:  
acctcom(1) doesn't properly report command exit status codes -- ATT

Problem:  
The STAT field in the output of the acctcom command was never documented very well. Users expected it to be the exit status of commands, similar to \$? in sh or ksh. If a command did an exit(1), they felt acctcom should show a 1 in that field.

Temporary solution:  
There is no workaround.

Fix information:  
The fix will appear in Release 8.0.

KPR #: 5000445296 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: KERNEL

One-line description:  
kernel should always check either euid or ruid - be consistent

Problem:  
The problem is that a program that had a real uid of other than "root", but an effective user id of "root", could not run the programs /bin/mkdir and /etc/mknod. Both mkdir and mknod would complain that you must be root, since they checked the real user id, not the effective user id. This is inconsistent with the kernel since, in almost all cases, the kernel checks the effective user id, not the real user id.

03/16/90

Cause:

This problem was caused by the fact that /bin/mkdir and /etc/mknod were, at one time, setuid programs themselves. Since running one of these programs would always change the effective user id to "root", they had to check what the real user id was to ensure that the caller had the correct permission.

This is a general problem with running a setuid program from a setuid program, and there is no real solution, except to minimize the number of setuid programs, especially for system utilities. The programs /bin/mkdir and /etc/mknod were setuid root since it was desired to allow a user to create directories and/or FIFO files, but the kernel routines need to perform these tasks required root permission.

As HP-UX has evolved, a mkdir(2) system call has been added that does not require root permission. Similarly, the mknod(2) system call has been modified to allow the creation of FIFO special files without requiring root permission. Consequently, /bin/mkdir and /etc/mknod are no longer setuid programs, so these programs may be invoked from a setuid program without requiring the real user id to be "root".

In the defect report, the submitter stated:

It has been suggested that having these #! <shell> scripts lying around on the system may be a security threat, but if this is so then how can HP justify scripts such as /etc/shutdown, /etc/backup, and /etc/netlinkrc.

Scripts beginning with "#!<shell>" are not a security threat. The security threat arises when one of these scripts is marked setuid or setgid. It is possible for a non-root user to invoke a setuid or setgid script in such a way as to cause arbitrary commands to run as another user. The exact sequence of of commands to cause this to happen is complicated (and is not described here, since it is best if the mechanism to take advantage of the security threat is not widely known), but it is possible.

Consequently, you should avoid setuid and setgid scripts. If you wish to invoke a script as another user, create a setuid program that merely runs the script. This causes no security threat.

KPR #: 5000445296 \*\*CONTINUED\*\*

03/16/90

Fix information:  
/bin/mkdir, fixed in the 7.0 release of HP-UX on the Series 300 and 800.  
/etc/mknod, fixed in the 8.0 release of HP-UX on the Series 300 and 800.

03/16/90

KPR #: 5000448654 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: LP

One-line description:  
Cannot do raw output to serial device using the hp2686a model script

Problem:  
The current HPUX 6.2 AXE or PE environments do not accommodate raw output to a serial device using the hp2686a model script, revision 56.16.

Cause:  
See fix text.

Fix information:  
Fixed in release 7.0.

Signed off 11/06/90 in release B07.00

KPR #: 5000458059 Product: S300 GENERAL HPUX 98680B 03.00

One-line description:  
Lint gives erroneous messages

Problem:  
The problem is that the following program has a well defined evaluation order and thus the lint message about evaluation order being undefined is spurious:

```

main(){
    void exit();
    char s[20],*gets();
    int n;
    if ((n = strlen(gets(s)))<6 || (n == n%2) > 2)
        printf("error\n");
}

```

lint complains:

warning: n evaluation order undefined

Cause:  
The cause is because lint didn't take into account the sequencing



KPR #: 5000458059 \*\*CONTINUED\*\*

operator ||.

Fix information:  
Fixed for release A.08.00.

KPR #: 5000458380 Product: S300 GENERAL HPUX 98680B 03.01

One-line description:  
swapon -a doesn't work

Problem:  
The swapon command, when invoked with the -a option, would not accept an entry in /etc/checklist unless it had all fields present, even if those missing were not used by swapon.

Cause:  
The cause of the problem was that the swapon command was not using library functions to return information about entries in /etc/checklist. Instead it had a home-brew interpretation. Using library functions permits missing fields to be handled gracefully.

Fix information:  
The fix will be in Release 8.0.

KPR #: 5000465161 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: LP

One-line description:  
lpstat generates bad output when IO is redirected

Problem:

The lpstat command works fine when you have a local printer and a remote printer and send the output to the screen but if you redirect the output to a file the order of the printers is corrupted.

The complaint here is that the lpstat output, when sent to a file, does not match the output when it is sent to the screen. In particular, the remote print queue information appears at the tail of the screen, but at the head of the file. The information is not corrupted, it just does not appear in the same order.

Cause:  
The cause of this defect was that output to a terminal is line buffered, where output to a pipe or file is fully buffered.

Fix information:  
This defect may be corrected in the 8.0 or 9.0 HPUX release.

KPR #: 5000468884 Product: S300 GENERAL HPUX 98680B

03.00

Keywords: STARBASE

One-line description:  
gopen with RESET\_DEVICE does not behave properly when using A1047A board

Problem:  
There is a timing problem with the graph2 driver and the nimbus (A1047) board. The problem shows up as a starbase error 2058 (I/O error).

Error occurred in a short program which did a gopen of a display (98730) and a locator (mouse). The program would work fine the first time it was run and fail the second time unless moved to a new name or recompiled.

The workaround was to put a sleep(1) between the two gopen statements.

Cause:

With the little information given and the fact that in 7.0, the problems is fixed, I do not know what caused this to happen.

Fix information:

The bug was fixed in release 7.0

KPR #: 5000470922 Product: S300 GENERAL HPUX 98680B

06.05

Keywords: CRON

One-line description:  
need to change the effective use of \ in crontab

Problem:  
The code in cron.c wasn't mapping \% to \% inside a command. It does now.

Cause:  
The code in cron.c wasn't mapping \% to \% inside a command. It does now.

Fix information:  
Fixed in release 8.0.

KPR #: 5000471979 Product: S300 GENERAL HPUX 98680B

06.05

Keywords: MKDIR

One-line description:  
mkdir has undocumented limit of 1000 sub directories

Problem:

- S300 GENERAL HPUX -

KPR #: 5000471979 \*\*CONTINUED\*\*

Hp-ux was changed to allow no more than {LINK\_MAX} links to a directory. This change was made so we could pass the SVCS and claim\_SVID conformance. We all hope that ATT will remove this as part of the definition of System V. The change is not documented on the mkdir(1) man page but is documented on the mkdir(2) page, although there is no indication of where LINK\_MAX is defined. I will update the man pages for 8.0 to make this clearer.

Fix information:  
Fixed in 8.0

KPR #: 5000475848 Product: S300 GENERAL HPUX 98680B

06.05

Keywords: CDB

One-line description:  
CDB COMES UP IN LINE MODE IF WRONG TERM TYPE SET

KPR #: 5000476200 Product: S300 GENERAL HPUX 98680B

06.05

Keywords: AR BACKUP

One-line description:  
ar(1) does not accept long filenames

Problem:  
The problem is that the portable ar(1) format does not support long filenames, so each vendor kludges around this differently. Our particular kludge gives more functionality than other vendors (ie, it allows files to co-exist that couldn't in other implementations and won't overwrite data) but is not seen as compatible with broken implementation like Sun's.

The new SVR4 spec attempts to standardize a way to actually support long filenames; we may adopt this at future release.

Duplicate Service Requests: 5000505198 1650122846

KPR #: 5000477828 Product: S300 GENERAL HPUX 98680B

06.05

Keywords: MKMF

One-line description:  
MKMF SHOULD UNDERSTAND SCCS FILES

Problem:  
mkmf does not know how to deal with s.file.c in the source directory and adds it to the SRCS list.

Cause:  
mkmf's original design did not expect SCCS files in the source directory.

- S300 GENERAL HPUX -

KPR #: 5000477828 \*\*CONTINUED\*\*

Temporary solution:

The work around is to edit the makefile after it is produced and remove SCCS file names. Be sure to remove "\newline" from preceding lines when necessary.

Fix information:

This will be fixed in the HP-UX Release 8.0

KPR #: 5000478107 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: FUSER

One-line description:

chgrp(1) and newgrp(1) don't handle \ in /etc/groups correctly

Problem:

IN /etc/groups file if you use the \ to escape the newline character the chgrp and newgroup commands fail to deal with the escape correctly. In all other cases the \ is invisible to the commands being run. This makes it impossible to have more than 12 lines as one whole line because vi and ed can not handle any characters per line.

Fix information:

May be fixed in a future release.

KPR #: 5000481465 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: KSH

One-line description:

Problem with timeouts in the Korn shell when in the vi editor

Problem:

If you run a ksh subshell from vi, and that subshell exits due to the timeout feature of ksh (the TMOUT variable was set), then after the ksh exits, vi is hung.

Cause:

In the case where ksh exits due to a timeout, ksh fails to set the process group of the tty back to vi's process group. When vi tries to access the tty, it is in the wrong process group and gets put to sleep.

Fix information:

Fixed in the 8.0 release of HP-UX.

KPR #: 5000482844 Product: S300 GENERAL HPUX 98680B

03.00

One-line description:

diskusg and acctdusg give different results

Problem:

acctdusg and diskusg gave different disk usages for the same user on the user's home file system even though the documentation clearly cites an example and says they should be the same. For example, if /users was /dev/dsk/c1d0s8 and /users/alvyn had the following files in his home directory:  
file1 alvyn 610 bytes  
file2 root 610 bytes  
then, acctdusg would add both and give disk usage in terms of 512 blocks while diskusg would add only the first one and report it in 1024 byte blocks.

Cause:

acctdusg was incorrectly adding all files in the users home directory as belonging to the user even if it was owned by somebody else. (This also caused the problem that if the -u option was given, it would not report the other owners files as not owned by anybody). Also, it was reporting the output in terms on 512 disk block size instead of the device block fragment size. Due to these, it the output of acctdusg and diskusg were not identical.

Fix information:

There were three fixes in acctdusg.c. The first one was to check if the current file was being owned by the user by comparing the login id and the uid from the file. This ensured that only the users file got added for the disk usage. The second fix was to round up the bytes of the file in terms of the device block fragment size for the Series 800 (usually 1024bytes). The variable DEV\_BSIZE was used to get the current fragment size. The third fix was to log the file if it was not owned by the user and if the "-u" option was present.

KPR #: 5000482943 Product: S300 GENERAL HPUX 98680B

03.01

One-line description:

SAM incorrectly translates mux0 driver LU in special file minor number

Problem:

The wrong major number was being used in certain cases in the mkterm.sh script in SAM's back end code.

Cause:

see .problem

Fix information:

KPR #: 5000482943 \*\*CONTINUED\*\*

This will be fixed for 8.0.

KPR #: 5000484337 Product: S300 GENERAL HPUX 98680B 03.01

One-line description:  
/bin/rsh does not allow users to specify paths starting with /

KPR #: 5000484378 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: TAR

One-line description:  
tar(1) creates files with // in front of file name

Duplicate Service Requests: 1650107037

KPR #: 5000487363 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: TERMINFO

One-line description:  
terminfo, vt100 and xterm do not work together

KPR #: 5000493288 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: KSH

One-line description:  
ksh(1) when trap on exit from a child in vi(1), terminal locks up

Problem:

If you spawn a ksh from vi, and the ksh has a trap set on EXIT, then when the ksh exits it leaves the tty unusable for vi (the process group associated with the tty is wrong).

Cause:

Ksh cleaned up the tty before it executed any trap on EXIT. As a result of executing the trap on EXIT, the tty's process group was left the same as ksh's process group. The process group of the tty should be set to vi's process group before ksh exits. Note: this will only happen if job control is turned on in ksh (set -o monitor).

Fix information:

Fixed in the 7.0 release of HP-UX.

Signed off 11/01/90 in release B07.00

KPR #: 5000493478 Product: S300 GENERAL HPUX 98680B

06.05

Keywords: MOUNT

One-line description:  
mount(1), df(1) say device mounted if its minor number same as root disk

Problem:  
mount and df commands report duplicate devices as being mounted

Cause:

This problem is caused by having duplicate entries in the /etc/mnttab file.

Temporary solution:

A stop gap workaround is to edit the /etc/mnttab file and remove duplicate entries.

Fix information:

This problem is fixed in release 8.0.

KPR #: 5000493999 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: SHUTDOWN

One-line description:  
"init s" or "shutdown 0" causes error message "HOME variable not set"

Problem:

The shell that is run in single user mode complains that the environment variable "HOME" is not set. This causes the "cd" builtin command to fail (when used without an argument), since the shell does not know where your home directory is.

All of the shells expect that a "reasonable" environment exist when you start them, this environment is expected to include "HOME".

03/19/90

Cause:

This problem is caused by the fact that /etc/init does not include the variable "HOME" in the environment that it sets up when running a shell in single-user mode. /etc/init should be setting up a "reasonable" environment for the shell, so that the shell can behave properly.

03/19/90

Temporary solution:

After the single-user shell is started, run the command:

HOME=/ exec /bin/sh

This will overlay the current shell with a new shell that has HOME set.

03/19/90



KPR #: 5000493999 \*\*CONTINUED\*\*

Fix information:  
Fixed in the 8.0 release of HP-UX on the Series 300 and 800.

03/19/90

KPR #: 5000495978 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: CURSES

One-line description:  
bus error in program on 300 using curses and shared memory allocation

Problem:

The kernel attaches a shared memory segment at a low address. This limits the amount of memory available for allocation by calloc. The caller of calloc in CURSES does not check for allocation failure. Bus error occurs when the null pointer returned by calloc is referenced.

Temporary solution:

Customer program can specify a high address in calling shmat. The shared memory segment will then be attached at that high address rather than at a low address chosen by the kernel. The address specified by the customer should be high enough so that enough memory is available for use by the calloc calls in CURSES.

Fix information:

This problem will be fixed in release 8.0.

KPR #: 5000496729 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: DISC

One-line description:  
du -s on NFS-mounted directory on SUN disk reports in 256-byte blocks

Problem:

When using the du command on files or file hierarchies that reside on a non HP-UX filesystem, the number of reported disk blocks may be inaccurate. This defect is new in the 6.05 release of HP-UX, the command worked correctly in the 6.0 release.

For example, when du is run on a filesystem that resides on a Sun system:

```
$ du /nfs/Sun-system/tmp
700 /nfs/Sun-system/tmp
```

the du command will report a value that is twice what it should be. The command should have reported:

- S300 GENERAL HPUX -

KPR #: 5000496729 \*\*CONTINUED\*\*

```
$ du /nfs/Sun-system/tmp
350 /nfs/Sun-system/tmp
```

(which is what it did in HP-UX 6.0).

This problem still exists in the HP-UX 7.0 release.

02/26/90

Cause:

This problem was caused by a change made to the du command that assumed that the value returned by stat() call on a file in the st\_blocks field are in units of 1024 bytes. This is true for HP-UX file systems, but not necessarily true for other vendor's.

In the 6.0 release, du used the st\_size value and then scaled it by 512 to calculate the number of blocks. This is not always as accurate as using the st\_blocks field for HP-UX filesystems, which is why the command was changed for the 6.05 release to use st\_blocks.

However, du should only use st\_blocks on HP-UX file systems. When calculating disk usage for foreign file systems, du should use the st\_size field and scale this value by 512 to calculate the number of blocks.

02/26/90

Fix information:

Fixed in the 8.0 release of HP-UX on the Series 300 and 800.

02/26/90

KPR #: 5000496885 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: KERNEL

One-line description:  
kernel parameter shmbrok should not affect size of kernel data structures

Problem:

In HP-UX 6.5 and 7.0 the shmbrok kernel parameter specifies the attach point for shmem segments and drastically effects kernel page table sizes since sparse virtual address spaces are not supported.

Cause:

This problem is due to the fundamental design of the system V VM system.

Temporary solution:

The user is aware of the two workarounds:

- 1) call malloc to allocate all dynamic memory before attaching shared memory
- 2) attach shared memory at a specific address in the address space.

- S300 GENERAL HPUX -

KPR #: 5000496885 \*\*CONTINUED\*\*

Fix information:  
The fix is a new VM system that supports large sparse virtual address spaces. This has been implemented for HP-UX release 8.0

KPR #: 5000499038 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: ACCOUNTING

One-line description:  
HOG factor returns wrong value when CPU-MIN and REAL-MIN are zero

KPR #: 5000500520 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: FIND

One-line description:  
"find" command fails to check context dependent files

Problem:  
The submitter states that find(1) is not working properly when used in a command of the form:

find . -hidden -print | cpio -pdmvx some\_directory

Actually the problem is not in find(1), but in a special version of cpio(1) that was left in /bin/cpio during the update to the 6.5 release in certain situations. The special version of cpio(1) does not handle symbolic links or CDFs properly. It was used by the /etc/update program and then later replaced with the real version of cpio that works correctly. However, in certain situations (running /etc/update a subsequent time and not loading the fileset containing the real version of cpio), the special version of cpio(1) was left in /bin.

The following messages:

Cannot chown </users/garvey/tmp/studpid/cron+> (errno:2)  
Cannot chown </users/garvey/tmp/studpid/sockets/X11+> (errno:2)  
Cannot chown </users/garvey/tmp/studpid/sockets/grmd+> (errno:2)

are consistent with the behavior of the special cpio when it is used to copy CDFs.

05/09/90

Cause:  
The problem is not in find(1), but in a special version of cpio(1) that was left in /bin/cpio during the update to the 6.5 release in certain situations. The special version of cpio(1) does not handle symbolic links or CDFs properly. It was used by the /etc/update program and then later replaced with the real version of cpio that works correctly. However, in certain situations (running /etc/update a subsequent time and not loading the fileset containing the real version of cpio), the special version of cpio(1) was left in /bin.

KPR #: 5000500520 \*\*CONTINUED\*\*

The following messages:

Cannot chown </users/garvey/tmp/studpid/cron+> (errno:2)  
Cannot chown </users/garvey/tmp/studpid/sockets/X11+> (errno:2)  
Cannot chown </users/garvey/tmp/studpid/sockets/grmd+> (errno:2)

are consistent with the behavior of the special cpio when it is used to copy CDFs.

05/09/90

Temporary solution:

The "special" version of cpio(1) may be identified by using the command:

\$ what /bin/cpio

If the "what" string indicates that it is an "update version", then you have the broken version of cpio(1).

You may restore a good version by running /etc/update with your 6.5 release install or update media and re-loading the fileset that contains /bin/cpio (the "CORE" fileset). This will restore the correct, working version of cpio.

This problem does not exist in 7.0 and later systems, no workaround is required if you are running a release later than 6.5.

05/09/90

Fix information:

Fixed in the 7.0 release of HP-UX on the Series 300 and 800.

05/09/90

Signed off 11/06/90 in release B07.00

KPR #: 5000501296 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: LP

One-line description:  
lp to a 2563 printer inserts extra form feeds

Problem:  
When the "-n" option is specified with lp command and the text file is longer than one page, the first copy is printed correctly but the remaining copies have extra form-feeds in the first page.

Cause:  
This is the result of the model not emitting a form-feed at the end of each print job as the printer is reset. The reset escape sequence is not interpreted by the lp driver and so the printer ejects a page (on reset) but the driver retains its old line count. Thus when the last page of a copy contains n lines, the page is ejected, the next copy is

KPR #: 5000501296 \*\*CONTINUED\*\*

started, 66-n lines are printed, then the driver inserts a form-feed. Additional pages of the copy are printed correctly.

Temporary solution:

This problem may be worked around by disabling the automatic insertion of form-feed by the ciper lp driver. Add the -n option to the existing "slp -k" command in the /usr/spool/lp/interface/printer\_name file for the printer as follows:

```
slp -k -n 2>/dev/null
```

or, add "\014" i(form feed) to the reset sequence after the file is printed:

```
echo "\014\033E\r\c" # Reset Printer
```

Fix information:

This defect is fixed in the PCI[234] models (and their links) in the 8.0 release.

KPR #: 5000502997 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: EX

One-line description:

CTAGS not processing if's properly

Problem:

The ctags program does not yield correct results for some blocks of C code which are not syntactically correct.

If the following code is in a file called test1:

```
x ()
{
  if (a)
  if (b)
}
```

and ctags is run on it:

```
ctags test1
```

then the correct tags file is produced:

```
x test1 /~x ()$
```

But if the following code is in a file called test2:

```
x ()
{
  if (a)
  {
  }
  if (b)
}
```

KPR #: 5000502997 \*\*CONTINUED\*\*

}

and ctags is run on it:

```
ctags test2
```

then an incorrect tags file is produced:

```
if test2 /~if (b)$/
x test2 /~x ()$/
```

Note that neither of the files test1 or test2 contain syntactically correct C code.

The user noticed that ctags(1) would produce bogus results in certain circumstances. The circumstances they site are not correct. The root problem is not with 'if' statements per se, but with programs that do not conform to the standard format produced by cb(1).

All the examples given will work correctly if filtered through cb(1). Programs which stray from the cb(1) standard may confuse ctags(1) and produce incorrect results.

Cause:

The ctags(1) command make some fundamental assumptions about its input when it is C code. In particular, it assumes that the code has been filtered through (or at least follows the conventions of) cb(1).

The command assumes that a '}' character in column 1 implies the end of a function. Internally, the command keeps track of {} pairs. Code which appears like this:

```
function foo1()
{
  <code deleted>
}
```

is correct according to cb(1). If for example the code does not follow cb(1) standards and looks like this:

```
function foo2()
{
  if (x) {
  }
  while (b) {
  }
}
```

then the code assumes that the } on the fourth line ends function foo2. It then decides that 'while' is the name of the next function when it sees the { character on that line. It puts 'while' into the tags file. This is incorrect.

Note that there is no claim that this code will compile. In fact, it possible to write code that ctags(1) will handle correctly and cc(1)

KPR #: 5000502997 \*\*CONTINUED\*\*

will not, and vice versa.

If the function is passed through cb(1), and appears as:

```
function foo2()
{
  if (x) {
  }
  while (b) {
  }
}
```

then this will work since no } are in column 1 other than the closing curly bracket for the function.

A good workaround in the meantime is to use cb(1), or to make certain that the only } characters in column 1 actually are the closing brackets for functions.

Temporary solution:  
The workaround for this problem is to use cb(1) on your code or to make certain that the only } characters in column 1 are the closing curly brackets of functions.

Fix information:  
The fix will appear in Release 8.0.

KPR #: 5000503367 Product: S300 GENERAL HPUX 98680B 03.10

Keywords: STARBASE

One-line description:  
sleep(2) followed by gopen(3) generates core dump

Problem:  
sleep followed by a gopen can cause a core dump

Fix information:  
The problem has been fixed in 7.0.

Signed off 02/05/90 in release B07.00

KPR #: 5000505990 Product: S300 GENERAL HPUX 98680B 05.05

Keywords: CU

One-line description:  
cu(1) doesn't transmit cursor movement escape codes correctly in vi

KPR #: 5000508044 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: ACCOUNTING

One-line description:  
garbage is printing after login names of 8 char long in accounting

- S300 GENERAL HPUX -

KPR #: 5000508044 \*\*CONTINUED\*\*

Problem:

The problem is that when prtacct was run, there was a garbage eighth character in the output. The defect was actually in acctmrg.

Cause:

The defect was caused by a bad printf format statement in acctmrg. This was fixed by a patch to 7.0 such that the name was truncated after eight characters.

Fix information:

Fixed in release 7.0.

It will also be available in Release 8.0.

Signed off 11/16/90 in release B07.00

KPR #: 5000508911 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: SH

One-line description:  
sh(1) loses positional parameters when executing ". script params"

Problem:

The problem is that if a script is executed from the Bourne shell as:

```
. script_name par1 par2 par3
so that another shell is not spawned the positional parameters are $1, $2, $3 ( in this case ) are lost.
```

Cause:

The Bourne shell does not setup the positional parameters before invoking the shell builtin command ". " (DOT).

The fix is to setup the positional parameters before invoking ". " command.

Fix information:

The fix will be in the 8.0 HP-UX release.

KPR #: 5000510636 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: DD

One-line description:

dd(1) will not read from a 9145 cartridge tape, but tar and tcio will

- S300 GENERAL HPUX -

KPR #: 5000511394 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: DOCUMENTATION

One-line description:  
configuration ref. manual is not current nor complete

Problem:  
Configuration Reference Manual, Part No. 98561-90020, is badly outdated. It needs to be updated and then kept current.

Fix information:  
May be fixed in a future release.

KPR #: 5000517565 Product: S300 GENERAL HPUX 98680B 05.20

Keywords: STARBASE

One-line description:  
"gclose" of "hpgl" driver fails with error about semaphore

Problem:

The problem is that gclosing the hpgl driver more than once will generate an error about not being able to free up a semaphore.

Cause:

This problem was caused by the first gopen freeing too many resources.

Fix information:

This bug is fixed in release 7.03.

KPR #: 5000519504 Product: S300 GENERAL HPUX 98680B 06.02

Keywords: ED

One-line description:  
ed(1) does not work on files larger than 128k

Problem:

Ed(1) can't edit the file larger than 128k bytes. But this is the specification for the current ed(1). See the man page of ed(1).

Cause:

Ed(1) reads the file to be edited into the temporary file. The contents of this temporary file are accessed by using 16-bit number. The eight bits of it represents the block number. The maximum number of block is limited to 255 and the size of block is 512 bytes so the limit of buffer size is about 128k bytes.

Temporary solution:  
Use ex instead of ed.

Fix information:

KPR #: 5000519504 \*\*CONTINUED\*\*

Will be fixed in the 8.0 release of HP-UX for the Series 300 and 800.

KPR #: 5000522896 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: FTIO

One-line description:  
ftio does not work with 7979 tape drive

KPR #: 5000523977 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: MAIL AXE

One-line description:  
AXE lp scheduler tries to use mail(1) but mail is not in AXE

Problem:  
AXE lp scheduler tries to use mail(1) even though mail(1) doesn't exist in AXE.

Cause:

Lpsched(lm) doesn't check if there's mail(1) or not. It should have done the checking before trying to invoke mail(1).

Fix information:

Will be fixed on the release 8.0.

KPR #: 5000527226 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: CPIO

One-line description:  
cpio(1) reads table of contents on only one side of optical media

KPR #: 5000527929 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: PWD

One-line description:  
"pwd" command reports wrong path for symbolic link over "netunam" command

Problem:

The submitter was reporting that, when they are on a diskless cnode and then cd to a directory across an RFA connection, the pwd command fails, and reports an error. This does not happen when the same situation is duplicated on a diskless server or standalone machine.

05/09/90

Cause:

This problem was caused by a kernel defect in the RFA code for diskless clients. This is a known problem and was documented with the 6.5 release in the file /etc/newconfig/Update\_info/to.6.5.

05/09/90

KPR #: 5000527929 \*\*CONTINUED\*\*

Temporary solution:

The following explains some simple workarounds which are easily implemented at the end-user's workstation:

1. If "csh(1)" is started on the local file system, and "cd" is then used to change to a remote directory, then the shell variable "cwd" WILL contain the correct directory. This is accessible by executing the command "echo \$cwd".
2. If "ksh(1)" is started on the local file system, and "cd" is then used to change to a remote directory, then the shell variable "PWD" WILL contain the correct directory. This is accessible by executing the command "echo \$PWD".
3. It is NOT possible using "sh" to determine the current directory (if the directory is remote), although using "ksh" instead of "sh" may solve the problem.

Fix information:

Fixed in the 7.0 release of HP-UX on the Series 300 and 800.

05/09/90

Signed off 11/06/90 in release B07.00

KPR #: 5000529883 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: MKRS

One-line description:  
modify mkrs to work with the optical disc

Problem:  
MKrs does not support the S6300.650A magneto-optic disk drive.

Cause:  
None, this is an enhancement.

Temporary solution:  
Tcio is only used during the cleanup procedure in mkrs after the recovery system is complete. Although support for MO does not exist in your mkrs, it may be the case that a good recovery system was created on your MO disk.

Fix information:  
Fixed in HP-UX release 8.0

KPR #: 5000537837 Product: S300 GENERAL HPUX 98680B

06.05

Keywords: VI

One-line description:

vi(1) does not display correct format for information when using telnet

KPR #: 5000538983 Product: S300 GENERAL HPUX 98680B 06.05

One-line description:

C1 internal error in "xxx": unknown optype passed to find().

Problem:

The problem occurred because of a function pointer cast on a constant. Insufficient information was passed from the first pass of the compiler to the global optimizer, thereby confusing its symbol table handler. The global optimizer handles most calls to functions by first looking up the function in its symbol table. Since there was no symbol in the table for this particular function, the global optimizer crashed.

Cause:

The global optimizer did not account for anonymous function references which can occur when a constant is cast to be a function pointer.

Fix information:

Fixed for release 7.40.

KPR #: 5000538991 Product: S300 GENERAL HPUX 98680B 06.05

One-line description:

C compiler error: register allocation error

Problem:

The S300 7.0 compiler fails to generate code for the statement:

```
*(((char *) (0x700)) + strlen (((char *) (0x700))) + 1) = '\0';
```

Cause:

This problem is caused by the C compiler underestimating how many registers it would need to generate code for the expression:

```
*(((char *) (0x700)) + strlen (((char *) (0x700))) + 1) = '\0';
```

If the compiler thinks it has enough registers but in reality it does not it will abort without generating code.

Fix information:

This problem will be fixed in the S300 7.40 Compiler release.

KPR #: 5000539379 Product: S300 GENERAL HPUX 98680B 06.05

One-line description:

Using pg "\n" preceded by "\0" doesn't produce new line.

Problem:

An attempt to use pg on files containing the NULL character was unsuccessful. Since pg(1) is designed for use only on text files (which

KPR #: 5000539379 \*\*CONTINUED\*\*

cannot contain NULL), this behavior is not a defect. Other programs suitable for viewing such files, such as vis, should be used as an intervening filter as in:

```
prog | vis | pg
```

Temporary solution:  
Use vis(1) to convert non-text characters before passing to pg. For example:

```
prog | vis | pg
```

Fix information:  
A documentation change will be made in the 8.0 release.

KPR #: 5000542357 Product: S300 GENERAL HPUX 98680B 06.05

One-line description:  
different results with -0

Problem:

Common subexpression elimination incorrectly deduced that the following expressions were CSEs and thus the following program is incorrectly optimized:

```
When I made a.out using 'cc test.c' and 'cc -0 test.c', I couldn't
get same result from a.out.
/**** test.c program *****/
unsigned char c[] = {0,1,2,3}; /* result from cc test.c is
0203001 */
```

```
main(){
sub(c);
return(0);
}
/* result from cc -0 is 02010001 */
```

```
sub(buf)
unsigned char buf[];
{
    unsigned long l;
    int ptr;
    ptr = 0;
    l = (unsigned long)(buf[ptr] << 8) + buf[ptr + 1];
    ptr += 2;
    l += (unsigned long)(buf[ptr] << 8) + buf[ptr + 1] << 16;
    ptr += 2;
    printf("4 byte data is %0x8lx\n",l);
}
```

Cause:  
Common Subexpression Elimination was done incorrectly in this case  
-- array references not handled properly.

Temporary solution:  
Compile with +01 or no optimization -- avoid -0 or +02.

KPR #: 5000542357 \*\*CONTINUED\*\*

Fix information:  
Fixed in HP-UX 7.0 release.

Signed off 11/01/90 in release B07.00

KPR #: 5000547547 Product: S300 GENERAL HPUX 98680B 06.05

Keywords: LP

One-line description:  
Permissions on lp(1) are incorrect.

Problem:  
lp allowed users to print files the could not read

Cause:  
lp is setuid for several reasons, and the code was not careful about setting the uid back for file opens

Temporary solution:  
Make lp setuid lp on your system, or update to 7.0

Fix information:  
The code as been significantly modified to allow it to safely run setuid root. Fixed in release 7.0.

Signed off 11/06/90 in release B07.00

KPR #: 5000579755 Product: S300 GENERAL HPUX 98680B 00.00

Keywords: C

One-line description:

When files are compiled with -g, there is a HUGE expansion in size.

Problem:

See .submitter file.

Cause:

See .problem file.

Temporary solution:

The workaround in this case is to re-structure the include file scheme, and include things that are only needed, as opposed to always including everything, whether it is needed or not.

Fix information:  
Fixed in release 7.40.

Signed off 11/01/90 in release B07.40

Known Problem Reports as of 11/21/90

Page: 303

KPR #: 500581595 Product: S300 GENERAL HPUX 98680B

01.00

Keywords: C

One-line description:

ANSI C: integral constant expression expected on enum range.

Problem:

The problem is that in the ANSI compiler, some enum constant names within a structure definition were accidentally looked up in the wrong name space, resulting in syntax errors.

Cause:

Cause is coding defect in compiler.

Temporary solution:

Replace enum constants with #define constants.

Fix information:

Fixed for A.07.40 and B.08.00

Known Problem Reports as of 11/21/90

Page: 304

KPR #: 1650063933 Product: SERIES 300 GKS 98672B

06.50

One-line description:

GSPKID returns wrong value

Problem:

GKS fails to set the PICKID attribute in a copied segment. A pick request to a copied segment returns the last value set by thei gspkid function.

Cause:

The cause of GKS not properly propagating the PICKID attribute when copying a segment into a new segment is unknown due to the bug being fixed and the subsequent documentation either lost or not completed.

Temporary solution:

No workaround is available.

Fix information:

Fixed in the 7.0 release of HPGKS for the Series [300,800].

KPR #: 1650086041

Product: SERIES 300 GKS

98672B

06.50

Keywords: GKS

STARBASE

One-line description:

gsfais() & gfa() don't draw right and bottom edges on x11



KPR #: 4700667626 Product: SNA3270 300 36590A 03.10

One-line description:  
SA msg queues should be created with permissions 660, not 666

Problem:  
If the standalone SNA3270 message queue is created with permission 666, everybody can read or write to it, not just users in the sna group. That might be a security loop hole.

Fix information:

The Standalone sna3270 messages queue is now created with the permissions 660 instead 666.

Signed off 06/30/89 in release A03.20

KPR #: 4700667634 Product: SNA3270 300 36590A 03.10

One-line description:  
sa\_sna3270 spins if given a remotesplit hostname (hpindlb:ibm)

Problem:

The hostname hpindlb:ibm is the last entry in the file /etc/sna/hostlist. When standalone SNA3270 is invoked with option -h hpindlb:ibm, SNA3270 spins and hangs there, trying to check if this hostname exists in file /etc/sna/hostlist.

Fix information:

When sa\_sna3270 or sa\_sna3770 looks for a hostname, it will browse through each line of the /etc/sna/hostlist file to check if that hostname exists.

The format of the hostfile is:

<hostname> <link device file> <link configuration file>

After checking the hostname, the PS will skip to the end of the line and then go to the next line. If the end-of-line is missing, the PS will spin. Therefore, the PS not only needs to check for end-of-line, it also checks for end-of-file.

A code change is made to the routine hostname\_ipc() (msgspc.c) to fix this defect.

Signed off 07/06/89 in release A03.20

KPR #: 5000443366 Product: SNA3270 300 36590A 02.10

One-line description:

SNA3270 causes the 800 to lock up and hang.

Problem:

NTI operated this product in the supported configuration and caused the system to hang. This was independent of the Genesis code that they normally operate. A dump was forced and the current process was the SNA3270 process. On analysis of the dump by the kernel lab, it was discovered that the failure was occurring in the select system call which is called by the SNA3270 process. This call was hanging

KPR #: 5000443366 \*\*CONTINUED\*\*

the system because it was operating at a real time priority less than any process that could preempt it. Neither netisr nor the timer satisfy the conditions necessary for this system call to complete, and therefore, the system deadlocked. The kernel people report that all network routines must have a higher priority than netise or a deadlock situation can always occur. The customer is no longer running the product in real time and is no longer having a problem. The lab will fix the problem in the 5.0 release of the product. This has been reported to the customer and he is satisfied with our current actions.

Signed off 01/30/90 in release A07.00

KPR #: 1650043760 Product: SNA3270 300 36591A 03.10

One-line description:  
Power off LU, send LUSTAT. Power on lu, send Notify ON. This is wrong.

Problem:  
The customer is using SNA3270 to logon to an application that does not unbind the session when you power off the terminal while in LU-LU session. Normally when you power off the terminal while in LU-LU session, we send an LUSTAT and the application sends an UNBIND. At the customer site, the problem is that when we stop the presentation service SNA3270 while in LU-LU session, we just send an LUSTAT (that's ok). However, as we start up SNA3270 again on the same LU, (from the IBM point of view, this lu is still in LU-LU session), we send a NOTIFY ON and that's not correct since we should send an LUSTAT.

Cause:  
When sna3270 is powered off during a LU-LU session, the snalink sends a LUSTAT 0831 to signal the host that the device is powered down.  
At Peugeot, the host +Rsp to that LUSTAT but does not send an UNBIND. Instead, it sends a BID to the link. The link accepts this BID, which is incorrect, and put the device into the Receive state. Therefore, as another sna3270 starts up on the same LU, it cannot send a LUSTAT 082B to re-establish the LU-LU session.

Fix information:  
A code change is made in the nuc code to reject the host BID after the device is powered down.

Signed off 03/29/89 in release A03.20  
KPR #: 4700667600 Product: SNA3270 300 36591A 03.11

One-line description:  
SNA3270 uses some help messages reserved for the Nuc.

Problem:  
Each product in the SNA family should have their own range of error messages, since for Gateway configuration, the SNALink could be on one machine, while a presentation service session (SNA3270, SNA3770, LU6.2, SNA3179G ...) could be on a different machine. The error message catalog of each product should stay on the same machine that the product runs.

Fix information:  
The following new help messages are added to the sna3270 help file:  
-4022 Fork failed  
-4023 Illegal option(s)  
-4024 Calling process now allowed to run sna3270  
-4025 Incompatible interface level

KPR #: 4700667600 \*\*CONTINUED\*\*

-4026 Could not open snagateways file  
The help messages in the following files are changed:

File:	Old help message	New help message
psmain.c	sna1001 sna2008	sna4022 sna4023
crtio.c	sna2015	sna4024
nsipcps.c	sna2041	sna4026
printer.c	sna2015	sna4024
ps_phys.c	sna2017	sna4025

The contents of the old help messages and the new help messages are basically the same. The numbers are modified to accommodate the new help facility.

Signed off 07/06/89 in release A03.20

Known Problem Reports as of 11/21/90 Page: 309

KPR #: 1650091587 Product: SNA3770 300 98184A 01.01

One-line description:  
AS SOON AS MON3770 SEES TRN IN A PUNCH FILE, IT STOPS INTERPRETING DATA

Signed off 11/30/89 in release A07.00

Duplicate Service Requests: 1650091504 1650091074

KPR #: 4700714915 Product: SNA3770 300 98184A 01.00

One-line description:  
JES3 receives Invalid FM header from host with recommended logmode

Signed off 03/31/89 in release A01.01

Known Problem Reports as of 11/21/90 Page: 310

KPR #: 1650107045 Product: SNA3770 300 98188A 01.01

One-line description:  
Enhancement: Enabling padding with trailing blanks, as real device does.

Signed off 05/24/90 in release A07.01

KPR #: 4700420307 Product: SNALINK 300 36592A 00.00

One-line description:  
When only 1 lu is defined in the config file, X-f occurs when a key hit  
Signed off 12/21/87 in release A03.10

KPR #: 4700474577 Product: SNALINK 300 36592A 00.00

One-line description:  
Session, file transfer, and character drop problems with SNALINK.

Cause:  
1) The last character of the file is a \$ and it is intermittantly  
dropped off in ispf screen because the screen painting routine  
did not update the screen appropriately.

2) When SNA3270 tried to establish a session with the host, it  
hang when user tried to logon to TSO. This problem happens  
because there is a race problem at SDLC level on the SNALINK  
product.

3) The SNA3270 hang during file transfer. This problem happens  
because there is a race problem at the Nuclues/PS interface  
on the SNALINK product.

Fix information:

- 1) After review the code of SNA3270, there is a defect found in  
the paint routine which is uses to paint the screen with the  
data receive from host. This routine did not function  
properly and cause some of the characters being dropped off.
- 2) There is a race problem in SNALINK at the SDLC level. The  
Nuclues did not know there is data which need to be send to  
the PS on the queue. The Nuclues enters the block mode to  
wait for the data from PS; meanwhile, the PS waits for data  
from Nuclues. Deadlock occurs and causes the PS hang. To re  
fix the problem, before Nuclues enters the block mode, check the  
flag which is set when there is data on the queue. If the flag  
is set, Nuclues will not block on IPC queue, and return to the  
scheduler to process the data.
- 3) There is a race problem in SNALINK at the Nuclues/PS IPC interface.  
Set the alarm before Nuclues blocks on IPC queue. When the alarm  
goes off, it will get the Nuclues out of the block mode. Nuclues  
will then return to the scheduler to see if there is any work need  
to be done.

Signed off 12/21/87 in release A03.10

KPR #: 4700667568 Product: SNALINK 300 36592A 03.10

One-line description:  
if SA nucleus is dead, error messages aren't very friendly

Fix information:

KPR #: 4700667568 \*\*CONTINUED\*\*

There are 2 problems to this defect report, after the Nuc is  
is killed -9:

(1) If the user starts up SNA3270, a timeout message is  
issued but it is not meaningful enough. A code change  
is made to read aif() in ps\_phys.c such that the  
error message reads:  
"Timeout while waiting for connection to host '<hostname>'"

(2) When you run snamg, a request for status message is sent  
to the Nuc. As the Nuc has died abnormally, that message  
will never get replied. Upon detecting this, the snamg  
command should issue a timeout error message.

To achieve that, an alarm is set before the request for  
status is sent to the Nuc. After 20 secs, if Nuc does  
not answer to that request, snamg will put out an error  
message.

The code change is made to check\_stat() in  
cmd/manage/snamg.c.

One small footnote: Do NOT 'kill -9' the Nuc unless you have no  
alternatives.

Signed off 12/14/88 in release A03.11

KPR #: 4700734566 Product: SNALINK 300 36592A 03.20

One-line description:  
if LU name is 8 chars, field formatting messed up in snarpt

Fix information:

snarpt use tab to go from field to field. Therefore, if the luname  
is 8 character long, it is right at the tab field mark and moves  
the status field over. This was brought up at the snarpt code  
review and fix was made to file snarpt.c such that all tabs  
were omitted and replaced by fields.

Also, snarpt no longer displays abbreviations such "w/", "rcvd" ...

Signed off 02/07/90 in release A07.00

KPR #: 5000520528 Product: SNALINK 300 36592A 03.21

One-line description:  
system panic when SNALink is installed and PSIDAD is run

Fix information:

The system panic that results from running PSIDAD is due to a problem in  
the PSI driver shipped with HP-UX 3.1; the driver has been corrected for  
HP-UX 7.0 so this problem should no longer occur.

KPR #: 5000520528 \*\*CONTINUED\*\*

Signed off 04/05/90 in release A07.00

KPR #: 5000542688 Product: SNALINK 300 36592A 03.21

One-line description:  
Snanuc fails when the host sends ua an second snrm.

Signed off 04/10/90 in release A07.01

Duplicate Service Requests: 5000549196

KPR #: 4700419606 Product: SNALINK 300/GW 36593A 00.00

One-line description:

Request to allow more valid PSERVICE parameters in logemode table.

Signed off 12/21/87 in release A03.10

KPR #: 4700667519 Product: SNALINK 300/GW 36593A 03.10

One-line description:  
ALPHA-SITE: Mod-2 BIND image rejected by SNALink/SNA3179G.

Fix information:

Upon receiving a BIND request from the Host, SNALink validates the BIND image on behalf of the PS (e.g SNA3179G). As we recently discovered, the SNA3179G PS must support both Mod-2 and Mod-3 bind requests.

The following rules describe the SNALink validation for the PSERVIC bind parameter, required for SNA3179G:

Byte	Meaning	Snanuc field	Validation required
1	LU profile	psprof	Reject if != 0x02
2	Queryable Device	psusg[0]	Not checked
3	Reserved	psusg[1]	Not checked
4	Reserved	psusg[2]	Not checked
5	Reserved	psusg[3]	Not checked
6	Reserved	psusg[4]	Not checked
7	Primary rows	psusg[5]	(See below)
8	Primary columns	psusg[6]	(See below)
9	Alternate rows	psusg[7]	(See below)
10	Alternate columns	psusg[8]	(See below)
11	Screen size type	psusg[9]	Reject if not one of the following: 0x00,0x02,0x7e,0x7f
12	Reserved	psusg[10]	Not checked

Screen size validation:

1. If byte 11 is 0x00 or 0x02, then bytes 7-10 are not checked, but the primary and alternate rows are set to 0x18, and the primary and alternate columns are set to 0x50.

2. If byte 11 is 0x7e then:  
0x01 <= byte 7 <= 0x20  
byte 8 = 0x50  
byte 9 = byte 7 (This byte is not validated)  
byte 10 = byte 8 (This byte is not validated)

3. If byte 11 is 0x7f then:  
0x01 <= byte 7 <= 0x20  
0x01 <= byte 9 <= 0x20  
byte 8 = byte 10 = 0x50

Given that the Host can bind with a variety of PSERVIC options,

KPR #: 4700667519 \*\*CONTINUED\*\*

SNA3179G must be notified of the BIND image so that it can set its primary and alternate partition sizes according to the BIND specification. Additionally, as SNA3179G requires, a notification of an UNBIND request (from the Host) also be sent from SNALink so that it can reset the partition sizes to their hardware default sizes when the LU-LU session is unbound.

To provide these notifications, a new "LU operation" is defined and packaged in the existing luib message format. The luib message would then make use of the following fields:

```

luop = SESCRL      Session control LU operation
luopmod = BIND     For BIND notification
                UNBIND For UNBIND notification
    
```

request = pointer to an MU containing the BIND image.

Since this is a "notification" message, SNALink need not wait for a response to this message.

The following files have been changed to accommodate this defect:

```

File      Routine
----      -
h/cmcrstr.h
nuc/nuc/snasched.c      snasched()
                        disprr()
                        add sndsesctrlmu()
nuc/nuc/nuksutil.c      toout()
nuc/csc/lusvcmgr.c      lussrcv()
                        vldtbind()
nuc/misc/tlfunc.c      logbindrej()
    
```

Signed off 12/14/88 in release A03.11

KPR #: 4700667576 Product: SNALINK 300/GW 36593A 03.10

One-line description:  
Incorrect processing of COMMS04 when in an SSCP-LU session.

Fix information:  
A code change is made to comchk() in nuc/misc/comchk() such that when SNALink determines that the communication line is down, it generates a COMM 504 display code, sends it to the PS's, and sets the i\_toggle of all luib's to UNOWNED.

When the session is UNOWNED, all keystrokes (data and AID keys)

KPR #: 4700667576 \*\*CONTINUED\*\*

are rejected with X-f and X-f if cleared by the RESET key to blanks. LUWRITE attempt and all its subsequent results will fail since hitting ENTER, an AID key, will be rejected with X-f.

The code change works for COMM 504 check processing for both SSCP-LU sessions and LU-LU sessions.

Signed off 12/14/88 in release A03.11

KPR #: 4700667584 Product: SNALINK 300/GW 36593A 03.10

One-line description:

Incorrect generation display codes when COMM 504 occurs in LU-LU session

Fix information:

When a COMM 504 check occurs, the Nuc performs the following:

- \* changes the session state to UNOWNED,
- \* clears the System Area fields (display code CLRDONT),
- \* sends the UNOWN status indicator to the PS (display code UNOWN),
- \* sends the COMM 504 display code.

By sending the display code UNOWN before COMM 504, the System Area fields will be cleared, and thus, correct.

Signed off 12/14/88 in release A03.11

KPR #: 4700667618 Product: SNALINK 300/GW 36593A 03.10

One-line description:

Incorrect msg "sna3270 for LU X is being ordered to terminate."

Fix information:

The LU type 'sna3270' was hard-coded in the routine manage\_fn(). Now a switch statement is added to print out the appropriate type for each LU in the manager kill message.

Signed off 12/14/88 in release A03.11

KPR #: 4700674499 Product: SNALINK 300/GW 36593A 03.10

One-line description:

snalink has snamchk226: :mchk\_end: code:901 file:./queue/dqeqmgr.c

Temporary solution:

CCC uses a line with the NSCONTINUE option. With this option, when the host goes down, they keep the NCP up and

KPR #: 4700674499 \*\*CONTINUED\*\*

the line active. However, when the host comes backup, it will run a cold start, resetting everything, including the line which has been kept active. In doing that, the host floods SNALink with so many deactivation and activation frames, all expedited. SNALink dies, because it runs out of dispatching blocks used to store all these frames.

There is a workaround : shutdown the line properly when bringing the host down. The lab is investigating a solution to this problem.

Fix information:

The number of DOE's (dispatching structures) is increased as (NUMDEVS \* 2), where NUMDEVS is 64. By doing this, SNALink is able to handle all the activations and deactivations frames that the host sends it after a host IPL.

Signed off 12/14/88 in release A03.11

KPR #: 4700733758 Product: SNALINK 300/GW 36593A 03.20

One-line description:

SNALink install script fails on AXE systems which lack /usr/bin/id

Fix information:

To allow the script to function properly on both regular and AXE HP 9000 / S300 systems the use of /usr/bin/id has been replaced by /usr/bin/whoami. The program /usr/bin/whoami is automatically installed on all S300 systems; consequently, the install script will function properly on these systems.

Signed off 02/07/90 in release A03.21

KPR #: 4000091660 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:

Typing very fast may cause characters to be lost or garble command line

Problem:

SoftPC was losing track of characters

Cause:

Most likely cause is that the character buffer was being overflowed before it could be checked by SoftPC.

Fix information:

This problem has been retested on SoftPC 2.0 and no longer exists.

KPR #: 4000091678 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
function keys do not work with evelys word program.

Problem:

Function keys broken

Fix information:

This will need to be fixed at the application level, i.e., I think this program requires hardware access to the function keys. We will need to investigate it.

KPR #: 4000091728 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
cannot connect an HP-IB plotter to a com port

Problem:

HP 9000/360, HPUK 6.2, X11 A.00.01 SoftPC V1.3f (final) X11 version  
HP 7475A Plotter connected to low-speed HP-IB.

PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

SEVERE - I cannot connect a HP-IB plotter to a COM PORT. After assigning a COM port to the device file, the COM/LPT setup panel disappears but SoftPC locks up. The portion of the screen where the COM/LPT menu had existed was blank, and SoftPC would not accept any keyboard or mouse input. If I kill the SoftPC process and start a new status is completely blank (not even the SoftPC logo was there.) I had to remove the offending lines from my .SoftPC file to get SoftPC running again.

KPR #: 4000091728 \*\*CONTINUED\*\*

The device file had the following attributes:  
crw-rw-rs i root other 21 0x070400 /dev/plt

SPECIAL NOTE: If I assign the plotter to a LPT port, SoftPC accepts it without complaints. However, I did not try to plot any data.

Cause:  
The problem was caused by SoftPC 1.3 and has been corrected in SoftPC 2.0

Fix information:

The problem was fixed by a code change in SoftPC 2.0. Caused by trying to treat /dev/<dev> as a serial device, even though it's an HPiB device. Added extra call to 'isatty()' as an extra check, HPiB devices are treated as files now.

KPR #: 4000091736 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:

"MS Learning DOS" hangs softpc just after start up, SCR160

Problem:

S800 running SoftPC on X11, and on a 2393 terminal and on s360 running X11 and on 2393 terminal.

PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

MS Learning DOS

We tried to run Microsoft's "Learning DOS" package. The program starts up but softpc will hang just after the introduction. This problem is easy to reproduce and is very consistent.

The problem is with the "Lessons for Systems" part and not with the "DOS Quick Reference" part.

Cause:

The problem was caused by some incompatibility in SoftPC.

Fix information:

This was fixed in the SoftPC 2.0B release.

KPR #: 4000091926 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:

caps lock key must be pushed twice to change state.

Problem:

CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problems occurs.)

- SOFT PC FOR 9000/300 -

KPR #: 4000091926 \*\*CONTINUED\*\*

s800 running X11, s360 running X11

PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

This seems to be an x11 bug.

The caps lock key must be pushed twice to change state.

Cause:

There was a problem with the X window/ SoftPC interface.

Fix information:

This was fixed with SoftPC 2.0 B.

KPR #: 4000091934 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:  
sidekick does not work in CGA mode

Problem:

Sidekick broken

Cause:

This was caused by a problem with color accessing.

Fix information:

This problem was corrected by SoftPC 2.0.

KPR #: 4000091983 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:  
SoftPC Comm ports do not have eight bit parity capabilities

Problem:

Comm ports broken

Cause:

Only seven bits were fully supported with comm ports.

Fix information:

This was fixed with SoftPC 2.0.

KPR #: 4000091991 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:

soft PC does not assign colors correctly, SCR254

- SOFT PC FOR 9000/300 -



KPR #: 4000091991 \*\*CONTINUED\*\*

KPR #: 4000092023 \*\*CONTINUED\*\*

Problem:  
There was a problem in the X color assignments.

Cause:  
There were errors in the X color assignments.

Fix information:  
This was fixed in SoftPC 2.0.

KPR #: 4000092015 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
copying from com1 to a file doesn't work correctly, SCR246

Problem:  
122) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)

SoftPC V1.3 (final Nov-11-88 release)

13) PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

DEGRADE - Running "copy com1 file" to read input from a terminal and copy it to a file does not work properly. After entering input from the terminal and hitting ctrl-Z, I noticed the file was over 50,000 bytes long. I didn't type that much! It appears like many garbage characters are being stuffed into the file. (I did not test this on an XT.)

To duplicate:

1. Connect terminal to s300 or s800 machine
2. Assign the tty file to a COM port
3. Run MODE to set communications link
4. Run COPY COM1 FILE

Cause:  
There is an incompatibility in the comm. port emulation.

Fix information:  
This was fixed in the SoftPC 2.0B release.

KPR #: 4000092023 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
word perfect graphics conversion locks up softpc, graphcnv.exe, SCR251

Problem:  
12) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)

- SOFT PC FOR 9000/300 -

Known Problem Reports as of 11/21/90

KPR #: 4000092023 \*\*CONTINUED\*\*

s300 workstation and v-11-88 release)  
s800 system with SoftPC running over lan to s350 workstation  
(Donna Griffiths verified)

13: PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

Word Perfect 5.0

Word Perfect has a stand alone program "GRAPAHCNV>EXE" which converts various graphics files, ie: HPGL, TIFF, PCX etc. to Word Perfect format (\*.WPG). This program will lock up SoftPC to the extent it has to be rebooted.

The HPGL files I tried can be incorporated into a document when running WP>EXE. The translation gets done properly.

14: DOCUMENTATION (List supporting documentation included with this report.)

None.

Cause:  
There is an incompatibility in the SoftPC emulation.

Temporary solution:  
The user may use the built in graphics conversion facilities of WordPerfect to get around this problem.

Fix information:  
This problem fixed with SoftPC 2.0B final release.

KPR #: 4000092049 Product: SOFT PC FOR 9000/300 98870A 00.00

Keywords: SOFT PC

One-line description:  
Color Graphics refresh is slow on Falcon game, SCR143

Problem:  
Color graphics refresh is slow on Falcon game, SCR143.

Fix information:  
Fixed in release 2.00.

Signed off 10/11/89 in release A02.00

KPR #: 4000092056 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
setup panel highlights random characters, SCR214

- SOFT PC FOR 9000/300 -

KPR #: 4000092056 \*\*CONTINUED\*\*

Problem:  
12) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)

HP 9000/360, HP-UCX 6.2, X11 A00.01, SoftPC V1.3f (final) x11 version

13) PROBLEM DESCRIPTION (Includes hardware, symptoms, what you were trying to do, what went wrong, and other helpful information.)

MINIMAL - When using the COM/LPT setup panel, random text edit entries get highlighted.

14) DOCUMENTATION (List supporting documentation included with this report.)

Cause:  
The graphics interface has a problem with highlighting.

Fix information:  
This is fixed in SoftPC 2.0.

KPR #: 4000092072 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
full ibm character set is not correctly implemented

Problem:  
12) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)  
SoftPC running on s350 workstation.

13) PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

While checking the DOS NLS support I found that some international characters were not mapped correctly. Upon further investigation I found three other characters that were not exactly mapped to the IBM PC character set. I used the program printc.exe to print out the entire character set and examine it. This program runs under DOS and if necessary, I will e-mail it to Insighnia.

Cause:  
Characters were not mapped properly.

Fix information:  
This was fixed in SoftPC 2.0.

KPR #: 4000092098 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
all legal termcap ID's for the 2393 terminal are not recognized by Softp

KPR #: 4000092098 \*\*CONTINUED\*\*

Problem:  
12) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)  
SoftPC running on s350 workstation using an 2397a terminal  
SoftPC running on an s835 with a 2397 terminal

13) PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

All the legal termcap ID's shown by "untic"ing the 2393 description file for all spc supported terminals need to be supported for term device drivers. Currently, this is a problem and hp2393a and hp2393a an hp2393A are unrecognized by SoftPC. We have gotten around this by modifying the initialization (dumbpc/spc term) script. It should be fixed in the code for next versions. This has been officially requested in HP/SPC Comm #59.

14) DOCUMENTATION (List supporting documentation included with this report.) None.

Cause:  
The terminal startup script did not contain all valid names for the supported terminals.

Fix information:

The script has now been recognized as a necessity for SoftPC terminal startup due to problems setting up the terminal configurations. This problem has been fixed for SoftPC 2.0.

KPR #: 4000092106 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:

Garbage appears on screen when using model 700/44 terminal, SCR222

Problem:  
12) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)  
SoftPC running on s350 workstation using an 70044 terminal

13) PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

When exiting SoftPC on the 70044 terminal garbage characters are echoed to the screen. The prompt must be returned before the next command is typed.

14) DOCUMENTATION (List supporting documentation included with this report.) None.

Cause:

There are a few garbage characters left after SoftPC exits the

KPR #: 4000092106 \*\*CONTINUED\*\*

700/44 terminal emulation.

Fix information:

The SoftPC exit was modified to include a few carriage returns so that the garbage would not be seen by the user. This is fixed for SoftPC 2.0.

KPR #: 4000092130 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:

cursor doesn't track properly when running "Word Perfect", SCR250

Problem:

12) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)

< A 350 running x11 with 16Meg memory.

13) PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)

>There is a cursor tracking problem when running WordPerfect version 5.0 under SoftPC. If, while editing a document, you hold down the arrow key >the cursor "warps" to its next destination invisibly. This makes it >\*very\* difficult to reposition the cursor within a line. Somehow we >need to make it work like the edit widget's cursor under hpwm in x11. >[This problem may be tied to the repeat key rate.]

14) DOCUMENTATION (List supporting documentation included with this report.)  
None.

Cause:

The cursor tracking is poor.

Fix information:

This is fixed in SoftPC 2.0.

KPR #: 4000092148 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:

line drawing characters aren't mapped correctly

Problem:

12) CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)  
SoftPC running on s350 workstation using an 2397a terminal  
SoftPC running on s835 with 2397 terminal

13) PROBLEM DESCRIPTION (Includes environment, symptoms, what you were trying to do, what went wrong, and other helpful information.)  
The line drawing graphics characters are mismatched as can be seen

KPR #: 4000092148 \*\*CONTINUED\*\*

by examining SK ascii tables. The problem arises due to the lack of sufficient double line line drawing characters. The characters that are mismatched are IBM PC:Oxc7, Oxbd and Ocd1 these are easily remapped to the thick line equivalents giving a more consistent "look" to the result.

14) DOCUMENTATION (List supporting documentation included with this report.) None.

Cause:

Some characters are mismatched.

Fix information:

This is fixed in SoftPC 2.0.

KPR #: 4000092205 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:

Cannot connect HPiB printer to comm port properly, SCR220

Problem:

CONFIGURATION (Includes hardware, options, ROMs, binaries and peripherals. Should be minimum configuration on which problem occurs.)  
HP 9000/360 HPiUX 6.2 x11 A.00.01, SoftPC V1.3f (final) x11 version  
HP 7475A Plotter connected to low-speed HPiB.

PROBLEM DESCRIPTION (Include environment, symptoms, what you were trying to do, what went wrong and other helpful information.)

SEVERE - I cannot connect a HPiB plotter to a COM port. After assigning a COM port to the device file, the COM/LPT setup panel disappears but SoftPC locks up. The portion of the screen where the COM/LPT menu had existed was blank, and SoftPC would not accept any keyboard or mouse input. If I kill the SoftPC process and start a new one, DOS boots ok but again SoftPC locks up. Also, the right-hand status is completely blank (not even the SoftPC logo was there.) I had to remove the offending lines from my SoftPC file to get SoftPC running again.

The device file had the following attributes:

crw-rw-rw 1 root other 21 0x070400 /dev/plt

SPECIAL NOTE: If I assign the plotter to a LPT port, SoftPC accepts it without any complaints. However, I did not try to plot any data.

Cause:

The printer could not be attached, it seems to be a problem with the way SoftPC checks device permissions.

Fix information:

Fixed with SoftPC 2.0.



KPR #: 4000093666 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:  
softpc kills the bell and autorepeat in x11

Problem:  
Bell, Autorepeat dead

Cause:  
This was caused by an interference with the environment.

Temporary solution:  
The workaround is to reset all environment variables after running SoftPC.

Fix information:  
This will have to be fixed in code.

Duplicate Service Requests: 4000092080

KPR #: 4000093674 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:  
softpc will not work properly with some types of reparenting windowmgr

Problem:  
SoftPC does not conform to ICCM and will not work correctly with reparenting window managers. In particular, submenus text edit fields (like Setup Disk Drives) do not permit input to be typed.

Cause:  
SoftPC was developed using UWM and so it was not designed to work with reparenting window managers like HPWM.

Temporary solution:  
The workaround is to isolate the SoftPC editing box on the screen. Move every other window out of its way so that none overlap and then you will be able to edit the configuration using the user interface. (it will let you write into the interface boxes then)

Fix information:  
This was fixed with the final SoftPC 2.0B release.

KPR #: 4000093690 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:  
reassigning devices will lock up soft pc

Problem:

KPR #: 4000093690 \*\*CONTINUED\*\*

Reassigning devices (especially when running an application) will lock up SoftPC. SoftPC needs to be restarted automatically as the menu claims.

Cause:  
This is probably caused by a problem with the device assignment.

Fix information:  
The problem has been fixed in SoftPC 2.0 final release.

KPR #: 4000093708 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: SOFT PC

One-line description:  
/usr/bin/dosls incorrectly specifies volume labels as filenames

Problem:  
The problem was that the dosls/dosll command could not differentiate between the volume labels and filenames.

Cause:  
There was no code in the dosls/dosll command implementation to distinguish between volume labels and filenames.

Fix information:  
The fix was to add a module to the dosls/dosll command to distinguish volume labels and filenames.

Signed off 01/29/90 in release A02.00

KPR #: 4000093757 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: DOCUMENTATION

One-line description:  
using softpc p 3-4 implies all home directories in /users.

Problem:  
The documentation was misunderstood in the SoftPC 1.3 manual.

Temporary solution:  
The user may call support to clarify the issue.

Fix information:  
The documentation has been expanded and clarified for SoftPC 2.0.

KPR #: 4000093765 Product: SOFT PC FOR 9000/300 98870A

01.03

Keywords: DOCUMENTATION

One-line description:  
using slave pc section p.4-21 configuration info inadequate.

KPR #: 4000093765 \*\*CONTINUED\*\*

Problem:  
"Using SLAVEPC" section of chapter 4 (page 4-21) is inadequate for proper configuration of SlavePC.

Temporary solution:  
The user may call support for more information.

Fix information:  
The documentation has been updated and expanded for SoftPC 2.0.

KPR #: 4000093781 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
pages A-2 and A-4 "using soft pc: should not refer to the DOS coprocessor

Problem:  
"Using SoftPC" manual pages A-2 and A-4 refer to the DOS coprocessor.

Temporary solution:  
The user may call support if they are confused by this.

Fix information:  
The documentation has been updated for SoftPC 2.0.

KPR #: 4000094904 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Turbo Prolog under CGA emulation broken.

Problem:  
When using Turbo Prolog if you zoom the edit window, the program will malfunction.

Cause:  
The problem only occurs when you zoom the edit window. It seems to work fine for everything else.

Temporary solution:  
Workaround is to use Hercules emulation or never zoom the edit window to be full screen. Zooming the edit window is very common since editing on a 3X5 card is painful.

Fix information:  
The problem is fixed with SoftPC 2.0.  
Signed off 01/31/90 in release A02.00

KPR #: 4000094912 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
ExecutiveMemomaker won't work. Too many file handles. config.sys OK.

Problem:

KPR #: 4000094912 \*\*CONTINUED\*\*

Executive Memomaker will not run, it fails with the message "too many file handles."

Cause:  
There is an incompatibility in the SoftPC emulation.

Temporary solution:  
The workaround is to install Memomaker on either drive C: or drive D: where it works fine. The only problems are encountered when using it on the E:, or FSA, drive.

Fix information:  
This problem was fixed in the final SoftPC 2.0B release.

Signed off 01/29/90 in release A02.00

KPR #: 4000094920 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Drawing Gallery drops character when entering a text string.

Problem:  
When entering text strings into Drawing Gallery a character may sometimes be lost.

Cause:  
This happens when the input character buffer gets confused/overflowed.

Fix information:  
This has been fixed for SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4000095026 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Cannot install Lotus 123 using SlavePC, SCR100

Problem:  
When you do a series of installing and deinstalling Lotus 123, using SlavePC, onto the hard disk, it gives random bug codes. This will cause you to lose the install from the Lotus hard disk and will sometimes hang SoftPC.

Cause:  
This was caused by problems with the SlavePC emulation.

Fix information:  
Fixed by final SoftPC 2.0 release.

Signed off 01/29/90 in release A02.00

KPR #: 4000095034 Product: SOFT PC FOR 9000/300 98870A

01.03

One-line description:  
Mouse user interface is unfriendly, can be hard to use, SCR55, SCR163

Problem:

The middle mouse button is "captured" by SoftPC and thus cannot be used by applications like WP; this should be changed so that SoftPC will allow the PC software to get the mouse signals unless the mouse is in the right hand control panel. When the mouse is in the control panel the mouse should be able to be unattached using the toggle switch.

Cause:

The problems are caused by the design of the user interface.

Fix information:

May be fixed in a future release.

KPR #: 4000095042 Product: SOFT PC FOR 9000/300 98870A

01.03

One-line description:  
Escape character does not exit demo mode properly MS Flight Sim., SCR161

Problem:

If you enter ESC to exit demo mode, you should switch to graphics mode 40 and the aircraft data should be displayed, however the 40 characters only cover the left hand side of the screen.

Cause:

There is a graphics incompatibility with SoftPC.

Fix information:

This was fixed with SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4000095059 Product: SOFT PC FOR 9000/300 98870A

01.03

One-line description:  
Sailing game will not run, encounters illegal instruction. SCR168

Problem:

Sailing game will not run; encounters illegal instruction.

Fix information:

May be fixed in a future release.

KPR #: 4000095067 Product: SOFT PC FOR 9000/300 98870A

01.03

One-line description:  
Advance Link won't install from floppy drive A: . SCR170

Problem:

When you try to install from the A: floppy drive as instructed and run the install program "c:\advancelink", it starts up and tells you

KPR #: 4000095067 \*\*CONTINUED\*\*

to press "return" to install or "esc" to escape. Pressing return causes it to hang up and you cannot escape, however, the menu windows still work.

Cause:

The problem was the program IBMWAIT.COM invoked from INSTALL.BAT. It is supposed to wait for <cr> or <esc> but just hangs.

Fix information:

This problem was fixed in the SoftPC 2.0 final release.

Signed off 01/29/90 in release A02.00

KPR #: 4000095075 Product: SOFT PC FOR 9000/300 98870A

01.03

One-line description:  
The SoftPC cursor was the wrong color with some applications. SCR42

Problem:

SoftPC cursor is the wrong color (blue!). Its ok on a monochrome screen.

Cause:

There was a problem with color mapping.

Fix information:

This was fixed in SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4000095083 Product: SOFT PC FOR 9000/300 98870A

01.03

One-line description:  
Graphics problems with text in pc mode 40, with Willy game. SCR102

Problem:

When you go to put your name into the score board, after the game is over, it shows half the screen with text, the other half with half the game on it. The text should be in mode 40.

Cause:

There were problems in the video emulation.

Fix information:

This was fixed for SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4000095091 Product: SOFT PC FOR 9000/300 98870A

01.03

One-line description:  
Problems updating complete screens of video memory, SCR167

Problem:

When painting to pages 1 and 4 of video memory the complete screen

KPR #: 4000095091 \*\*CONTINUED\*\*

was not updated, refreshing the screen cured the problem.

Cause:  
There is some incompatibility in the SoftPC graphics emulation.

Temporary solution:  
The workaround is to refresh the screen.

Fix information:  
This was fixed in the SoftPC 2.0 release.

Signed off 01/29/90 in release A02.00

KPR #: 4000095109 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Round42 game has slow and bad graphics.SCR169

Problem:  
Graphics are slow and are not working correctly.

Fix information:  
May be fixed in a future release.

KPR #: 4000095117 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
PrintMaster program will not run from the FSA drive, E.,SCR172

Problem:  
When you first run Printmaster and create a greetings card and try to save it with no name, the screen fills with funny characters. But if you press "ESC" twice you can get back to the option of saving it over again. The second time you try to save it with no name Printmaster says "I'm having trouble using the disk."

Cause:  
There is some incompatibility with the SoftPC emulation.

Fix information:  
This has been fixed with SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4000095448 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Mouse attached to Smalltalk V Application is inoperative

Problem:  
I just installed SoftPC Rev 1.3 from the distribution tape, and encountered some problems:

I tried to run Smalltalk V, by Digital. Smalltalk V is very graphics intensive, and is optimized for use with a mouse. When

KPR #: 4000095448 \*\*CONTINUED\*\*

I tried to attach the mouse, using the SoftPC button or the middle mouse button menu selection to attach the mouse, the SoftPC mouse button lit up, showing that the mouse was attached to the Smalltalk application. However, there was no mouse sprite (cursor) shown. If I moved the mouse rapidly out and back into the SoftPC window, I could see the X11 mouse cursor appear and disappear. But was unable to use the mouse in the Smalltalk V application, no matter what I tried.

Fix information:  
May be fixed in a future release.

KPR #: 4000095455 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Crosstalk XVI doesn't work with PC bulletin board yellow pages,SCR#162

Problem:  
If you use the modem an Crosstalk, and connect to Electronic Yellow pages it asks you for a login. This should be 3264 in this case, but when it was entered the characters appeared as 3|6|. This happened all the time. Although crosstalk seems ok with all other bulletin boards.

Fix information:  
May be fixed in a future release.

KPR #: 4000095463 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Graphics problem with Typ-Set, bad characters and backgrounds,SCR#86

Problem:  
On the C drive when you start up TYP-SET, it draws the following: "Sweet-P", whereas on FSA it draws a mess from the corner of the screen. However, on both occasions it leaves the first screen, in blue, on the background when you enter the actual package.

Cause:  
There was a graphics incompatibility in SoftPC.

Fix information:  
This was fixed in SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4000095505 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
The scenery flashes when using MS Flight Simulator,SCR205

Problem:  
The scenery flashed when using flight simulator due to slow graphics refreshes.

KPR #: 4000095505 \*\*CONTINUED\*\*

Cause:  
 This was primarily caused due to the slow performance of graphics in SoftPC 1.3.

Fix information:  
 SoftPC 2.0 has greatly improved graphics capability and so does not cause the scenery to flash as obviously during updates.

Signed off 01/29/90 in release A02.00

KPR #: 4000095588 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
MS Windows does not list files selectively with WIN DRAW command, SCR202

Problem:  
 When you run "WIN DRAW" and select a file to draw, it should show only \*.PIC files. Instead it shows all types including \*.EXE, & \*.TXT files. This is also on the s800. This happens on FSA only.

When you run "WIN DRAW" and select a file to draw, it should show only \*.PIC files. Instead it shows all types including \*.EXE, & \*.TXT files. This is also on the s800. This happens on FSA only.

Cause:  
This is caused by problems with FSA/HEX HP-UX filesystem access.

Fix information:  
This is fixed in SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4000095695 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
The right hand alt key doesn't work, SCR232

Problem:  
The right hand alt key on the console keyboard using the X11 version does not work.

Cause:  
There is an omission from the X11 keyboard mapping file.

Fix information:  
The X11 keyboard mapping file was updated for SoftPC 2.0.

KPR #: 4000095810 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Crosstalk XVI has timing problems, SCR162

Problem:

- SOFT PC FOR 9000/300 -

KPR #: 4000095810 \*\*CONTINUED\*\*

SoftPC was connected to a real PC and XTALK CALL was entered. XTALK ANSWER was entered on the PC. Then two files were sent at the default settings. Change speed to say 1200 baud, send two more files and quit Crosstalk from SoftPC, but leave the PC running. You can then enter a few characters after which SoftPC will hang. A number of keyboard or mouse actions cause the window to disappear as the Xserver is not getting in to clear the event queue. Note that if you quit Crosstalk from the PC first then the problem doesn't arise.

Fix information:  
May be fixed in a future release.

Signed off 01/29/90 in release A02.00

KPR #: 4000096206 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
executing cat890511.exe from hpccf gets "CRC Error" (works on XT)

Problem:

Here is the exact sequence to get the file from hpccf and cause a failure. This failure is slightly different from the one with cat90511.exe:

```

$ ftp hpccf
Connected to hpccf.
Name (hpccf:ijg): ftp
Password (hpccf:ftp): abc
331 Guest login ok, send ident as password.
230 Guest login ok, access restrictions apply.
ftp> cd VECTRA-IBM
200 CWD command okay.

```

```
ftp> bin
200 Type set to I.
```

```

ftp> get new90511.com
200 PORT command okay.
150 Opening data connection for new90511.com (15.1.104.2,1609) (9072 bytes)
226 Transfer complete.
9072 bytes received in 3.45 seconds (2.57 Kbytes/sec)

```

```
ftp> quit
221 Goodbye.
$
```

Then in the SoftPC window do:

```
E:\>new90511
LHarc's SFX 1.12bs (c)Yoshi 1989
```

890511.NEW .Write Error

- SOFT PC FOR 9000/300 -



KPR #: 4000096206 \*\*CONTINUED\*\*

KPR #: 5000463372 \*\*CONTINUED\*\*

E:\>

Again, if the file was cat890511.exe, the failure would be:

E:\>cat890511  
LHarc's SFX 1.12bS (c)Yoshi 1989

.....CRC Error

E:\>

Cause:  
The program is probably malfunctioning due to some emulation error in SoftPC.

Fix information:  
Fixed in the final release of SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 4700921791 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Falcon game will not run in Hercules graphics mode

Problem:  
HGA: game won't run

Temporary solution:  
The workaround is to use the game in EGA or CGA mode where it appears to function normally.

KPR #: 4700921882 Product: SOFT PC FOR 9000/300 98870A 01.03

One-line description:  
Test Drive will not run in HGA mode

Problem:  
HGA problems

KPR #: 5000463372 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
Soft PC does not understand local:0 DISPLAY variable

Problem:  
Configuration: 360 with 6.5.

Soft PC requires that the display variable set to unix:0.0 not local:0.0 as documented in the 6.5 information. Soft PC will not come up unless the display variable is set correctly. This should be documented or

Known Problem Reports as of 11/21/90

KPR #: 5000463372 \*\*CONTINUED\*\*

Soft PC should be recompiled on the 6.5 version of X Windows.

Cause:  
The SoftPC was originally designed under HP-UX 6.2 which did not use local:0.0 as the display variable.

Temporary solution:  
The workaround is to use "unix:0.0" as the display variable.

Fix information:  
This has been fixed for SoftPC 2.0.

KPR #: 5000464107 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
Request:reposition window used to create new devices to avoid overlap

Problem:  
The problem is that if any of the user interface menu windows is overlapping or overlapped by any other window, the user will not be able to write into it.

Cause:  
The reason the windows cannot overlap any others is that SoftPC 1.3 was not developed to work with reparenting window managers such as HPWM.

Fix information:  
This has been corrected for SoftPC 2.0.

Signed off 01/29/90 in release A02.00

KPR #: 5000474726 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
can't enter text into menu box when adding a new hard drive using menu

Problem:  
The problem is that SoftPC 1.3 does not function well with some reparenting window managers.

Cause:  
The cause of the problem is that SoftPC cannot get access into the menu windows due to conflicts with the window manager.

Fix information:  
This defect has been fixed in SoftPC 2.0. The 2.0 version will now function properly with reparenting window managers, such as hpwm.

Signed off 01/29/90 in release A02.00

KPR #: 5000527143 Product: SOFT PC FOR 9000/300 98870A 01.03

Keywords: SOFT PC

One-line description:  
Lotus, Work Perfect will not work with drive e on SPC 1.3

Problem:  
The problem with Lotus 123 version 2.2 has been investigated and found to occur with SoftPC 2.0 on drive E:. Files can be created on the E: drive, but they cannot be subsequently accessed. The Lotus 123 version 2.01 can access these files with no problems nor does it have any other problems on drive E. This is being worked on now.

The WordPerfect problem was investigated and due to insufficient detail (i.e. no version numbers, no display information (i.e. ega, cga or hga) and no exact package name information) the following packages were tested: WordPerfect 5.1, WordPerfect 5.0, WordPerfect Office 2.0. No problems were found with any of these packages when accessing drive E:.. Thus, we need further information to define the WordPerfect problem.

Cause:  
This problem was caused by Lotus 2.2 making a call to a new networking function of MS DOS. The particular call was not handled properly and so the file could not be accessed when using the E: drive (which appears as a networked drive to SoftPC.)

Temporary solution:  
The workaround to this defect is to use Lotus on either drive D: or C:.. Otherwise, Lotus 2.01 may be used on any of the available hard disk files, it works properly on all of them.

Fix information:  
This was fixed by updating the SoftPC handling of MS DOS network calls. Fixed in release 2.00.

Signed off 10/16/90 in release A02.00

KPR #: 4700887851 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
Mouse driver: current version is old/doesn't work properly w/new apps.

Problem:  
Mouse driver obsolete

Cause:  
This problem was caused by an incompatibility with the mouse driver.

Temporary solution:  
The workaround is to install one of the newer device drivers included with some of the software packages. The MS Word 5.0 package provides a mouse driver, mouse.sys, that can be installed using the config.sys program as follows.

Add the following line to the config.sys.  
device=mouse.sys

Using this workaround, the mouse seems to work properly.

Fix information:  
There was a new mouse driver shipped with SoftPC to replace the older, faulty driver. Other problems related to the mouse were fixed in the actual code.

KPR #: 4700911818 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Running WordPerfect slows down SoftPC by 4 times

Problem:  
WordPerfect Slow down

Cause:  
It seems like this problem is caused by an access to the filesystem.

Temporary solution:  
The workaround to this defect is to restart SoftPC immediately following use of WordPerfect. The SoftPC will then return to "normal" performance.

Fix information:  
This problem was due to a problem with the way WP opened files. It disappeared completely after restarting SoftPC.

KPR #: 4700921700 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
drive B doesn't work unless on at DOS boot time

Problem:  
If drive B (which is half of a 9122D) is not on when I boot MS-DOS,

KPR #: 4700921700 \*\*CONTINUED\*\*

I cannot subsequently use it, as the system is then configured for single-drive operation. Any request for drive B produces the prompt "insert diskette for Drive B", and the system then uses drive A.

If I have both drives on when I boot DOS, then I can use both with no problems.

Temporary solution:

The workaround is to restart SoftPC once the drive B has been turned on. This is relatively simple and easy to do using the menu panel.

KPR #: 4700921718 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:

MKS "ls" command makes drive E unusable

Problem:

MKS confuses driveE

KPR #: 4700921726 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:

Cursor sometimes vanishes forever

Problem:

Cursor vanishes

Cause:

There is some incompatibility in the graphics emulation.

KPR #: 4700921734 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:

all files created on drive E have execute permission

Problem:

Permissions: DriveE

KPR #: 4700921742 Product: SOFT PC FOR 9000/300 98870B 01.02

One-line description:

can't use DOS coprocessor hard disk

Problem:

When using SoftPC with autoflush it will only work for one X11 instantiation of SoftPC at a time. For example, if you have two SoftPCs and one has the PRN assigned to COM1 and the other has PRN assigned to COM3, and you print autoexec.bat from both SoftPCs, only the SoftPC that was first assigned will be autoflushed. The other SoftPC will not autoflush, although the manual flush will work. This happened when attempting to copy to the COM ports also. This was using both the EGA and HGA displays on the C: drive.

Cause:

- SOFT PC FOR 9000/300 -

KPR #: 4700921742 \*\*CONTINUED\*\*

The DOS Coprocessor disk doesn't work because of a "disk geometry" check that SoftPC does to insure that the file is a proper hard disk file.

Fix information:

A new algorithm was used for hard disk validation. The new method looks at the signature byte in the hard disk which is loaded and verified. It also looks at the file size to see if it is a multiple of 30 cylinders, which it should be. If it is not, then the maximum allowable cylinders variable is set to be 1023 (the max. for DOS disks). This is not dangerous since it will expand up to the original partition size. Fixed in release 2.00.

Signed off 10/19/90 in release B02.00

KPR #: 4700921775 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:

autofreeze behaves incorrectly with explicit keyboard focus

Problem:

The SoftPC auto-freeze option does not behave correctly when the KeyboardFocusPolicy is set to "explicit" under hpwm. Using the explicit policy, you must click the title bar of a window to get the keyboard focus. The keyboard focus remains until you explicitly move it to another window. Thus the mouse can leave the window, but the keyboard focus will remain with the window until another window's title bar is clicked. Because of this, the auto-freeze option should be triggered on keyboard focus, not strictly mouse enter/leave events. SoftPC does not do this. Under explicit policy, SoftPC still freezes itself whenever the mouse leaves the window which is incorrect.

Cause:

The SoftPC auto-freeze option does not behave correctly when the KeyboardFocusPolicy is set to "explicit" under hpwm. Using the explicit policy, you must click the title bar of a window to get the keyboard focus. The keyboard focus remains until you explicitly move it to another window. Thus the mouse can leave the window, but the keyboard focus will remain with the window until another window's title bar is clicked. Because of this, the auto-freeze option should be triggered on keyboard focus, not strictly mouse enter/leave events. SoftPC does not do this. Under explicit policy, SoftPC still freezes itself whenever the mouse leaves the window which is incorrect.

Fix information:

This was fixed in the final SoftPC 2.0 release.

Signed off 10/19/90 in release B02.00

KPR #: 4700921783 Product: SOFT PC FOR 9000/300 98870B 01.20

One-line description:

assigning /dev/tty to COM1 causes SoftPC to hang

Problem:

- SOFT PC FOR 9000/300 -

KPR #: 4700921783 \*\*CONTINUED\*\*

Assigning /dev/tty to COM1 results in SoftPC hanging up when OK is hit in the COM/LPT panel. I realize that /dev/tty is not something you'd normally assign to a COM/LPT port since it's neither a RS232 or HPiB device (with the X11 version, that is). However, it seems like SoftPC should detect that the device is illegal, print an appropriate error message and let you continue. This is also a problem on the s800.

Cause:  
This is probably caused by problems with the signal handling.

Fix information:  
This is fixed with SoftPC 2.0.  
Signed off 10/23/90 in release B02.00

KPR #: 4700921809 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
SoftPC terminal version numeric keypad mapping gets confused

Problem:  
Terminal: key map

KPR #: 4700921825 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
key repeat delay too long

Problem:  
key delay too long

KPR #: 4700921833 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
spc.term link should use basename

Problem:  
Executable Name

KPR #: 4700921858 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
EGA area fill test hangs

Problem:  
EGA test hangs

KPR #: 4700921866 Product: SOFT PC FOR 9000/300 98870B 01.03

One-line description:  
MS Windows 2.03 crashes

Problem:

KPR #: 4700921866 \*\*CONTINUED\*\*

MS Windows 2.03 does not function properly. The mouse will attach fine and the tracking is better than with MS Windows 1.03 and SoftPC 1.3, but when attempting to use the return key on the keyboard MS Windows will crash with a "divide by zero" message. Some of the MS Windows applications, like reversi and cardfile will run, while the attempting to run the calendar program will also lock up MS Windows and require a KILL -9 to reset (the menus do not work) CIL-Alt-DELETE will not reset the SoftPC in either case and it must be done using the menu. This was tested using drive E, the ega.sys MS Windows driver and the EGA display.

Cause:  
This was caused by the way SoftPC was handling INT 6F, which is a CMOS read on HP PC clones. On a standard AT this will cause just an IRET, which is what we now do. In addition Delta was modified to spot self modifying code.

Fix information:  
The fix was to change the handling of INT 6F so that it just caused an IRET. Fixed in release 2.00.

Signed off 10/23/90 in release B02.00

KPR #: 4700921874 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Character Attributes do not function properly

Problem:  
Blinking broken

KPR #: 4700921890 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
3.5-inch floppy read errors

Problem:  
Floppy problems

KPR #: 4700921908 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
FSA, malfunctions with similarly named files, can lose data

Problem:  
FSA problems

KPR #: 4700921916 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
no screen refresh during mediainit

KPR #: 4700921965 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Some of the text on the menus is cut off by the borders.  
Temporary solution:  
The problem is that the menu geometries are not being computed correctly based on the font size. The menu boxes are pre-sized and so if a global font is defined that does not fit into the boxes properly the menus will be cut off and characters lost. The workaround is to include the following line in the users .Xdefaults file:  
softPC\*font: fixed

KPR #: 4700921973 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Codepage Switching command "chcp" sometimes performs incorrectly  
Problem:  
DOS CHCP broken

KPR #: 4700921981 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Microsoft Excel locks up SoftPC if invoked twice in a row  
Problem:  
MS Excel crashes  
Temporary solution:  
Do not invoke Excel consecutively, i.e. if you must exit Excel, do whatever you have to do, reboot the SoftPC and then re-enter Excel.

KPR #: 4700921999 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Word Perfect learn program behaves incorrectly  
KPR #: 4700922005 Product: SOFT PC FOR 9000/300 98870B 02.00  
One-line description:  
Second or Third invocation of SoftPC may fail with internal error

KPR #: 4700922013 Product: SOFT PC FOR 9000/300 98870B 02.00  
One-line description:  
BIOS Data Wrong coming from Debug program  
Problem:  
BIOS data wrong

KPR #: 4700922021 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Multiple file compare fails with DOS comp command  
Problem:  
Mul file comp. fail

KPR #: 4700922039 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Zoom using Mouse  
Problem:  
Zoom using mouse

KPR #: 4700922054 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
MS windows logo should not always come up  
Problem:  
Windows Logo

KPR #: 4700922070 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Cursor appears in wrong place in Chartmaster  
Problem:  
Cursor lost

KPR #: 4700922088 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Caps lock not disabled  
Problem:  
Capslock broken

KPR #: 4700922096 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Pointer Stuck on MS Windows  
Problem:  
Pointer Stuck

Duplicate Service Requests: 4700923078

KPR #: 4700922104 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Data Error using DOS restore  
Problem:  
Data Error

KPR #: 4700922112 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
RMVC causing minor error

Problem:  
RMVC causing error

KPR #: 4700922120 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:

Fastopen works, and probably shouldn't

Problem:  
Fastopen works!

KPR #: 4700922138 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Two scrolling Screens have problems with EGA Demo

Problem:  
Two Scrolling Screens

KPR #: 4700922146 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:  
Errors when editing or creating drawings with Autocad

Problem:  
Autocad comes up with "fatal error disk full" when attempting to edit an existing drawing or create new one.

Cause:  
Autocad comes up with "fatal error disk full when attempting to edit an existing drawing or create new one.

Fix information:  
A simple fix to FSA/HFX cured this problem. The calculation involving the size of a file during random writes was incorrect. Fixed in release 2.00.

Signed off 10/23/90 in release B02.00

KPR #: 4700922153 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:  
LIM user interface is hard to use

Problem:  
Setting up a LIM size that SoftPC cannot allocate (eg 8MB on a low memory system), you get an error panel saying "Bad CMOS:Equip byte is wrong" you do a "continue" and you get an error panel saying "spoc cannot allocate enough memory" with quit as the only option. This is very tedious it should be like the disk config that puts you straight back into the disk panel if you select a non-existent disk.

KPR #: 4700922153 \*\*CONTINUED\*\*

Cause:  
The user interface does not allow an alternative to "quit" when problems with LIM are encountered.

Fix information:  
This was fixed in SoftPC 2.0.

Signed off 10/23/90 in release B02.00

KPR #: 4700922161 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:  
Tests operate incorrectly with PC Labs

Problem:  
When doing fill demo incorrect lines appear on screen.

Cause:  
This was probably caused by problems in the graphics emulation.

Fix information:  
Fixed in release 2.00.

Signed off 10/23/90 in release B02.00

Duplicate Service Requests: 4700922302

KPR #: 4700922179 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Detect Caps and Numlock

Problem:  
Detect Caps+Numlock

KPR #: 4700922187 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Improper Display with NYET

Problem:  
Improper Display

KPR #: 4700922203 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:  
File error with Multimate advantage

Problem:  
Cannot open existing document. Get the following error: Fatal diskette I/O error F:22/S:01/A:1900 please reboot system

Cause:

KPR #: 4700922203 \*\*CONTINUED\*\*

There is a problem with the HP-UX filesystem access that is somehow causing this problem.

Fix information:  
Modifications to FSA/HFX have corrected this problem.  
Fixed in release 02.00.

Signed off 10/23/90 in release B02.00

KPR #: 4700922211 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:  
Executing VGA tests fails with internal error using PCLabs test

Problem:  
When running the display tests on an EGA graphics mode I accidentally pressed I7 and ran the tests for VGA, SoftPC failed with a signal 11 internal error.

Cause:  
The SoftPC video emulator was falling off the end of an internal table.

Fix information:  
This has been fixed to fail gracefully, since SoftPC 2.0 does not support VGA. Fixed in release 2.00.

Signed off 10/23/90 in release B02.00

KPR #: 4700922229 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Display problems with NVET

Problem:  
When playing this game if you press esc to pause the game you get black text on a yellow background saying Bame paused press any key to continue.  
When you press any key the text disappears but the yellow block stays there still.

KPR #: 4700922237 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
File access error with PFS First Choice

Problem:  
File access error

KPR #: 4700922245 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:  
All keys in MS Word autorepeat

Problem:

KPR #: 4700922245 \*\*CONTINUED\*\*

All keys autorepeat

Temporary solution:  
The workaround is to use drive D or E for MS Word. MS Word 5.0 appears to run properly from these drives.

Fix information:  
Fixed in release 2.00.

Signed off 10/23/90 in release B02.00

KPR #: 4700922252 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
SKPlus HFX hard disk full

Problem:  
SKPlus/HFX disk full

KPR #: 4700922260 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Error with Framework II reading disk

Problem:  
Disk Read error

KPR #: 4700922278 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
MicroSoft RBase volume label bad

Problem:  
Volume label bad

KPR #: 4700922286 Product: SOFT PC FOR 9000/300 98870B 01.30

One-line description:  
RMVC.SYS formatting D: drive will fail

Problem:  
Formatting the D drive starts as normal then instead of saying "system transferred" and prompting for a volume label, format reports "General Failure error reading in Drive D:"

Cause:  
This was caused by errors in RMVC.SYS.

Fix information:  
The RMVC.SYS file now works correctly, there was no other impact on SoftPC. Fixed in release 2.00.

Signed off 10/23/90 in release B02.00

KPR #: 4700922294 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
The Antix game hangs when you start it up

Problem:  
Antix hangs

KPR #: 4700922310 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
The BIOS test BL-13-3 hangs SoftPC

Problem:  
BIOS TEST fails

KPR #: 4700922328 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
Printing a file does not work properly sometimes with a parallel printer

Problem:  
Printing broken

KPR #: 4700922336 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
No error message if spcterm run on terminal assigned as com port output

Problem:  
Bad Setup, stern err.

KPR #: 4700922344 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
DOS Graph: Garbage on screen

Problem:  
Garbage on Screen

KPR #: 4700922351 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
Using QT windows small blobs on screen, bad display

Problem:  
Small blobs on screen

KPR #: 4700922369 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
The boot message for SoftPC doesn't include the year 1989

Problem:  
SoftPC Boot Message

KPR #: 4700922377 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
The SoftPC Mouse may be attached in two SoftPC windows at once

Problem:  
Works in 2 SoftPC's

KPR #: 4700922385 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
", " key works intermittently on 2392, 2393, 70094 terminals

Problem:  
", " key doesn't work

KPR #: 4700922393 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
The SoftPC menu editing does not always provide autorepeat

Problem:  
Autorepeat error

KPR #: 4700922401 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
The SoftPC SlavePC runs very slowly

Problem:  
SlavePC Slow

KPR #: 4700922419 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
PC Tools Deluxe does not display all files properly in a listing

Problem:  
Files not displayed.

KPR #: 4700922427 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
Cannot play Niteorc game

Problem:  
Niteorc game cannot be played. When playing the game you can only type in the first couple of commands. After that, all you can see when you type is the cursor moving about the screen and you have to reboot SoftPC to get out.

KPR #: 4700922435 Product: SOFT PC FOR 9000/300 98870B

02.00

One-line description:  
Cannot play Tetris game because you cannot see shapes

Problem:



KPR #: 4700922435 \*\*CONTINUED\*\*

Can't see shapes

KPR #: 4700922443 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Mouse doesn't work properly with Ventura publishing

Problem:  
Ventura mouse fails

KPR #: 4700922450 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
File retrieval with Turbo Prolog may have problems

Problem:  
Filename moves

KPR #: 4700922468 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
The CIL-Break key is not detected properly with test

Problem:  
Ctrl Break not seen

KPR #: 4700922476 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
SoftPC Filename mapping shouldn't use shell wildcard characters

Problem:  
FSA:shell conflict

Temporary solution:  
The workaround is to enclose the odd filename with ' (left pointing) quotes, so that the shell interprets the file name as a literal and does not attempt substitution.

KPR #: 4700922484 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
The printscr key does not function on the 700/44

Problem:  
TERM: no printscr

KPR #: 4700922492 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Switching graphics modes from EGA to Hercules and back may confuse SPC

Problem:  
UIF:graphics modes

KPR #: 4700922492 \*\*CONTINUED\*\*

Temporary solution:

In order to switch from Hercules to EGA or vice versa, use the CGA mode as an intermediate step, i.e., switch to CGA mode and then to Hercules or switch to CGA and then to EGA. This takes more time but it works consistently.

KPR #: 4700922500 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Starflight game will not run in EGA mode

Problem:  
The starflight game will not run in EGA mode.

KPR #: 4700922518 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
cannot use MODE to set 19.2K baud rate

KPR #: 4700922526 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
SoftPC behaves incorrectly with explicit KB focus policy

KPR #: 4700922534 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
should not permit "block" device files for floppy

KPR #: 4700922583 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Advancelink: Ctrl-F6 doesn't work

Temporary solution:  
You can bring up the Global Configuration screen by hitting the Terminal softkey and then choosing "Config Keys".

KPR #: 4700922591 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Advancelink hangs after Alt-H

KPR #: 4700922757 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
X11 keyboard:Numeric keypad "/" key does not work

KPR #: 4700922765 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
X11 keyboard: ScrLckBreak key does not register on Diagnostic Programs

KPR #: 4700922773 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Codepage language support: German, "7"key, "\" dead key broken

KPR #: 4700922781 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
70044 terminal: Asterisk key not working on numeric keypad

KPR #: 4700922799 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
FSA, filenames with certain extensions not accessible from SoftPC

Temporary solution:  
The workaroud is to rename the desired files so that they are lower case and follow the DOS naming conventions.

KPR #: 4700922807 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Reverse video does not work on the 2392,2394 and 7009x terminals

Cause:  
There could be a problem with the escape sequence used to enter reverse video. I suspect that the HP escape sequence is used, thus the older, simpler terminals allow it, while the newer terminals ignore it. This is a problem because the terminal is in Ansi mode and so the ANSI escape sequence should be used instead. Perhaps a simple change of escape sequence would work.

KPR #: 4700922815 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
DOS Xcopy command doesn't work properly with FSA directories

KPR #: 4700922823 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Concurrent PC-DOS won't install on SoftPC

KPR #: 4700922831 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Displaywrite4 screen not refreshed completely

KPR #: 4700922849 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Problems resetting LIM (memory) to zero

KPR #: 4700922856 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
learn program from Microsoft Works locks entire SoftPC window

Problem:  
While using the learn program that comes with Microsoft Works, I reached a point where the prompt directed me to hit PgDn to get to the next screen. After hitting PgDn, the entire window hung where the middle mouse button would not even bring down a menu. The process had to be killed from another window. I recovered the previous release of spc.x11 and it did not have the problem. HP-UX 6.5, X11 windows, 370 with 16 Mbyte memory, 98547A graphics card, 98751A monitor, 7959B disk. BTW, the 800 version of SoftPC also exhibits the problem.

KPR #: 4700922864 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Microsoft Works 2.0: using same arrow key causes unwanted repeating

KPR #: 4700922880 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
Trying to start Quattro Pro fails and occasionally locks all windows

KPR #: 4700923094 Product: SOFT PC FOR 9000/300 98870B 02.00

One-line description:  
does not handle input before boot message is up

KPR #: 4700922914 Product: SOFT PC FOR 9000/300 98870C

One-line description:  
spc hangs when HP BASIC-UX is active

KPR #: 4000096396 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
render\_scene gives incorrect error message for unclosed trim curves

Problem:  
The "improper parameter message" should be changed to something more meaningful.

Cause:  
At the time of release, a meaningful error message did not exist in the error catalog.

Fix information:  
A new error message has been added to the error catalog. "Improper parameter value" now reads "Cannot perform this operation if trim curves are not closed". The new error message was added to version B.02.00.

Signed off 10/23/90 in release A02.02

KPR #: 4000096412 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
Objects disappear when they are placed exactly on the hither plane.

Problem:  
The ray tracer starts exactly on the hither plane. When a polygon is intersected, if it occurs within a certain epsilon of the origin of the intersection, it is rejected. The problem only occurs if a polygon is exactly on the hither.

Temporary solution:  
The user can work around this problem by making sure that all objects are within the clipping volume. The easiest way to do this is to adjust the clipping volume with a call to view\_camera.

Fix information:  
Because the frequency of the problem is so low, and because the problem can easily be avoided, it is viewed as an enhancement request, not a defect.

Signed off 10/23/90 in release A02.00

KPR #: 4000096438 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
Radiosity shadows not computed for extremely small environments.

Problem:  
The problem resulted from the fact that the ray tracing shadow test had to move off the surface to avoid self-intersection and to avoid intersecting other polygons that the touch the surface at the vertex from which the ray is being shot.

KPR #: 4000096438 \*\*CONTINUED\*\*

Temporary solution:  
This problem can be avoided by scaling the data to larger values.

Fix information:  
The shadow testing algorithm has been modified in Version B.02.00, eliminating the problem.

Signed off 10/23/90 in release A02.00

KPR #: 4000096446 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
False shadows are produced at some polygon vertices

Problem:  
The ray tracing shadow tests, used in radiosity, were incorrectly setting an epsilon value for vertices along the exterior boundaries of polygons.

Fix information:  
The shadow testing algorithm in radiosity has been revised. The new algorithm eliminates the problem. The problem has been fixed in version B.02.00.

Signed off 10/23/90 in release A02.00

KPR #: 4000096461 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
Complex polygons may get holes punched in them.

Problem:  
In very complex polygons with lots of overlapping holes and edges, extra loops are created by the mesher that shouldn't be there. It is unlikely that this type of polygon would be encountered by users.

Temporary solution:  
This is expected to be a corner case, that will appear only with certain types of data. Which data cause this problem is not well categorized. In some cases the user may be able to generate the same shape using different data which avoids the problem.

Fix information:  
The mesher has been modified for Version B.02.00.

Signed off 01/30/90 in release B02.00

KPR #: 4000096479 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
"Invalid global environment id" should read "Invalide scene id"

Problem:  
"Global environment" should read "scene".

- STARBASE RAD & RAY -

KPR #: 4000096479 \*\*CONTINUED\*\*

Cause:  
The error message catalog was worded incorrectly.

Fix information:  
The global environment error message has been replaced in Version B.02.00.

Signed off 10/23/90 in release A02.00

KPR #: 4000097113 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
Facets disappear in some ray traced spline surfaces.

Problem:  
Facets disappear in ray trace of certain spline shapes

Temporary solution:  
The problem can be somewhat alleviated by scaling down the spline surface by a factor of 1000.

Fix information:  
This problem will be fixed in the next revision.

Signed off 01/30/90 in release A01.01

KPR #: 4000097121 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
Facets have "acne" in ray trace of certain spline surfaces

Problem:  
Surfaces have "acne" in ray trace of certain spline surfaces.

Fix information:  
This problem will be fixed in the next revision.

Signed off 01/30/90 in release A01.01

KPR #: 4000097139 Product: STARBASE RAD & RAY 98885A 01.00

One-line description:  
Gamma correction causes a crash for backgrounds and flat shade items.

Problem:  
Gamma correction causes a crash for backgrounds and flat shade items.

Fix information:  
This problem will be fixed in the next release.

Signed off 01/30/90 in release A01.01

- STARBASE RAD & RAY -

KPR #: 400097147 Product: STARBASE RAD & RAY 98885A

01.00

One-line description:  
Facets get shadowed when radiosity done on specific spline surface

Problem:  
Facets get shadowed on particular spline surfaces.

Fix information:  
May be fixed in a future release.

Signed off 01/30/90 in release A01.01

KPR #: 400097154 Product: STARBASE RAD & RAY 98885A

01.00

One-line description:  
When a trimming curve is applied to certain spline surfaces edges drop

Problem:  
When a trimming curve is applied to a spline surface sometimes the edge drops out.

Fix information:  
This problem will be fixed in the next revision.

Signed off 01/30/90 in release A01.01

KPR #: 400098533 Product: STARBASE RAD & RAY 98885A

01.00

One-line description:  
Intensities per/vertex not blended correctly on meshed polygons.

Problem:  
The intensities per/vertex not blended correctly on meshed polygons.

Fix information:  
Fixed in version B.02.00.

KPR #: 470085252 Product: X.400 SERV SOFTWARE 32058A

00.00

One-line description:  
Some x400 utils, when run as root, leave behind \*.conf belonging to root

KPR #: 4700876714 Product: X.400 SERV SOFTWARE 32058A

00.00

One-line description:  
MR version contains several man pages from FT

KPR #: 4700883124 Product: X.400 SERV SOFTWARE 32058A

00.00

One-line description:  
Queueview only works when the full pathname is specified

KPR #: 4700885632 Product: X.400 SERV SOFTWARE 32058A

00.00

One-line description:  
x4perm has a problem changing premissions for x4dump, x4mailer, etc

KPR #: 4700929372 Product: X.400 SERV SOFTWARE 32058A

00.00

One-line description:  
Zero length subject causes encoder to go down(error 5029 or event 505)

Fix information:  
Problem has been fixed. Patch is available. Patch name is encoder.B.01.11. The patch is available with Response Centers.

Signed off 08/15/90 in release B01.11

KPR #: 4700941898 Product: X.400 SERV SOFTWARE 32058A

00.00

One-line description:  
X4xfer fails if MPE nodename extension is > 16 characters

Fix information:

This problem has been fixed. It will be included in the next release of X.400.

KPR #: 5000558338 Product: X.400 SERV SOFTWARE 32058A

00.00

One-line description:  
X4admin core dumps when hit <field help> on local x.25 nsap field.

Problem:  
This SR is actually against the X.400/9000 Server, version B.01.00. In x4admin, go to 'LOCALTA Configure Local MTA' screen. Tab down to 'Local NSAPS: X.25' field and then press <f7> to get Field Help. Terminal hangs and following message displayed in X.25 field:

Segmentation error: core dump

Reproduced this problem on 2 different systems.

Cause:

KPR #: 500058338 \*\*CONTINUED\*\*

The real cause of this problem is the fact that the x4mailer process is using some of the same sets in the message catalog as x4admin. It turns out that this was happening because x4mailer has msgs. 450 through 456 in set 42 of msgcat. These x4mailer messages all have "%1\$s" in them. The x4admin help messages for the X.25 NSAP field are msgs. 401 through 500 in set 42. X4admin is doing an nl\_sprintf on all these messages, and is not supplying any arguments to be substituted in because help messages are just plain text. Since message 450 has "%1\$s" when x4admin tries to sprintf it without giving it an argument, x4admin core dumps. Note that x4admin only core dumps if compiled with optimize on, which is why we did not catch this problem before MR.

Note: X4mailer is an X.400/9000 process, not an X.400 Server process, but its messages are in the X.400 Server catalog because there is only one 300 version of msgcat for both the X.400 Server and X.400/9000.

Fix information:

X4mailer will be modified to use some other message catalog sets which x4admin is not using, which will fix this particular problem. In addition, we are changing our testing strategy so that we do more testing with the code optimized and debug turned off.

This problem exists in the B.01.00 release (MR release) of both the HP X.400 Server and HP X.400/9000, and in pre-release GOSIP versions. This problem will be fixed in the GOSIP release.

Software release contents

PAGE I 1

Product name	Product number	uu.ff	prev
ADVMAIL FOR TERMINAL	B1601A	00.00	00.00
OPENMAIL	B1600A	00.00	00.00
OPENMAIL ADMN HELP	B1602-90002	00.00	00.00
OPENMAIL/X.400	B1600X4	00.00	00.00

Product name	Product number	SSB ISSUE DATE	Page
ADVMAIL FOR TERMINAL	B1601A	10/09/90	3
OPENMAIL	B1600A	10/09/90	1
		10/09/90	5
OPENMAIL/X.400	B1600X4	10/09/90	2
		10/09/90	29



KPR number	page	KPR number	page	KPR number	page	KPR number	page
1600103309	5	1600105296	14	1600106120	21	1600108225	31
1600103317	6	1600105304	14	1600106278	29	1600108233	32
1600103358	6	1600105312	15	1600106385	21	1600108241	32
1600103366	8	1600105346	16	1600106716	22	1600108662	24
1600103408	8	1600105361	16	1600106823	22	1600108696	24
1600103424	9	1600105379	17	1600106849	22	1600108720	25
1600103432	10	1600105387	17	1600106856	23	1600108753	25
1600103457	10	1600105452	18	1600106963	4	1600108761	26
1600103499	11	1600105544	3	1600107334	29	1600108803	26
1600103531	11	1600105619	18	1600107656	23	1600109215	32
1600105007	3	1600105791	19	1600107698	4	1600109223	33
1600105080	12	1600105809	3	1600107797	4	1600109264	1
1600105163	29	1600105965	19	1600108068	30	1600109330	2
1600105171	12	1600106047	20	1600108134	24	5000538389	26
1600105197	13	1600106054	20	1600108191	30	5000550467	27
1600105270	13	1600106070	20	1600108217	31	5000550756	28

CUMULATIVE KEYWORD INDEX

- ADVMAIL FOR TERMINAL - SSB ISSUE DATE: 10/09/90

Keyword	Product number	uu.ff	Description	KPR number	page
*****none*****	B1601A	00.00	Internal error 401 occurs when using shift/home after a re-order.	1600106963	4
ADVMAIL	B1601A	00.00	If BCC is a Public DistList then recips. do NOT see name when msg. read	1600107797	4
	B1601A	00.00	^L does not refresh function key labels - they are removed	1600105544	3
	B1601A	00.00	Screen output from advmail that doesn't occur via JAM is in ISO8859/1	1600105809	3
	B1601A	00.00	Only "End of Item" line displayed on message entry	1600107698	4
FOLDER	B1601A	00.00	Folder functions within the wastebasket do not work properly	1600105007	3
OUTPUT	B1601A	00.00	Screen output from advmail that doesn't occur via JAM is in ISO8859/1	1600105809	3
PATCHED	B1601A	00.00	Screen output from advmail that doesn't occur via JAM is in ISO8859/1	1600105809	3
SCREEN	B1601A	00.00	Screen output from advmail that doesn't occur via JAM is in ISO8859/1	1600105809	3
WASTEBASKET	B1601A	00.00	Folder functions within the wastebasket do not work properly	1600105007	3

- OPENMAIL - SSB ISSUE DATE: 10/09/90

*****none*****	B1600A	00.00	Temporary files gradually accumulate in the user 'g' directories	1600106716	22
	B1600A	00.00	Some 8-bit characters are not displayed on Term U/I function keys	1600108720	25
	B1600A	00.00	Submission date of messages is creation date NOT the mailing date	1600108753	25
ACKNOWLEDGEMENT	B1600A	00.00	PC ASCII files with lines longer than 80 chars are not copied correctly	1600108761	26
	B1600A	00.00	Reply ACKs set on messages from Desk to OpenMail are not satisfied.	1600105171	12
ADVMAIL	B1600A	00.00	Ack on message from PC Advmail to Desk user with name >26 chars errors	1600105296	14
	B1600A	00.00	Can't put acks on a message forwarded from your pending tray.	1600103366	8
	B1600A	00.00	Delete part of message to be sent, get "Internal Error: 5001"	1600103499	11
	B1600A	00.00	Wrong error message if edit non-writable file in "configuration" area	1600103531	11
	B1600A	00.00	Ack on message from PC Advmail to Desk user with name >26 chars errors	1600105296	14
CATALOG	B1600A	00.00	If BCC is an alias name the recipient does NOT see it when reading msg.	1600105619	18
	B1600A	00.00	Non-delivery text generated by Desk gateway can contain non-Roman8 chars	1600105965	19
	B1600A	00.00	omvers checks the n-computer message catalogs instead of checking \$LANG	1600106070	20
	B1600A	00.00	Daemons are started but don't process any messages.	1600103358	6
	B1600A	00.00	Messages from unix mail to Desk, via OpenMail sometimes do not arrive	1600105304	14
DBVISTA	B1600A	00.00	Non-delivery forwarded from OM to HP Desk to OM gets corrupted.	1600103317	6
DESK	B1600A	00.00	Reply ACKs set on messages from Desk to OpenMail are not satisfied.	1600105171	12
DESK GATEWAY	B1600A	00.00	Trailing spaces are removed on binary files sent between OM and Desk	1600105197	13
	B1600A	00.00	Messages from unix mail to Desk, via OpenMail sometimes do not arrive	1600105304	14
	B1600A	00.00	If text with control codes is sent from Desk to OM, text is lost.	1600105452	18
	B1600A	00.00	Non-delivery text generated by Desk gateway can contain non-Roman8 chars	1600105965	19
DIRECTORY	B1600A	00.00	X.400 ORNames require that a surname is entered	1600109264*	1
ENVIRONMENT	B1600A	00.00	Desk gateway rejects text lines greater than 152 characters	1600107656	23
FILE	B1600A	00.00	Function keys in omadmin are displayed badly if TERM is corrected.	1600106054	20
HANG	B1600A	00.00	ommodu does not change ownership of user's files	1600105312	15
HELP	B1600A	00.00	omon and omoff can appear to hang when CPU loop on the HP 9000.	1600103408	8
LOCAL DELIVERY	B1600A	00.00	The omshowdir MAN page references "genadddir"	1600106047	20
LOOP	B1600A	00.00	Large message sent to Openmail lost without trace	5000550467	27
MAILNODE	B1600A	00.00	Tight CPU loop stopping terminal over LAN if in compose editor.	1600103309	5
MODIFY	B1600A	00.00	Omadmin can produce "link layer" error when displaying a "*" mailnode	1600105361	16
OMADDDIR	B1600A	00.00	Bad error displayed for "List Directory by Mailnode" with no mailnode	1600105379	17
OMADMIN	B1600A	00.00	ommodu does not change ownership of user's files	1600105312	15
	B1600A	00.00	The omshowdir MAN page references "genadddir"	1600106047	20
	B1600A	00.00	Title half way down output with version listing to the printer.	1600103424	9
	B1600A	00.00	Add 2 users in omadmin, 2nd gets the password of the first.	1600103457	10

CUMULATIVE KEYWORD INDEX

- OPENMAIL - SSB ISSUE DATE: 10/09/90

Keyword	Product number	uu_ff	Description	KPR number	page
OMADMIN	B1600A	00.00	ommodu does not change ownership of user's files	1600105312	15
	B1600A	00.00	omadmin can produce "link layer" error when displaying a "*" mailnode	1600105361	16
	B1600A	00.00	Bad error displayed for "List Directory by Mailnode" with no mailnode	1600105379	17
	B1600A	00.00	omadmin doesn't have single line function key labels for vt100 & vt220s	1600105387	17
	B1600A	00.00	Screen output from omadmin that doesn't occur via JAM is in ISO8859/1	1600105791	19
	B1600A	00.00	Function keys in omadmin are displayed badly if TERM is corrected.	1600106054	20
	B1600A	00.00	Refresh omadmin screen doesn't refresh softkeys	1600106823	22
OMCHECK	B1600A	00.00	omadmin does not accept "*" in HPDesk mailnode translation	1600108662	24
OMEDIT	B1600A	00.00	omcheck complains about permissions on database and check files.	1600103432	10
OMLOCKMGR	B1600A	00.00	Some 8-bit chars are not properly displayed by omedit	1600108134	24
OMOFF	B1600A	00.00	Daemons are started but don't process any messages.	1600103358	6
OMON	B1600A	00.00	omon and omon can appear to hang when CPU loop on the HP 9000.	1600103408	8
	B1600A	00.00	The usage errors for omon and omon are syntactically incorrect.	1600105270	13
	B1600A	00.00	omon and omon can appear to hang when CPU loop on the HP 9000.	1600103408	8
	B1600A	00.00	The usage errors for omon and omon are syntactically incorrect.	1600105270	13
OMSCAN	B1600A	00.00	omscan produces inaccurate number of kilobytes for each user	1600106385	21
OMSHOWLOG	B1600A	00.00	Usage error message for omshowlog inconsistent with man page & omshowlog	1600105346	16
OMSTORE	B1600A	00.00	omstore MAN page does not fully document openmail data restore process	5000550756	28
OMVERS	B1600A	00.00	omvers checks the n-computer message catalogs instead of checking \$LANG	1600106070	20
OM RECORD	B1600A	00.00	Setting OM_R variable fails to redirect omadmin commands to file	1600108696	24
OUTPUT	B1600A	00.00	Screen output from omadmin that doesn't occur via JAM is in ISO8859/1	1600105791	19
PATCHED	B1600A	00.00	Some 8-bit chars are not properly displayed by omadmin	1600105080	12
	B1600A	00.00	omadmin doesn't have single line function key labels for vt100 & vt220s	1600105387	17
	B1600A	00.00	Screen output from omadmin that doesn't occur via JAM is in ISO8859/1	1600105791	19
	B1600A	00.00	Function keys in omadmin are displayed badly if TERM is corrected.	1600106054	20
	B1600A	00.00	"Back-end" admin commands always o/p 8-bit chars in ISO8859/1	1600106849	22
	B1600A	00.00	Printed output from 'omadmin' does not treat 8-bit chars correctly	1600106856	23
PC	B1600A	00.00	Unix gateway does not map host name correctly on reply	5000538389	26
PROCESS	B1600A	00.00	Ack on message from PC Advmail to Desk user with name >26 chars errors	1600105296	14
SCREEN	B1600A	00.00	Usage error message for omshowlog inconsistent with man page & omshowlog	1600105346	16
SERVICE	B1600A	00.00	Screen output from omadmin that doesn't occur via JAM is in ISO8859/1	1600105791	19
SERVICE ROUTER	B1600A	00.00	Usage error message for omshowlog inconsistent with man page & omshowlog	1600105346	16
	B1600A	00.00	Recipient fields in an X.400 delivery report can contain illegal values	1600106120	21
TERMINAL	B1600A	00.00	Large message sent to Openmail lost without trace	5000550467	27
TERMINALS	B1600A	00.00	Tight CPU loop stopping terminal over LAN if in compose editor.	1600103309	5
UNIX GATEWAY	B1600A	00.00	omadmin doesn't have single line function key labels for vt100 & vt220s	1600105387	17
	B1600A	00.00	Messages from unix mail to Desk, via OpenMail sometimes do not arrive	1600105304	14
	B1600A	00.00	X.400 names with initials but no forename are incorrectly mapped -> unix	1600108803	26
	B1600A	00.00	Large message sent to Openmail lost without trace	5000550467	27

- OPENMAIL/X.400 - SSB ISSUE DATE: 10/09/90

*****none*****	B1600X4	00.00	X400 Interface insisting on OR name in p2.Ordscriptor	1600107334	29
	B1600X4	00.00	OpenMail/X.400 left t files in iq	1600108068	30
	B1600X4	00.00	Timestamps generated by mappers had an offset that was wrong by 1 hour	1600108191	30
	B1600X4	00.00	Outmapper insists on ORNames being present in IPMsgids (Ack Ids)	1600108217	31
	B1600X4	00.00	X.400 PDU with binary bodypart encoded as plain Octet string is rejected	1600108225	31
	B1600X4	00.00	X.400 PDU rejected, if Binary bodypart is sequence of Octet strings	1600108233	32

CUMULATIVE KEYWORD INDEX

- OPENMAIL/X.400 - SSB ISSUE DATE: 10/09/90

Keyword	Product number	uu. ff	Description	KPR number	page
*****none*****	B1600X4	00.00	Outmapper fails while trying to create OpenMail NonDeliveryNotification	1600108241	32
	B1600X4	00.00	X.400 out mapper not encoding numerical country codes correctly	1600109215	32
	B1600X4	00.00	Null ADMs and PRMDs cause problems in ORNames for X.400 mappers	1600109223	33
	B1600X4	00.00	X.400 Mappers do not support NBS/COS Special Character Encoding for DDAs	1600109330*	2
ERROR MESSAGE	B1600X4	00.00	The X.400 error messages are in the wrong part of the PSS	1600105163	29
GATEWAY	B1600X4	00.00	X.400 interface rejects incoming DeliveryReports if no IntermediateTrace	1600106278	29
X.400	B1600X4	00.00	The X.400 error messages are in the wrong part of the PSS	1600105163	29

Known Problem Reports as of 10/09/90

Page: 1

KPR #: 1600109264 Product: OPENMAIL

B1600A

00.00

Keywords: DESK GATEWAY

One-line description:

Desk gateway rejects text lines greater than 152 characters

Problem:

This problem is only found in the HP Desk Gateway patch version A.00.00.07. The revised dscopy transport detects file transfer problems by checking dscopy's stdout for any output. It cannot tell the difference between a warning and a 'real' error. Dscopy, by default will truncate text files with records longer than 152 characters and generate a warning. The gateway interprets this warning as a potential problem and aborts the transfer. The transfer gets re-tried for 3 days, then the message is returned to the sender.

Fix information:

This problem is fixed in OpenMail release A.00.01. Dscopy is no longer configured to truncate text file records to any length. Instead the desk gateway configuration program 'omconfdsk' may now be used to enable text file folding at a record width set by the OpenMail administrator.

Known Problem Reports as of 10/09/90

Page: 2

KPR #: 1600109330 Product: OPENMAIL/X.400

B1600X4

00.00

One-line description:

X.400 Mappers do not support NES/COS Special Character Encoding for DDAS

Problem:

This fix is required to support the @ character found in DDAS when a user sends from a remote Unix node to OpenMail then onto X.400. The character does not get passed and causes problems in the OutMapper.

If other characters outside the printable character set are required in DDAS this enhancement will be required.

Fix information:

Fix was made to the in and outmappers.

Code changes:

Inmapper - consl.c  
Outmapper - orn.c

Common library - created new file called ps\_to\_ascii.c

KPR #: 1600105007 Product: ADVMAIL FOR TERMINAL BI601A

00.00

Keywords: WASTEBASKET FOLDER

One-line description:

Folder functions within the wastebasket do not work properly

Problem:

If you enter the waste basket, press "FILE", "CREATE Folder", do not type a name, then "MOVE to folder" the message is removed from the screen display, even though it is not deleted.

Cause:

The term.ui program may not be dealing with the waste basket as a special case correctly

KPR #: 1600105544 Product: ADVMAIL FOR TERMINAL BI601A

00.00

Keywords: ADVMAIL

One-line description:

"L does not refresh function key labels - they are removed

Problem:

"L does not refresh function key labels (they are removed)

Cause:

Problem caused by JAM, function key labels are not supported properly on other than HP terminals. JAM does not really know the labels are there on a VT100/220

Fix information:

JAM internally traps the refresh key, it can be trapped only in some cases. Keys are now refreshed correctly where data entry is not required. It will now also refresh keys on an HP terminal under these circumstances.

KPR #: 1600105809 Product: ADVMAIL FOR TERMINAL BI601A

00.00

Keywords: ADVMAIL PATCHED

SCREEN

OUTPUT

One-line description:

Screen output from advmail that doesn't occur via JAM is in IS08859/1

Problem:

Screen output from advmail that does not occur via the JAM interface is always in the IS08859/1 char-set. This occurs in 2 known places, the 'Type exit to return' message when breaking out to the shell, and the termination message. (Only affects localised version).

Cause:

simple ISO???? -> ROMAN8 mapping needs to be added where needed.

Fix information:

Text printed outside of JAM is now converted where needed.

KPR #: 1600106963 Product: ADVMAIL FOR TERMINAL BI601A

00.00

One-line description:

Internal error 401 occurs when using shift/home after a re-order.

Problem:

An internal error, number 401, code: 0, occurs when shift/home is used after re-ordering a folder in the filing cabinet. This only occurs when there are too many folders in the filing cabinet to be displayed on one screen, and the folder being repositioned is on the second or subsequent screen, and is moved to a position on a previous screen.

KPR #: 1600107698 Product: ADVMAIL FOR TERMINAL BI601A

00.00

Keywords: ADVMAIL

One-line description:

Only "End of Item" line displayed on message entry

Problem:

Very occasionally when reading a message, only 'End of Item' is displayed even though the message exists. On re-reading the message it is displayed correctly. A timing problem exists between the U/I process and the Item Browser process.

KPR #: 1600107797 Product: ADVMAIL FOR TERMINAL BI601A

00.00

One-line description:

If BCC is a Public DistList then recips. do NOT see name when msg. read

Problem:

If a Public Distribution List name is used as a BCC recipient then the PDL recipients do not see themselves (ie. do not see the PDL recipient) on the Distribution List when the message is read. This occurs because the message browser does not currently have access to the expanded PDL and therefore can not determine whether any individual user should be able to see the BCCed PDL recipient name.

KPR #: 1600103309 Product: OPENMAIL B1600A 00.00

Keywords: LOOP TERMINAL

One-line description:  
Tight CPU loop stopping terminal over LAN if in compose editor.

## Problem:

If either the terminal interface or the administration interface receive and end-of-file from their input, they will go into a tight CPU loop.

This seems to happen is when you have a data-switch that doesn't send a "hang-up" signal before it drops the line, or when you just get rid of a LAN connection before you have come out of the terminal interface or the administration interface.

You may see this problem when you do an "omstat -s" or "omstat -q" and they appear to hang. Or, "omon" and "omoff" may appear not to work. The "omon" and "omoff" problem is detailed in SR 1600-103408.

To see if you are having this problem, type:

```
ps -ef
```

and look for "term.ui" or "admin.prog" or "compose.edit" programs that have used more than about 30 minutes of CPU.

The amount of CPU that a process has used is given by field 7 of the "ps" output. The name of the program is given in field 8.

## Cause:

The problem is due to the software ignoring end-of-file. The software keeps reading until it gets a character. When an end-of-file is hit, the software simply attempts the read again. Each repeated read will get end-of-file, resulting in the software "looping".

## Temporary solution:

You must kill the programs that are using up CPU. Log on as root and type:

```
Kill -1 PID
```

where PID is the PID of the program you identified as specified in the "submitter text". The PID of the process is given in field 2 of the "ps" output.

There is a script called "ommon" that will look for such situations. If you type "man ommon", it will tell you about this script.

If you're using a data-switch you should reconfigure it to issue a "hang-up" signal before dropping lines.

If you are using LANs, then don't drop the LAN connection before coming out of the terminal and administration user interfaces.

## Fix information:

- OPENMAIL -

Known Problem Reports as of 10/09/90

KPR #: 1600103309 \*\*CONTINUED\*\*

EOF is now correctly handled.

Duplicate Service Requests: 1600105049

KPR #: 1600103317 Product: OPENMAIL B1600A 00.00

Keywords: DESK GATEWAY

One-line description:  
Non-delivery forwarded from OM to HP Desk to OM gets corrupted.

Problem:  
If you forward a non-delivery notification from your OpenMail In tray into HP Desk and then back into OpenMail, you will get an error when trying to read the forwarded non-delivery.

## Cause:

The record size of the non-delivery is filled to 256 because it is binary. This happens when going from OpenMail to HP Desk. When it comes back from HP Desk, OpenMail treats it as corrupt because there are trailing nulls.

## Fix information:

The Desk gateway now makes use of OpenMail converters to map OpenMail non-delivery and trace parts to ROMAN8 text

KPR #: 1600103358 Product: OPENMAIL B1600A 00.00

Keywords: OMLCKMGR DBVISTA

One-line description:  
Daemons are started but don't process any messages.

## Problem:

When any one of the OpenMail daemons accesses the database, it does so through a program called "/usr/openmail/bin/omlockmgr". As its name suggests, this program manages the locking of the database.

When you start an OpenMail daemon, the omlockmgr program must be running. However, you can kill the omlockmgr program while the OpenMail daemon is running, and the daemon will not notice.

If another omlockmgr program is started while the OpenMail daemons are running, they will not "see" the new omlockmgr.

The result is that all calls to the database will hang indefinitely because they are waiting for a response from a non-existent lock manager program.

## Cause:

The problem is due to the database access routines not detecting that the omlockmgr is no longer running (or a new omlockmgr process has been started, which does not know anything about the existing processes attempting to access the database).

- OPENMAIL -

KPR #: 1600103358 \*\*CONTINUED\*\*

Temporary solution:

To verify that you have this problem, type

omstat -s

This will tell you which services have messages queued up. This will also tell you when the services where started.

Next, type:

ps -fe | grep "omlockmgr"

If the start time/date of the omlockmgr is after the start time/dates of any of the OpenMail services, then you will need to "fix" this occurrence of the problem.

Note that the start times in both "omstat" and "ps" change format. If the service/program was started today, then the time is given. If started before today, then the date is given. Thus, if the dates against the services in "omstat" are the same as the start date of "omlockmgr", the "omlockmgr" program may have been started after the OpenMail services.

To fix this occurrence of the problem, the first step is to get the PIDs of all of the OpenMail processes. Type :

ps -fu openmail

and note down the PIDs (the number given in the second field) of the following programs:

service.router  
local.delivery  
test.server  
error.manager  
desk.in  
desk.out  
desk.mon  
desk.link  
mon3000

Also, type

ps -fu root | grep "unix.out"  
and  
ps -fu root | grep "xport.out"

and note the PIDs for these processes.

Next, you must kill all of these processes:

kill -15 PIDS

where PIDS is the list of PIDs you have built up from the "ps"

KPR #: 1600103358 \*\*CONTINUED\*\*

commands.

To restart the daemons, type:

omon -s all

KPR #: 1600103366 Product: OPENMAIL E1600A 00.00

Keywords: ADVMAIL

One-line description:

Cant put acks on a message forwarded from your pending tray.

Problem:  
If you forward a message in your pending tray and try to set acks on it, you get error "OM.UI 9998" when you mail the message.

Cause:

Whenever you put an ack on a message in your terminal interface, the pending tray is opened and a copy of the message is put into it.

The terminal interface doesn't check to see if you are already in the pending tray, and just opens it anyway. This fails because the pending tray is already open --- you are in it!

Temporary solution:

Once you get the OM.UI 9998 error, check to see what is logged in the OpenMail log file. Do this by typing:

omshowlog -s term | more

You should see details about an error:

[OM 3420] A container can't be opened twice by the same process.

To set acks on a forwarded message which is in your pending tray, go into the pending tray. Select the message and hit the "forward" key. Type in your forwarding text as you would normally. Set the ack on the message and then hit the "hold" key.

This will copy the message to your "outtray". Go into your outtray and hit the "mail" key.

Fix information:

The terminal user interface code has been corrected.

Duplicate Service Requests: 1600106351

KPR #: 1600103408 Product: OPENMAIL E1600A 00.00

Keywords: OMON OMOFF HANG

One-line description:

omon and omooff can appear to hang when CPU loop on the HF 9000.



KPR #: 1600103408 \*\*CONTINUED\*\*

Problem:  
"omom" and "omoff" can appear to hang when a process on the HP 9000 is in a tight CPU loop.

Cause:  
The OpenMail background daemons like "service.router" are run with a nice value of 19. In order to get the daemons into the "nice"d state, the program the fires them off is also run with a nice value.  
If there is a tight CPU loop on your system, the startup programs will move very slowly. Because things are moving so slowly, "omstat -s" thinks that the daemons have "aborted".

Because the daemon's states are "aborted", you can do another "omom". This "omom" also goes very slowly, so its state shows as "aborted". So, you can do another "omom", and so on.

Temporary solution:  
To find out if you are having this problem, do an "omstat -s". If the omstat gives the state of the OpenMail services as "aborted", type:

ps -ef | more

If you see the processes for the services that are supposed to be aborted, you know that they are just taking a long time to get going. A list of processes verses service names is contained in the "man" page for openmail(5). To see this man page type:

man 5 openmail

Look in the "ps -ef" output for a process that is using an extraordinary amount of CPU. You will need to kill this process.

KPR #: 1600103424 Product: OPENMAIL

B1600A

00.00

Keywords: OMADMIN

One-line description:  
Title half way down output with version listing to the printer.

Problem:  
If you print the OpenMail version from omadmin, you will see the heading line  
Service Name Version Patch  
half way down the listing.

Cause:  
The output from the omvers command is sorted before being output to the printer. Because the WHOLE output is sorted, the title is moved to the middle of the output.

Fix information:  
The omvers command no longer puts out the heading line, so it doesn't get sorted with the rest of the output.

- OPENMAIL -

Known Problem Reports as of 10/09/90

KPR #: 1600103424 \*\*CONTINUED\*\*

The heading line is produced seperately.

KPR #: 1600103432 Product: OPENMAIL

B1600A

00.00

Keywords: OMCHECK

One-line description:  
omcheck complains about permissions on database and check files.

Problem:  
"omcheck", the installation checking program, complains about the permission on files in /users/openmail/release.sys/db/\* and in /users/openmail/check/dist.\*.

Cause:  
/etc/update on version 7.0 of HP-UX has a defect that causes it to lose write permission for "group" and "other" during installation.

The files that omcheck reports are copied from their installed position to a working area. The permissions on the working files are changed by the installation script.

So, the files that omcheck complains about are not used by a running version of OpenMail.

Fix information:

The next release of OpenMail should contain the fix. The customize script for the OM\_CORE fileset resets the permissions of the affected files so they are not reported as being in error.

KPR #: 1600103457 Product: OPENMAIL

B1600A

00.00

Keywords: OMADMIN

One-line description:  
Add 2 users in omadmin, 2nd sets the password of the first.

Problem:  
If you add a user in "omadmin" and give them a password, and then add another user, the second user will get the password of the first user added.

Cause:  
The password field when adding a user in "omadmin" is "non-display". When you have finished adding one user, all fields remains as they were. Because the password field is "non-display" you don't notice that it has something in it.

Temporary solution:  
When you add a user in "omadmin" and give them a password, if you want to give the next user no password, tab into the password field and type in eight spaces.

Note that users can add their own passwords from the terminal and FC user interfaces. You could therefore give people no password, and let

- OPENMAIL -

KPR #: 1600103457 \*\*CONTINUED\*\*

them set their own.

You can see if a user has a password either by selecting the user and selecting the "display user" action from "omadmin", or by using the "omshowu" command in the shell. If you type:

```
man omshowu
```

this will give you details of the omshowu command.

Fix information:

The second user getting the password of the first is in fact the correct behavior, because an administrator might want to add many users, passwording them all to prevent them logging on until authorized. However, as this behavior is a probable source of confusion, whenever the cursor is in the "Name" field of the add user screen, a message warning the administrator that the password doesn't get changed between adding users is now displayed.

KPR #: 1600103459 Product: OPENMAIL 00.00

Keywords: ADVMAIL

One-line description:  
Delete part of message to be sent, get "Internal Error 5001".

Problem:

If you create a message and compose some text, then include a file, then delete the next part and try to mail a message, you get an "Internal Error 5001".

Cause:

The terminal interface builds up a list of the parts of the message that you are creating. If you delete any part of this message, the list is not updated. When you go to mail the message, the list does not correspond to the parts that are really present, and the terminal interface gives out the "Internal Error 5001".

Temporary solution:

After the Internal Error 5001, advmail will stop. If you go back into Advmail and go into your Outtray, you can mail the message without any problems.

Fix information:

The Terminal user interface code has been corrected.

KPR #: 1600103531 Product: OPENMAIL 00.00

Keywords: ADVMAIL

One-line description:  
Wrong error message if edit non-writable file in "configuration" area

Problem:

- OPENMAIL -

KPR #: 1600103531 \*\*CONTINUED\*\*

You enter the text editor from the "configuration" screen of the terminal interface. You opt to edit a file that you can't write to. You then specify one to which you can write. You edit the second file and save it. The "advmail" status line reads "Selected file name cannot be written". The file has been saved, however.

Cause:

Error status from non-writable file appears not to be being cleared

KPR #: 1600105080 Product: OPENMAIL B1600A 00.00

Keywords: PATCHED

One-line description:

Some 8-bit chars are not properly displayed by omadmin

Problem:

Some 8-bit characters are converted to a space when displayed by omadmin. This happens for text that is derived from the back-end programs and then displayed in a field, and also for softkey labels.

Cause:

The software didn't correctly handle characters with the high bit set.

Fix information:

The omadmin program has been modified to circumvent this problem.

This is fixed in patch release A.00.00.01

KPR #: 1600105171 Product: OPENMAIL B1600A 00.00

Keywords: DESK GATEWAY ACKNOWLEDGEMENT

One-line description:

Reply ACKs set on messages from Desk to OpenMail are not satisfied.

Problem:

Reply acks on messages sent from HP Desk to OpenMail, do not get satisfied.

In fact, the reply appears as a simple message. There is no indication to the desk user that the message is actually a reply.

Cause:

At the time OpenMail released, the supported version of HP Desk. (B.03.B0) had a fault which prevented OpenMail from sending REPLY messages into the HP Desk network. To overcome this problem, the OpenMail - HP Desk gateway converts any Replies from OpenMail users into simple messages before they are passed into HP Desk. This prevents reply acks from being satisfied

- OPENMAIL -

KPR #: 1600105171 \*\*CONTINUED\*\*

KPR #: 1600105296 Product: OPENMAIL

00.00

Keywords: DESK GATEWAY

Fix information:  
This problem is fixed in OpenMail Release A.00.01. The restrictions in the gateway to allow the gateway to operate with the Hp Desk B.03.B0 gateway intrinsics have been removed, as the problems that the restrictions avoided are now cleared with the B.03.R0 intrinsics

Keywords: ACKNOWLEDGEMENT ADVMAIL

PC

One-line description:

Ack on message from PC Advmail to Desk user with name >26 chars errors

Problem:

Ack set on message from PC AdvMail user to HPDesk user whose name length exceeds 26 characters (eg. Maurice ABRAHAM / HP1600/01) will a -5003 error when the Ack is returned and down-loaded to the PC. This will happen once per message recipient whose name exceeds 26 chars but after that the fault is cleared.

Cause:

The error is caused after the Acknowledgement information has been transferred to the PC and the ACK is being deleted on the host. As part of the generic delete operation the temporary list is updated. This should not be done for ACK lists, and an invalid list handle is picked up if the recipient name exceeds 26 characters, otherwise a NULL handle is successfully used.

Temporary solution:

The error occurs after the ACK has been processed, it will only occur once for each long recipient name, so AdvMail will run successfully if re-entered unless there are more Acks from HPDesk recipients whose names exceed 26 chars.

Fix information:

Code fixed to deal with the deletion of Full acks properly.

KPR #: 1600105304 Product: OPENMAIL

00.00

Keywords: UNIX GATEWAY DESK GATEWAY

DESK

One-line description:

Messages from unix mail to Desk, via OpenMail sometimes do not arrive

Problem:

This fault concerns mail sent to HP desk recipients, from Unix mail via OpenMail.

If the desk recipient is addressed, using only a location, then spurious characters can be placed in the sublocation and foreign address parts of the recipient address, as the message passes through the OpenMail - Hp Desk gateway.

eg Smith\_John/HpDesk used instead of Smith\_John/HpDesk\_ma where HpDesk is the heirarchic location of the HP Desk user John Smith and ma is his sublocation.

These spurious characters may cause HP Desk to reject the recipient. The sender of the message would then get a non - delivery report for the recipient who appears to the sender, to be perfectly valid.

If the sublocation of the desk recipient is specified, then the fault

KPR #: 1600105171 \*\*CONTINUED\*\*

KPR #: 1600105296 Product: OPENMAIL

00.00

Keywords: DESK GATEWAY

Fix information:  
This problem is fixed in OpenMail Release A.00.01. The restrictions in the gateway to allow the gateway to operate with the Hp Desk B.03.B0 gateway intrinsics have been removed, as the problems that the restrictions avoided are now cleared with the B.03.R0 intrinsics

Keywords: ACKNOWLEDGEMENT ADVMAIL

PC

One-line description:

Ack on message from PC Advmail to Desk user with name >26 chars errors

Problem:

Ack set on message from PC AdvMail user to HPDesk user whose name length exceeds 26 characters (eg. Maurice ABRAHAM / HP1600/01) will a -5003 error when the Ack is returned and down-loaded to the PC. This will happen once per message recipient whose name exceeds 26 chars but after that the fault is cleared.

Cause:

The error is caused after the Acknowledgement information has been transferred to the PC and the ACK is being deleted on the host. As part of the generic delete operation the temporary list is updated. This should not be done for ACK lists, and an invalid list handle is picked up if the recipient name exceeds 26 characters, otherwise a NULL handle is successfully used.

Temporary solution:

The error occurs after the ACK has been processed, it will only occur once for each long recipient name, so AdvMail will run successfully if re-entered unless there are more Acks from HPDesk recipients whose names exceed 26 chars.

Fix information:

Code fixed to deal with the deletion of Full acks properly.

KPR #: 1600105304 Product: OPENMAIL

00.00

Keywords: UNIX GATEWAY DESK GATEWAY

DESK

One-line description:

Messages from unix mail to Desk, via OpenMail sometimes do not arrive

Problem:

This fault concerns mail sent to HP desk recipients, from Unix mail via OpenMail.

If the desk recipient is addressed, using only a location, then spurious characters can be placed in the sublocation and foreign address parts of the recipient address, as the message passes through the OpenMail - Hp Desk gateway.

eg Smith\_John/HpDesk used instead of Smith\_John/HpDesk\_ma where HpDesk is the heirarchic location of the HP Desk user John Smith and ma is his sublocation.

These spurious characters may cause HP Desk to reject the recipient. The sender of the message would then get a non - delivery report for the recipient who appears to the sender, to be perfectly valid.

If the sublocation of the desk recipient is specified, then the fault

KPR #: 1600105304 \*\*CONTINUED\*\*

KPR #: 1600105312 \*\*CONTINUED\*\*

does not show itself.

Cause:

The OpenMail - HP Desk gateway, accesses a translation table when conversion from OpenMail to HP Desk mailnodes is performed. If no translation is found, the first two OpenMail Org Units are parsed as an HP Desk location and sublocation.

The gateway is not initialising the location and sublocation fields before a lookup in the translation table is performed. If no lookup is found and no sublocation was specified then the sublocation will contain a random string of bytes. This random string can also extend into the foreign address field of HP desk recipient record.

Temporary solution:

1. Ask the sender to specify the full HP Desk mailnode, including the sublocation, not just the location.
2. OR configure translations in the HP Desk Gateway mailnode translation table for HP Desk heirarchic mailnodes.

eg if 'hpdesk' is a heirarchic mailnode, configure a translation as follows, using omadmin:

```

OpenMail      HPDesk
Mailnode      Loc/Subloc
-----
hpdesk

```

Fix information:

The outbound desk mapper, 'dko.out' was modified. The address mapping routines were at fault and have been updated.

Duplicate Service Requests: 5000586982

KPR #: 1600105312 Product: OPENMAIL B1600A 00.00

Keywords: MODIFY FILE OMADMIN

One-line description:  
ommodu does not change ownership of user's files

Problem:  
Changing the unix login of an openmail user using the ommodu command (e.g. ommodu -o butler -u pete) doesn't change the unix ownership of his openmail files (such as his "u" directory). This can then cause problems later.

Cause:  
The ommodu program does not check for files that need their ownership changed. It should change any dependent files (such as their "u" directory).

KPR #: 1600105312 \*\*CONTINUED\*\*

Temporary solution:

As root do the following:  
cd into ~openmail/user

Look for a directory which is owned by the old user.  
If there is one, then there should only be one, and its name should start with u and be followed by 6 alphanumeric chars.  
If there isn't one, then cd into ~openmail/user01 and look.

Repeat this, looking in ~openmail/user02, ~openmail/user03.... until the directory owned by the user is found.  
cd into it.

Execute the following find command to change the ownership of all the files & directories of the user:  
find . -exec chown "newowner" {} \;

Fix information:

ommodu now changes the ownership of the u??????? directory.

KPR #: 1600105346 Product: OPENMAIL B1600A 00.00

Keywords: OMSHOWLOG SERVICE PROCESS

One-line description:

Usage error message for omshowlog inconsistent with man page & omshowlog

Problem:

Usage error message for omshowlog implies that a sub-component of a service can be used as a selection criteria, e.g. -s service[.process] The man page does not describe the .process option, and specifying one gives an "Incorrect format for service" error.

The usage error message also implies that the -e and -d options can not be used together. This is incorrect, and the message should show that -d may optionally used with the -e option.

Cause:

The problem is due to an error in the usage message given by omshowlog. The usage error should only refer to -s service (without the [.process] bit).

KPR #: 1600105361 Product: OPENMAIL B1600A 00.00

Keywords: OMADMIN MAILNODE

One-line description:  
Omadmin can produce "link layer" error when displaying a "\*" mailnode

Problem:  
In omadmin, go to the "Local Users" screen, select "Show By Mailnode" action. Enter \* for the mailnode. Get "[OM 8005] The mailnode contains invalid characters" error, or "[OM 8010] the address contains a dot, which is an invalid character" error.  
Then next time the "Local Users" screen is entered, an invalid list of users is shown.

Cause:

KPR #: 1600105361 \*\*CONTINUED\*\*

omadmin runs back-end programs to actually perform its administration. To show all users, omshowu -m is run. omadmin should trap the ".\*", but doesn't. So, what happens is that omshowu -m \* is run, and of course the \* gets expanded to the names of all of the files in the current working directory.....

Temporary solution:

- If you want to get a list of users at all addresses on the machine, use "all" instead of ".\*".
- If you do use ".\*" and mess up the local users screen, then it can be restored by (from the local users screen):
- 1) hitting the "Action Menu" softkey,
- 2) Select Show by MNode
- 3) When the Define Mailnode window appears, hit Clear Line, and enter "all" as the mailnode, and press Perform Query.

Fix information:

The address field passed onto the back-end program is now quoted to prevent its expansion by the shell.

KPR #: 1600105379 Product: OPENMAIL B1600A 00.00

Keywords: OMADMIN MAILNODE

One-line description:

Bad error displayed for "List Directory by Mailnode" with no mailnode

Problem: omadmin - List Directory by Mailnode. If no mailnode is specified the error message displayed is incorrect, it says use '-m "all"' to list all the names whereas the wildcard character '.\*' must be used.

Cause: ".\*" is allowed because omadmin and omshowdir allow wildcarding in mailnodes when listing the directory. The error message generated when nothing is given for the mailnode to search for is wrong.

Fix information: If omshowdir is given no mailnode, then it checks to see if it was called from omadmin to see which error message it should generate.

KPR #: 1600105387 Product: OPENMAIL B1600A 00.00

Keywords: OMADMIN TERMINALS PATCHED

One-line description:

omadmin doesn't have single line function key labels for vt100 & vt220s

Problem:

omadmin does not have any single line function key labels for use with vt100 and vt220 terminal. In all cases the 1st line of the 2 line

KPR #: 1600105387 \*\*CONTINUED\*\*

function keys are used. This results in confusing or incorrect labels appearing when omadmin is used on a vt100/vt220 terminal.

Cause: The functionality to allow single line function key labels for use with vt100 and vt220 terminals was not added to omadmin (as it was to the advmail terminal interface).

Temporary solution:

Whenever possible, use an HP terminal for running omadmin.

Fix information:

omadmin has been enhanced to have single line function keys

This is fixed in patch release A.00.00.01

KPR #: 1600105452 Product: OPENMAIL B1600A 00.00

Keywords: DESK GATEWAY

One-line description:

If text with control codes is sent from Desk to OM, text is lost

Problem:

If a text containing control codes, eg a formatted TDP file, is sent from HP Desk to OpenMail most of the text is lost.

Cause:

The problem occurs because DSRcopy copies over the control codes to the HP-UX machine, and most control codes generated by TDP are NULL (ascii value 0), which is treated as end of string (line) in HP-UX/C. This problem will occur with other spool files that contain NULLs as control code characters

Fix information:

The inbound desk gateway will now detect lines in text files that begin with the null char. This character is then replaced with a space. Other control characters are passed through unchanged.

KPR #: 1600105619 Product: OPENMAIL B1600A 00.00

Keywords: ADVMAIL

One-line description:

If BCC is an alias name the recipient does NOT see it when reading msg.

Problem:

BCC name in a distribution list is not displayed to that user if the original BCC name was an alias.

Cause:

KPR #: 1600105619 \*\*CONTINUED\*\*

When a distribution list is displayed a BCC name is compared with the name of user browsing the message. If the names match then the BCC name is displayed, if not then the BCC is not displayed. If the original BCC name is an alias then the original name in the Distribution List will not match that of the recipient, so the recipient will not see his/her name (or an alias of it) when browsing the message.

KPR #: 1600105791 Product: OPENMAIL BI600A 00.00

Keywords: OMADMIN SCREEN OUTPUT  
 PATCHED

One-line description:  
 Screen output from omadmin that doesn't occur via JAM is in IS08859/1

Problem:  
 Screen output from omadmin that does not occur via the JAM interface is always in the IS08859/1 char-set. This occurs in 3 known places, the copyright message at the beginning, the 'Type exit to return' message when breaking out to the shell and the termination message.

Cause:  
 simple ISO???? -> ROMAN8 mapping needs to be added where needed.

Fix information:  
 Text printed outside of JAM is now converted where needed.

KPR #: 1600105965 Product: OPENMAIL BI600A 00.00

Keywords: DESK GATEWAY CATALOG

One-line description:  
 Non-delivery text generated by Desk gateway can contain non-Roman8 chars

Problem:  
 When an OpenMail non delivery report is sent through the OpenMail - HP Desk gateway, into HP Desk, the report is converted into a textual message. The text of this message is localisable.

The character set used for localised text is IS08859/1. The localised report text is not converted to the roman8 character set used by HP Desk. The result, the non delivery report text, received by an HP Desk user if a localised version of OpenMail is being used, may well contain incorrect characters.

Cause:  
 The desk outbound mapper is assuming that the localised non delivery report text is in the roman8 character set, whereas the localised text is in fact in IS08859/1 character set.

Fix information:  
 A conversion to ROMAN 8 is now performed on the non delivery report text generated by the gateway

KPR #: 1600106047 Product: OPENMAIL BI600A 00.00

Keywords: OMADDDIR HELP

One-line description:  
 The omshowdir MAN page references "genaddair"

Problem:  
 There is a reference to "genaddair" on the last line of the description section of the "omshowdir" man page. The reference should be to "omaddair" instead.

Cause:  
 The man page was written before the name of the product was known. Once the name of the product was known, the names of the commands were finalised. However, although most of the man pages, etc, were updated, the last line of this page was missed.

Fix information:  
 The text of the man page has been corrected to refer to "omaddair" instead of "genaddair".

KPR #: 1600106054 Product: OPENMAIL BI600A 00.00

Keywords: OMADMIN ENVIRONMENT PATCHED

One-line description:  
 Function keys in omadmin are displayed badly if TERM is corrected.

Problem:  
 If 'omadmin' is entered with an illegal TERM environment variable set then an english-language message is always displayed and when a valid term-type is entered the function keys in omadmin are displayed badly.

Cause:  
 omadmin is a shell script which sets up the environment for the actual administration program, admin.prog.

omadmin should make sure that \$TERM is set to something valid, but instead its leaving this for admin.prog to do, which it can't.

Temporary solution:

Make sure that \$TERM is a valid value BEFORE running omadmin.  
 Valid values are : hp hp2622 hp2392 hp2392a HP HP2392 HP2392A 2392 vt220 vt100

Fix information:  
 The script omadmin has been modified to make sure that \$TERM is valid before it runs admin.prog.

This is fixed in patch release A.00.00.01

KPR #: 1600106070 Product: OPENMAIL BI600A 00.00

Keywords: OMVERS CATALOG

One-line description:

omvers checks the n-computer message catalogs instead of checking \$LANG

KPR #: 1600106070 \*\*CONTINUED\*\*

Problem:  
omvers only checks the message catalogs in the /usr/lib/nls/n-computer directory. Message catalogs in other directories are not checked.

Cause:  
Omvers only looks at OpenMail message catalogs in the OM\_MESSCATS\_DIR directory, which is defined as /usr/lib/nls/n-computer. It ought to either take account of the \$LANG variable, or look at all the installed OpenMail message catalogs.

Fix information:  
In future versions of OpenMail, omvers will report on all openmail message catalogs, for all languages. The catalogs will be displayed as language/mc\_cat.cat instead of mc\_cat.cat in order for the various catalogs to be identified.

KPR #: 1600106120 Product: OPENMAIL BI600A 00.00

Keywords: SERVICE ROUTER

One-line description:  
Recipient fields in an X.400 delivery report can contain illegal values

Problem:  
The PerRecipient fields in an X.400 delivery Report PDU sent out of the OpenMail/X400 system can contain illegal values for the Report Request Bits ( Bits 1 and 2 ). The bits are always cleared to zero, a value marked as 'Not Used' in X.411

Cause:  
The problem, is that the OpenMail Service router is not preserving the recipient info fields in the original message. The fields are effectively cleared.

Fix information:  
The OpenMail service router has been modified to preserve the recipient info when routing the original message.

KPR #: 1600106385 Product: OPENMAIL BI600A 00.00

Keywords: OMSCAN

One-line description:  
omscan produces inaccurate number of kilobytes for each user

Problem:  
The report of disc usage by each OpenMail user given by omscan is inaccurate. Most of a message is attributed to one user, the remaining part of the message is attributed to every other user in receipt of it.

KPR #: 1600106716 Product: OPENMAIL BI600A 00.00

One-line description:  
Temporary files gradually accumulate in the user 'g' directories

Problem:  
The temporary files created in the user 'g' directories by Terminal users are never deleted (not even by omscan).

Cause:  
The deletion of these files fail because they are treated as User/User files instead of Openmail/User files.

Temporary solution:  
Periodically these files must be deleted manually, this can be done by executing the following command while running as root:  
find /users/openmail/user/g\* -name 'tmp\*' -exec rm {} \;

\*\* N.B. only do this when there are no active Openmail users on the system (Terminal or PC). Executing this command as part of the normal omscan script would be a reasonable thing to do.

Fix information:  
Code corrected to treat temporary files in the Openmail/User directory as Openmail files when deleting them.

KPR #: 1600106823 Product: OPENMAIL BI600A 00.00

Keywords: OMADMIN

One-line description:  
Refresh omadmin screen doesn't refresh softkeys

Problem:  
In omadmin, the refresh key does not redraw the softkeys.

On a vt100, this has the effect of making any visible softkeys disappear

Cause:  
The underlying screen/forms handling package does not refresh softkeys when told to refresh the screen.

Fix information:  
Refresh now explicitly redraws the softkeys.

KPR #: 1600106849 Product: OPENMAIL BI600A 00.00

Keywords: PATCHED

One-line description:  
"Back-end" admin commands always o/p 8-bit chars in IS08859/1

Problem:  
'Back-end' admin commands do not convert 8-bit chars to Roman-8 in their output displays.

Cause:  
The back-end commands output strings picked up from the messcat

KPR #: 1600106849 \*\*CONTINUED\*\*

unchanged. These strings reside in the messcat in ISO8859/1 charset format - they need to be translated into HPRoman-8 if the user is using an HP terminal.

Fix information:

Script produced for each back-end command that filters output to produce Roman-8 characters if HP terminal is being used. These scripts are installed in:

/usr/openmail/hpbin

This directory needs to be added to an administrator's PATH to be searched BEFORE /usr/openmail/bin for this fix to work.

This is fixed in a patch available from the global patch machine.

KPR #: 1600106856 Product: OPENMAIL B1600A 00.00

Keywords: PATCHED

One-line description:

Printed output from 'omadadmin' does not treat 8-bit chars correctly

Problem:

Printed output from 'omadadmin' that contains 8-bit character does not produce correct printed output.

Cause:

Output for the printer from omadadmin can contain 8-bit characters in the ISO8859/1 charset - these characters need to be translated to Roman-8.

Fix information:

All printed output from omadadmin is piped through the script omputhdr. This script has been modified to convert ISO8859/1 characters to Roman-8 characters. (There is one exception, the script 'omsceanat' - this script has been modified explicitly.)

This is fixed in a patch available from the global patch machine.

KPR #: 1600107656 Product: OPENMAIL B1600A 00.00

Keywords: DIRECTORY

One-line description:

X.400 ORNames require that a surname is entered

Problem:

A surname must be entered when entering ORNames that do not have to contain a Surname. For example when entering a Form 1 Variant 3 or a Form 2 ORName a surname must entered - this can be confusing since the actual X.400 ORName does not contain a surname.

Cause:

The surname is required because it is used as a key by the lookup directory.

KPR #: 1600108134 Product: OPENMAIL B1600A

00.00

Keywords: OMEDIT

One-line description:

Some 8-bit chars are not properly displayed by omedit

Problem:

8 bit characters are not displayed properly on function key labels

KPR #: 1600108662 Product: OPENMAIL B1600A 00.00

Keywords: OMADMIN

One-line description:

omadadmin does not accept "\*" in HPDesk mailnode translation

Problem:

omadadmin does not allow "\*" to be specified in the HPDesk mailnode when adding a mailnode translation for the HPDesk gateway. The back end command "omadmt" does allow the "\*" to be specified.

Cause:

The problem is caused by the field checking in omadmin only allowing alphanumeric and "/". It should also have allowed "\*".

Fix information:

omadadmin has been modified to accept "\*" as well as alphanumeric and "/" characters.

KPR #: 1600108696 Product: OPENMAIL B1600A 00.00

Keywords: OM\_RECORD

One-line description:

Setting OM\_R variable fails to redirect omadadmin commands to file

Problem:

The problem is that the setting of the OM\_R shell variable is ignored by /usr/openmail/bin/adminprog. This is because the omadmin shell script is explicitly overriding it.

Cause:

The problem is caused by /usr/openmail/bin/omadadmin explicitly setting the shell variable OM\_R to \$HOME/om\_record, which overrides any value the user may have supplied for the variable.

Temporary solution:

A temporary fix is to edit /usr/openmail/bin/omadadmin to either comment out the lines setting OM\_R, or change them to set OM\_R to the value required by the user.

The lines in question are:

```
OM_R=$HOME/om_record
export OM_R
```

To comment them out, change them to:



KPR #: 1600108696 \*\*CONTINUED\*\*

#OM\_R=\$HOME/om\_record  
#export OM\_R

Fix information:  
OM\_R will no longer be set in /usr/openmail/bin/omadmin, in future versions of OpenMail.

KPR #: 1600108720 Product: OPENMAIL B1600A 00.00

One-line description:  
Some 8-bit characters are not displayed on Term U/I function keys

Problem:  
This problem is caused by the standard 'isspace' function that it used by the code that displays the function keys. This system routine gives an erroneous return that indicates that some 8-bit characters should be treated as spaces.

Cause:  
See Problem text...

Temporary solution:  
There is no temporary fix for this problem - apply the patch

Fix information:  
Fixed by explicitly checking for space in the affected routines.

Duplicate Service Requests: 1600108704

KPR #: 1600108753 Product: OPENMAIL B1600A 00.00

One-line description:  
Submission date of messages is creation date NOT the mailing date

Problem:  
Submission date of message created by Terminal or PC U/Is can be wrong.

Cause:  
The creation date of the message put in the transaction file is the creation date of the message. It should be the date at which the TF is created, ie. the mailing time of the msg.

Temporary solution:  
This problem will only show up if messages are created and then kept in the outtray before mailing. This will lead to incorrect delivery durations being recorded for these msgs. ie. the time taken to deliver the message will include all the time it spent sitting in the Outtray.  
There is no temporary fix.

Fix information:  
The mailing code has been modified to use the current time for the CREATE DATE of the message when mailing occurs.



KPR #: 1600108761 Product: OPENMAIL B1600A 00.00

One-line description:

PC ASCII files with lines longer than 80 chars are not copied correctly

Problem:  
When an ASCII file is transferred as part of a message from LAN PC Advmail any lines that exceed 80 characters become corrupted after the 80th character.

Cause:  
The host file transfer code for the LAN PC AdvMail does not transfer any characters after the 80th on a line, 'dirty store' is picked up instead.

Temporary solution:  
Long lines should be avoided.

Fix information:  
Correct the LAN file transfer code.

KPR #: 1600108803 Product: OPENMAIL B1600A 00.00

Keywords: UNIX GATEWAY

One-line description:  
X.400 names with initials but no forename are incorrectly mapped - unix

Problem:  
A message sent to unix via OpenMail from an X.400 user with initials but no forename does not have the senders name mapped correctly. For example, if the message is sent from "F. BLOGGS", this is mapped to "BLOGGS\_F" (with one \_ character) rather than "BLOGGS\_F" (with two \_s)

The problem can also occur if the sender has a generation identifier but does not have a forename or does not have initials. For example, "JOHN ROSS JNR." is mapped to "ROSS\_JOHN\_JNR" when it should be mapped to "ROSS\_JOHN\_\_JNR".

Cause:  
The problem is caused by an error in the unix gateway code suppressing repeated " " delimiters when it should only suppress trailing " " delimiters.

Fix information:  
The unix gateway has been corrected to only suppress the trailing (redundent) " " characters.

KPR #: 5000538389 Product: OPENMAIL B1600A 00.00

Keywords: PATCHED

One-line description:  
Unix gateway does not map host name correctly on reply

Problem:  
When a message is sent through unix mail, into OpenMail and then back

KPR #: 5000538389 \*\*CONTINUED\*\*

to unix mail again (e.g. via a public dist list), if the sending unix user's address contains a @, % or !, then the recipient might not be able to reply to the message.

Cause:

The problem is due to the OpenMail unix gateway not converting the special characters @, % and ! to something else (for the sender, etc) when the message is passed to unix mail. The characters should be converted to something else so that the unix mail does not attempt to use these for routing of reply, but instead passes the message back to OpenMail.

Fix information:

The outgoing part of the unix gateway has been modified to map the characters @, % and ! to the strings #@, #% and #! respectively. The incoming part of the unix gateway has been modified to map the strings back again. This is similar to the mapping of other characters that are special to unix mail sender/recipient names (e.g. blank maps to #b#).

KPR #: 5000550467 Product: OPENMAIL B1600A 00.00

Keywords: UNIX GATEWAY LOCAL DELIVERY SERVICE ROUTER

One-line description:

Large message sent to Openmail lost without trace

Problem:

Two problems can occur that result in the loss of a message if OpenMail runs out of disc space.

1. If the OpenMail Service Router runs out of disc space when it is routing a message, some of the content of the message's Transaction File may be lost.
2. If the Service Router, Local Delivery or the Outgoing Transport process runs out of disc space, it attempts to put the message on the #ERROR queue before continuing. However, if it fails to put the message on the #ERROR queue, it will still continue (effectively discarding the message).

Cause:

Problem #1 may occur because the Service Router copies the Transaction File as it "routes" the message, but it doesn't "flush" and "sync" to disc the buffers of the new Transaction File before removing the old Transaction File. If it is possible for the "flush" and "sync" to fail due to lack of disc space.

Problem #2 occurs because of the way the Service Router, Local Delivery and Transport Outgoing processes were written to "continue no matter what happens". This should not be the case if it can result in the loss of messages.

Fix information:

Problem #1 has been fixed by modifying the Service Router to "flush"

KPR #: 5000550467 \*\*CONTINUED\*\*

and "sync" the new Transaction File before removing the old one. Problem #2 has been fixed by changing the Service Router, Local Delivery and the Outgoing Transport to terminate (abort) if they fail to process a message AND they fail to put the message on the #ERROR queue.

KPR #: 5000550756 Product: OPENMAIL B1600A 00.00

Keywords: OMSSTORE

One-line description:

omstore MAN page does not fully document openmail data restore process

Problem:

OpenMail will not run after restoring the data according to the MAN pages or the system administrator's manual. After restore, OMADMIN fails with a Vista data base error and will not allow services to be turned on. Restore was performed after the data had been altered so that the environment could be restored to a known state.

Cause:

The problem is due to some steps being omitted from the MAN page.

Temporary solution:

Problem was verified on an 835 system and a work around was identified. You must perform the following tasks to restore OpenMail data.

1. Shutdown all OpenMail services (use omadmin or omoff)
2. Kill the omlockmgr and advmail daemons
3. rm -r /users/openmail (delete all openmail files)
4. cd /
5. cpio -icdmux <filename (to restore openmail from a file)
6. cd /etc
7. omrc (execute openmail start up script)

The only step documented in the man pages or the admin manual was step number 5.

KPR #: 1600105163 Product: OPENMAIL/X.400 B1600X4 00.00

KPR #: 1600107334 \*\*CONTINUED\*\*

Keywords: X.400 ERROR MESSAGE

One-line description:  
The X.400 error messages are in the wrong part of the PSS

Problem:  
The X.400 error messages are tacked onto the end of the X.400 "solution" part in the problem solving system (omsolve). They should have their numbers put against them in the "detail" section.

Cause:  
There is no X.400 option in the "details" section of the Problem Solving System (omsolve). For this reason, the "details" were added to the end of the X.400 text in the "solutions" section. There should really be an X.400 option in the "details" section.

Temporary solution:  
If an specific X.400 problem occurs (with a given error number), then look for it in the "solutions" section rather than the "details" section, and continue to page down the text until the text for the particular error is displayed.

KPR #: 1600106278 Product: OPENMAIL/X.400 B1600X4 00.00

Keywords: GATEWAY

One-line description:  
X.400 interface rejects incoming DeliveryReports if no IntermediateTrace

Problem:  
X.400 interface rejects incoming DeliveryReports that do not have IntermediateTrace in the DeliveryReport Content.

Cause:  
TraceInformation is mandatory in the Envelope of a DeliveryReport, but the IntermediateTraceInformation in the Content of a DeliveryReport is optional. The X.400 Interface insisted on both these elements being present in the DeliveryReport, when it should have only insisted on the former. Many other X.400 implementations do not insert Intermediate TraceInformation in the DeliveryReports they generate, and these Reports were thus rejected by the OpenMail/X.400 Interface.

Fix information:  
This fix will be incorporated in the next release, but meanwhile, a patch is available which contains the fix - OpenMail Patch OM000002. The problem is fixed in the code by treating the Intermediate TraceInformation in the Content of DeliveryReports as an optional field, so no error is generated if it is not present.

KPR #: 1600107334 Product: OPENMAIL/X.400 B1600X4 00.00

One-line description:  
X400 Interface insisting on OR name in p2.Ordrescriptor

Problem:

- OPENMAIL/X.400 -

The OpenMail/X.400 Interface rejects an incoming X.400 PDU if the Ordrescriptor for the P2.PrimaryRecipient doesn't contain an ORName

Cause:  
The OpenMail/X.400 Inmapper maps the recipients in the P2 portion of the X.400 PDU into the OpenMail distribution list only if the recipient Ordrescriptor contains an ORName. However, a P2 Ordrescriptor is allowed to contain either an ORName or a FreeFormName; the Inmapper was insisting (incorrectly) on the presence of ORNames in these Ordrescriptors, and rejecting the PDUs otherwise.

Fix information:  
This fix will be incorporated into the next release. Meanwhile, the OpenMail patch OM000006 will be available, which includes this fix. The problem has been fixed as follows - the Inmapper skips over the P2 Recipient Ordrescriptors that don't contain ORNames, instead of rejecting the entire message

KPR #: 1600108068 Product: OPENMAIL/X.400 B1600X4 00.00

One-line description:  
OpenMail/X.400 left t files in iq.

Problem:  
When the outbound mapper is converting OpenMail messages into X.400 PDUs, if it aborts because of an error, it sometimes leaving temporary files lying in the MTA's input queue.

Cause:  
This problem occurs because of a programming error in the outbound portion of the X.400 interface, specifically an error in the executable /usr/openmail/bin/x400.out. When processing of a message terminates abnormally (because of an error), in some cases temporary files may be left in the MTA Input Queue (/usr/spool/x400/iq).

KPR #: 1600108191 Product: OPENMAIL/X.400 B1600X4 00.00

One-line description:

Timestamps generated by mappers had an offset that was wrong by 1 hour  
Problem:  
The offsets in the timestamps generated by the mappers were wrong by an hour

Cause:  
The mappers used the HP-UX system variable "daylight" to compute whether an hour was to be added/subtracted for Daylight Savings Time. However, the "daylight" variable is always Set in places where the concept of Daylight Savings Time exists, whether or not it is in effect at that time of year. An error of one hour thus resulted when Daylight Savings Time went away and Standard time returned.

Fix information:

- OPENMAIL/X.400 -

KPR #: 1600108191 \*\*CONTINUED\*\*

This fix will be incorporated into the next release. Meanwhile, the fix has been included in OpenMail patch OM000006. The fix is as follows: The "daylight" variable is only used to tell if the concept of Daylight Savings exists locally. A different flag, the tm\_isdst flag in the "tm" structure, is used to tell if Daylight Savings time is currently in effect, so the offset can be correctly computed.

KPR #: 1600108217 Product: OPENMAIL/X.400 BI600X4 00.00

One-line description:  
Outmapper insists on ORNames being present in IPMsgIds (Ack Ids)

Problem:  
The Outmapper rejects a message if an ORName is not present in the IPMessageId

Cause:  
The Outmapper checks to see if the OpenMail message it is processing was created by the Inmapper, in which case it expects the Ack Id to be encoded the way the Inmapper would have done it, with the IPMsgId (IDstring + ORName) encoded into the Ack Id string. However, it is possible that the IPMsgId contained no ORName and only an IDstring, but the Outmapper isn't geared for this case, and returns an error when it finds no ORName in the Ack Id.

Fix information:

This problem will be fixed in the next release. Meanwhile, the fix has been included in the OpenMail patch OM000006. The fix is fairly straightforward - the OutMapper may look for an ORName in the Ack Id, but it doesn't complain if it doesn't find one.

KPR #: 1600108225 Product: OPENMAIL/X.400 BI600X4 00.00

One-line description:  
X.400 PDU with binary bodypart encoded as plain Octet string is rejected

Problem:  
Message containing a binary bodypart encoded as a simple Octet string, was rejected

Cause:  
The OpenMail/X.400 mappers use the X.400 Intrinsic functions to read and create X.400 PDUs. The Intrinsic handle various kinds of bodyparts including Binary bodyparts. However, they did not handle the specific case where the Binary bodypart was a plain Octet string, and this caused the given X.400 message to be rejected.

Fix information:

The fix will be incorporated into the next release. Meanwhile, it has been included in OpenMail Patch OM000006. The fix is straightforward - it basically involves the Intrinsic being modified to handle the specific case where the Binary bodypart shows up as an Octet string, so the In mapper now accepts the PDU.

KPR #: 1600108233 Product: OPENMAIL/X.400 BI600X4 00.00

One-line description:  
X.400 PDU rejected, if Binary bodypart is sequence of Octet strings

Problem:  
Incoming X.400 Message containing a binary bodypart was rejected, though other tests with binary files have succeeded in the past.

Cause:

The mappers use functions from the X.400 Intrinsic library to access the X.400 PDU. The given binary file was encoded as a sequence of Octet strings, and the Intrinsic didn't handle this case, but returned an error instead.

Fix information:

The fixed version of the Intrinsic will be used in the next release. Meanwhile, the fix is available in OpenMail Patch OM000006. The fix itself simply consists of the Intrinsic being modified to handle the case where the binary bodypart is encoded as a sequence of Octet strings.

KPR #: 1600108241 Product: OPENMAIL/X.400 BI600X4 00.00

One-line description:  
Outmapper fails while trying to create OpenMail NonDeliveryNotification

Problem:

Outmapper fails while creating a Nondelivery notification

Cause:

The Outmapper module involved in generating OpenMail NonDelivery Notifications had a local and global buffer defined with the same name, resulting in a situation where the wrong buffer was used without being initialized. The contents of the buffer were thus unknown, and ultimately caused the OutMapper to fail while creating the NDN.

Fix information:

This fix will be incorporated into the next release. Meanwhile, it has been included in OpenMail Patch OM000006. The fix simply involves using different names for the local and global buffers, so their names don't collide, and the correct buffer is initialized and used by the OutMapper.

KPR #: 1600109215 Product: OPENMAIL/X.400 BI600X4 00.00

One-line description:

X.400 out mapper not encoding numerical country codes correctly

Fix information:

Checking of the country code is done now. Changes have been made to the modules orn.c and wrtcc.c in the outmapper.

Known Problem Reports as of 10/09/90

Page: 33

KPR #: 1600109223 Product: OPENMAIL/X.400 B1600X4 00.00

One-line description:

Null ADMDS and PRMDS cause problems in ORNames for X.400 mappers

Fix information:

The problem is that the OM configuration held by X4admin represents a NULL ADMD or PRMD as a underscore (which represents a space). This has got to be compensated for in the mappers so that correct comparisons are made. For an incoming ADMD it can be a space or a NULL for the checking as to whether the name is that of an OM user. For a PRMD the comparison is for just NULL.

On outgoing stamping of an ORName the ADMD if NULL is encoded as a single space. If the PRMD is NULL the encoding is that of a NULL.

Code was also changed to do away with the rules that if ADMD is present that COUNTRY code must also be present. Giving better flexibility.



**READER COMMENT SHEET**

**PINEWOOD INFORMATION SYSTEMS DIVISION**

**Issue 1.0 (10/15/90)**

**We welcome your evaluation of this bulletin. Your comments and suggestions help us to improve our publications. Please use additional pages if necessary.**

**Is this bulletin technically accurate?                      Yes [ ] No [ ]                      (If no, explain under Comments, below.)**

**Are the concepts and wording easy to understand?                      Yes [ ] No [ ]                      (If no, explain under Comments, below.)**

**Is the format of this bulletin convenient in size, arrangement and readability?                      Yes [ ] No [ ]                      (If no, explain or suggest improvements under Comments, below.)**

**Comments:**

\*\*\*\*\*

**Date:** \_\_\_\_\_

**FROM:**

**Name** \_\_\_\_\_

**Company** \_\_\_\_\_

**Address** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_









Software release contents

PAGE I 1

Product name	Product number	uu.ff	prev
VUE 2.0	B1171A	00.03	00.00
X10 WINDOWS	82320A	11.50	00.00
X11 800 ONLY 3.0/3.1	B1155A	B3.00	00.00
X11 WINDOWS 6.2/3.0	B1152A	00.03	00.00
X11 WINDOWS 6.5/3.1	B1152B	00.03	00.00
X11 WINDOWS 7.0	B1152C	02.00	00.00

Product name	Product number	SSB ISSUE DATE	Page
X DOCUMENTATION ONLY	B1161A	11/09/90	1
X10 WINDOWS	82320A	11/09/90	4
X11 800 ONLY 3.0/3.1	B1155A	11/09/90	7
X11 WINDOWS 6.2/3.0	B1152A	11/09/90	29
X11 WINDOWS 6.5/3.1	B1152B	11/09/90	56
X11 WINDOWS 7.0	B1152C	11/09/90	78

KPR number	page	KPR number	page	KPR number	page	KPR number	page
1650079012	4	3900006593	42	3900007286	58	3900007765	76
1650099572	56	3900006601	42	3900007294	58	3900007773	54
3900006072	29	3900006619	43	3900007302	59	3900007781	54
3900006122	29	3900006825	43	3900007310	59	3900007799	7
3900006130	29	3900006833	43	3900007328	59	3900007807	7
3900006148	29	3900006841	43	3900007336	60	3900007815	7
3900006155	30	3900006858	44	3900007344	60	3900007823	8
3900006163	30	3900006866	44	3900007351	61	3900007831	8
3900006171	30	3900006874	44	3900007369	61	3900007849	77
3900006189	30	3900006882	44	3900007377	61	3900007856	8
3900006197	31	3900006890	44	3900007385	61	3900007864	9
3900006205	31	3900006908	45	3900007393	62	3900007872	77
3900006213	31	3900006916	45	3900007401	62	3900007880	9
3900006221	31	3900006924	45	3900007419	62	3900007898	9
3900006239	32	3900006932	45	3900007427	63	3900007914	9
3900006247	32	3900006940	46	3900007435	63	3900007922	10
3900006254	32	3900006957	46	3900007443	63	3900007930	10
3900006262	33	3900006965	46	3900007450	63	3900007948	10
3900006270	33	3900006973	46	3900007468	64	3900007955	11
3900006288	33	3900006981	46	3900007476	64	3900007963	11
3900006296	34	3900006999	47	3900007484	65	3900007971	11
3900006304	34	3900007005	47	3900007492	65	3900007989	12
3900006312	34	3900007013	47	3900007500	65	3900007997	12
3900006320	35	3900007021	48	3900007518	66	3900008003	13
3900006338	35	3900007039	48	3900007526	67	3900008011	13
3900006346	35	3900007047	49	3900007534	67	3900008029	13
3900006353	36	3900007054	49	3900007542	68	3900008037	13
3900006361	36	3900007062	50	3900007559	68	3900008045	14
3900006379	37	3900007070	50	3900007567	69	3900008052	14
3900006403	37	3900007088	51	3900007575	69	3900008060	14
3900006411	37	3900007096	4	3900007583	69	3900008078	14
3900006429	37	3900007104	51	3900007591	70	3900008086	15
3900006437	38	3900007112	51	3900007609	70	3900008094	15
3900006445	38	3900007120	51	3900007617	70	3900008102	15
3900006452	38	3900007138	52	3900007625	70	3900008110	16
3900006460	38	3900007146	52	3900007633	71	3900008128	16
3900006478	39	3900007153	53	3900007641	71	3900008136	16
3900006486	39	3900007161	53	3900007658	72	3900008144	17
3900006494	39	3900007179	53	3900007666	72	3900008151	17
3900006502	40	3900007187	53	3900007674	73	3900008169	17
3900006510	40	3900007195	54	3900007682	74	3900008177	18
3900006528	41	3900007211	56	3900007690	74	3900008185	19
3900006536	41	3900007229	56	3900007708	74	3900008193	19
3900006544	41	3900007237	56	3900007716	75	3900008201	20
3900006551	41	3900007245	57	3900007724	75	3900008219	20
3900006569	42	3900007252	57	3900007732	76	3900008227	21
3900006577	42	3900007260	58	3900007740	76	3900008235	21
3900006585	42	3900007278	58	3900007757	76	3900008243	21

KPR number	page	KPR number	page	KPR number	page	KPR number	page
3900008250	22	3900009001	78	3900009183	81	5000300467	6
3900008268	22	3900009019	78	3900009191	81	5000416461	6
3900008276	22	3900009027	78	3900009217	81	5000427872	6
3900008284	23	3900009035	27	3900009225	81	5000474411	55
3900008292	23	3900009050	79	3900009233	81	5000476838	77
3900008300	24	3900009068	79	3900009241	1	5000535153	82
3900008318	25	3900009076	79	3900009258	2	5000538942	3
3900008326	25	3900009084	79	3900009571	81	5000540823	3
3900008334	25	3900009092	80	5000206219	4	5000544791	3
3900008342	26	3900009100	80	5000206268	4	5000552307	82
3900008359	26	3900009118	80	5000225623	4	5000553131	3
3900008367	26	3900009126	80	5000228676	5	5000554493	82
3900008375	26	3900009134	1	5000240184	5	5000557215	82
3900008383	27	3900009142	1	5000253872	5	5000557223	82
3900008391	27	3900009159	81	5000258749	6	5000573956	83
3900008995	78	3900009167	1	5000274225	6		

CUMULATIVE KEYWORD INDEX

- X DOCUMENTATION ONLY - SSB ISSUE DATE: 11/09/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	B1161A	00.00 Man pg XHPSetKeyboardMapping (3X): XComposeStatus should be pointer	3900009134	1
	B1161A	00.00 man pg XHPNlioc1 (3x) arg parameter should be int for some commands	3900009142	1
	B1161A	00.00 Manual does not explain how to use -C option (console output)	3900009167	1
	B1161A	00.00 man pages for Xt calls do not correspond to actual call	3900009241	1
	B1161A	00.00 Online man pages for many of (Motif) widget calls display incorrectly	3900009258	2
	B1161A	00.00 No documentation is provided on how to use block term mode of hpterm	5000538942	3
	B1161A	00.00 7.0 Version of Install & Config does not explain set up procedures for X	5000540823	3
	B1161A	00.00 7.0 Beginner's Guide wrong on pg. 6-2. csh does not use [ for test	5000544791	3
	B1161A	00.00 7.0 Documentation example for xmodmap does not work	5000553131	3

- X10 WINDOWS - SSB ISSUE DATE: 11/09/90

*****none*****	82320A	11.50 XCheckWindowEvent and XCheckMaskEvent calls don't work	3900007096	4
	82320A	10.40 Documentation problem; index gives incorrect page number in Xr1ib manual	1650079012	4
	82320A	06.20 XTERM hangs when cutting and pasting a large section of text	5000427872	6
	82320A	06.00 XTERM does not generate SIGINT from the break key	5000300467	6
	82320A	05.50 parameter list description for "xtexit(3X)" is in error	5000206219	4
	82320A	05.50 Manual doesn't explain how to pop-up menu from program	5000206268	4
	82320A	05.50 Xterm does not recognize Backspace key when using \$HOME/.Xkeymap file.	5000228676	5
	82320A	05.50 CreateTTYWindow call doesn't work w/ release 5.5	5000253872	5
	82320A	05.50 wxinstall, pre 6.2, will alter and remove related files in /usr/bin	5000274225	6
	82320A	05.20 Only get root window with hostnames > 8 characters.	5000225623	4
	82320A	05.05 Typos in "programming with the X Window System" manual.	5000240184	5
	82320A	03.02 Install errors on 6.2 and 6.5 when long filenames are enabled	5000416461	6
	82320A	01.00 X doesn't create "pty" entries for use on discless node	5000258749	6

- X11 800 ONLY 3.0/3.1 - SSB ISSUE DATE: 11/09/90

*****none*****	B1155A	B3.00 TSRX combined mode rendering problems, images listed 1st in screens file	3900007799	7
	B1155A	B3.00 With hpterm in pointer blank mode, the pointer blanks on shift & meta	3900007807	7
	B1155A	B3.00 The Fortran bindings don't return a function pointer correctly	3900007815	7
	B1155A	B3.00 X Server defaults to using /dev/crt should be /dev/crt0 on s800	3900007823	8
	B1155A	B3.00 loader falls on s800 due to duplicate ul1toR8 routines	3900009035	27
	B1155A	00.03 In hpterm, pastes of >-512 chars drop data (s800 only).	3900007831	8
	B1155A	00.03 All special properties have parsing problems in xfc.	3900007856	8
	B1155A	00.03 Bitmap with-nodashed, then do invert all results in lines becoming dots	3900007864	9
	B1155A	00.03 hpwm title remains pushed in shen concurrent interact. place is done	3900007880	9
	B1155A	00.03 Hpwm.man says f.refresh will actis like f.refresh in root context.	3900007898	9
	B1155A	00.03 Textedit widget created with empty file, change to full file, hang	3900007914	9
	B1155A	00.03 icon over save button in save view in hpwm. Both get select signal.	3900007922	10
	B1155A	00.03 hpwm interactive placement when mouse is busy - window (0,0) can't move	3900007930	10
	B1155A	00.03 "<BtnUp> title f.raise_lower" only does f.raise in hpwm.	3900007948	10
	B1155A	00.03 Unexpected window position with negative geometry co-ordinates.	3900007955	11
	B1155A	00.03 XtNtittlePosition defined differently for 2 different widgets	3900007963	11
	B1155A	00.03 type converters in libXw don't generate warning on bad conversions	3900007971	11
	B1155A	00.03 TextEditP.h: uses defines XtTextEditPrivate_h instead of _XwTextEdit...	3900007989	12
	B1155A	00.03 BackgroundTile resources not properly propagated	3900007997	12

CUMULATIVE KEYWORD INDEX

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	B1155A	00.03 multiple traversal highlights can sometimes appear	3900008003	13
	B1155A	00.03 SWindow: horizontal scroll bar y resource always returns 0 on getvalues	3900008011	13
	B1155A	00.03 monochrome Z format image handled incorrectly in 'xpr' and 'xwd2sb'	3900008029	13
	B1155A	00.03 xwcreate indicates an invalid background pixel when using TSRX display	3900008037	13
	B1155A	00.03 In xpr -trailer string truncated by 1 char when -append -noff spec after	3900008045	14
	B1155A	00.03 xwcreate does not give an error for exceeding window count	3900008052	14
	B1155A	00.03 -depth arg (= 0 in xwcreate, s/b 'invalid window depth' not 'bad option	3900008060	14
	B1155A	00.03 In hpterm, an extra cursor appears after pressing [Next][Next]	3900008078	14
	B1155A	00.03 Programmatically turning key labels on/off repeatedly resizes hpterm wind	3900008086	15
	B1155A	00.03 hpterm will display wrong menu instead of user menu (sometimes)	3900008094	15
	B1155A	00.03 Mode menu check mark does not come on for reverse video option	3900008102	15
	B1155A	00.03 When clicking mouse inside, then outside hpterm, hpterm dies	3900008110	16
	B1155A	00.03 TSRX colors allocated incorrectly in overlays if first in STACKED MODE.	3900008128	16
	B1155A	00.03 Running two servers at the same display won't work	3900008136	16
	B1155A	00.03 Using non-HP Xlib may cause client termination for LARGE requests	3900008144	17
	B1155A	00.03 grmd process size grows by 2K for each Starbase application	3900008151	17
	B1155A	00.03 In depths greater than 8, resizing a backing store window crashes server	3900008169	18
	B1155A	00.03 On LCC or Hexagon display copying window sometimes is not right	3900008177	18
	B1155A	00.03 HP98556 and STACKED SCREENS Mode: colormap hosed when server resets	3900008185	19
	B1155A	00.03 Server doesn't always handle "Unsorted" XSetClipRectangles correctly	3900008193	19
	B1155A	00.03 backing store is not deleted for depth 24 DHA windows	3900008201	20
	B1155A	00.03 redMask in the Visual structure zero in stacked mode on SRX/TSRX	3900008219	20
	B1155A	00.03 Colors stored incorrectly in upper bank on TSRX double buffer mode	3900008227	21
	B1155A	00.03 White RGB value incorrect on 98548 display	3900008235	21
	B1155A	00.03 On TSRX (hp98730/98731) some tiles are rendered incorrectly	3900008243	21
	B1155A	00.03 Remnants of SB cursors left when obscuring/unobscuring window	3900008250	22
	B1155A	00.03 SB cursors in reserved planes are not turned off by the screen saver	3900008268	22
	B1155A	00.03 client clip ignored when rendering to obscured window with backing store	3900008276	22
	B1155A	00.03 If X server restarted, ScreenSaver time not initialized	3900008284	23
	B1155A	00.03 Multiple keycodes with same keySYM in USASCII keypad	3900008292	23
	B1155A	00.03 X Server error message: "Illegal state: prev stat=2 keycode=0"	3900008300	24
	B1155A	00.03 Compiler error when referencing XHPSTACKED_SCREEN_MODE constant	3900008318	25
	B1155A	00.03 Last client termination MAY cause the X Server to abort	3900008326	25
	B1155A	00.03 XOpenDisplay through local 0 disables access control of server	3900008334	25
	B1155A	00.03 Gwind can hang when large number of windows are created	3900008342	26
	B1155A	00.03 xset gives error if pixel value is used outside of range 1-255	3900008359	26
	B1155A	00.03 xwud does not use the colors saved; it uses just the pixels	3900008367	26
	B1155A	00.03 HPwm leaves X server grabbed and forgets pending resize if menu pops up	3900008375	26
	B1155A	00.03 XtNtitlePosition defined differently for 2 different widgets	3900008383	27
	B1155A	00.03 Remnants of SB cursors left when obscuring/unobscuring window	3900008391	27

*****none*****	B1152A	00.03 TextEdit Widget leaves highlight droppings	3900006122	29
	B1152A	00.03 Form doesn't size itself correctly for certain sets of constraints	3900006130	29
	B1152A	00.03 Toolkit generates warnings if widgets put in empty slots of listwidget	3900006148	29
	B1152A	00.03 SWindow doesn't propagate all resources to its children	3900006155	30
	B1152A	00.03 Select up key can be lost causing incorrect widget state	3900006163	30



Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	B1152A	00.03 TextEdit does not handle returns followed by backspaces correctly.	3900006171	30
	B1152A	00.03 Shell doesn't account for border width of its child.	3900006189	30
	B1152A	00.03 The 2 byte string "\n" is treated as a newline like the 1 byte '\n'.	3900006197	31
	B1152A	00.03 StaticRaster will choose it's size wrong.	3900006205	31
	B1152A	00.03 Certain increments of highlight thickness can be lost.	3900006213	31
	B1152A	00.03 Vpane Widget setting invalid padding and border frame causes Xtoolkit Er	3900006221	31
	B1152A	00.03 Shell: a realized shell doesn't resize to the size of its new children	3900006239	32
	B1152A	00.03 SWin: produces a valuator warning on some resizing.	3900006247	32
	B1152A	00.03 XtNinsertPosition is defined for both TextEdit and Manager classes.	3900006254	32
	B1152A	00.03 TextEdit: Editing text in middle of buffer messes up selection.	3900006262	33
	B1152A	00.03 TextEdit: Doesn't reset margins when highlight thickness changes.	3900006270	33
	B1152A	00.03 TextEdit: clears an area of shadow on inputting characters.	3900006288	33
	B1152A	00.03 TextEdit Widgets occasionally drop the first char of a line of text.	3900006296	34
	B1152A	00.03 Assorted TextEdit code deficiencies.	3900006304	34
	B1152A	00.03 XtNfile resource cannot be modified through SetValues.	3900006312	34
	B1152A	00.03 The macro DefaultDepth returns incorrect depth on many displays.	3900006320	35
	B1152A	00.03 Deleting translations can cause problems.	3900006338	35
	B1152A	00.03 TextEdit: Segmentation Fault when Writing from empty cut buffer.	3900006346	35
	B1152A	00.03 Spring-loaded popup widgets don't interact well with keyboard focus.	3900006353	36
	B1152A	00.03 Destroying popup children, then their parent widget, dumps core.	3900006361	36
	B1152A	00.03 TextEdit forgets Leave callback if highlight_traversal is set	3900006379	37
	B1152A	00.03 Malloc failure causes Server to terminate.	3900006403	37
	B1152A	00.03 DisplayHeight(MM()) and Width(MM()) return same values for all displays.	3900006411	37
	B1152A	00.03 keysyms for left and right quote on german keyboard are backwards.	3900006429	37
	B1152A	00.03 XGrabPointer will not confine to a root window	3900006437	38
	B1152A	00.03 root-window backing store malfunctions	3900006445	38
	B1152A	00.03 SRX server in stacked mode leaves the wrong screen showing at startup.	3900006452	38
	B1152A	00.03 Text output causes mouse cursor to flicker even if window is unmapped.	3900006460	38
	B1152A	00.03 rtprio on any X process can cause deadlock.	3900006478	39
	B1152A	00.03 XSetModifierMapping allows duplicate key codes in a keymap.	3900006486	39
	B1152A	00.03 Output to UNMAPPED window (with BackingStore) NOT there when W is mapped	3900006494	39
	B1152A	00.03 CopyPlane, CopyArea and backing store may not copy everything	3900006502	40
	B1152A	00.03 XQueryColors Xlib function returns incorrect results	3900006510	40
	B1152A	00.03 Popping up a uwm menu over a bitmap grid can black out grid markers.	3900006528	41
	B1152A	00.03 hpterm dies when changing colors if colormap is full	3900006536	41
	B1152A	00.03 hpterm ignores .STOP key.	3900006544	41
	B1152A	00.03 In hpterm, <esc>&JA displays the wrong menu (should be modes).	3900006551	41
	B1152A	00.03 In hpterm, cursor is left in incorrect position after processing <esc>d.	3900006569	42
	B1152A	00.03 In hpterm, pastes of >-512 chars drop data (s800 only).	3900006577	42
	B1152A	00.03 In hpterm, <esc>a can not return a row >999.	3900006585	42
	B1152A	00.03 hpterm display messages are over written by status block.	3900006593	42
	B1152A	00.03 when hpterm gets a soft reset, the cursor is left off	3900006601	42
	B1152A	00.03 Bitmap with-nodashed, then do invert all results in lines becoming dots	3900006619	43
	B1152A	00.03 Gwind daemon left running if given invalid display argument	3900006825	43
	B1152A	00.03 Gwind doesn't handle negative geometry positioning, off by border width	3900006833	43
	B1152A	00.03 Gwindstop does not accept multiple directories	3900006841	43
	B1152A	00.03 Gwindstop doesn't return nonzero status when destroying nonexistent wind	3900006858	44
	B1152A	00.03 rgb returns status 0 for illegal color names/values	3900006866	44
	B1152A	00.03 Can't resize info when resizing windows with large borders	3900006874	44

Keyword	Product number	uu.ff	Description	KPR number	page
*****none*****	B1152A	00.03	Using xclock with option chime only beeps once on the hour, not twice.	3900006882	44
B1152A	B1152A	00.03	xkc doesn't complain if both -l and -m options at same time	3900006890	44
B1152A	B1152A	00.03	All special properties have parsing problems in xfc	3900006908	45
B1152A	B1152A	00.03	Man page example for xinit is wrong: --l is wrong; (should be --:1)	3900006916	45
B1152A	B1152A	00.03	Default screen is used if an invalid screen number is given.	3900006924	45
B1152A	B1152A	00.03	Wrong message given when using xmodmap -n -e	3900006932	45
B1152A	B1152A	00.03	A bad keySYM when using xmodmap does not terminate with error	3900006940	46
B1152A	B1152A	00.03	When using Xmodmap, X protocol error can result vs. correct error msg	3900006957	46
B1152A	B1152A	00.03	X11start man page doesn't mention \$PATH is changed.	3900006965	46
B1152A	B1152A	00.03	xwcreate returns status of 0 even if there was an error.	3900006973	46
B1152A	B1152A	00.03	-inverse option in xwd doesn't work on a monochrome display.	3900006981	46
B1152A	B1152A	00.03	In using xwcreate, color parameters expect pixel indices not rgb values	3900006999	47
B1152A	B1152A	00.03	TextEdit: Changing fonts using setvalues dumps core on input or bspace.	3900007005	47
B1152A	B1152A	00.03	TurboSRX server forgets current cursor if moved out of then into scree	3900007013	47
B1152A	B1152A	00.03	Blow through on screen when non font file name filename.scf	3900007021	48
B1152A	B1152A	00.03	XFillArc() does not handle negative angles properly.	3900007039	48
B1152A	B1152A	00.03	Problems with stippling a bitmap	3900007047	49
B1152A	B1152A	00.03	Problem w/ copy plane from window to bitmap.	3900007054	49
B1152A	B1152A	00.03	Problem with copy-area to window with neg. co-ords.	3900007062	50
B1152A	B1152A	00.03	XDrawLines chokes on duplicates in array of points.	3900007070	50
B1152A	B1152A	00.03	Xwinfor returns status of 1 even if there was no error.	3900007088	51
B1152A	B1152A	00.03	Inconsistent handling of vertices in 0-width polyline	3900007104	51
B1152A	B1152A	00.03	SetValues of TitleBar's internal StaticText widget causes memory fault.	3900007112	51
B1152A	B1152A	00.03	Xserver can crash on XCopyPlane when dealing with depth 1.	3900007120	51
B1152A	B1152A	00.03	XPutImage on fireye sometimes munges offscreen memory.	3900007138	52
B1152A	B1152A	00.03	display enhancements in hpterm not always displayed the same as terminal	3900007146	52
B1152A	B1152A	00.03	finnish keyboard doesn't work with Product-Line software	3900007153	53
B1152A	B1152A	00.03	Reading multi-line translations in resource files returns wrong \$ length	3900007161	53
B1152A	B1152A	00.03	xwm does not take large border widths into account when placing windows	3900007179	53
B1152A	B1152A	00.03	X server doesn't work on kernel without ITE configured in. (S800)	3900007187	53
B1152A	B1152A	00.03	Copy plane sometimes doesn't work	3900007195	54
B1152A	B1152A	00.03	Problems w/ copy-plane from window to bitmap	3900007773	54
B1152A	B1152A	00.03	Problems w/ copy-plane from window to bitmap	3900007781	54
B1152A	B1152A	00.03	xwcreate does not size window correctly in 6.2 - fixed in 6.5	5000474411	55
B1152A	B1152A	00.00	TextEdit forgets Leave callback if highlight_traversal is set	3900006072	29

*****none*****	B1152B	00.03	Duplicate typedefs for short INT8 cause compiler to abort	16500099572	56
B1152B	B1152B	00.03	hpwm title remains pushed in shen concurrent interact. place is done	3900007211	56
B1152B	B1152B	00.03	Hpwm.man says f.refresh will actis like f.refresh in root context.	3900007229	56
B1152B	B1152B	00.03	Core Dump when sizing windows in a VPANE	3900007237	56
B1152B	B1152B	00.03	TextEdit widget created with empty file. change to full file. hang	3900007245	57
B1152B	B1152B	00.03	icon over save button in save view in hpwm. Both get select signal.	3900007252	57
B1152B	B1152B	00.03	hpwm interactive placement when mouse is busy - window (0.0) can't move	3900007260	58
B1152B	B1152B	00.03	<Buttonup> title f.raise lower" only does f.raise in hpwm.	3900007278	58
B1152B	B1152B	00.03	Unexpected window position with negative geometry co-ordinates.	3900007286	58
B1152B	B1152B	00.03	XtNtitlePosition defined differently for 2 different widgets	3900007294	58

Keyword	Product number	uu.ff Description	KPR number	page
*****nonone*****				
B1152B		00.03 type converters in libXw don't generate warning on bad conversions	3900007302	59
B1152B		00.03 TextEditPrivate.h: uses defines XtTextEditPrivate.h instead of _XtTextEdit...	3900007310	59
B1152B		00.03 BackgroundTile resources not properly propagated	3900007328	59
B1152B		00.03 multiple traversal highlights can sometimes appear	3900007336	60
B1152B		00.03 SWindow: horizontal scroll bar y resource always returns 0 on getvalues	3900007344	61
B1152B		00.03 monochrome Z format image handled incorrectly in `xpr` and `xwd2sb`	3900007351	61
B1152B		00.03 xwcreate indicates an invalid background pixel when using TSRX display.	3900007369	61
B1152B		00.03 In xpr -trailer string truncated by 1 char when -append -noif spec. after	3900007377	61
B1152B		00.03 xwcreate does not give an error for exceeding window count.	3900007385	61
B1152B		00.03 -depth arg <= 0 in xwcreate, s/b `invalid window depth`, not `bad option	3900007393	62
B1152B		00.03 In hpterm, an extra cursor appears after pressing [Next][Next].	3900007401	62
B1152B		00.03 Programmatically turning key labels on/off repeatedly resizes hpterm wind	3900007419	62
B1152B		00.03 hpterm will display wrong menu instead of user menu (sometimes)	3900007427	63
B1152B		00.03 Mode menu check mark does not come on for reverse video option	3900007435	63
B1152B		00.03 When clicking mouse inside, then outside hpterm, hpterm dies.	3900007443	63
B1152B		00.03 TSRX colors allocated incorrectly in overlays if first in STACKED MODE.	3900007450	63
B1152B		00.03 Running two servers at the same display won't work.	3900007468	64
B1152B		00.03 Using non-HP Xlib may cause client termination for LARGE requests.	3900007476	64
B1152B		00.03 Restarting a second s300 server after changing Xscreens file may fail.	3900007484	65
B1152B		00.03 grnd process size grows by 2K for each Starbase application	3900007492	65
B1152B		00.03 In depths greater than 8, resizing a backing store window crashes server	3900007518	66
B1152B		00.03 On LCC or Hexagon display, copying window sometimes is not right	3900007526	67
B1152B		00.03 XGetImage behaves wrong for backing store windows of depth 2,3,4,6.	3900007534	67
B1152B		00.03 HP98556 and STACKED SCREENS Mode: colormap hosed when server resets.	3900007542	68
B1152B		00.03 Server doesn't always handle "Unsorted" XSetClipRectangles correctly	3900007559	68
B1152B		00.03 Backing store is not deleted for depth 24 DHA windows	3900007567	69
B1152B		00.03 Backing store may not be rendered to correctly on some displays (s300)	3900007575	69
B1152B		00.03 redMask in the Visual structure zero in stacked mode on SRX/TSRX	3900007583	69
B1152B		00.03 Colors stored incorrectly on 98548 display	3900007591	70
B1152B		00.03 White RGB value incorrect on 98548 display	3900007609	70
B1152B		00.03 On TSRX (hp98730/98731) some tiles are rendered incorrectly	3900007617	70
B1152B		00.03 Tiles may be drawn incorrectly on SRX (HP 98720/98721) (s300)	3900007625	70
B1152B		00.03 Remnants of SB cursors left when obscuring/unobscuring window	3900007633	71
B1152B		00.03 SB cursors in reserved planes are not turned off by the screen saver.	3900007641	71
B1152B		00.03 client clip ignored when rendering to obscured window with backing store	3900007658	72
B1152B		00.03 If X server restarted, ScreenSaver time not initialized.	3900007666	72
B1152B		00.03 Multiple keycodes with same keysym in USASCII keypad.	3900007674	73
B1152B		00.03 X Server error message: "Illegal state: prev stat=2 keycode=0"	3900007682	74
B1152B		00.03 Compiler error when referencing XHPSTACKED_SCREEN_MODE constant	3900007690	74
B1152B		00.03 Last client termination MAY cause the X Server to abort	3900007708	74
B1152B		00.03 XOpenDisplay through local 0 disables access control of server	3900007716	75
B1152B		00.03 Existing SB_DISPLAY_ADDR variable may interfere with X server (s300)	3900007724	75
B1152B		00.03 Gwind can hang when large number of windows are created.	3900007732	76
B1152B		00.03 Certain bitmaps does not tile correctly as a root background (s300)	3900007740	76
B1152B		00.03 xset gives error if pixel value is used outside of range 1-255.	3900007757	76
B1152B		00.03 xwd does not use the colors saved; it uses just the pixels	3900007765	77
B1152B		00.03 HPwm leaves X server grabbed and forgets pending resize if menu pops up	3900007789	77
B1152B		00.03 All special properties have parsing problems in xfc.	3900007872	77
B1152B		00.03 Bitmap with-nodashed, then do invert all results in lines becoming dots		

CUMULATIVE KEYWORD INDEX

- X11 WINDOWS 6.5/3.1 - SSB ISSUE DATE: 11/09/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	B1152B	00.03 Duplicate reference to _bcopy in libX11.a and libndbm.a	5000476838	77
*****none*****	B1152C	02.00 On SRX and TSRX, XGetVisualInfo incorrectly reports bits_per_rgb as 4	3900008995	78
	B1152C	02.00 wxcreate cannot create windows on multiple servers	3900009001	78
	B1152C	02.00 mkfontdir doesn't unlink fonts.dir before creating new fonts.dir	3900009019	78
	B1152C	02.00 cvtINI16ToInt in XGetMotionEvents causes cc to abort	3900009027	78
	B1152C	02.00 XGetPixel returns invalid data for 98547S Topcat 300h:6 double buffer	3900009050	79
	B1152C	02.00 XErrorDB does not include any error information for errors over #127	3900009068	79
	B1152C	02.00 hpterm when maximized does not handle geometry changes when [Menu] on	3900009076	79
	B1152C	02.00 old style (pre 7.0) grmd+ socket not removed by AGRM customize script	3900009084	79
	B1152C	02.00 sys.Xdefaults lacking colon in line for "HPTerm*Font	3900009092	80
	B1152C	02.00 hpterm may leave highlighting on in erased regions	3900009100	80
	B1152C	02.00 Xos.h needs to default to SYSV, not Berkeley stuff	3900009118	80
	B1152C	02.00 TextEditP.h: extra characters after #endif	3900009126	80
	B1152C	02.00 Changing Xthick on static raster causes X Protocol error	3900009159	81
	B1152C	02.00 hpterm {block mode} loses character on read from cursor to end of line	3900009183	81
	B1152C	02.00 hpterm { 7.0 } does not read correctly from specified column to end of lin	3900009191	81
	B1152C	02.00 hpterm } 0 does not display alternate character_set with curses program	3900009217	81
	B1152C	02.00 Memory leak when create/destroy PromptDialog widget; Motif 1.0	3900009225	81
	B1152C	02.00 Problems reading with Esc-D in hpterm block mode	3900009233	81
	B1152C	02.00 XHPGetClipList trashes malloc data	3900009571	81
	B1152C	02.00 hpbkterm does not warn user that lines are being lost in TDP buffer	5000535153	82
	B1152C	02.00 xterm with -title option does not work properly and not equiv to -T	5000552307	82
	B1152C	02.00 xterm does correctly emulate the function keys of the VT100/102 term	5000554493	82
	B1152C	02.00 xterm - selecting "Interrupt" from xterm menu can cause system problems	5000557215	82
	B1152C	02.00 hpterm does not refresh Keyboard mapping after receiving MappingNotify	5000557223	82
	B1152C	02.00 Xlib-line width 0 and PlaneMask set to other than AllPlanes - no line	5000573956	83

KPR #: 3900009241 \*\*CONTINUED\*\*

Temporary solution:  
About all one can do is look at /usr/man/man3.Z and try to equate manpage to file.

KPR #: 3900009258 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
Online man pages for many of (Motif) widget calls display incorrectly

Problem:  
The online man pages for mwm, and some Xt (Toolkit Intrinsic) calls, and some Xm (the Motif (1.0) library) are display incorrectly. The man pages for these calls are affected:

- mwm.1
- Application.3x
- Composite.3x
- Core.3x
- Object.3x
- OverriderShe.3x
- RectObj.3x
- Shell.3x
- TopLevelShe.3x
- TransientSh.3x
- VendorShell.3x
- WMShell.3x
- XmArrowButA.3x
- XmArrowButB.3x
- XmBulletinB.3x
- XmCascadeBA.3x
- XmCascadeBB.3x
- XmCommand.3x
- XmDialogShe.3x
- XmDrawingAR.3x
- XmDrawnButt.3x
- XmFileSelea.3x
- XmForm.3x
- XmFrame.3x
- XmGadget.3x
- XmLabel.3x
- XmLabelGadg.3x
- XmList.3x
- XmMainWinda.3x
- XmManager.3x
- XmMenuShell.3x
- XmMessageBA.3x
- XmPanedWind.3x
- XmPrimitive.3x
- XmPushButta.3x
- XmPushButtb.3x
- XmRowColumn.3x
- XmScale.3x
- XmScrollBA.3x
- XmScrolledA.3x
- XmSelectionA.3x

KPR #: 3900009134 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
Man pg XHPSetKeyboardMapping (3X): XComposeStatus should be pointer

Problem:  
In the man page description of XHPSetKbdMapInit macro, the last parameter, status\_in\_out should be of type XComposeStatus \* ( a pointer ). The macro passes this value as arguments to XHPNlioct1 which requires a pointer argument.

KPR #: 3900009142 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
man pg XHPNlioct1 (3x) arg parameter should be int for some commands

Problem:  
The arg parameter for this routine is not always a char \* . It varies from command to command. Please check with the documentation for communicating with the nlio process.

KPR #: 3900009167 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
Manual does not explain how to use -C option (console output)

Problem:  
The -C option is in hpterm and xterm to allow programs that direct their output to "/dev/console" to have that output go to a terminal emulator window that has been designated to receive console output. Unfortunately, the documentation and man pages do not offer any hint on how to set this up.

KPR #: 3900009241 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
man pages for Xt calls do not correspond to actual call

Problem:  
try: man -k XtAppCreateShell  
and you get the keyword for the call.

Then try:  
man -k XtAppCreateShell  
and you get "no manual entry for XtAppCreateShell"

Cause:  
MIT has truncated or abbreviated file names with no way to equate the actual manpage name to the file name. In this case XtAppCreateShell is actually in XtAppCSh and that's what you have to use with the "man" command. We ALWAYS have a file that is the same name as the manpage and it either provides the manpage online or tells you what to enter to get what you want. MIT manpages will have this problem and about all one can do is look at /usr/man/man3.Z and try to equate manpage to file.



KPR #: 3900009258 \*\*CONTINUED\*\*

XmSeparatorA.3X  
XmSeparatorB.3X  
XmText.3X  
XmToggleBua.3X  
XmToggleBub.3X

Cause:  
In the raw man files for the calls, there is a source statement (.so), but there is no corresponding file. After that, output is garbled.  
Temporary solution:  
Temporary workaround: via HP Support representative, obtain a copy of the corrected man pages (they have placed on the Ft. Collins patch machine), OR  
use the printed manual page in the printed manuals.

KPR #: 5000538942 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
No documentation is provided on how to use block term mode of hpterm

KPR #: 5000540823 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
7.0 Version of Install & Config does not explain set up procedures for X

KPR #: 5000544791 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
7.0 Beginner's Guide wrong on pg. 6-2. csh does not use '[' for test

KPR #: 5000553131 Product: X DOCUMENTATION ONLY B1161A 00.00

One-line description:  
7.0 Documentation example for xmodmap does not work

KPR #: 1650079012 Product: X10 WINDOWS 82320A 10.40

One-line description:  
Documentation problem; index gives incorrect page number in Xr1ib manual

KPR #: 3900007096 Product: X10 WINDOWS 82320A 11.50

One-line description:  
XCheckWindowEvent and XCheckMaskEvent calls don't work

Problem:  
Both the "XCheckMaskEvent" and "XCheckWindowEvent" calls (in X10) appear to be disabled. If they are the only method used for acquiring input in a simple X program, none is ever received. They do not appear to detect any of the input events requested.

Temporary solution:  
No workaround.

KPR #: 5000206219 Product: X10 WINDOWS 82320A 05.50

One-line description:  
parameter list description for "xtext(3X)" is in error

Problem:  
The manual, Programming with Xwindow system, reference page xtext(3x) is missing the parameter bwidth in the parameter list. This needs to be fixed.

KPR #: 5000206268 Product: X10 WINDOWS 82320A 05.50

One-line description:  
Manual doesn't explain how to pop-up menu from program

Problem:  
There is a documentation problem with the Xwindows manual explaining how to bring up a menu programmatically. The Xwindows people are aware of this problem and are currently fixing the manual. A few hints: You must do the following calls to bring up a menu programmatically.  
Xrmenu(mymenu,MSG\_ACTIVATEMENU,windowid)  
XrMenuItemSelect-XrLEFTBUTTONDOWN; or can use XrRIGHTBUTTONDOWN.  
This call must be made and with one of these two options.  
XrMenu(mymenu,MSG\_EDIT,&menuItem) This call makes the active menu current.

This needs to be done along with all the normal preparation for a menu pop up.

I almost forgot to mention that the x,y parameters on where to place the menu don't work either. The menu will come up where the cursor is.

KPR #: 5000225623 Product: X10 WINDOWS 82320A 05.20

One-line description:  
Only get root window with hostnames > 8 characters.

Problem:

KPR #: 5000225623 \*\*CONTINUED\*\*

Requesting a documentation enhancement for installing XWINDOWS on s300 with LAN installed.  
 Found that the hostname command accepts a name longer than 8 characters but then truncates it to eight. In /etc/host file names up to 11 characters are valid. This causes a problem with a hostname 910, or 11 characters. The truncated hostname does not match the entry in /etc/hosts, therefore X does not come up.  
 When xstart is executed the grey background with X in middle appears, nothing else. Once the entry in /etc/hosts was cut down to 8 characters to match hostname, X came up properly.

KPR #: 5000228676 Product: X10 WINDOWS 82320A 05.50

One-line description:  
 xterm does not recognize Backspace key when using \$HOME/.Xkeymap file.

Problem:  
 If you use keycomp(1x) on the default keymapping file that comes with the system, /usr/lib/X/Xkeymap.default, and place the output in \$HOME/.Xkeymap, xterm(1) behaves differently. It does not recognize the Backspace key at the top right of the keyboard.

Please change /usr/lib/X/Xkeymap.default so that it reflects what's compiled in to xterm(1).

KPR #: 5000240184 Product: X10 WINDOWS 82320A 05.05

One-line description:  
 Typos in "Programming with the X Window System" manual.

Problem:  
 In "Programming with the X Window System" manual dated 6/87 (82320-90001), under "OVERVIEW" section, page 1-20 :

Line 2: XrSetRect(&windowData.windowRect,50,50,400,200);  
 should be: XrSetRect(&windowData.windowRect,50,50,400,200);

Line 3: windowData.foreFile = BlackPixMap  
 should be: windowData.foreFile = BlackPixmap

Line 4: windowData.backFile = WhitePixMap  
 should be: windowData.backFile = WhitePixmap

KPR #: 5000253872 Product: X10 WINDOWS 82320A 05.50

One-line description:  
 CreateTTYWindow call doesn't work w/ release 5.5

Problem:  
 The Xwindows function Xtty(3X), CreateTTYWindow, does not work in hpux 5.5. It used to work in hpux 5.3 on the 9000/350.

Duplicate Service Requests: 5000410100

- X10 WINDOWS -

KPR #: 5000258749 Product: X10 WINDOWS 82320A 01.00

One-line description:  
 X doesn't create "pty" entries for use on discless node

Problem:  
 Customer has X windows rev A.01.00 for the s300, p/n 82320A.

Customer has found that this revision does not support Discless nodes and is requesting that X windows be enhanced to support Discless nodes.

Fix information:  
 Fixed in version A.03.00

Signed off 03/31/89 in release A03.00

KPR #: 5000274225 Product: X10 WINDOWS 82320A 05.50

One-line description:  
 wxinstall, pre 6.2, will alter and remove related files in /usr/bin

Problem:  
 wxinstall and wxuninstall command remove /usr/bin/wxstart.  
 System Config: 9000/300 HP-UX (Rev. 5.5) X-window(Rev. A.01.00)  
 Kanji I/O subsystem (Rev. 5.2)

When the system configuration is like above, "wxinstall" command remove unexpected files such as /usr/bin/wxstart. "wxinstall" command replace /usr/bin/wxstart to emulate WINDOW/9000 on X-WINDOW, and "wxuninstall" command should recover /usr/bin/wxstart from backup of this file.  
 But when user has Kanji I/O subsystem also, this "wxuninstall" command doesn't recover /usr/bin/wxstart and seems to be removed.

KPR #: 5000300467 Product: X10 WINDOWS 82320A 06.00

One-line description:  
 XTERM does not generate SIGINT from the break key

KPR #: 5000416461 Product: X10 WINDOWS 82320A 03.02

One-line description:  
 Install errors on 6.2 and 6.5 when long filenames are enabled

KPR #: 5000427872 Product: X10 WINDOWS 82320A 06.20

One-line description:  
 XTERM hangs when cutting and pasting a large section of text

- X10 WINDOWS -

KPR #: 3900007799 Product: X11 800 ONLY 3.0/3.1 B1155A

B3.00

One-line description:  
 SRX combined mode rendering problems, images listed 1st in screens file  
 Problem:  
 Assume the following configuration:  
 TSRX display (HP 98730/98731)  
 3 plane overlay device = /dev/ocrt0)  
 Image plane device = /dev/crt

The following X0screens entry will result in improper rendering in the overlay planes:

/dev/crt /dev/ocrt0

This is due to the display drivers inability to determine the overlay plane configuration from the image planes.

Symptoms include generally incorrect appearance for most clients running in the overlay planes.

Temporary solution:  
Workaround:

List the overlay plane device first. For example, the following X0screens entry would correct the behavior:

/dev/ocrt0 /dev/crt

KPR #: 3900007807 Product: X11 800 ONLY 3.0/3.1 B1155A

B3.00

One-line description:  
With hpterm in pointer blank mode, the pointer blanks on shift & meta

Problem:  
When run on the s800 with pointer blank mode on, hpterm will blank the pointer when noncharacter keys are pressed, such as return, shift, extend. This is due to a lack of "return(false);" at the end of the ProcesskeyInput function.

KPR #: 3900007815 Product: X11 800 ONLY 3.0/3.1 B1155A

B3.00

One-line description:  
The Fortran bindings don't return a function pointer correctly

Problem:  
On the series 800, a function pointer is not returned properly by the Fortran bindings. The following program should print the address of the subroutine "fixit":

include 'Xf/sfalias.h'  
program test  
include 'Xf/Xflib.h'  
external fixit

KPR #: 3900007815 \*\*CONTINUED\*\*

integer\*4 pfi,ppfi

ppfi = XfCreate(XFT\_xrPFI)  
if (.not. XfInsert(ppfi,1,fixit)) call error  
if (.not. XfExtract(ppfi,0,pfi)) call error  
print \*,pfi  
if (.not. XfDestroy(ppfi)) call error  
end

subroutine fixit  
return  
end

subroutine error  
print \*,'Error'  
return  
end

Temporary solution:  
Pass an index of 1 rather than 0 in the call to XfExtract.

KPR #: 3900007823 Product: X11 800 ONLY 3.0/3.1 B1155A

B3.00

One-line description:  
X Server defaults to using /dev/crt, should be /dev/crt0 on s800

Problem:  
If no /usr/lib/X11/X0screens file exists, the X Server attempts to open the device "/dev/crt". This file does not exist on S800 systems.

Cause:  
Server has the wrong default file name.

Temporary solution:  
Set up a correct /usr/lib/X11/X0screens file, containing:  
/dev/crt0

KPR #: 3900007831 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

One-line description:  
In hpterm, pastes of >-512 chars drop data (s800 only).

KPR #: 3900007856 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

One-line description:  
All special properties have parsing problems in xfc.

Problem:  
The validity of data specified for special properties is not checked by xfc.

Temporary solution:  
Workaround:



KPR #: 3900007856 \*\*CONTINUED\*\*

The user must ensure that special property data is correct.

KPR #: 3900007864 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Bitmap with-nodashed, then do invert all results in lines becoming dots

Problem:  
Using bitmap with -nodashed, then do invert all results in lines becoming dots.

If bitmap is started with the -nodashed option and the user then specified 'invert all', the solid lines become dots.

Temporary solution:  
No workaround.

KPR #: 3900007880 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
hpwm title remains pushed in shen concurrent interact. place is done

Problem:  
If the title is already pushed in when a concurrent interactive place is done, the title will not pop back. This is a cosmetic defect.

Temporary solution:  
Workaround:

Repaint the screen.

KPR #: 3900007898 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

Hpwm.man says f.refresh\_wil actls like f.refresh in root context.

Problem:  
The man page incorrectly states that firefresh\_win acts the same as firefresh in root context.

Temporary solution:  
No workaround.

KPR #: 3900007914 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Textedit widget created with empty file, change to full file, hang

Problem:  
I have a widget based mail program. If I create a textedit widget that has a sourceType of XwdiskSrc and file that is empty and then I change the parameters in a callback to point to a non empty file my program hangs.

Temporary solution:

KPR #: 3900007914 \*\*CONTINUED\*\*

Workaround:

By putting some text in the original file everything works O.K.

KPR #: 3900007922 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
icon over save button in save view in hpwm. Both get select signal.

Problem:  
icon was over the save button on a fileview. I doubleclicked to deiconize. The icon deiconized but the button beneath was selected as well. Fortunately it is a nondamaging request. This is really a bug in hpwm. The bug is that after a double click to deiconize, the release event is making it through to the window underneath. Since the double click is "owned" by the window manager, it shouldn't allow it to be passed to an application (this requires some sort of grab, I think). Hpwm carries out the double-click action when it receives the second button down event. The second button-up event is not consumed by hpwm.

Temporary solution:  
Change your selection for the button to be btnDown rather than btnUp.

KPR #: 3900007930 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

hpwm interactive placement when mouse is busy - window (0,0) can't move

Problem:  
When hpwm has interactive placement on, if a window appears while the mouse button is down, hpwm puts the top left corner of the window at (0,0). Unfortunately, the title bar is hidden, so the gadget to move the window cannot be reached. I have to kill the window and start over.

Temporary solution:  
No workaround.

KPR #: 3900007948 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

"<BtnUp> title f.raise\_lower" only does f.raise in hpwm.

Problem:  
The following bindings for f.raise\_lower work:

```
<Key>Select      window/icon      f.raise_lower
<BtnUp>          icon              f.raise_lower
Meta<BtnUp>     icon              f.raise_lower
Menu DefaultSystemMenu
{
  "Raise/Lower"  f.raise_lower
}
The following only execute f.raise:
<BtnUp>         title      f.raise_lower
```

KPR #: 3900007948 \*\*CONTINUED\*\*

Meta<BtnUp> title f.raise\_lower  
Meta<BtnUp> window f.raise\_lower

Temporary solution:  
No workaround.

KPR #: 3900007955 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Unexpected window position with negative geometry co-ordinates.

Problem:  
There is a general problem with Xlib when negative geometry coordinates are used. This problem can be exhibited when using hpwm or some of the clients.

Temporary solution:  
No workaround.

KPR #: 3900007963 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
XtNtittlePosition defined differently for 2 different widgets

Problem:  
The resource XtNtittlePosition is defined differently for 2 different widgets:

Cascade - type int  
uses XwTOP, XwBOTTOM or XwBOTH

TitleBar - type int  
seems to use numbers different from the enum values above

Temporary solution:  
No workaround.

KPR #: 3900007971 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
type converters in libXw don't generate warning on bad conversions

Problem:  
In tracking another problem, I discovered that some of my resources were illegal in my app-defaults. The converter functions are supposed to generate warnings when illegal values are specified, but did not. In particular, I had specified something like:  
\*StaticText.Gravity: False

instead of giving it a real value. It failed to tell me that False was not a legal value for gravity.

Temporary solution:

KPR #: 3900007971 \*\*CONTINUED\*\*

No workaround.

KPR #: 3900007989 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
TextEditP.h: uses defines XtTextEditPrivate\_h instead of \_XwTextEdit....

Problem:

To prevent multiple inclusion, ifdefs and defines were added to the header files. TextEditP.h uses ifdef XtTextEditPrivate\_h and define Xt... to prevent multiple inclusion instead of using the proper \_Xw prefix. This will only cause problems if an application defines XtTextEditPrivate\_h somewhere (which is very unlikely). But for consistency sake it should use the \_Xw prefix.

Temporary solution:  
No workaround.

KPR #: 3900007997 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
BackgroundTile resources not properly propagated

Problem:

If the resource file contains:  
\*BackgroundTile: 50\_foreground  
\*StaticText.backgroundTile: background

the list widget comes up with very strange defaults. The static text entries are correct (solid) but the row column manager underneath is tiled. The bulletin board manager is solid again (so the list manager window has an apparent random pattern of solid and tile). The correct values would have been for the bulletin board to use the same background as the row column, but what I really wanted to set was everything solid but the scrollbar.

To fix the problem, I added:

\*List\*BackgroundTile: background  
\*List\*Scrollbar\*BackgroundTile: 50\_foreground

but the problem is the second resource is ignored. It should be possible to set subresources for the scrollbar color and tile. Either that, or the resources need to be made available at the manager level with something like vsbBackgroundTile, etc.

This is actually a problem with ScrolledWindow as well.

Temporary solution:  
No workaround.

KPR #: 3900008003 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
multiple traversal highlights can sometimes appear

Problem:  
I have some code which pops up a transient shell and calls XtSetKeyboardFocus(). It then pops down the transient shell and later pops it up, again setting the focus. If the user changes the kbd focus before popping down the shell (dialog box), then when the box reappears, both highlights are sometimes visible. I think when no intervening management requests come in, but the focus is correctly placed in the one on which XtSetKeyboardFocus() was last called.

Temporary solution:  
Workaround:

I can work around this by calling XtSetKeyboardFocus(popup\_shell, None) when I pop down the box.

KPR #: 3900008011 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
SWindow: horizontal scroll bar Y resource always returns 0 on getvalues

Problem:  
None

Temporary solution:  
None

KPR #: 3900008029 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
monochrome Z format image handled incorrectly in `xpr' and `xwd2sb'.

Problem:  
Xpr & xwd2sb incorrectly handles monochrome images generated in ZPixmap format when the image is packed one bit per pixel. This due to a defect in the "Z\_image\_pixel" function contained in the x2jet.c file.

Temporary solution:  
Workaround:

Use the -xy command line option when generating the image via "xwd". This forces the image to be dumped in XYPixmap format which is handled correctly by xpr.

KPR #: 3900008037 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
xwcreate indicates an invalid background pixel when using TSRX display.

Problem:  
xwcreate displays a wrong error message and exits if pixel number is specified for the background. This happened when using a TurboSRX

KPR #: 3900008037 \*\*CONTINUED\*\*

display in 24 plane mode in the image planes.

Temporary solution:  
Workaround:

Use color names when specifying background.

KPR #: 3900008045 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
In xpr -trailer string truncated by 1 char when -append -noff spec. after

Problem:  
None

Temporary solution:  
Workaround:

Simply add an extra space to the end of a trailer string if -append and -noff is to be used after it.

KPR #: 3900008052 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
xwcreate does not give an error for exceeding window count.

Problem:  
xwcreate will not create window if window count is exceeded and does not give an error message.

Temporary solution:  
No workaround

KPR #: 3900008060 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
-depth arg != 0 in xwcreate, s/b `invalid window depth', not `bad option

Problem:  
None

Temporary solution:  
No workaround

KPR #: 3900008078 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
In hpterm, an extra cursor appears after pressing [Next][Next].

Problem:  
An extra cursor is left on the screen if you do the following:

Show multiple pages on the screen. Press Shift home to go to the last page. Then Prev. Scroll the page down a couple of lines with shift down arrow. Then press Next Next. An extra cursor will appear.

KPR #: 3900008078 \*\*CONTINUED\*\*

Temporary solution:  
workaround:

Typing over extra cursor will make it disappear.

KPR #: 3900008086 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Programmatically turning key labels on/off repeatedly resizes hpterm wind

Problem:  
The following program will reproduce the problem:

```
#include <stdio.h>

main()
{
    int i;
    for (i=0; i<1000; i++)
        if (i%2) write(1, "\033&J0", 4);
        else write(1, "\033&JB", 4);
}

```

Temporary solution:  
No workaround.

KPR #: 3900008094 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
hpterm will display wrong menu instead of user menu (sometimes)

Problem:  
If you bring up an hpterm menu and turn off the menu via "MENU" and then turn it back on (via "MENU" again), it will display the same menu but the buttons will invoke the user's function keys. The action is right, the display is wrong.

Temporary solution:  
No workaround.

KPR #: 3900008102 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Mode menu check mark does not come on for reverse video option

Problem:  
Even though reverse video option is toggled on, the check mark does not appear in the menu.

Temporary solution:  
No workaround.

KPR #: 3900008110 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
When clicking mouse inside, then outside hpterm, hpterm dies.

Problem:

This defect will occur if you:

- begin a cut operation in an hpterm window,
  - move the cursor outside of the window without generating any pointer motion events from inside of the window,
  - end the cut operation (release mouse button).
- If this is done, hpterm will attempt to unhighlight text from the start position to an x and y position that is uninitialized and is only set by pointer motion events generated inside of the window.

Temporary solution:  
No workaround.

KPR #: 3900008128 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
TSRX colors allocated incorrectly in overlays if first in STACKED MODE.

Problem:

If the four plane overlay device is the first screen of a Stacked Screen Mode configuration on a Turbo SRX display system (HP98730/98731) then colors will be allocated incorrectly in cells 8-15 of the colormap. Symptoms will be that colors allocated in cells 0-7 will be replicated in cells 8-15 and colors allocated in cells 8-15 will not be installed.

Temporary solution:  
Two potential workarounds exist:

- 1) List the screens in opposite order so that the image planes are the lower numbered screen.
- 2) Allow the screen blanking screen saver to be installed. For example
 

```
xset s 1
  <wait a few seconds>
  xset s 3600
```

 will correct the color allocation.

KPR #: 3900008136 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Running two servers at the same display won't work.

Problem:

If the user starts two 11 servers, both of them to the same display, then the second one may eit gracefully, with a memory fault. The first server continues to run normally.

Cause:

The cause is due to the second server's having no knowledge that another server is already using a given display device. During the initialization of that device, the second server receives an expected message from the Graphics Resource Manager and so behaves unexpectedly.

KPR #: 3900008136 \*\*CONTINUED\*\*

Temporary solution:  
Workaround:

Don't try running two servers to the same display.

KPR #: 3900008144 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Using non-HP Xlib may cause client termination for LARGE requests.

Problem:

The server ungracefully handles large request packets from clients. For client requests larger than 16,384 bytes (normal request size is about 32 bytes), the server disconnects the client! This isn't a problem for HP clients--because the HP Xlib guarantees a smaller packet size--but could be a problem for non-HP Xlib clients.

Cause:

The X protocol states that the server return a "bad length" error for requests that exceed MAX\_REQUEST\_SIZE (16,384 bytes), set up at server initialization time, but in the actual request code, the A.01 server checks against the wrong size (256K bytes).

Temporary solution:  
Workaround:

Use the HP libx11.a library for writing clients.

KPR #: 3900008151 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
grmd process size grows by 2K for each Starbase application

Problem:

Every time a Starbase application is run in an X window, the grmd process size will grow by 2K. If the grmd process grows large enough, the system could run out of swap space.

Cause:

The grmd process does not free a 2K buffer used for IPC with the Starbase process when the Starbase process terminates.

Temporary solution:  
Workaround:

Take down the X Window system periodically so that the grmd process will terminate.

KPR #: 3900008169 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
In depths greater than 8, resizing a backing store window crashes server

Problem:

The backing store of a window is kept in either frame-buffer or in

KPR #: 3900008169 \*\*CONTINUED\*\*

virtual memory. When a window is registered to be a DHA (Direct Hardware Access) window, its backing store, if any, is moved to "Shared Memory". Shared memory is a piece of memory that can be accessed by drawing routines of the Xserver as well as by the drawing routines in Starbase library. However the shared memory is a limited resource and sometimes may be unavailable. This may happen if there are several windows or one large window has been declared to be DHA window. If the Shared memory is not available, the Xserver should backoff and refuse to provide backing store support for the DHA window. Because of a bug, the Xserver sometimes fail to recognize this situation and tries to render to nonexistent backing store in the shared memory. Consequently the server crashes. This bug is being fixed in the next release. The problem is particularly visible for windows of depth 24 because the large quantities of memory are required to support backing store operation of these windows and consequently the shared memory reservoir runs out quicker.

Temporary solution:  
Workaround:

The problem may be avoided (minimized) by doing the following:

- 1) do not have many DHA-windows with backing store.
- 2) do not declaring large full screen windows with backing store to be DHA-windows.
- 3) increase the size of allocated shared memory by instructing the Graphics Resource Manager (GRM). See the relevant GRM-document for instructions on how to do this.

KPR #: 3900008177 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

On LCC or Hexagon display copying window sometimes is not right

Problem:

If a window has backing store and it is partly obscured, then when the window is unobscured its contents are to be copied from the backing store to the screen. In the LCC or Hexagon displays sometimes it does not work properly.

Cause:

The backing store of a window resides in either the frame buffer or in virtual memory. When the backing store contents are to be copied to the screen the Xserver employs one of two different routines to copy the backing store to the screen. One of these routines is specifically used to copy from a backing store in frame buffer to the screen. Another routine is used to specifically copy backing store in virtual memory to screen. The former routine as implemented for the above displays has a bug, such that sometimes it does not copy the contents of the backing store from the frame buffer if the area to be copied is partially visible and partially obscured. On most displays, the problem manifests only once when the Xserver is initialized. On the LCC and Hexagon displays, this problem may persist.

Temporary solution:  
Workaround:

KPR #: 3900008177 \*\*CONTINUED\*\*

Large windows will have their backing store in virtual memory. This problem will not be visible then.

KPR #: 3900008185 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
HP98556 and STACKED SCREENS Mode: colormap hosed when server resets

Problem:  
Running a server in STACKED-SCREENS MODE with a HP98556 integer accelerator present causes problems. When the last client dies, the server resets, as expected. However, it also trashes the colormap in such a way that most everything goes black (in a stippled fashion - the mesh of the root window). Using the mouse to toggle between the two screens causes the colormaps to reset correctly.

Cause:  
The server will attempt to use the HP98556 if it is running when the server is started. If it is not running, but can be successfully started, the server will do so. There are some firmware difficulties in using the HP98556 and timing of toggling between the image and overlay planes in STACKED-SCREENS mode.

Temporary solution:  
Workaround:

None: Using a HP98556 in STACKED-SCREENS mode is not supported. One way to turn off the HP98556 is as follows:

- 1) Shut down the X system
- 2) Rename the HP98556 microcode file
- 3) Issue a "gopen (...; RESET\_DEVICE)". This will reset the HP98556 and cause it to reload its microcode. Since the file has been renamed, the reload will fail and the HP98556 will shut down.

To start the HP98556 again, rename the microcode file back to normal and issue the gopen again.

Note: If the HP98556 is not running, but the microcode file is present, the server will start the HP98556.

KPR #: 3900008193 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Server doesn't always handle "Unsorted" XSetClipRectangles correctly

Problem:  
The X lib procedure "XSetClipRectangles" allows the client to specify a set of rectangles in which to restrict rendering. The client must specify the ordering of the rectangles (Unsorted, YSorted, XSorted, YXBanded). Rectangles that are "Unsorted" are not always handled correctly.

KPR #: 3900008193 \*\*CONTINUED\*\*

Cause:  
The server always works with rectangles in YXBanded format. Rectangle lists specified in another format are converted to YXBanded. The algorithm to convert Unsorted rectangles to YXBanded is incorrect.

Temporary solution:  
Workaround:

Order the rectangles into one of YSorted, XSorted, or YXBanded.

KPR #: 3900008201 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Backing store is not deleted for depth 24 DHA windows

Problem:  
If a depth 24 window is registered for Direct Hardware Access, any backing store present is not deleted. Also, a request to create backing store for such a window is not denied. If the window is obscured and then exposed, the contents of the backing store will be drawn. This is only a problem if the DHA client can not render into the backing store.

Cause:  
The X server can render into depth 24 backing store. DHA Starbase clients can not. When a depth 24 window with backing store becomes registered for DHA, the server should delete the backing store. Similarly, if a depth 24 DHA client requests backing store, it should be denied.

Temporary solution:  
Workaround:

Before registering the window for DHA, explicitly delete any backing store via the XSetWindowAttributes library procedure.

KPR #: 3900008219 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
redMask in the Visual structure zero in stacked mode on SRX/TSRX

Problem:  
On the SRX (HP 98720/98721) and TSRX (HP98730/98731) displays, if the first screen of a Stacked Screen mode configuration has a visual class of DirectColor (i.e., its depth is either 12 bits double buffered, or 24 bits), then the ConnectionInfo that is transmitted to the client at XOpenDisplay time will have a bad value for the redMask of the DirectColor visual. The net result is that it is impossible to tell what bits of the Pixel actually define the red component.

Temporary solution:  
Workaround:

Reverse the order of the screens in the X?screens file.

KPR #: 3900008227 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

## One-line description:

Colors stored incorrectly in upper bank on TSRX double buffer mode

## Problem:

On the Turbo SRX display system (HP 98730/98731) if the X server is started in 12/12 double buffer mode (depth 24) then colors that are stored into the high bank will have the value intended for the green bank stored into the red bank, altering the red bank and leaving the green bank untouched. This problem should be unnoticeable in most cases. However, if the situation arises where a Starbase application is designed to utilize the X default colormap of the X server, then the display will flash with incorrect colors at each call to `dbuffer_switch()`.

## Temporary solution:

No workaround.

KPR #: 3900008235 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

## One-line description:

White RGB value incorrect on 98548 display

## Problem:

The value stored in the colormap for the color white for the 98548 display system is Red = 0xffff, Green = 0xffff, Blue = 0xffff. It should be 0xff00 for all three components to correctly match the rgb color database.

This results in being unable to allocate the color white. Thus a command such as the following will fail:

```
xsetroot -solid white
```

## Temporary solution:

No workaround.

KPR #: 3900008243 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

## One-line description:

On TSRX (hp98730/98731) some tiles are rendered incorrectly

## Problem:

On the Turbo SRX display system (HP98730/98731) tiles (patterns used for certain fill operation) whose width is between 16 and 23 pixels wide will not be rendered correctly. Visually, it looks as though only the left-hand portion of the tile is correct, with the right-hand portion looking like random data.

## Temporary solution:

No workaround.

KPR #: 3900008250 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

## One-line description:

Remnants of SB cursors left when obscuring/unobscuring window

## Problem:

On the Turbo-SRX, when an accelerated window with a Starbase cursor is being or will be obscured by another window (accelerated or not) that has a Starbase cursor in it, the cursor is not put down properly. This will happen even if the Starbase program is not accessing the device. The result is that pieces of Starbase cursors will be left on the screen.

## Temporary solution:

No workaround.

KPR #: 3900008268 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

## One-line description:

SB cursors in reserved planes are not turned off by the screen saver.

## Problem:

If a direct hardware access window has a Starbase cursor in it on the Turbo-SRX or SRX that cursor is not turned off by the screen saver.

## Temporary solution:

No workaround.

KPR #: 3900008276 Product: X11 800 ONLY 3.0/3.1 B1155A

00.03

## One-line description:

client clip ignored when rendering to obscured window with backing store

## Problem:

It is permissible for a client to specify that all rendering is to be contained within a sub-area of the window. This is called a client clip and is specified via the `XSetClipRectangles` or `XSetClipMask` client routines.

It is also permissible for a client to request backing store for a window. Any rendering to an obscured area of the window will then be directed to the backing store memory rather than discarded.

If both these options are in effect, any rendering outside the client clip area should be discarded and not rendered to the backing store. In the current product, this does not happen. Any rendering to an obscured area of the screen is directed to the backing store, irregardless of the client clip area. When the obscured area becomes visible, the unwanted rendering is copied from the backing store memory to the screen, creating an undesirable result.

## Cause:

The clip list that is passed to the SDI drivers contains two types of rectangles, "visible" and "obscured". A visible rectangle is a portion of the window that is visible. An obscured rectangle is a portion of the window that is obscured by another window, is offscreen, or is outside the client specified clip area. Rendering to a "visible" rectangle goes to the screen. Rendering to an "obscured" rectangle is discarded unless backing store is present in which case the rendering is



KPR #: 3900008276 \*\*CONTINUED\*\*

directed there.  
The union of all rectangles in the clip list covers the entire window. There is no way for the SDI drivers to distinguish between an "obscured" rectangle that is caused by window obscurity (and should be rendered to backing store) from an "obscured" rectangle caused by being outside the client clip area (and should ALWAYS be discarded!).

Temporary solution:  
Workaround:

One potential workaround is to use the 6.2/3.0 X11 Server instead. This defect has been introduced by the 6.5/3.1 Server implementation. However, using the 6.2/3/1 X11 Server will cause a loss of functionality present in the new product. If this is unsatisfactory, the customer should contact his HP Support representative. A server with the defect corrected will be supplied to the Support organization.

KPR #: 3900008284 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

If X server restarted, ScreenSaver time not initialized.

Problem:

Users of X can specify a timeout value for the server. If no input is received by the server during that time, a screensaver background pattern will be drawn over the X display.  
If the timeout value is reached, so that the background pattern is drawn, and then the last client exits, so that the server restarts itself and redraws the root window, the time used to determine when the server next saves the screen will be incorrect.

Cause:

The code that waits for input before checking to see if it is time to save the screen waits longer than the screensaver time.

Temporary solution:

Workaround:

Type a key or move the mouse after the server restarts.

KPR #: 3900008292 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

Multiple keycodes with same keysym in USASCII keymap.

Problem:

The X library provides functions to look up an X server keycode using a key symbol, and vice versa. In order for these to work correctly, there must be a one-on-one correspondence between keycodes and key symbols.

In the USASCII keymap, more than one keycode is defined to the same key symbol. The effect of this is that a client program can redefine a key symbol based on the keycode, then look up the key symbol that it has redefined, and still find it even though it should no longer be there.

KPR #: 3900008292 \*\*CONTINUED\*\*

Cause:

More than one keycode is defined to the same key symbol.

There are no keys on the USASCII keyboard that can generate the duplicate keycodes, so this is only a problem for client programs that redefine the affected key codes and then look up the key symbols that have been redefined. The affected key codes and key symbols are:

keycode	key symbol	description
0x14	KP_6	- the '6' key on the keypad
0x28	KP_6	- doesn't exist on the keyboard
0x1c	KP_3	- the '3' key on the keypad
0x29	KP_3	- doesn't exist on the keyboard
0x25	Kanji	- doesn't exist on the keyboard
0x83	Kanji	- doesn't exist on the keyboard

Temporary solution:

Workaround:

Be aware that if XChangeKeyboardMapping is used to redefine the key symbols associated with the affected keycodes, and XKeysymToKeyCode is then used to look up the symbol that was redefined, it will still be found and will be the second instance of that symbol.

KPR #: 3900008300 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

X Server error message: "Illegal state: prev\_stat=2 keycode=0".

Problem:

If you use a two-button mouse with the X server, and the X server is heavily loaded, it is possible to get an internal error message from the X server when pressing mouse buttons. The message is something like "Illegal state: pre\_state=2 keycode=0".

and indicates that a button has been lost by the HIL driver, so that the X server has seen two consecutive button down or button up codes.

Cause:

The HIL driver has a finite sized buffer. If the X server is busy and does not read from that buffer, and the user continues to move the mouse it is possible to cause that buffer to overflow. The result is that a button can be lost and the user needs to press that same button again to get the server to see it. There is usually no ill effect other than the irritation of seeing the error message and having to press the button again.

Temporary solution:

Workaround:

Make sure that standard error output from the server is redirected to a file so that it does not come to the console. If the server is slow



KPR #: 3900008300 \*\*CONTINUED\*\*

because it is busy, don't keep moving the mouse or banging on the buttons in an attempt to get its attention.

KPR #: 3900008318 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Compiler error when referencing XHPSTACKED\_SCREEN\_MODE constant

Problem:

If you use the XHPGetServerMode function to determine the mode of the server, a value is returned that should be compared to constants defined in <X11/XHPproto.h>. One of these constants, XHPSTACKED\_SCREEN\_MODE, is defined as STACKED\_SCREEN\_MODE. If you reference the constant XHPSTACKED\_SCREEN\_MODE, the compiler will report that STACKED\_SCREEN\_MODE is undefined.

Cause:  
STACKED\_SCREEN\_MODE is undefined. The constant that should have been used is STACKED\_MODE.

Temporary solution:  
Use the constant STACKED\_MODE instead of XHPSTACKED\_SCREEN\_MODE.

KPR #: 3900008326 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Last client termination MAY cause the X Server to abort

Problem:

When the last X client terminates, the X Server goes through a virtual reset. The Server may abort when during this virtual reset. We have one widget program which evidences this behavior. In most instances, the Server will successfully reset.

Temporary solution:  
Workaround:

Run an X Client which will not be terminated, like xclock. This will ensure that the Server will not go through the reset process.

KPR #: 3900008334 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
XOpenDisplay through local:0 disables access control of server

Problem:

When a client connects via the local:0 display specifier, it will disable the server's access control mechanism for an indeterminate period of time. Thus, unauthorized hosts can run clients against the server. This disabling will continue until some system error occurs within the server, resetting the global variable "errno."

Temporary solution:

Do not use the display specifiers local:0 or unix:0

KPR #: 3900008342 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
Gwind can hang when large number of windows are created.

Problem:

This defect can cause the gwind daemon to hang. gwind hangs when a about 50 graphics windows have been created. This is an unusually high number for a user, but not out of the question. This is a low frequency defect, with serious consequences.

We have placed a warning in our update.info file stating: Using more than 24 graphics windows at the same time can cause the gwind program to hang. Killing the gwind process is the best way to restore the ability to create graphics windows for starbase applications.

Temporary solution:  
Workaround:

The workaround is to kill the gwind process. This destroys the graphics windows and allows the user to start creating graphics windows again.

KPR #: 3900008359 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
xset gives error if pixel value is used outside of range 1-255.

Problem:

On direct color systems like the TurboSRX, if a large pixel value is used an error condition is generated. The expected behavior is that this operation should work.

Temporary solution:  
No workaround.

KPR #: 3900008367 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:  
xwud does not use the colors saved; it uses just the pixels

Problem:

Xwd saves the window contents along with the colormap; however, when xwud displays the saved contents, it ignores the colormap and instead uses the pixels.

Temporary solution:  
No workaround.

KPR #: 3900008375 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

HPwm leaves X server grabbed and forgets pending resize if menu pops up

Problem:

HPwm forgets about a pending window resize operation and leaves the X server grabbed if a button press causes a menu to pop up during the resize. The following line of my button bindings causes a menu to pop

KPR #: 390008375 \*\*CONTINUED\*\*

up for button 3 presses in the window frame area. If I start a resize with a menu then press button 3 while over a frame area the pop up menu is displayed. When button 3 is released the menu is removed and the resize is no longer occurring. The server is still grabbed, preventing clients from running.

Temporary solution:

The window manager will umgrab the server if another resize is done on any window.

KPR #: 390008383 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

XtNttitlePosition defined differently for 2 different widgets

Problem:

The resource XtNttitlePosition is defined differently for 2 different widgets:

Cascade - type int  
uses XwTOP, XwBOTTOM or XwBOTH

TitleBar -

type int  
seems to use numbers different from the enum  
values above

Temporary solution:

No workaround.

KPR #: 390008391 Product: X11 800 ONLY 3.0/3.1 B1155A 00.03

One-line description:

Remnants of SB cursors left when obscuring/unobscuring window

Problem:

On the Turbo-SRX, when an accelerated window with a Starbase cursor is being or will be obscured by another window (accelerated or not) that has a Starbase cursor in it, the cursor is not put down properly. This will happen even if the Starbase program is not accessing the device. The result is that pieces of Starbase cursors will be left on the screen.

Temporary solution:

No workaround.

KPR #: 390009035 Product: X11 800 ONLY 3.0/3.1 B1155A B3.00

One-line description:

loader fails on s800 due to duplicate uLitoR8 routines

Problem:

There is a routine called "uLitoR8" which is duplicated on both the libXw.a and libXhpl1.a libraries. It is used to translate ISO Latin 1 characters to HP Roman8 characters, it is in both libraries

KPR #: 390009035 \*\*CONTINUED\*\*

since an application developer might use HP widgets without HP extensions, or vice versa, and need the routine.

The problem occurs when a program uses both HP widgets and HP extensions, and is compiled on a series 800. If you do this on a series 300, the compiler issues a warning, "duplicate entry points", then resolves the uLitoR8 external reference against whichever library (libXhpl1.a or libXw.a) is specified first and produces a valid executable binary. On the series 800, the compiler aborts after issuing the warning.

Temporary solution:

The work-around is as follows:

- 1) Compile your program with -c to produce relocatable object files (suppressing the link edit phase of the compile).  
e.g. "cc -c foo.c" produces "foo.o".
- 2) Invoke the loader explicitly to link in the first library, but still produce a relocatable object file as a result (no undefined symbols will be reported).  
e.g. "ld -r -lXhpl1 foo.o" produces a new "foo.o" with routine by marking it as "local".
- 3) Invoke the loader explicitly a second time to hide the resolved routine by marking it as "local".  
e.g. "ld -r -h uLitoR8 foo.o" produces a new "foo.o" with the "uLitoR8" external reference hidden for future links
- 4) Invoke the loader explicitly one last time to resolve the rest of the unresolved externals and produce an executable binary.  
e.g. "ld -o foo foo.o -lXw -lX11" produces the executable binary "foo" with the "uLitoR8" routine referenced only once.

KPR #: 3900006072 Product: X11 WINDOWS 6.2/3.0 B1152A 00.00

One-line description:  
TextEdit forgets Leave callback if highlight\_traversal is set

Problem:  
If the traversal\_type resource for a TextEdit widget is set to highlight\_traversal, then when the cursor leaves the instance, the widget does not invoke its Leave callback: it assumes that since traversal is on, leaving the widget is meaningless - when we actually get a focus out event (because the cursor left the topmost widget) we will invoke our Leave callbacks.

Temporary solution:  
WORKAROUND: NONE

KPR #: 3900006122 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TextEdit Widget leaves highlight droppings

Problem:  
When typing into a StaticText 3D widget with traversal on and you reach the righthand border, the old traversal highlight is not erased when new one is drawn as the widget grows.

Temporary solution:  
No workaround.

KPR #: 3900006130 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Form doesn't size itself correctly for certain sets of constraints.

Problem:  
A problem occurs when there is a constraint set whose widget on the end is shorter than an intermediate widget.

Temporary solution:  
workaround:

This can generally be gotten around by referencing the constraints in a different manner to ensure that the end child in the constraint set is the longest.

KPR #: 3900006148 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Toolkit generates warnings if widgets put in empty slots of listwidget.

Problem:  
If a list widget is created with children explicitly put in row, columns, then destroy those children, then create new children with the same explicit row, columns, the toolkit generates warnings, saying user is putting widgets in places already taken/occupied.

Temporary solution:

KPR #: 3900006148 \*\*CONTINUED\*\*

No workarounds.

KPR #: 3900006155 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
SWindow doesn't propagate all resources to its children.

Problem:  
If a scrolled window is created, and a background pixel is specified within the arglist, the scrollbars will inherit this value, but the bulletin board will not. If one child inherits its, all of them should.

Temporary solution:  
Workaround:

From defaults file: (include following two lines)  
\*Scrolled Window, Bulletin Board  
background: [value]

KPR #: 3900006163 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Select up key can be lost causing incorrect widget state.

Problem:  
This occurs when the select key is pressed and the cursor is moved out of the widget hierarchy, and the select key is released. The select up will be lost.

Temporary solution:  
No workaround.

KPR #: 3900006171 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TextEdit does not handle returns followed by backspaces correctly.

Problem:  
While editing a field, any field within a textEdit widget, hit return then try to backspace up past the return. It doesn't allow it.

Temporary solution:  
Workaround:

Use [Ctrl][P] to move to previous line.

KPR #: 3900006189 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Shell doesn't account for border width of its child.

Problem:  
Create a wide-bordered child of a shell. The shell ignores the borders on the top and left hand sides.

KPR #: 3900006189 \*\*CONTINUED\*\*

Temporary solution:  
Workaround:

Put the wide-bordered child inside a frame.

KPR #: 3900006197 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

The 2 byte string "\n" is treated as a newline like the 1 byte '\n'.

Problem:

When loading a string into the StaticText widget (or the list widget or anything else that uses static text) loading a string that includes the two byte sequence '\n' causes the one byte '\n' (newline) to be put in the widget. The man page documents that this will be the case when the string comes from the .Xdefaults, but not when set programmatically.

Temporary solution:  
No workaround.

KPR #: 3900006205 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

StaticRaster will choose it's size wrong.

Problem:

If the image is sent to the StaticRaster via SetValues, and if shadow is OFF, and if there is a non-zero highlight thickness, the StaticRaster widget chooses its size two highlight thicknesses too small.

Temporary solution:  
No workaround.

KPR #: 3900006213 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

Certain increments of highlight thickness can be lost.

Problem:

Primitive and Manager lose highlight thickness increments of 2 greater than the current thickness when shadow is on. They also lose increments of 2 less than the current if both the thickness is decreased and the shadow is turned off.

Temporary solution:  
Workaround:

Don't change highlight thickness by increments of 2.

KPR #: 3900006221 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

Vpane Widget setting invalid padding and border\_frame causes Xtoolkit Er

Problem:

- X11 WINDOWS 6.2/3.0 -

KPR #: 3900006221 \*\*CONTINUED\*\*

Setting large negative values for padding and/or frame causes Xtoolkit error and aborts program.

Temporary solution:  
No workaround.

KPR #: 3900006239 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

Shell: a realized shell doesn't resize to the size of its new children

Problem:

When the shell is realized and a child is created to go in the shell, the shell doesn't resize to the size of it's child when a child is created. It also won't change during SetValues of the child if the height or width doesn't change if the shell is previously realized. (i.e if the width changes the changeMask is only set to change the width, thus the shell resizes to the width and the height doesn't change. This results in a funky looking display) If the child needs to be larger than the shell at creation time, the child is clipped. (e.g. a button will not display all of it's label if the label extend beyond the width set for the shell.) Note: All these problems occur when the shell is previously realized and a new child is being created with the realize shell as the parent.

Temporary solution:  
Workaround:

Make sure shell isn't realized when you insert the child.

KPR #: 3900006247 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

Swin: produces a valuator warning on some resizing.

Problem:

When resizing is done and the scrollbars are unnecessary, the scrolled window sometimes (not consistently) produces the following X-Toolkit warning:

X Toolkit Warning: Valuator: the origin is less than the valuator min or greater than the valuator max minus the valuator extent.

Temporary solution:  
No workaround.

KPR #: 3900006254 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

XtWinsetPosition is defined for both TextEdit and Manager classes.

Problem:

When creating a text edit widget within a row column manager, if the application specifies the XtInsetPosition resource, with the intention of setting the text insertion position within the text edit widget, it

- X11 WINDOWS 6.2/3.0 -

KPR #: 3900006254 \*\*CONTINUED\*\*

will also cause the Manager class to use this value as an indication of where within the parent's child list this child should be placed.

Thus, if this resource is set to 0, the cursor is placed at position 0, and the text edit widget is placed as the first child within its parent. Workaround:

If you want to control the positioning of the widget within its parent's list of children, the use XtNinsertPosition resource at create time. If you want to control the TextEdit cursor position, then create the widget without this resource, the use SetValue to edit the XtNinsertPosition resource.

Temporary solution:  
Workaround:

If you want to control the positioning of the widget within its parent's list of children, the use XtNinsertPosition resource at create time. If you want to control the TextEdit cursor position, then create the widget without this resource, the use SetValue to edit the XtNinsertPosition resource.

KPR #: 3900006262 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TextEdit: Editing text in middle of buffer messes up selection.

Problem:  
When editing in the middle of the text buffer, the text at the end of that line and at the end of all subsequent lines is not selectable.

Temporary solution:  
No workaround.

KPR #: 3900006270 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TextEdit: Doesn't reset margins when highlight\_thickness changes.

Problem:  
TextEdit: Doesn't reset margins when highlight\_thickness changes.

Temporary solution:  
Workaround:

Reset Left and Right margins to Highlight\_thickness + 3.  
Reset Top and Bottom to Highlight\_thickness.

KPR #: 3900006288 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TextEdit: clears an area of shadow on inputting characters.

Problem:  
If the size of the TextEdit widget isn't large enough to accommodate the

KPR #: 3900006288 \*\*CONTINUED\*\*

text, an area of the shadow can be cleared on text entry.

Temporary solution:  
Workaround:

Make widget larger taking into account font size, amount of text, highlight thickness and border size.

KPR #: 3900006296 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

TextEdit Widgets occasionally drop the first char of a line of text.

Problem:

After a TextEdit widget is resized, if text needs to be wrapped around, the first character of the text that was wrapped will be dropped.

Temporary solution:  
No workaround.

KPR #: 3900006304 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Assorted TextEdit code deficiencies.

Problem:  
- XtTextCopySelection does not return a character pointer.  
- XtTextCopySubString does not return a character pointer.  
No workaround.

Temporary solution:  
No workaround.

KPR #: 3900006312 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
XtNfile resource cannot be modified through SetValues.

Problem:  
The XtNfile resource is defined at create time and cannot be changed later by SetValue in order to view/edit a different file.  
Workaround:

To edit a different file than is currently specified by XtNfile, first read the file into a buffer, then use StringSrc to read the buffer into XtNstring which can then be viewed and/or edited. The XtNfile resource is defined at create time and cannot be changed later by SetValue in order to view/edit a different file.  
Workaround:

To edit a different file than is currently specified by XtNfile, first read the file into a buffer, then use StringSrc to read the buffer into XtNstring which can then be viewed and/or edited.

Temporary solution:

KPR #: 3900006312 \*\*CONTINUED\*\*

Workaround:

To edit a different file than is currently specified by Xtnfile, first read the file into a buffer, then use StringSrc to read the buffer into XtNstring which can then be viewed and/or edited.

KPR #: 3900006320 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
The macro DefaultDepth returns incorrect depth on many displays.

Problem:  
Instead of returning the number of color planes, the server will return the number of bits used internally to represent one pixel.

Temporary solution:  
Workaround:

The client should inspect the value returned for the number of color cells.

KPR #: 3900006338 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Deleting translations can cause problems.

Problem:  
A set of translations can be supplied for a complete class of widgets (i.e. for all Pushbutton widgets). This works fine as long as the user doesn't ever delete one of the pushbuttons; as soon as this happens, a core dump will occur the next time a new pushbutton is created.

Temporary solution:  
Workaround:

There are two workarounds:

1. If it is necessary to specify new translations for an entire class of widgets, then do not destroy widgets of this class within the application.
2. Specify new translations for specific named widgets, rather than for the entire widget class.

KPR #: 3900006346 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TextEdit: Segmentation Fault when Writing from empty cut buffer.

Problem:  
When using the textedit widget with an empty cut buffer and the user tries to paste with [Ctrl][V] or [Shift][V], a segmentation fault will occur.

Temporary solution:

KPR #: 3900006346 \*\*CONTINUED\*\*

No workaround.

KPR #: 3900006353 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Spring-loaded popup widgets don't interact well with keyboard focus.

Problem:  
If the Xtk keyboard focus is currently pointed at a particular widget, and the user initiates an action which causes a popup menu to be posted (as spring loaded and exclusive grab), the widget with the keyboard focus never dehighlights itself or removes its focus entry from the grablist; this can cause strange things to happen as the user moves through the popup menu. The problem occurs because the current focus widget never receives its LeaveNotify event, because by the time it is dispatched, the focus widget is not part of the currently active grablist, so the event (which is of type ignore) is discarded.

Temporary solution:  
Workaround:

Before anything is put on the grablist, create a fake focus\_out event and dispatch it to the top level shell.

KPR #: 3900006361 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:

Destroying popup children, then their parent widget, dumps core.

Problem:  
Recently, a fix was added to the toolkit which cleared up many of the problems associated with destroying popup widgets. Unfortunately, the fix has itself introduced several new bugs (refer to another shell destroy bug I submitted last week). All of the problems I have encountered occur as a result of the fact that the core and shell destroy procedures attempt to use the popup children list to store the window Ids for the popup children being destroyed.

To properly fix these bugs, we need to add two new fields to the core instance structure; a pointer to an array of window Ids, and a count of the number of entries in this array. We shouldn't attempt to use the popup list to contain both widget and window Ids. The problem occurs when the XtDestroyWidget() call is made for the widget, it attempts to recursively destroy all other widgets descending from it. Unfortunately, its popup children have already been destroyed, and the widget's popup list now contains the window Ids for its children, instead of the widget Ids for its children. When XtDestroyWidget() tries to recursively destroy the widgets, it dumps core because it tries to treat a window Id as a widget Id.

Temporary solution:  
Workaround:

Destroy parent only (not children).

KPR #: 3900006379 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
TextEdit forgets Leave callback if highlight\_traversal is set

Problem:

If the traversal\_type resource for a TextEdit widget is set to highlight\_traversal, then when the cursor leaves the instance, the widget does not invoke its Leave callback; it assumes that since traversal is on, leaving the widget is meaningless - when we actually get a focus out event (because the cursor left the topmost widget) we will invoke our Leave callbacks.

Temporary solution:  
No workaround.

KPR #: 3900006403 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Malloc failure causes Server to terminate.

Problem:

The ddx calls in the Server often needs to malloc memory.

If the malloc calls fail then the Server may terminate. This only happens when the system has run out of memory. When the system is that sick there may be no easy solution. However, the desired behavior would be to return an error code to DIX that made the call, and then DIX would return an X error to the X Client.

Temporary solution:  
No workaround.

KPR #: 3900006411 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
DisplayHeightMM() and WidthMM() return same values for all displays.

Problem:  
No problem text.

Temporary solution:  
No workaround.

KPR #: 3900006429 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
keysyms for left and right quote on german keyboard are backwards.

Problem:  
No problem text.

Temporary solution:  
No workaround.

KPR #: 3900006437 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
XGrabPointer will not confine to a root window

Problem:

Due to the fact that a pointer sprite which is defined for a particular screen will not work on another screen, I attempted to issue an XGrabPointer() using a confine to window of DefaultRootWindow(dpy) (otherwise, if you move off the screen, the sprite changes to something that no longer indicates an active grab is in progress).

Anyway, if the confine to window is at the edge of the screen (this applies to the root window as a special case, but happens with other confine\_to windows that are adjacent to the edge of the screen), the confine does not work and the pointer can be dragged to the other screen.

Temporary solution:  
No workaround.

KPR #: 3900006445 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
root-window backing store malfunctions

Problem:

I have a report that turning on backing store for the root window can cause strange stuff to appear in the root window.

Temporary solution:  
Workaround:

Not a recommended practice to turn on backing store in root window.

KPR #: 3900006452 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
SRX server in stacked mode leaves the wrong screen showing at startup.

Problem:  
SRX server in stacked mode leaves the wrong screen showing at startup.

Temporary solution:  
Workaround:

Move the mouse continuously left or right until you see the X cursor. At that point operation is normal.

KPR #: 3900006460 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

Text output causes mouse cursor to flicker even if window is unmapped.

Problem:

Output to windows may cause mouse cursor flicker even if the cursor is not in direct contact to the output region.

KPR #: 3900006460 \*\*CONTINUED\*\*

Temporary solution:  
No workaround.

KPR #: 3900006478 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
rtprio on any X process can cause deadlock.

Problem:  
rtprio on any X process can cause deadlock.

Temporary solution:  
Workaround:

rtprio should not be used in conjunction with X windows.

KPR #: 3900006486 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
XSetModifierMapping allows duplicate key codes in a keymap.

Problem:  
The documentation for XSetModifierMapping specifies that a keycode may not appear more than once in the map. Using 'xmodmap', a user may specify the same keycode for the two different modifiers. Now 'xmodmap' keeps its own copy of a key map, modifying it with the parameters given to it by the user and then at the end it calls XSetModifierMapping. At this point, if the same keycode appears more than once in the map given to XSetModifierMapping, I would expect the routine to return an error since the Xlib manual specifies that "no keycode may appear twice in the entire map". Needless to say, XSetModifierMapping does not return an error, but accepts the map as is. When 'xmodmap' is used to print the current map, the keycode is listed twice.

Example:

```
xmodmap +4 Shift_R +5 Shift_R
xmodmap
```

The first command will place Shift\_R in the modifier FOUR and FIVE. If you are using the default mapping, Shift\_R will also show up in the SHIFT modifier.

Temporary solution:  
Workaround:

Make sure there are no duplicate key codes.

KPR #: 3900006494 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Output to UNMAPPED window (with BackingStore) NOT there when W is mapped

Problem:  
Backing store is not turned on until window gets an expose event.

KPR #: 3900006494 \*\*CONTINUED\*\*


Windows don't get this event until they are mapped. Window backing store will ignore all output until exposed.

Temporary solution:  
No workaround.

KPR #: 3900006502 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
CopyPlane, CopyArea and backing store may not copy everything

Problem:  
There is a bug with the backing store implementation (which also exists in R2): CopyPlane window W1 (area A obscured) to window W2 (area B obscured) and area C (the intersection of A and B) will be ignored (ie miBSCopyPlane() (via miHandleExposures) which tuned around and called miBSCopyPlane() to render to area C but since miBSCopyPlane() had set pPriv->inUse, nothing was rendered.



Very likely the same window to window CopyPlane bug exists for CopyArea.

Temporary solution:  
No workaround.

KPR #: 3900006510 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
XQueryColors Xlib function returns incorrect results

Problem:  
The colormap values appear to get converted from their hardware representation to their X domain short int representation. The conversion seems to be done by shifting left by 8 bits or multiplying by 256. This will improperly cause a full intensity 0xFF hardware value to appear as 0xFF00, or a very light grey (dim white?), after conversion.

The X documentation clearly states that the full intensity value should be 0xFFFF. If 257 is used for the conversion constant the hardware-to-X mapping will be equally spaced values from 0..0xFFFF.

Temporary solution:  
No workaround.



KPR #: 3900006528 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

Popping up a uwm menu over a bitmap grid can black out grid markers.

Problem:

Place a bitmap grid, then do a 'set all'. Pop-up a uwm menu over the grid then select move and move from the grid, intervening lines will stay black and move from the grid, intervening lines will stay black instead of changing back to white.

Temporary solution:

Workaround:

Refresh display.

KPR #: 3900006536 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

hpterm dies when changing colors if colormap is full

Problem:

When user is using escape sequences to change colors and the colormap is full, hpterm will die.

Temporary solution:

No workaround.

Make sure colormap is not completely full when changing colors.

KPR #: 3900006544 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

hpterm ignores 'STOP' key.

Problem:

When the old X10 hpterm border was removed from hpterm, the code to toggle xon/xoff mode was removed as well.

Temporary solution:

No workaround.

KPR #: 3900006551 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

In hpterm, <esc>&JA displays the wrong menu (should be modes).

Problem:

Displays top level menu instead of the Modes menu.

Temporary solution:

No workaround.



KPR #: 3900006569 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

In hpterm, cursor is left in incorrect position after processing <esc>d

Problem:

After processing an enter (via <esc>d), hpterm should leave the cursor in column 0. It leaves it in the same col as when the processing began.

Temporary solution:

No workaround.

KPR #: 3900006577 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

In hpterm, pastes of >-512 chars drop data (s800 only).

KPR #: 3900006585 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

In hpterm, <esc>a can not return a row >999.

Problem:

In hpterm, <esc>a can not return a row 999.

Temporary solution:

Workaround:

Use rows of less than 999.

KPR #: 3900006593 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

hpterm display messages are over written by status block.

Problem:

When a status message is displayed in the softkey window (via <esc>j<len>L<msg>, the center status block will overwrite it if insert char mode is entered (or anything else that modifies it).

Temporary solution:

No workaround.

KPR #: 3900006601 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:

When hpterm gets a soft reset, the cursor is left off

Problem:

When hpterm gets a soft reset, the cursor is left off.

Temporary solution:

Workaround:

Hit a character and cursor returns.

KPR #: 3900006619 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Bitmap with-nodashed, then do invert all results in lines becoming dots

Problem:  
Using bitmap with -nodashed, then do invert all results in lines becoming dots.

If bitmap is started with the -nodashed option and the user then specified 'invert all', the solid lines become dots.

Temporary solution:  
No workaround.

KPR #: 3900006825 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Gwind daemon left running if given invalid display argument

Problem:  
If gwind is given an invalid display argument, the resulting error condition will leave the gwind daemon running, instead of terminating.

Temporary solution:  
Workaround:

Kill the gwind process if this error occurs.

KPR #: 3900006833 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Gwind doesn't handle negative geometry positioning, off by border width

Problem:  
Gwind doesn't handle negative geometry positioning, off by border width.

Temporary solution:  
Workaround:  
Place windows with positive coordinates.

KPR #: 3900006841 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Gwindstop does not accept multiple directories

Problem:  
The documentation indicates that gwind can handle multiple directories, however, only one directory is processed.

Temporary solution:  
Workaround:

Specify multiple 'gwind dir' for each desired directory.

KPR #: 3900006858 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Gwindstop doesn't return nonzero status when destroying nonexistent wind

Problem:  
Gwindstop is not indicating that a window was not successfully destroyed by returning the correct exit status. Instead the status is zero, indicating the window destroy was successful when the window was nonexistent

Temporary solution:  
No workaround.

KPR #: 3900006866 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
rgb returns status 0 for illegal color names/values

Problem:  
rgb is not indicating an error status if an illegal color name or value is used.

Temporary solution:  
No workaround.

KPR #: 3900006874 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Can't resize info when resizing windows with large borders

Problem:  
For some large borders on windows that are being resized, the pop-up resize info window sometimes does not appear.

Temporary solution:  
No workaround.

KPR #: 3900006882 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
Using xclock with option, chime only beeps once on the hour, not twice.

Problem:  
Using xclock with option, chime only beeps once on the hour, not twice.

Temporary solution:  
No workaround.

KPR #: 3900006890 Product: X11 WINDOWS 6.2/3.0 B1152A

00.03

One-line description:  
xfc doesn't complain if both -l and -m options at same time

Problem:  
xfc doesn't complain if both -l and -m options at same time.

KPR #: 3900006890 \*\*CONTINUED\*\*

Temporary solution:  
Workaround:

User should only specify one of the options: -m or -l.

KPR #: 3900006908 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
All special properties have parsing problems in xfc.

Problem:  
The validity of data specified for special properties is not checked by xfc.

Temporary solution:  
Workaround:

The user must ensure that special property data is correct.

KPR #: 3900006916 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Man page example for xinit is wrong:---1... is wrong;(should be --:1)

Problem:  
man page examplefor xinit is wrong: ... -- 1 ... is incorrect; (should be --:1)

Temporary solution:  
No workaround.

KPR #: 3900006924 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Default screen is used if an invalid screen number is given.

Problem:  
If invalid screen number is given in [hostname:display.screen] default screen is used instead of returning error.

Temporary solution:  
No workaround.

KPR #: 3900006932 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Wrong message given when using xmodmap -n -e.

Problem:  
If using xmodmap with options -n & -e, the message appears telling the user 'add @=9' instead of the correct message 'add shift = 9'.

Temporary solution:  
No workaround.

KPR #: 3900006940 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
A bad keysym when using xmodmap does not terminate with error.

Problem:  
If a bad keysym is found when using xmodmap, the processing continues for all the valid keysyms. The desired behavior is to terminate and not make any changes to the mappings if there is an invalid keysym.

Temporary solution:  
Workaround:

Use the option -n to check the validity of the mappings without changing them.

KPR #: 3900006957 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
When using Xmodmap, X protocol error can result vs. correct error message

Problem:  
If using an invalid expression in xmodmap, such as: 'keycode 4 = 9', an X protocol error is generated instead of an 'expression wrong' error message.

Temporary solution:  
No workaround.

KPR #: 3900006965 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
X11start man page doesn't mention \$PATH is changed.

Problem:  
The man page for x11start does not indicate that it will modify the PATH variable to assure that /usr/bin/X11 is in the users PATH variable in front of /usr/bin.

Temporary solution:  
No workaround.

KPR #: 3900006973 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Xwcreate returns status of 0 even if there was an error.

KPR #: 3900006981 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
-inverse option in xwd doesn't work on a monochrome display.

KPR #: 3900006999 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
In using xwcreate, color parameters expect pixel indices not rgb values

Problem:  
When specifying color for background or border, xwcreate expects pixel indices only and not rgb values

Temporary solution:  
No workaround.

KPR #: 3900007005 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TextEdit: Changing fonts using setvalues dumps core on input or bspace.

Problem:  
When the font is changed using setvalues, the font appears to change (cursor spacing changes) but what is displayed is incorrect. Upon entering a second character on the series 300's it dumps core with a segmentation fault. On the series 800's it doesn't dump core until an attempt is made to backspace all the characters.

Neither the new font nor the old font is actually displayed when the font is changed. A quick blink of the inserted characters is shown inserting each new character.

Temporary solution:  
No workaround.

KPR #: 3900007013 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
TurboSRX server 'forgets' current cursor if moved out of then into scree

Problem:  
When using the TurboSRS server on the series 300, I noticed the following behavior:

<NOTE: I had both an overlay and image server running>

- 1) Run a program, and wait for the window manager to change the cursor to the one used to prompt the user to place a window.
- 2) Move the cursor off the edge of the screen, and into the other screen.
- 3) Re-enter the original screen.  
The cursor is now the regular 'cross' cursor instead of the cursor it was when we left the screen.

Temporary solution:  
No workaround.

KPR #: 3900007021 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Blow through on screen when non font file name 'filename.scf'.

Problem:  
When a non font file with the suffix '.scf' is given as a font parameter to a client, a message is blown through on the screen.

"stdin: not in compressed format"

The screen is scrolled and generally ugly looking, though a refresh will restore the screen to its proper configuration. Unfortunately, I don't know how many customers will realize that is all it takes to clean up the screen.

Temporary solution:  
Workaround:  
Repaint the screen to restore.

KPR #: 3900007039 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
XFillArc() does not handle negative angles properly.

Problem:  
The following short program illustrates several cases where attempting to fill an arc using a negative (clockwise) angle causes incorrect results to be displayed. The problem is also affected by the choice of starting angle; note that some clockwise arcs are filled correctly, depending on their starting angle.

```
#####  
#include <X11/Xlib.h>
```

```
main()
```

```
{  
    Display *dpy;  
    int scrn;  
    GC gc;  
    Window win, root;  
    XEvent event;  
    unsigned long fg, bg;
```

```
    dpy = XOpenDisplay ("unix:0.0");  
    scrn = DefaultScreen(dpy);  
    root = DefaultRootWindow(dpy);  
    fg = WhitePixel(dpy, scrn);  
    bg = BlackPixel(dpy,scrn);  
    win = XCreateSimpleWindow(dpy, root, 10, 10, 200, 100, 4 fg, bg);  
    XSelectInput(dpy, win, ExposureMask);  
    XMapWindow(dpy, win);  
    XNextEvent(dpy, &event);  
    gc = DefaultGC(dpy, scrn);
```

KPR #: 3900007039 \*\*CONTINUED\*\*

```
XSetBackground(dpy, gc, bg);
XSetForeground(dpy, gc, fg);

XFillArc(dpy, win, gc, 25, 25, 20, 25, 90*64, -360*64); /* Fails */
XFillArc(dpy, win, gc, 75, 25, 20, 25, 0*64, -360*64); /* Fails */
XFillArc(dpy, win, gc, 25, 75, 20, 25, 90*64, -350*64); /* Fails */
XFillArc(dpy, win, gc, 75, 75, 20, 25, -90*64, -360*64);
XFillArc(dpy, win, gc, 125, 25, 20, 25, 0*64, -270*64);
XFillArc(dpy, win, gc, 175, 25, 20, 25, 0*64, -300*64);
XFillArc(dpy, win, gc, 125, 75, 20, 25, 90*64, -300*64); /* Fails */
XFillArc(dpy, win, gc, 175, 75, 20, 25, 45*64, -360*64); /* Fails */
XSync(dpy);
XSelectInput(dpy, win, ButtonPressMask);
XNextEvent(dpy, &event);
}
```

Temporary solution:  
No workaround.

KPR #: 3900007047 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Problems with stippling a bitmap

**Problem:**  
Four bitmaps are created -- a 32x32 bitmap containing lines forming an "X", a 32x32 bitmap containing lines forming a "+", a 32x32 bitmap containing lines forming a "x", a 32x32 bitmap used as a stipple pattern to fill a fourth 300x300 bitmap. Also, a window is created to display the final fourth bitmap. The action goes as follows: as soon as the bitmaps are created and correctly initialized, the "X" bitmap is copied to the stipple bitmap. The large bitmap is then filled with the stipple pattern and then displayed (via copy plane) to the window. This phase works correctly, displaying a lot of little "X"s in the window. Next, the "+" bitmap is copied to the stipple bitmap, and then the large bitmap is filled again. The large bitmap is also displayed again. This should display a lot of "+"s in the window, but it does not, instead displaying the original "X"s.  
The problem is that the large bitmap is not being updated correctly. If a fill operation is made with a different bitmap, and then the stipple bitmap is used again, things work fine.

Temporary solution:  
No workaround.

KPR #: 3900007054 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Problem w/ copy plane from window to bitmap.

**Problem:**  
There is a bug in copy plane when the source is a window, the destination is a bitmap, and the destination region is something other than 0,0. First, a window is created, mapped, and an "X" is drawn into it. The program then waits for a mouse event. Then a portion of the

KPR #: 3900007054 \*\*CONTINUED\*\*

Window is copied from 0,0 into a bitmap, and the contents of the bitmap is immediately redisplayed to the window. The program will then wait for another mouse event. The copying is then repeated, but this time the window is copied from 100, 100 to the bitmap. The program then waits for a final mouse event.

The correct results of this program is that the window should not appear to change, since portions of the window are being copied to a bitmap and then immediately copied back. What happens is that the first copy / copy back works correctly, but the second one does not, resulting in a hole in the "X".

Temporary solution:  
No workaround.

KPR #: 3900007062 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Problem with copy-area to window with neg. co-ords.

**Problem:**  
There is a bug with copy-area to a window. It will create and map a window, then follow any cursor motion in that window with a "butterfly", a figure which draws two boxes -- one with the upper left corner at the cursor and another with the lower right corner at the cursor.

The bug is that if the "butterfly" is moved off the screen towards the upper left corner of the window, parts of the upper box get erased. The closer the cursor gets to the corner, the more of the box which gets erased. This erasure is caused by negative coordinates being passed to copy-area.

Temporary solution:  
No workaround.

KPR #: 3900007070 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
XDrawLines chokes on duplicates in array of points.

**Problem:**  
When a stream of points is fed to XDrawLines that contains sequential points that have identical X and Y values, the polyline is terminated on that point. The rest of the array of points is silently ignored.

To illustrate this behavior use two static arrays of points. The first array has three sets of duplicate points; the second array is identical, except the duplicate points have been removed. The program creates a window and clears it, pauses for 5 seconds, attempts to draw the first array of lines (this fails; only the first quarter of the array is drawn), pauses for 5, then draws the second array (which works).

This is a big problem for us, as we are using a smoothing algorithm to process some data and generate the list of points; sometimes the algorithm generates multiple duplicate points like this. The static

KPR #: 3900007070 \*\*CONTINUED\*\*

array of points used here is an example of points generated by the algorithm.

KPR #: 3900007088 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Xwininfo returns status of 1, even if there was no error.

KPR #: 3900007104 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Inconsistent handling of vertices in 0-width polyline

Problem:  
Drawing of zero-width polylines to windows (performed with hp code) draws each vertex exactly once. Drawing of the same to pixmaps (performed with mi code) draws non-terminal vertices twice. Results can differ between windows and pixmaps when the replacement rule is XOR (or any other alu with binary value 10xx or xx10).

This was observed with a rectangular polyline -- only vertical and horizontal lines. I don't know what happens for other cases.

Temporary solution:  
No workaround.

KPR #: 3900007112 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
SetValues of TitleBar's internal StaticText widget causes memory fault.

Problem:  
None.

Temporary solution:  
Instead of having the TitleBar create the static text widget, create it yourself. You may then do your own set values without core dumps.

KPR #: 3900007120 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Xserver can crash on XCopyPlane when dealing with depth 1.

Problem:  
XCopyArea may fail and crash server when dealing with depth 1 (width is multiple of 8, source != , source (x,y), and dst (x,y) == (0,0)). Clipping may fail and copy too much. This can happen when the user requests that more data be copied than actually exists. The problem shows up in XCopyPlane because it calls XCopyArea.

Temporary solution:  
Workaround:

Don't try to copy more data than exists.

KPR #: 3900007138 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
XputImage on fireye sometimes munges offscreen memory.

Problem:

The problem was observed when some characters in the fixed font were somewhat mangled.

Temporary solution:  
No workaround.

KPR #: 3900007146 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
display enhancements in hpterm not always displayed the same as terminal

Problem:

Enhancement requests do not handle the case of no characters being placed on the screen where the enhancement request is placed. The standard terminals handle this by blank filling to reach wherever and enhancement request is placed. This has come up in several cases. Sample requests are included. You can also see the problem when using JYACC or same.

Put the next nine lines in a file:

ESC@a0c10YESCKESC@a1c10YESC@dESC@a-ICESC@dJESC@a\*79c10YESC@dJESC@a1c12Y  
ESC@a0c11YESCKESC@a1c11YESC@dESC@a-ICESC@dJESC@a\*79c11YESC@dJESC@a1c13Y

ESC@a0c10Y  
ESC@dJ  
ESC@d@  
ESCK

Put the next nine lines in a file:

ESC@a0c10YESCKESC@a1c10YESC@dESC@a-ICESC@dJESC@a\*79c10YESC@dJ1ESC@a1c12  
Y  
ESC@a0c11YESCKESC@a1c11YESC@dESC@a-ICESC@dJESC@a\*79c11YESC@dJ2ESC@a1c13  
Y

ESC@a0c10Y  
ESC@dJ  
ESC@d@  
ESCK

Change the sequence ESC to the escape character.

Dump each file to a standard terminal and to hpterm and not that on hpterm you do not get an enhancement at the end of the line for the first file.

Temporary solution:  
No workaround.

KPR #: 3900007153 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
finnish keyboard doesn't work with 'Product-Line' software

Problem:  
7-bit European characters don't seem to be working correctly for input.  
Temporary solution:  
No workaround.

KPR #: 3900007161 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Reading multi-line translations in resource files returns wrong \$ length  
Problem:  
With multi-line translations read in from a resource file, the length of the translation string (as passed to \_CompileTranslations) is wrong.

This looks like a problem in Xrm.c, PutLineResources(). When it parses a string in a resource file like:

```
*translations: <Btn2Down>: select()\n<Btn2up>: release()
```

the count is incremented by 3 when the "\n" is processed, rather than 1.

KPR #: 3900007179 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
XPutImage does not work correctly with shorts.

Problem:  
No problem text.  
Temporary solution:  
No workaround.

KPR #: 3900007187 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
wmm does not take large border widths into account when placing windows  
Problem:  
Bring up a window with a wide border such as:

```
xfd -bw 100
```

When the size prompt comes up, press the left button and note the outline displayed by wmm. It does not take into account the 200 pixels needed by the border. When you release the button, a window much wider than the outline will appear.

Temporary solution:  
Workaround:

KPR #: 3900007187 \*\*CONTINUED\*\*

Don't use very large borders when creating windows.

KPR #: 3900007195 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
X server doesn't work on kernel without ITE configured in. (S800)

Problem:  
If I generate a kernel without the ITE configured into it, I can't launch the X-server to a graphics devise. It comes back and says that the "Mobley" server is missing, and that I should build it in.

This is a problem for people who want to use their graphics devises only as a X workstations. The ITE takes a lot of space in kernel, and should not be required.

Temporary solution:  
No workaround.

KPR #: 3900007773 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Copy plane sometimes doesn't work

Problem:  
First create bitmap and a window, mapping the window. Then blit the bitmap onto itself, using GXinvert. Then copy the entire bitmap to the window, using copy-plane w/ operation "GXxor. Then copy pieces of the bitmap to the window, again using GXxor. The pieces cover the entire bitmap, and so when the copies are done the window should be blank.

Temporary solution:  
No workaround.

KPR #: 3900007781 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
Problems w/ copy-plane from window to bitmap

Problem:  
There is a bug in copy plane when the source is a window, the destination is a bitmap, and destination region is something other than 0,0. First, a window is created, mapped, and an "X" is drawn into it. The program then waits for a mouse event. Then a portion of the window is copied from 0,0 into a bitmap, and the contents of the bitmap is immediately redisplayed to the window. The program will then wait for another mouse event. The copying, isthen repeated, but this time the window is copied from 100, 100 to the bitmap. The program then waits for a final mouse event.

The correct results of this program is that the window should not appear to change, since portions of the window are being copied to a bitmap and then immediately copied back. What happens is that the first copy/copy back works correctly, but the second one does not, resulting in a

KPR #: 390007781 \*\*CONTINUED\*\*

hole in the "X".

Temporary solution:  
No workaround.

KPR #: 5000474411 Product: X11 WINDOWS 6.2/3.0 B1152A 00.03

One-line description:  
xwcreate does not size window correctly in 6.2 - fixed in 6.5

KPR #: 1650099572 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Duplicate typedefs for short INT8 cause compiler to abort

Problem:  
Apparently, the C compiler is calling a warning an error and then aborting. The problem is caused by a duplicate definition in include files for short, long and char. The compiler should issue a warning "duplicate typedefs" and keep on going. This defect really should be lodged with the division responsible for the C compiler

KPR #: 390007211 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
hpwm title remains pushed in shen concurrent Interact. place is done

Problem:  
If the title is already pushed in when a concurrent Interactive place is done, the title will not pop back. This is a cosmetic defect.

Temporary solution:  
Workaround:

Repaint the screen.

KPR #: 390007229 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Hpwm.man says f.refresh\_wil actis like f.refresh in root context.

Problem:  
The man page incorrectly states that firefresh\_win acts the same as firefresh in root context.

Temporary solution:  
No workaround.

KPR #: 390007237 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Core Dump when sizing windows in a VPANE

Problem:  
In the latest version of the Excalibur BUILD tool, I have been playing with the VPANE widget to eliminate some of the sashes (make only certain parts of the tool resizable). My Widget hierarchy is as follows:

```

PANEL
  VPANE
    MENU-BAR
    FORM
    <lots of stuff>
  LIST <list mgr stuff>
  FORM
  <lots of stuff>
  (min=55, max=55)
  (min=25)
  (min=25, max=25)

```



KPR #: 3900007237 \*\*CONTINUED\*\*

Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

```
FORM ("File View")
<lots of stuff>
<horizontal scroll bar>
```

What I end with is a screen with 1 sash mark (what I want), it is attached to the bottom of the LIST widget. When I grab the sash and move it all the way down to the bottom of the screen, I die with a floating point exception.

Temporary solution:  
Workaround:

If I make the MIN for the bottom form bigger (e.g. 60 instead of 25), things work fine.

KPR #: 3900007245 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

Textedit widget created with empty file, change to full file, hang

Problem:

I have a widget based mail program. If I create a textedit widget that has a sourceType of XwdIsSrc and file that is empty and then I change the parameters in a callback to point to a non empty file my program hangs.

Temporary solution:  
Workaround:

By putting some text in the original file everything works O.K.

KPR #: 3900007252 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

icon over save button in save view in hpwm. Both get select signal.

Problem:

icon was over the save button on a fileview. I doubleclicked to deiconize. The icon deiconized but the button beneath was selected as well. Fortunately it is a nondamaging request. This is really a bug in hpwm. The bug is that after a double click to deiconize, the release event is making it through to the window underneath. Since the double click is "owned" by the window manager, it shouldn't allow it to be passed to an application (this requires some sort of grab, I think). Hpwm carries out the double-click action when it receives the second button down event. The second button-up event is not consumed by hpwm.

Temporary solution:  
Change your selection for the button to be btnlDown rather than btnlUp.

Known Problem Reports as of 11/09/90

KPR #: 3900007260 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

hpwm interactive placement when mouse is busy - window (0,0) can't move

Problem:

When hpwm has interactive placement on, if a window appears while the mouse button is down, hpwm puts the top left corner of the window at (0,0). Unfortunately, the title bar is hidden, so the gadget to move the window cannot be reached. I have to kill the window and start over.

Temporary solution:  
No workaround.

KPR #: 3900007278 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

"<Btnlup> title f.raise\_lower" only does f.raise in hpwm.

Problem:

The following bindings for f.raise\_lower work:

```
<Key>Select window/icon f.raise_lower
<Btnlup> icon f.raise_lower
Meta<Btnlup> icon f.raise_lower
Menu DefaultSystemMenu
```

{ "Raise/Lower" f.raise\_lower }

The following only execute f.raise:

```
<Btnlup> title f.raise_lower
Meta<Btnlup> title f.raise_lower
Meta<Btnlup> window f.raise_lower
```

Temporary solution:  
No workaround.

KPR #: 3900007286 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

Unexpected window position with negative geometry co-ordinates.

Problem:

There is a general problem with Xlib when negative geometry coordinates are used. This problem can be exhibited when using hpwm or some of the clients.

Temporary solution:  
No workaround.

KPR #: 3900007294 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

XtNtittlePosition defined differently for 2 different widgets

Problem:

KPR #: 3900007294 \*\*CONTINUED\*\*

The resource XtNtitlePosition is defined differently for 2 different widgets:

Cascade - type int  
uses XwTOP, XwBOTTOM or XwBOTH

TitleBar - int  
seems to use numbers different from the enum values above

Temporary solution:  
No workaround.

KPR #: 3900007302 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
type converters in libXw don't generate warning on bad conversions

Problem:  
In tracking another problem, I discovered that some of my resources were illegal in my app-defaults. The converter functions are supposed to generate warnings when illegal values are specified, but did not. In particular, I had specified something like:  
\*StaticText.Gravity: False

instead of giving it a real value. It failed to tell me that False was not a legal value for gravity.

Temporary solution:  
No workaround.

KPR #: 3900007310 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
TextEditP.h: uses defines XtTextEditPrivate\_h instead of \_XwTextEdit...

Problem:  
To prevent multiple inclusion, ifdefs and defines were added to the header files. TextEditP.h uses ifdef \_XtTextEditPrivate\_h and define Xt... to prevent multiple inclusion instead of using the proper \_Xw prefix. This will only cause problems if an application defines \_XtTextEditPrivate\_h somewhere (which is very unlikely). But for consistency sake it should use the \_Xw prefix.

Temporary solution:  
No workaround.

KPR #: 3900007328 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
BackgroundTile resources not properly propagated

Problem:  
If the resource file contains:

- X11 WINDOWS 6.5/3.1 -

KPR #: 3900007328 \*\*CONTINUED\*\*

\*BackgroundTile: 50\_foreground  
\*StaticText.backgroundTile: background

the list widget comes up with very strange defaults. The static text entries are correct (solid) but the row column manager underneath is tiled. The bulletin board manager is solid again (so the list manager window has an apparent random pattern of solid and tile). The correct values would have been for the bulletin board to use the same background as the row column, but what I really wanted to set was everything solid but the scrollbar.

To fix the problem, I added:

\*List\*BackgroundTile: background  
\*List\*Scrollbar\*BackgroundTile: 50\_foreground

but the problem is the second resource is ignored. It should be possible to set subresources for the scrollbar color and tile. Either that, or the resources need to be made available at the manager level with something like vsbBackgroundTile, etc.

This is actually a problem with ScrolledWindow as well.

Temporary solution:  
No workaround.

KPR #: 3900007336 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
multiple traversal highlights can sometimes appear

Problem:  
I have some code which pops up a transient shell and calls XtSetKeyboardFocus(). It then pops down the transient shell and later pops it up, again setting the focus. If the user changes the kbd focus before popping down the shell (dialog box), then when the box reappears, both highlights are sometimes visible. I think when no intervening management requests come in, but the focus is correctly placed in the one on which XtSetKeyboardFocus() was last called.

Temporary solution:  
Workaround:

I can work around this by calling XtSetKeyboardFocus(popup\_shell, None) when I pop down the box.

KPR #: 3900007344 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

SWindow: horizontal scroll bar Y resource always returns 0 on getvalues

Problem:  
None

- X11 WINDOWS 6.5/3.1 -

KPR #: 3900007344 \*\*CONTINUED\*\*

Temporary solution:  
None

KPR #: 3900007351 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
monochrome Z format image handled incorrectly in `xpr` and `xwd2sb`.

Problem:  
Xpr & xwd2sb incorrectly handles monochrome images generated in ZPixmap format when the image is packed one bit per pixel. This due to a defect in the "Z\_image\_pixel" function contained in the x2jet.c file.

Temporary solution:  
Workaround:

Use the -xy command line option when generating the image via "xwd". This forces the image to be dumped in XPixmap format which is handled correctly by xpr.

KPR #: 3900007369 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
xwcreate indicates an invalid background pixel when using TSRX display.

Problem:  
xwcreate displays a wrong error message and exits if pixel number is specified for the background. This happened when using a TurboSRX display in 24 plane mode in the image planes.

Temporary solution:  
Workaround:

Use color names when specifying background.

KPR #: 3900007377 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
In xpr -trailer string truncated by 1 char when -append -noff spec. after

Problem:  
None

Temporary solution:  
Workaround:

Simply add an extra space to the end of a trailer string if -append and -noff is to be used after it.

KPR #: 3900007385 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
xwcreate does not give an error for exceeding window count.

Problem:

KPR #: 3900007385 \*\*CONTINUED\*\*

xwcreate will not create window if window count is exceeded and does not give an error message.

Temporary solution:  
No workaround

KPR #: 3900007393 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
-depth arg <= 0 in xwcreate, s/b `invalid window depth`, not `bad option

Problem:  
None

Temporary solution:  
No workaround

KPR #: 3900007401 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
In hpterm, an extra cursor appears after pressing [Next][Next].

Problem:  
An extra cursor is left on the screen if you do the following:

Show multiple pages on the screen. Press Shift home to go to the last page. Then Prev. Scroll the page down a couple of lines with shift down arrow. Then press Next Next. An extra cursor will appear.

Temporary solution:  
Workaround:

Typing over extra cursor will make it disappear.

KPR #: 3900007419 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Programmatically turning key labels on/off repeatedly resizes hpterm wind

Problem:  
The following program will reproduce the problem:

```
#include <stdio.h>
main()
{
    int i;
    for (i=0; i<1000; i++)
        if (i%2) write(1, "\033&j0", 4);
        else write(1, "\033&jB", 4);
}
```

Temporary solution:  
No workaround.

KPR #: 3900007427 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
hpterm will display wrong menu instead of user menu (sometimes)

Problem:  
If you bring up an hpterm menu and turn off the menu via "MENU" and then turn it back on (via "MENU" again), it will display the same menu but the buttons will invoke the user's function keys. The action is right, the display is wrong.

Temporary solution:  
No workaround.

KPR #: 3900007435 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Mode menu check mark does not come on for reverse video option

Problem:  
Even though reverse video option is toggled on, the check mark does not appear in the menu.

Temporary solution:  
No workaround.

KPR #: 3900007443 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
When clicking mouse inside, then outside hpterm, hpterm dies.

Problem:  
This defect will occur if you:  
-begin a cut operation in an hpterm window,  
-move the cursor outside of the window without generating any pointer motion events from inside of the window,  
-end the cut operation (release mouse button).  
If this is done, hpterm will attempt to unhighlight text from the start position to an x and y position that is uninitialized and is only set by pointer motion events generated inside of the window.

Temporary solution:  
No workaround.

KPR #: 3900007450 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
TSRX colors allocated incorrectly in overlays if first in STACKED MODE.

Problem:  
If the four plane overlay device is the first screen of a Stacked Screen Mode configuration on a Turbo SRX display system (HP98730/98731) then colors will be allocated incorrectly in cells 8-15 of the colormap. Symptoms will be that colors allocated in cells 0-7 will be replicated in cells 8-15 and colors allocated in cells 8-15 will not be installed.

Temporary solution:

KPR #: 3900007450 \*\*CONTINUED\*\*

Two potential workarounds exist:

- 1) List the screens in opposite order so that the image planes are the lower numbered screen.
- 2) Allow the screen blanking screen saver to be installed. For example
  - xset s 1
  - wait a few seconds
  - xset s 3600
 will correct the color allocation.

KPR #: 3900007468 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Running two servers at the same display won't work.

Problem:  
If the user starts two 11 servers, both of them to the same display, then the second one may exit gracefully, with a memory fault. The first server continues to run normally.

Cause:  
The cause is due to the second server's having no knowledge that another server is already using a given display device. During the initialization of that device, the second server receives an expected message from the Graphics Resource Manager and so behaves unexpectedly.

Temporary solution:  
Workaround:

Don't try running two servers to the same display.

KPR #: 3900007476 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Using non-HP Xlib may cause client termination for LARGE requests.

Problem:  
The server ungracefully handles large request packets from clients. For client requests larger than 16,384 bytes (normal request size is about 32 bytes), the server disconnects the client! This isn't a problem for HP clients--because the HP Xlib guarantees a smaller packet size--but could be a problem for non-HP Xlib clients.

Cause:  
The X protocol states that the server return a "bad length" error for requests that exceed MAX\_REQUEST\_SIZE (16,384 bytes), set up at server initialization time, but in the actual request code, the A.01 server checks against the wrong size (256K bytes).

Temporary solution:  
Workaround:  
Use the HP libX11.a library for writing clients.

KPR #: 3900007484 Product: X11 WINDOWS 6.5/3.1 B1152B

KPR #: 3900007500 \*\*CONTINUED\*\*

One-line description:  
Restarting a second s300 server after changing X\*screens file may fail.

Problem:  
When you've got TWO X11 servers running on the same s300 computer system, and then you stop and restart one of them, the restarted server may complain that "your user address space is too small" and exit.

The problem will occur if you've changed your X\*screens file before trying to restart the second server.

This problem exists on s300 HP-UX 6.5 only; it has been fixed for s800 HP-UX 3.1.

Cause:  
The cause is that the Graphics Resource Manager (GRM), which tracks server usage, maintains an outdated notion of the second server's offscreen memory when the second server exits. When the second server tries to reinitialize its display with new X\*screens file information, the GRM will not honor that request.

Temporary solution:  
Workaround:

Instead of stopping just one server, stop BOTH servers. With no servers running, the Graphics Resource Manager will stop running as well. Restarting the servers will then restart a new GRM, and screen initialization will occur correctly.

KPR #: 3900007492 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
grmd process size grows by 2K for each Starbase application

Problem:  
Every time a Starbase application is run in an X window, the grmd process size will grow by 2K. If the grmd process grows large enough, the system could run out of swap space.

Cause:  
The grmd process does not free a 2K buffer used for IPC with the Starbase process when the Starbase process terminates.

Temporary solution:  
Workaround:

Take down the X Window system periodically so that the grmd process will terminate.

KPR #: 3900007500 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
In depths greater than 8, resizing a backing store window crashes server

Problem:

- X11 WINDOWS 6.5/3.1 -

The backing store of a window is kept in either frame-buffer or in virtual memory. When a window is registered to be a DHA (Direct Hardware Access) window, its backing store, if any, is moved to "Shared Memory". Shared memory is a piece of memory that can be accessed by drawing routines of the Xserver as well as by the drawing routines in Starbase library. However the shared memory is a limited resource and sometimes may be unavailable. This may happen if there are several windows or one large window has been declared to be DHA window. If the Shared memory is not available, the Xserver should backoff and refuse to provide backing store support for the DHA window. Because of a bug, the Xserver sometimes fail to recognize this situation and tries to render to nonexistent backing store in the shared memory. Consequently the server crashes. This bug is being fixed in the next release. The problem is particularly visible for windows of depth 24, because the large quantities of memory are required to support backing store operation of these windows and consequently the shared memory reservoir runs out quicker.

Temporary solution:  
Workaround:

The problem may be avoided (minimized) by doing the following:  
1)do not have many DHA-windows with backing store.  
2)do not declaring large full screen windows with backing store to be DHA-windows.

3)increase the size of allocated shared memory by instructing the Graphics Resource Manager (GRM). See the relevant GRM-document for instructions on how to do this.

KPR #: 3900007518 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
On LCC or Hexagon display copying window sometimes is not right

Problem:

If a window has backing store and it is partly obscured, then when the window is unobscured its contents are to be copied from the backing store to the screen. In the LCC or Hexagon displays sometimes it does not work properly.

Cause:

The backing store of a window resides in either the frame buffer or in virtual memory. When the backing store contents are to be copied to the screen the Xserver employs one of two different routines to copy the backing store to the screen. One of these routines is specifically used to copy from a backing store in frame buffer to the screen. Another routine is used to specifically copy backing store in virtual memory to screen. The former routine as implemented for the above displays has a bug, such that sometimes it does not copy the contents of the backing store from the frame buffer if the area to be copied is partially visible and partially obscured. On most displays, the problem manifests only once when the Xserver is initialized. On the LCC and Hexagon displays, this problem may persist.

Temporary solution:

- X11 WINDOWS 6.5/3.1 -

KPR #: 3900007518 \*\*CONTINUED\*\*

Workaround:

Large windows will have their backing store in virtual memory. This problem will not be visible then.

KPR #: 3900007526 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

XGetImage behaves wrong for backing store windows of depth 2,3,4,6.

Problem: If a client calls XGetImage on a window with backing store, whose depth is greater than 1 and less than 8, and a portion of the window is obscured, then the obscured region of the window image returns the pixel representation of the screen when it should return the image stored in the backing store.

Temporary solution:

Make sure such a window is not obscured before XGetImage is called.

KPR #: 3900007534 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

HP98556 and STACKED SCREENS Mode: colormap holed when server resets

Problem:

Running a server in STACKED-SCREENS MODE with a HP98556 integer accelerator present causes problems. When the last client dies, the server resets, as expected. However, it also trashes the colormap in such a way that most everything goes black (in a stippled fashion - the mesh of the root window). Using the mouse to toggle between the two screens causes the colormaps to reset correctly.

Cause:

The server will attempt to use the HP98556 if it is running when the server is started. If it is not running, but can be successfully started, the server will do so. There are some firmware difficulties in using the HP98556 and timing of toggling between the image and overlay planes in STACKED-SCREENS mode.

Temporary solution:

Workaround:

None: Way to turn off the HP98556 is not supported. One way to turn off the HP98556 is as follows:

- 1) Shut down the X system
- 2) rename the HP98556 microcode file
- 3) issue a "gopen (... , RESET\_DEVICE)". This will reset the HP98556 and cause it to reload its microcode. Since the file has been renamed, the reload will fail and the HP98556 will shut down.

To start the HP98556 again, rename the microcode file back to normal and issue the gopen again.

KPR #: 3900007534 \*\*CONTINUED\*\*

Note: If the HP98556 is not running, but the microcode file is present, the server will start the HP98556.

KPR #: 3900007542 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

Server doesn't always handle "Unsorted" XSetClipRectangles correctly

Problem:

The X lib procedure "XSetClipRectangles" allows the client to specify a set of rectangles in which to restrict rendering. The client must specify the ordering of the rectangles (Unsorted, YSorted, XSorted, YXBanded). Rectangles that are "Unsorted" are not always handled correctly.

Cause:

The server always works with rectangles in YXBanded format. Rectangle lists specified in another format are converted to YXBanded. The algorithm to convert Unsorted rectangles to YXBanded is incorrect.

Temporary solution:

Workaround:

Order the rectangles into one of YSorted, XSorted, or YXBanded.

KPR #: 3900007559 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

backing store is not deleted for depth 24 DHA windows

Problem:

If a depth 24 window is registered for Direct Hardware Access, any backing store present is not deleted. Also, a request to create backing store for such a window is not denied. If the window is obscured and then exposed, the contents of the backing store will be drawn. This is only a problem if the DHA client can not render into the backing store.

Cause:

The X server can render into depth 24 backing store. DHA Starbase clients can not. When a depth 24 window with backing store becomes registered for DHA, the server should delete the backing store. Similarly, if a depth 24 DHA client requests backing store, it should be denied.

Temporary solution:

Workaround:

Before registering the window for DHA, explicitly delete any backing store via the XSetWindowAttributes library procedure.

KPR #: 3900007567 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

Backing store may not be rendered to correctly on some displays (s300)

Problem:

On the 98542, 98543, 98544, 98545, and 98547 display interfaces, any operation that results in the copying of data from one area of the screen to another area that is obscured AND has Backing Store enabled will result in the backing store being rendered incorrectly. Typical operations such as moving a window or obscuring a window will NOT cause this behavior to appear. Only copying on screen data to another area of the screen that is obscured by another window will cause this.

Temporary solution:

No workaround.

KPR #: 3900007575 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

redMask in the Visual structure zero in stacked mode on SRX/TSRX

Problem:

On the SRX (HP 98720/98721) and TSRX (HP98730/98731) displays, if the first screen of a Stacked Screen mode configuration has a visual class of DirectColor (i.e., its depth is either 12 bits double buffered, or 24 bits), then the ConnectionInfo that is transmitted to the client at XOpenDisplay time will have a bad value for the redMask of the DirectColor visual. The net result is that it is impossible to tell what bits of the Pixel actually define the red component.

Temporary solution:

Workaround:

Reverse the order of the screens in the X?screens file.

KPR #: 3900007583 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

Colors stored incorrectly in upper bank on TSRX double buffer mode

Problem:

On the Turbo SRX display system (HP 98730/98731) if the X server is started in 12/12 double buffer mode (depth 24) then colors that are bank stored into the high bank will have the value intended for the green bank stored into the red bank, altering the red bank and leaving the green bank untouched. This problem should be unnoticeable in most cases. However, if the situation arises where a Starbase application is designed to utilize the X default colormap of the X server, then the display will flash with incorrect colors at each call to dbuffer\_switch().

Temporary solution:

No workaround.

KPR #: 3900007591 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

White RGB value incorrect on 98548 display

Problem:

The value stored in the colormap for the color white for the 98548 display system is Red = 0xffff, Green = 0xffff, Blue = 0xffff. It should be 0xff00 for all three components to correctly match the rgb color database.

This results in being unable to allocate the color white. Thus a command such as the following will fail:

xsetroot -solid white

Temporary solution:

No workaround.

KPR #: 3900007609 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

On TSRX (hp98730/98731) some tiles are rendered incorrectly

Problem:

On the Turbo SRX display system (HP98730/98731) tiles (patterns used for certain fill operation) whose width is between 16 and 23 pixels wide will not be rendered correctly. Visually, it looks as though only the left-hand portion of the tile is correct, with the right-hand portion looking like random data.

Temporary solution:

No workaround.

KPR #: 3900007617 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

Tiles may be drawn incorrectly on SRX (HP 98720/98721) (s300)

Problem:

On the SRX (HP 98720/98721) display system, some tiles (pixmaps used as fill pattern for rendering operations) may be drawn incorrectly depending on their alignment on the screen. This is a purely cosmetic defect.

Temporary solution:

No workaround.

KPR #: 3900007625 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

Remnants of SB cursors left when obscuring/unobscuring window

Problem:

On the Turbo-SRX, when an accelerated window with a Starbase cursor is being or will be obscured by another window (accelerated or not) that has a Starbase cursor in it, the cursor is not put down properly. This will happen even if the Starbase program is not accessing the device.



KPR #: 3900007625 \*\*CONTINUED\*\*

KPR #: 3900007641 \*\*CONTINUED\*\*

The result is that pieces of Starbase cursors will be left on the screen.

Temporary solution:  
No workaround.

Workaround:

One potential workaround is to use the 6.2/3.0 X11 Server instead. This defect has been introduced by the 6.5/3.1 Server implementation. However, using the 6.2/3/1 X11 Server will cause a loss of functionality present in the new product. If this is unsatisfactory, the customer should contact his HP Support representative. A server with the defect corrected will be supplied to the Support organization.

KPR #: 3900007633 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
SB cursors in reserved planes are not turned off by the screen saver.

KPR #: 3900007658 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
If X server restarted, ScreenSaver time not initialized.

Problem:

Users of X can specify a timeout value for the server. If no input is received by the server during that time, a screensaver background pattern will be drawn over the X display. If the timeout value is reached, so that the background pattern is drawn, and then the last client exits, so that the server restarts itself and redraws the root window, the time used to determine when the server next saves the screen will be incorrect.

Temporary solution:  
No workaround.

Problem:

It is permissible for a client to specify that all rendering is to be contained within a sub-area of the window. This is called a client clip and is specified via the XSetClipRectangles or XSetClipMask client routines.

It is also permissible for a client to request backing store for a window. Any rendering to an obscured area of the window will then be directed to the backing store memory rather than discarded. If both these options are in effect, any rendering outside the client clip area should be discarded and not rendered to the backing store. In the current product, this does not happen. Any rendering to an obscured area of the screen is directed to the backing store, irregardless of the client clip area. When the obscured area becomes visible, the unwanted rendering is copied from the backing store memory to the screen, creating an undesirable result.

Cause:

The clip list that is passed to the SDI drivers contains two types of rectangles, "visible" and "obscured". A visible rectangle is a portion of the window that is visible. An obscured rectangle is a portion of the window that is obscured by another window, is offscreen, or is outside the client specified clip area. Rendering to a "visible" rectangle goes to the screen. Rendering to an "obscured" rectangle is discarded unless backing store is present in which case the rendering is directed there.

The union of all rectangles in the clip list covers the entire window. There is no way for the SDI drivers to distinguish between an "obscured" rectangle that is caused by window obscurity (and should be rendered to backing store) from an "obscured" rectangle caused by being outside the client clip area (and should ALWAYS be discarded!).

Temporary solution:

- X11 WINDOWS 6.5/3.1 -

One-line description:

If X server restarted, ScreenSaver time not initialized.

Problem:

Users of X can specify a timeout value for the server. If no input is received by the server during that time, a screensaver background pattern will be drawn over the X display. If the timeout value is reached, so that the background pattern is drawn, and then the last client exits, so that the server restarts itself and redraws the root window, the time used to determine when the server next saves the screen will be incorrect.

Cause:

The code that waits for input before checking to see if it is time to save the screen waits longer than the screensaver time.

Temporary solution:  
Workaround:

Type a key or move the mouse after the server restarts.

KPR #: 3900007666 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Multiple keycodes with same keysym in USASCII keymap.

Problem:

The X library provides functions to look up an X server keycode using a key symbol, and vice versa. In order for these to work correctly, there must be a one-on-one correspondence between keycodes and key symbols.

In the USASCII keymap, more than one keycode is defined to the same key symbol. The effect of this is that a client program can redefine a key symbol based on the keycode, then look up the key symbol that it has redefined, and still find it even though it should no longer be there.

Cause:

More than one keycode is defined to the same key symbol.

There are no keys on the USASCII keyboard that can generate the duplicate keycodes, so this is only a problem for client programs that redefine the affected key codes and then look up the key symbols that have been redefined. The affected key codes and key symbols are:

- X11 WINDOWS 6.5/3.1 -



KPR #: 3900007666 \*\*CONTINUED\*\*

keycode	key symbol	description
0x14	KP_6	- the '6' key on the keypad
0x28	KP_6	- doesn't exist on the keyboard
0x1c	KP_3	- the '3' key on the keypad
0x29	KP_3	- doesn't exist on the keyboard
0x25	Kanji	- doesn't exist on the keyboard
0x83	Kanji	- doesn't exist on the keyboard

Temporary solution:  
Workaround:

Be aware that if XChangeKeyboardMapping is used to redefine the key symbols associated with the affected keycodes, and XKeySymtoKeyCode is then used to look up the symbol that was redefined, it will still be found and will be the second instance of that symbol.

KPR #: 3900007674 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

X Server error message: "Illegal state: prev\_stat=2 keycode=0".

Problem:

If you use a two-button mouse with the X server, and the X server is heavily loaded, it is possible to get an internal error message from the X server when pressing mouse buttons. The message is something like "Illegal state: pre\_state=2 keycode=0"

and indicates that a button has been lost by the HIL driver, so that the X server has seen two consecutive button down or button up codes.

Cause:

The HIL driver has a finite sized buffer. If the X server is busy and does not read from that buffer, and the user continues to move the mouse it is possible to cause that buffer to overflow. The result is that a button can be lost and the user needs to press that same button again to get the server to see it. There is usually no ill effect other than the irritation of seeing the error message and having to press the button again.

Temporary solution:

Workaround:

Make sure that standard error output from the server is redirected to a file so that it does not come to the console. If the server is slow because it is busy, don't keep moving the mouse or banging on the buttons in an attempt to get its attention.

KPR #: 3900007682 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:  
Compiler error when referencing XHPSTACKED\_SCREEN\_MODE constant

Problem:

If you use the XHPGetServerMode function to determine the mode of the X server, a value is returned that should be compared to constants defined in <X11/XHPproto.h>. One of these constants XHPSTACKED\_SCREEN\_MODE, is defined as STACKED\_SCREEN\_MODE. If you reference the constant XHPSTACKED\_SCREEN\_MODE, the compiler will report that STACKED\_SCREEN\_MODE is undefined.

Cause:

STACKED\_SCREEN\_MODE is undefined. The constant that should have been used is STACKED\_MODE.

Temporary solution:

Use the constant STACKED\_MODE instead of XHPSTACKED\_SCREEN\_MODE.

KPR #: 3900007690 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

Last client termination MAY cause the X Server to abort

Problem:

When the last X client terminates, the X Server goes through a virtual reset. The Server may abort when during this virtual reset. We have one widget program which evidences this behavior. In most instances, the Server will successfully reset.

Temporary solution:

Workaround:

Run an X Client which will not be terminated, like xclock. This will ensure that the Server will not go through the reset process.

Signed off 02/08/90 in release C02.00

KPR #: 3900007708 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

XOpenDisplay through local:0 disables access control of server

Problem:

When a client connects via the local:0 display specifier, it will disable the server's access control mechanism for an indeterminate period of time. Thus, unauthorized hosts can run clients against the server. This disabling will continue until some system error occurs within the server, resetting the global variable "errno."

Temporary solution:

Do not use the display specifiers local:0 or unix:0

Signed off 02/08/90 in release C02.00

KPR #: 3900007716 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:  
Existing SB\_DISPLAY\_ADDR variable may interfere with X server (s300)

Problem:  
For the windows/9000 product on the s300, users can set the SB\_DISPLAY\_ADDR environment variable to specify the location in user data space where the frame buffer mapping should occur. This same environment variable can cause the X server to generate aspiruous error message:  
"Unable to open the Graphics Resource Manager."  
--and then exit.

Cause:  
Windows/9000 interprets the SB\_DISPLAY\_ADDR setting to be in decimal by default. The X11 server interprets the setting in hexadecimal, causing unreasonable values for the frame buffer base address to be passed to the Graphics Resource Manager and the resulting error exit condition.

Temporary solution:  
Remove the SB\_DISPLAY\_ADDR from your environment before running X Windows.

From 'csh', use: unsetenv SB\_DISPLAY\_ADDR  
From 'sh' and 'ksh' use: unset SB\_DISPLAY\_ADDR

KPR #: 3900007724 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:  
Gwind can hang when large number of windows are created.

Problem:  
This defect can cause the gwind daemon to hang. Gwind hangs when a about 50 graphics windows have been created. This is an unusually high number for a user, but not out of the question. This is a low frequency defect, with serious consequences.

We have placed a warning in our update\_info file stating: Using more than 24 graphics windows at the same time can cause the gwind program to hang. Killing the gwind process is the best way to restore the ability to create graphics windows for starbase applications.

Temporary solution:  
Workaround:

The workaround is to kill the gwind process. This destroys the graphics windows and allows the user to start creating graphics windows again.

Signed off 02/08/90 in release C02.00

KPR #: 3900007732 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:  
Certain bitmap(s) does not tile correctly as a root background (s300)

Problem:  
A particular bitmap is not rendered correctly when used as a root window background and there are clipping rectangles to the left. We have not seen this defect with all bitmaps.

Temporary solution:  
Workaround:

If the user has control over the windows that generate the clip rectangles then moving those windows can be a workaround. Similarly if the user can control the bitmaps, then there may be a different bitmap that is usable and work as it should. It is conceivable that for some users there will not be a workaround.

Signed off 02/08/90 in release C02.00

KPR #: 3900007740 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:  
xset gives error if pixel value is used outside of range 1-255.

Problem:  
On direct color systems like the TurboSRX, if a large pixel value is used an error condition is generated. The expected behavior is that this operation should work.

Temporary solution:  
No workaround.

Signed off 02/08/90 in release C02.00

KPR #: 3900007757 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:  
xwd does not use the colors saved; it uses just the pixels

Problem:  
Xwd saves the window contents along with the colormap; however, when xwd displays the saved contents, it ignores the colormap and instead uses the pixels.

Temporary solution:  
No workaround.

Signed off 02/08/90 in release C02.00

KPR #: 3900007765 Product: X11 WINDOWS 6.5/3.1 B1152B

00.03

One-line description:

HPwm leaves X server grabbed and forgets pending resize if menu pops up

Problem:

KPR #: 3900007765 \*\*CONTINUED\*\*

ipwm forgets about a pending window resize operation and leaves the X server grabbed if a button press causes a menu to pop up during the resize. The following line of my button bindings causes a menu to pop up for button 3 presses in the window frame area. If I start a resize with a menu then press button 3 while over a frame area the pop up menu is displayed. When button 3 is released the menu is removed and the resize is no longer occurring. The server is still grabbed, preventing clients from running.

Temporary solution:

The window manager will ungrab the server if another resize is done on any window.

Signed off 02/08/90 in release C02.00

KPR #: 3900007849 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

All special properties have parsing problems in xfc.

Problem:

The validity of data specified for special properties is not checked by xfc.

Temporary solution:

Workaround:

The user must ensure that special property data is correct.

Signed off 02/08/90 in release C02.00

KPR #: 3900007872 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

Bitmap with-nodashed, then do invert all results in lines becoming dots

Problem:

Using bitmap with -nodashed, then do invert all results in lines becoming dots.

If bitmap is started with the -nodashed option and the user then specified 'invert all', the solid lines become dots.

Temporary solution:

No workaround.

Signed off 02/08/90 in release C02.00

KPR #: 5000476838 Product: X11 WINDOWS 6.5/3.1 B1152B 00.03

One-line description:

Duplicate reference to \_bcopy in libX11.a and libndbm.a

KPR #: 3900008995 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:

On SRX and TSRX, XGetVisualInfo incorrectly reports bits\_per\_rgb as 4

Problem:

The problem is in line 319 of xosDD.c

Temporary solution:

No workaround - Fixed in next release

KPR #: 3900009001 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:

xwcreate cannot create windows on multiple servers

Problem:

The gwind daemon in 7.0 only created a pointer cursor for the first window generated by a call to xwcreate and then attempted to share it with all subsequently created windows. Since this will only work correctly for windows residing on the same display:screen combination as the first window, a non-fatal X protocol error was generated.

Temporary solution:

No workaround - fixed in next release

KPR #: 3900009019 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:

mkfontdir doesn't unlink fonts.dir before creating new fonts.dir

Problem:

If two font directories are linked together, the server may get mixed up in finding the correct location of a font file

Cause:

mkfontdir should rm the fonts.dir file before it writes a new one

KPR #: 3900009027 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:

cvtINT16toInt in XGetMotionEvents causes cc to abort

Problem:

There is a typo in the source code for libX11.a, specifically in the for the routine XGetMotionEvents(). In this routine, there is a reference to the macro "cvtINT16toInt", which is misspelled as "cvtINT16toInt". As a result, any X program which calls XGetMotionEvents() will fail to compile with the message:

```
ld: Undefined external -
cvtINT16toInt
```

```
ld: output file still contains undefined symbols
```

```
ld: (Warning) did not generate an output file
```

```
unless you add the include file <X11/Xmh.h> to your program,
```

```
and also include a bogus subroutine which effectively
```

```
cvtINT16toInt to cvtINT16toInt.
```

KPR #: 3900009027 \*\*CONTINUED\*\*

Temporary solution:  
include this text in program:

```

cvtINT16ToInt(a)
{
    return cvtINT16ToInt(a);
}
    
```

KPR #: 3900009050 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
XGetPixel returns invalid data for 98547S Topcat 300h:6 double buffer

Problem:  
When a topcat hexagon is run in double buffered mode, and the XGetPixel routine is called, a "whitepixel" value is returned as 0x9 ( binary 00 100 100). The upper three bits of the double buffered value are not being masked off properly (by the XGetPixel xlib routine). It should read 00 001 001.

KPR #: 3900009068 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
XErrorDB does not include any error information for errors over #127

Problem:  
Xlib does not sufficiently check when using the error messages from XErrorDB. XErrorDB only has 127 error messages and error number greater than 127, the message is garbage.

Temporary solution:  
It is possible to create your own error handler in Xlib adm it would be possible to trap errors greater than #127

KPR #: 3900009076 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
hpterm when maximized does not handle geometry changes when [Menu] on

Problem:  
When an hpterm window is maximized (under mwm or hpwm) and then the [Menu] key is toggled on/off; strange things happen to the window's geometry and the original size and position of the window is lost.

KPR #: 3900009084 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
old style (pre 7.0) grmd+ socket not removed by AGRM customize script

Problem:  
The AGRM fileset presently does not have a customize script. It needs one and that script should change any old-style sockets for the grmd to the current style. This involves checking to see if there

KPR #: 3900009084 \*\*CONTINUED\*\*

exists a grmd+ cdf in /usr/spool/sockets and removing it.

KPR #: 3900009092 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
sys.Xdefaults lacking colon in line for "HPterm\*Font <font>"

Problem:  
The sys.Xdefaults file shipped at 7.0 has a line that reads:  
! HPterm\*Font <font>  
This line is wrong because it is missing a colon ':' after Font:  
! HPterm\*Font:  
<font>

Temporary solution:  
Add colon (:) at end of word Font:  
! HPterm\*Font:  
<font>

KPR #: 3900009100 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
hpterm may leave highlighting on in erased regions

Problem:  
If there is a color change (e.g. ^(&v4S) or inverse video (e.g. ^(&dB) on a line, but no text, and the line is deleted with the [Clear display] button, the color property remains set.

KPR #: 3900009118 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
Xos.h needs to default to SYSV, not Berkeley stuff

Problem:  
The file Xos.h should be tailored to our hp-ux system a bit better. Possibly, the xos.h file should have the defines for SYSV removed. This will aid its use when included by customers.

For example, if a customer does not define SYSV in their program, the Xos.h file does an include of <strings.h> and this file does not exist on hp-ux systems.

KPR #: 3900009126 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
TextEditP.h: extra characters after #endif

Problem:  
Submitter claims that ANSI-C does not allow non-comment tokens to follow an #endif.  
Therefore, change:  
#endif \_XtTextEditPrivate\_h  
to  
#endif /\* \_XtTextEditPrivate\_h \*/  
in /usr/include/Xw/TextEditP.h

KPR #: 390009159 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
Changing Xtnhighlightthickness on static raster causes X Protocol error

Problem:  
When the height, width and highlightthickness are changed on a static raster widget, the following error is produced:

```
< Protocol error detected by server: parameter not a GC
Failed request major op code 70 X.PolyFillRectangle
Failed request minor op code 0 (if applicable)
ResourceID 0xc00008 in failed request (if applicable)
Serial number of failed request 155
Current serial number in output stream 165
```

KPR #: 3900009183 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
hpterm (block mode) loses character on read from cursor to end of line

KPR #: 3900009191 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
hpterm (7.0) does not read correctly from specified column to end of line

Duplicate Service Requests: 3900009209

KPR #: 3900009217 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
hpterm 7.0 does not display alternate character set with curses program

KPR #: 3900009225 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
Memory leak when create/destroy PromptDialog widget; Motif 1.0

KPR #: 3900009233 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
Problems reading with Esc-D in hpterm block mode  
Fix information:  
A new hpterm has been made available on the patch machine in Fort Collins.

KPR #: 3900009571 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
XHPGetClipboardList trashes malloc data  
Problem:  
XHPGetClipboardList keeps a count of the number of allocated rectangles in a clip list. According to the comment in the function the count is a four byte integer.

KPR #: 3900009571 \*\*CONTINUED\*\*

The first four bytes of the allocated memory contain a count of the number of clipping rectangles the block can hold. The user is returned a pointer to the remainder of the memory block which contains the actual clipping rectangles.

In the code the count is actually kept in a signed char. The result is that when the count reaches 128 the signed char wraps to a negative number. The count is then cast to an unsigned int, resulting in an enormous number when comparing to test for a need to realloc. The clip list is never reallocated when it should be, and the list data clobbers malloc pointers. This can result in core dumps, infinite loops, and other bad behaviors.

KPR #: 5000535153 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
hpbkterm does not warn user that lines are being lost in TDP buffer

KPR #: 5000552307 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
xterm with -title option does not work properly and not equiv to -T

KPR #: 5000554493 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
xterm does correctly emulate the function keys of the VT100/102 term

KPR #: 5000557215 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
xterm - selecting "Interrupt" from xterm menu can cause system problems

KPR #: 5000557223 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
hpterm does not refresh keyboard mapping after receiving MappingNotify

Problem:  
hpterm does not refresh keyboard mapping after receiving MappingNotify and may end up issuing wrong key symbol for any given key that has been re-mapped.

Cause:  
This is not really an hpterm problem since hpterm relies upon Xt, the X Toolkit Intrinsics from MIT, to get keyboard input.  
There is a bug in Xt such that it does not correctly handle MappingNotify events

Known Problem Reports as of 11/09/90 Page: 83

KPR #: 5000573956 Product: X11 WINDOWS 7.0 B1152C 02.00

One-line description:  
Xlib-line width 0 and PlaneMask set to other than AllPlanes - no line







Product name	Product number	uu.ff	prev
LAN MANAGER/X S300	B1003A	01.00	00.00
S/300 NET NODE MGR	B1009A	01.00	00.00
S/300 TCP/IP AGENT	B1010A	01.00	00.00
S2/300 SRM ACC/HPUX	98693A	06.20	05.10
S200 NETWORK SERVICE	5095YA	05.10	00.00



CUMULATIVE PRODUCT INDEX

PAGE I 2

Product name	Product number	SSB ISSUE DATE	Page
S2/300 SRM ACC/HPUX	98693A	11/20/90	1

KPR number	page	KPR number	page	KPR number	page	KPR number	page
------------	------	------------	------	------------	------	------------	------

4000091777	1						
------------	---	--	--	--	--	--	--

CUMULATIVE KEYWORD INDEX

PAGE I 4

- S2/300 SRM ACC/HPUX - SSB ISSUE DATE: 11/20/90

Keyword	Product number	uu.ff Description	KPR number	page
*****none*****	98693A	06.20 srmcp reports "unknown SRM error 31041" when HP Basic/UX locks same file	4000091777	1

Known Problem Reports as of 11/20/90

Page: 1

KPR #: 400091777 Product: S2/300 SRM ACC/HPUX 98693A

06.20

One-line description:  
srmcp reports "unknown SRM error 31041" when HP Basic/UX locks same file

Temporary solution:  
Here are some work arounds for this problem.

1. Retry the srmcp command later whenever the 31041 error is seen.
2. Avoid accessing the same files with srmcp and HP Basic/UX.
3. Use some synchronizing mechanism on HP-UX to ensure that srmcp and HP Basic/UX do not access the file at the same time.
4. Move the srmcp and HP-Basic/UX activity onto separate HP-UX systems.













---

WORLDWIDE RESPONSE CENTER OPERATIONS HEADQUARTERS

100 Mayfield Avenue

Mountain View, California 94043

U.S.A.

Main Switchboard Phone No. (415) 968-5600

WWRCO Manager: Maurice Vink (415) 691-5818

Secretary: Diane Hill

---

ARGENTINA

Hewlett-Packard Argentina S.A.

Montaneses 2140

1428 Buenos Aires

Argentina

Ph: (54-1) 781-4059 (main)

(54-1) 781-4086 (C.A.T. direct)

Manager: Eduardo Thompson

---

AUSTRIA

Hewlett-Packard GmbH

Lieblgasse 1

A-1222 Vienna

Austria

Ph: (43) 22-2500-0 (main)

Manager: Herbert Krautschneider (ext. 280)

Secretary: Uschi Mastny

---

AUSTRALIA

Australian Response Centre

Hewlett-Packard

31-41 Joseph Street

Blackburn, Victoria 3130

Australia

Ph: (61) 03 895-2895 (main)

(61) 03 895-2510 (response centre)

Manager: Graham Gunson

Secretary: Carole Moore

---

BELGIUM

Hewlett-Packard Belgium SA/NV

Boulevard de la Woluwe, 100 Woluwedal

B-1200 Brussels

Belguim

Ph: (32) 2/761 31 11

Manager: Willy Vercaigne

---

BRAZIL

Hewlett-Packard do Brazil

Ind. e Com. Ltda.

Alemeda Rio Negro,

750-Alphaville

06400-Barueri-SP  
Brazil

Ph: (55) 11 421-1311 (main)  
Manager: Vidalencio Silva  
Secretary: Rosana Higa

---

#### DENMARK

Hewlett-Packard A/S  
Kongevejen 25  
DK-3460 Birkerod  
Denmark

Ph: (45) 2/816 640 (main)  
Manager: Halldor Faerch

---

#### FINLAND

Hewlett-Packard OY  
Country Response Center  
Piispankalliontie 17  
02200 Espoo  
Finland

Ph: (358) 0-887 21  
Manager: Matti Nirikko  
Secretary: Kristiina Laiho

---

#### FRANCE

Hewlett-Packard  
Country Response Center  
Immeuble France Evry  
Tour Lorraine  
Boulevard de France  
91035 Evry Cedex  
France

Ph: (33) 1/60-77-90-90 (main)  
Manager: Edouard Hemery  
Secretary: Christine Guyon

---

#### GERMANY

Hewlett-Packard GmbH  
Support Zentrum  
Berliner Strasse 111  
4030 Ratingen 3  
West Germany

Ph: (49) 2102/4940 (main)  
(49) 2012/475040 (Klaus' direct line)  
Manager: Klaus-Dieter Klein

---

#### HONG KONG

Hewlett-Packard Asia Ltd.  
22/FL - 30/FL, West Tower  
Bond Centre

89 Queensway  
Central Hong Kong

Ph: (852) 5-8330833 (main)  
(852) 5-8323328

Manager: Bill Lui

---

#### ISRAEL

Hewlett-Packard  
Computation & Measurement Systems (CMS) Ltd.  
11, Masad Street  
67060 Tel Aviv  
Israel

Ph: (972) 3-388388  
(972) 3-388458

Manager: Peter Gerstenhaber

---

#### ITALY

Hewlett-Packard Italiana S.p.A  
Via G. di Vittorio 9  
20063 Cernusco Sul Naviglio, Milan  
Italy

Ph: (39) 2-923691

Manager: Renato Sommocal

---

#### JAPAN

Yokogawa Hewlett-Packard Ltd.  
Response Center  
29-21 Takaido-Higashi, 3-chome  
Suginami-ku, Tokyo, 168  
Japan

Ph: (81) 3/331-6111

Manager: Takeru Omuro

Secretary: Yuki Hosoi

---

#### KOREA

Samsung Hewlett-Packard  
Response Center  
Dong Bang Yeoeuido Building  
#36-1, Yeoeuido-Dong  
Yeongdeungpo-Ku  
Seoul, Korea

Ph: (82) 2/784-4666

(82) 2/784-2576 (direct)

Manager: Kyu-Youl Park

Secretary: Yu Ra Lee

---

#### MALAYSIA

Hewlett-Packard Sales Sdn. Bhd.  
9th Floor, Chung Khaiw Bank Building  
Sec. 56 Jin Raja Laut  
Kuala Lumpur

Malaysia

Ph: (60) 32-986555 (main)

Manager: Kin-Kong Ngho

---

MEXICO

Hewlett-Packard De Mexico

S.A. de C.V.

Monte Pelvoux #111

Lomass de Chapultepec

11000 Mexico D.F., Mexico

Ph: (905) 596-7933

Manager: Rafael Diaz

---

MIDDLE EAST

Modern Electronic Establishment

Hewlett-Packard Division

P.O. Box 22015

Riyadh, Saudi Arabia 11495

Ph: (966) 1-476-30-30

Manager: Shadid Munir

---

NETHERLANDS

Hewlett-Packard Nederland B.V.

Country Response Center

Van der Hooplaan 241

1185 LN Amstelveen

Ph: (20) 547-6644

(20) 547-6491 (Ewout)

Manager: Ewout Costeris

Secretary: Yvonne Van-Der Ven

---

NORWAY

Hewlett-Packard Norge A/S

Country Response Center

P.O. Box 34

Osterndalen 16-18

N-1345 Osteras

Norway

Ph: (47) 2-17-11-80

Manager: Petter Bakken

---

SINGAPORE

Hewlett-Packard Singapore Pte. Ltd.

1150 Depot Road

Singapore 0410,

Republic of Singapore

Ph: (65) 273-7388

Manager: Kin-Kong Ngho

---

SOUTH AFRICA

Hewlett-Packard S. Africa (PTY) Ltd.

(4)

Private Bag Wendywood  
Sandton 2144  
South Africa

Ph: (27) 11-802-5111 (main)  
(27) 11-804-1332 (response center dedicated line)

Manager: Ernest Puchades

---

SPAIN

Hewlett-Packard Espanola S.A.  
Carretera de la Coruna km  
16,400 Las Rozas E-Madrid  
Spain

Ph: (34) 1-637-00-11  
Manager: Jose Luis Perez

---

SWEDEN

Hewlett-Packard Sverige AB  
Support Center  
Skalholtsgatan 9,  
Kista Box 19 S-163 93 Spanga  
Sweden

Ph: (46) 8-750-20-00  
Manager: Hans Gunnarsson

---

SWITZERLAND

Hewlett-Packard (Schweiz)  
Country Response Center  
Meriedweg 7  
3172 Niederwangen  
Switzerland

Ph: (41) 31-34-34-41  
Manager: Urs Brunner

---

TAIWAN

Hewlett-Packard Taiwan Ltd.  
8th Floor Hewlett-Packard Building  
337 Fu Hsing North Road  
Taipei, Taiwan  
Republic of China

Ph: (886) 2-412-0404  
Manager: Simon Huang  
Secretary: Linda Liang

---

UNITED KINGDOM

Hewlett-Packard Ltd.  
King Street Lane  
Winnersh, Wokingham  
Berkshire RG11 5AR  
United Kingdom

Ph: (44) 734-784774

Manager: Dave Ellis  
Secretary: Sandra Gathergood

---

UNITED STATES OF AMERICA

Hewlett-Packard Company  
North American Response Center - East  
2000 South Park Place  
Atlanta, Georgia 30348

Ph: (404) 953-1840 (main)  
Manager: Nick Voigt  
Secretary: Louise Howell

---

Hewlett-Packard Company  
North American Response Center - West  
100 Mayfield Avenue  
Building 37  
Mountain View, California 94043

Ph: (415) 968-5600 (main)  
Manager: Dan Grove  
Secretary: Donna Nattkemper

---

VENEZUELA

Hewlett-Packard de Venezuela C.A.  
Response Center  
Tercera Transersal  
Los Ruices Norte  
Edificio Segre, 2 y 3 Pisos  
Caracas 1071, Venezuela

Ph: (58) 2-239-4133  
Manager: Haroldo Level

---





Customer Order Number

**NONE**

Printed in USA

**\*\* For HP Internal Reference Only \*\***

Manufacturing Part Number

**5960-0682**

