

\*rB

\*rB FULL DUPLEX HARDWIRED Port 1  
BaudRate 9600 Parity Odd DataBits 7 Clock INT  
Asterisk OFF Stop Bits 1 EnqAck Yes  
TR(CD) Hi Check Parity No SR(CH) Lo  
RecvPace Xon/Xoff SRRXmit No RR(CF)Recv No  
XmitPace None SRRInvert No CS(CB)Xmit No DM(CC)Xmit No

WS/250 HP-150 Port 1 terminal settings.  
Use straight through 25-pin M-M cable.